

CIVIL AERONAUTICS BOARD  
Washington 25, D. C.

July 1950

Oswald Ryan - Acting Chairman

Josh Lee, Member  
Harold A. Jones, Member  
Russell B. Adams, Member

William K. Andrews, Director  
Bureau of Safety Investigation

Jesse W. Lankford, Chief  
Accident Analysis Division

Ben W. Ashmead, Chief  
Statistical Analysis Section

**ACCIDENTS IN U. S. SCHEDULED AIR CARRIER  
PASSENGER OPERATIONS  
(Calendar Years 1949 & 1948)**

U. S. air carrier accidents in scheduled domestic and scheduled international passenger service during 1949 and 1948 are summarized in this report. Statistics are attached which show number of accidents, passenger and revenue plane miles flown, passengers carried, passenger fatalities per 100 million passenger miles, and crew fatalities. Tabulations are also attached showing in detail accident types and causes, personal injuries and aircraft damage.

**COMPOSITE DOMESTIC AND U. S. FLAG INTERNATIONAL OPERATIONS (Table I)**

**Record Annual Passenger Total—Lowest Passenger Fatality Rate**

The U. S. scheduled air carriers in passenger operation, domestic and international, in 1949 transported a record annual total of 16,640,082 revenue passengers 9,239,822,000 passenger miles with a passenger fatality rate of 1.0 per 100 million passenger miles. This compared with 14,540,951 revenue passengers carried 8,207,539,000 passenger miles at a 1.3 passenger fatality rate in 1948. The passenger fatality rate of 1.0 for combined operations in 1949 was the lowest ever achieved in any previous calendar year.

In the 1949 operations, there were 37 accidents, of which 4 were fatal resulting in 93 passenger, and 11 crew fatalities. In 1948 there were 63 accidents of which 6 were fatal causing 103 passenger and 25 crew fatalities. Revenue plane miles flown in 1949 aggregated 432,746,476 against 414,754,584 in 1948.

**ALL DOMESTIC SCHEDULED OPERATIONS (Table I)**

The Bureau of Economic Regulation<sup>1/</sup> separates the scheduled domestic air carriers into 3 specific groups, defined as follows:

1. "Trunk Lines: Those permanently certificated scheduled air carriers engaged in the transportation of mail, passengers and property over the major airline networks of the country."

<sup>1/</sup> Also, the source of all traffic statistics used in this report.

2. "Feeder Lines: Those temporarily certificated scheduled air carriers engaged in local services of a regional scope." Los Angeles Airways, Inc. and Helicopter Air Service although included in the "feeder group" are not considered in this report because of their specialized service involving the carrying of mail by helicopter.
3. "Territorial Lines: Consist of those permanently certificated scheduled air carriers conducting services wholly in territories or possessions of the United States."

#### Over 15 Million Passengers Carried in Domestic Operations

The trunk, feeder and territorial scheduled airlines in 1949 flew 15,120,015 revenue passengers 7,071,042,000 passenger miles at a passenger fatality rate of 1.3 per 100 million passenger miles. In 1948, a total of 13,168,095 revenue passengers were transported 6,245,745,000 passenger miles at an identical passenger fatality rate. In the four fatal accidents for 1949, there were 93 passenger and 11 crew fatalities against 83 passenger and 15 crew fatalities in 1948.

Revenue plane miles in this class of operation during 1949 totaled 333,707,756 against 320,834,753 in the preceding year. There were 4 fatal and 25 non-fatal accidents in 1949 in comparison with 5 fatal and 47 non-fatal accidents in 1948.

#### Record Number of Plane Miles per Fatal Accident

In 1949, both plane miles flown per fatal accident and per accident were higher than in any previous calendar year. Comparative figures in domestic passenger operations for the 1938 - 1949 period are shown below:

##### PLANE MILES FLOWN

	<u>Per Fatal Accident</u>	<u>Per Accident</u>
1938.....	13,679,665	3,109,015
1939.....	41,457,043	3,070,892
1940.....	36,623,681	3,788,657
1941.....	33,374,422	5,134,526
1942.....	21,944,063	4,770,449
1943.....	50,619,218	7,231,317
1944.....	42,645,848	5,330,731
1945.....	27,694,694	5,874,632
1946.....	33,256,332	9,655,064
1947.....	62,628,604	8,698,417
1948.....	64,166,950	6,169,899
1949.....	83,426,939	11,918,134

### TRUNK LINE CARRIERS (Table Nos. I & II)

The 16 trunk carriers during 1949 flew 14,021,047 revenue passengers 6,69,350,000 passenger miles at a passenger fatality rate of 1.4 in comparison with 12,324,038 revenue passengers flown 6,095,365,000 passenger miles at an identical fatality rate in 1948. Revenue plane miles flown in 1949 totaled 301,072,766 (301,194,517 in 1948). The 4 fatal and 22 non-fatal accidents in 1949 compared with 5 fatal and 39 non-fatal accidents in 1948. Ninety three passengers and 11 crew members were fatally injured against 83 and 15, respectively, in 1948.

### FEEDER AIRLINES (Table Nos. I & VII)

These carriers flew 677,817 revenue passengers 147,999,000 passenger miles without a single passenger or crew fatality in 1949. The respective figures in 1948 were 425,685 passengers and 96,965,000 passenger miles likewise without a single passenger or crew fatality. There were no fatalities in feeder operation during 1946 and 1947.

### TERRITORIAL CARRIERS (Table Nos. I & VIII)

The territorial carriers transported 421,151 revenue passengers 53,693,000 passenger miles without fatality and accident free in 1949. In 1948 a total of 411,372 revenue passengers were carried 53,415,000 passenger miles also without fatality.

### TYPES, CAUSES, OPERATIONAL PHASES, INJURY AND DAMAGE IN DOMESTIC AIR CARRIER ACCIDENTS (Table Nos. III, IV, V and VI) (Trunk, Feeder, & Territorial)

#### Type of Accident vs Operational Phase (Table III)

In 1949 there were 6 accidents involving collision with objects other than aircraft (8 in 1948). Two occurred during landing roll, 1 each in taxiing to take off, taxiing from landing, and take off run, and 1 in normal flight. There were 3 mid-air collisions between aircraft, 3 stalls, and 3 instances of overshooting. Undershooting and fire in air accounted for 2 accidents each. Ground-loop, wheels up, hard landing, nose up-over, collision two aircraft (both on ground) and airframe failure resulted in 1 accident each. Four other accidents involved the following: Prop. failure 2, hailstorm 1, and severe pitching in air 1.

#### Type of Accident vs Injury (Table IV)

Of the 4 fatal accidents in domestic scheduled operation, 2 involved mid-air collision between aircraft, and 2 stalls. There were 3 serious injury accidents which resulted from overshooting, severe pitching in air, and stall.

#### Operational Phase vs Injury (Table V)

Of the 4 fatal accidents in 1949, one occurred during normal flight, 2 in landing approach, and 1 in a go-around. Three of the 5 fatal accidents in 1948 occurred in normal flight, and 1 each in take off climb and landing approach. The 3 serious injury accidents in 1949 were during take off climb, normal flight and landing roll. The 2 serious injury accidents in 1948 happened in normal flight.

Included with the 22 minor and no injury accidents were 8 during the landing roll, 5 in normal flight, and 2 each in take off run and landing approach. The remaining 5 accidents fell under diversified phase headings.

During 1949, six aircraft were destroyed, 21 received substantial damage and 2 received minor or no damage. Seven aircraft were destroyed, 43 substantially damaged and 2 received minor or no damage in 1948.

#### Primary Cause vs Operational Phase (Table VI)

Pilot error was the primary cause of 9 (31%) of the 29 accidents for domestic scheduled operations in 1949. This factor accounted for 18 (34.6%) of the 52 accidents in 1948. Other personnel error was the primary cause of 4 accidents in 1949 (1 in 1948), powerplant 4 (8), airframe 1 (2), landing gear 2 (8), equipment and accessories 1 (1), weather 2 (8), airport terrain 3 (3), miscellaneous 1 (2), and undetermined 0 (1). Two accidents are still in process with respect to determination of probable cause.

The detailed factors of these primary causes are set forth in Table VI in relation to the operational phase of the aircraft at time of accident.

#### U. S. FLAG INTERNATIONAL SCHEDULED CARRIERS

##### Record Level of Operations Without Fatality

The international scheduled carriers (see Tables I & IX) transported 1,520,067 revenue passengers 2,168,780,000 passenger miles without a single passenger or crew fatality in 1949. This compares with 1,372,856 revenue passengers and 1,961,794,000 passenger miles in 1948 at a 1.0 passenger fatality rate per 100 million passenger miles. In that year there was one fatal accident which caused 20 passenger and 10 crew fatalities.

##### Type of Accident (Tables X & XI)

In the 8 accidents for international operations in 1949, the type of accident included undershooting 1, collision between aircraft (both airborne) 1, collision with other objects 4, fire in air 1 and turbulence 1.

##### Primary Cause (Table XII)

Pilot error was the primary cause of 6 (75%) of the 8 accidents in 1949 and of 3 (27.3%) of the 11 accidents in 1948. Powerplant and weather accounted for 1 accident each.

##### Operational Phase vs Injury and Damage (Table XIII)

Of the 8 accidents in 1949, 1 resulted in serious injury and 7 in minor or no injury. Three occurred in normal flight, 3 in landing approach and 1 each in taxiing from landing and taxiing in returning to ramp. None of the air carrier aircraft involved in the 8 accidents incurred greater than substantial damage.

In 1948, the single fatal accident occurred during the landing approach.

INDEX OF TABULATIONS

Tables

- I Comparative Safety Record of All Classes of U. S. Air Carriers in Scheduled Passenger Operations (Calendar Years 1949 and 1948)
- II Comparative Safety Record of Individual Domestic Trunk Line Air Carriers in Domestic Scheduled Passenger Operations (Calendar Years 1949 and 1948)
- III Type of Accident vs Operational Phase in Scheduled Domestic Trunk, Feeder and Territorial Air Carrier Passenger Operations (Calendar Years 1949 and 1948)
- IV Type of Accident vs Injury and Damage in Scheduled Domestic Trunk, Feeder and Territorial Air Carrier Passenger Operations (Calendar Years 1949 and 1948)
- V Operational Phase vs Injury and Damage in Scheduled Domestic Trunk, Feeder and Territorial Air Carrier Passenger Operations (Calendar Years 1949 and 1948)
- VI Primary Cause of Accidents vs Operational Phase in Scheduled Domestic Trunk, Feeder and Territorial Air Carrier Passenger Operations (Calendar Years 1949 and 1948)
- VII Comparative Safety Record of Individual U. S. Domestic Feeder Air Carriers in Scheduled Passenger Operations (Calendar Years 1949 and 1948)
- VIII Comparative Safety Record of Individual U. S. Territorial Air Carriers in Scheduled Passenger Operations (Calendar Years 1949 and 1948)
- IX Comparative Safety Record of U. S. Flag Scheduled Air Carriers in International Passenger Operations (Calendar Years 1949 and 1948)
- X Type of Accident vs Operational Phase in U. S. Flag Scheduled Air Carriers in International Passenger Operations (Calendar Years 1949 and 1948)
- XI Type of Accident vs Injury and Damage in U. S. Flag Scheduled Air Carriers in International Passenger Operations (Calendar Years 1949 and 1948)
- XII Primary Cause of Accidents vs Operational Phase in U. S. Flag Scheduled Air Carriers in International Passenger Operations (Calendar Years 1949 and 1948)
- XIII Operational Phase vs Injury and Damage in U. S. Flag Scheduled Air Carriers in International Passenger Operations (Calendar Years 1949 and 1948)

Charts

- A Passenger Fatality Rate and Passenger Miles in Domestic Air Carrier Scheduled Passenger Carrying Operations (Calendar Years 1938 - 1949)
- B Number of Air Carrier Accidents in Scheduled Domestic Passenger Carrying Operations (Calendar Years 1938 - 1949)

**COMPARATIVE SAFETY RECORD OF ALL CLASSES OF U. S. AIR CARRIERS  
IN SCHEDULED PASSENGER OPERATIONS**  
(Calendar Years 1949 & 1948 by Quarters)

TABLE I

Classes of Operation	Accidents	Total	Passenger Carried	Passenger Fatal	Passenger			Crew Fatalities	Revenue <sup>2</sup> /Plane Miles
					Miles	(000)	per 100 Mil- lion Passen- ger Miles	Pilot	Copilot
<b>DOMESTIC</b>									
Trunk Lines									
1st Quarter 1949	6	-	2,780,362	-	1,424,758	-	-	-	69,180,846
2nd Quarter 1949	5	-	3,927,007	-	1,894,910	-	-	-	78,891,990
3rd Quarter 1949	9	1	4,006,951	12	1,932,236	.6	1	1	82,498,076
4th Quarter 1949	6	2	3,206,727	81	1,617,446	5.0	2	4	75,501,854
Total.....	26	4	14,021,047	93	6,869,350	1.4	3	5	306,072,766
1st Quarter 1948	11	3	2,326,912	11	1,223,432	.9	2	2	66,613,844
2nd Quarter 1948	8	1	3,331,887	39	1,647,557	2.4	1	1	77,054,574
3rd Quarter 1948	11	1	3,562,031	33	1,718,213	1.9	1	1	82,713,433
4th Quarter 1948	14	5	3,103,208	53	1,506,163	1.4	4	7	76,812,696
Total.....	44	5	12,324,038	133	6,095,365	1.4	4	7	301,194,517
Feeder Lines									
1st Quarter 1949			103,929		24,080				4,631,388
2nd Quarter 1949		2	176,446		38,715				5,670,746
3rd Quarter 1949		-	225,016		47,248				6,581,385
4th Quarter 1949		5	172,422		37,956				7,040,812
Total.....		3	677,817		147,999				23,924,331
1st Quarter 1948		1	56,051		12,914				2,646,547
2nd Quarter 1948		2	106,057		23,877				3,943,043
3rd Quarter 1948		2	142,860		32,350				4,784,069
4th Quarter 1948		2	120,717		27,824				4,205,513
Total.....		7	425,685		96,965				16,279,202

- 6 -

TABLE I (Continued)

Classes of Operation	Accidents Total Fatal	Passenger 2/ Carried/ Fatal 2/		Passenger 2/ Miles (000)		Passenger 2/ Per 100 Mil- lion Passen- ger Miles		Passenger Fatalities		Revenue 3/ Plane Miles	
		Passenger	Crew	Pilot	Copilot	Other	Pilot	Copilot	Other	Pilot	Copilot
<u>Territorial Lines</u>											
1st Quarter 1949	95,637	11,829	-	-	-	-	-	-	-	769,758	
2nd Quarter 1949	105,713	13,304	-	-	-	-	-	-	-	859,876	
3rd Quarter 1949	128,326	16,931	-	-	-	-	-	-	-	1,149,682	
4th Quarter 1949	91,475	11,629	-	-	-	-	-	-	-	921,342	
Total.....	421,151	53,693	-	-	-	-	-	-	-	3,710,659	
1st Quarter 1948	97,344	12,181	-	-	-	-	-	-	-	759,117	
2nd Quarter 1948	101,733	13,092	-	-	-	-	-	-	-	828,225	
3rd Quarter 1948	124,873	16,424	-	-	-	-	-	-	-	1,032,750	
4th Quarter 1948	94,422	11,718	-	-	-	-	-	-	-	740,942	
Total.....	418,372	53,415	-	-	-	-	-	-	-	3,361,034	
Sub-Total Domestic	7	2,979,928	-	-	1,460,667	-	-	-	-	74,531,1992	
1st Quarter 1949	7	4,209,168	-	-	1,946,929	-	-	-	-	85,422,612	
2nd Quarter 1949	1	4,360,295	12	1,996,415	.6	-	-	-	-	90,229,113	
3rd Quarter 1949	2	3,570,624	81	1,667,031	4.9	-	-	-	-	93,474,009	
4th Quarter 1949	6	15,120,015	92	7,071,042	1.3	-	-	-	-	333,707,756	
Total.....	29	4	-	-	-	-	-	-	-	-	
1st Quarter 1948	12	2,480,307	11	1,248,527	.9	-	2	2	3	70,219,476	
2nd Quarter 1948	10	3,539,677	39	1,684,526	2.3	-	1	1	2	81,925,842	
3rd Quarter 1948	13	3,829,764	33	1,766,987	1.9	-	1	1	2	88,530,252	
4th Quarter 1948	17	2,218,347	83	1,545,705	1.1	-	1	1	2	80,259,181	
Total.....	52	5	13,168,095	6,245,745	1.3	-	1	1	2	320,834,753	
INTERNATIONAL	9	-	-	-	-	-	-	-	-	23,152,557	
1st Quarter 1949	1	361,526	165,247	-	-	-	-	-	-	24,955,544	
2nd Quarter 1949	1	385,516	575,793	-	-	-	-	-	-	27,035,945	
3rd Quarter 1949	1	431,524	640,400	-	-	-	-	-	-	23,894,674	
4th Quarter 1949	3	340,501	487,340	-	-	-	-	-	-	29,038,720	
Total.....	9	1,530,067	2,168,780	-	-	-	-	-	-	-	
1st Quarter 1948	3	317,639	-	-	-	-	-	-	-	21,011,759	
2nd Quarter 1948	5	230,353	495,160	40	-	-	-	-	-	22,906,760	
3rd Quarter 1948	1	393,891	573,210	-	-	-	-	-	-	25,722,105	
4th Quarter 1948	2	230,973	496,152	-	-	-	-	-	-	24,249,297	
Total.....	11	1	1,372,856	1,961,794	1.0	-	-	-	-	93,919,831	

TABLE I (Continued)

Classes of Operation	Accidents		Passenger Carried	Passenger Fatal	Passenger 2/ Miles (000)		Crew Fatalities Pilot Copilot Other	Revenue 3/ Plane Miles
	Total	Fatal			Miles	Per 100 Miles		
<b>Grand Total All Carriers</b>								
1st Quarter 1949	10	-	3,341,454	-	1,925,914	-	-	97,734,549
2nd Quarter 1949	8	-	4,594,684	-	2,525,722	-	-	110,378,156
3rd Quarter 1949	10	1	4,791,819	12	2,636,815	.5	1	117,265,088
4th Quarter 1949	9	2	3,912,125	81	2,154,371	2.8	2	107,268,683
Total.....	37	4	16,640,082	93	9,241,160	1.0	3	432,746,476
1st Quarter 1948	15	3	2,797,946	11	1,645,799	.7	2	91,261,237
2nd Quarter 1948	15	2	3,870,030	59	2,179,686	2.7	2	104,732,602
3rd Quarter 1948	14	1	4,223,655	33	2,340,197	1.4	1	114,252,357
4th Quarter 1948	19	-	3,649,320	-	2,041,857	.5	1	104,508,388
Total.....	63	6	14,340,951	103	8,207,539	1.3	3	414,754,584

1/ Revenue passengers only.

2/ Both revenue and non-revenue.

3/ In scheduled passenger operations.

NOTE: Excludes propeller accidents to persons.

Statistics for 1949 contained in this and subsequent tables are subject to slight revision.

CARRIERS IN DOMESTIC SCHEDULED PASSENGER OPERATIONS  
(Calendar Years 1949 & 1948 by Quarters)

TABLE II

Operators	Accidents			Passenger 2/		Revenue 3/		
	Total	Fatal	Carried	Miles (000)	Passenger Miles Carried	Crew Fatalities	Plane Miles	
			Fatal 12/		Pilot Copilot Other		Miles	
<b>American Airlines</b>								
1st Quarter 1949	1	-	623,366	-	330,570	-	-	11,361,748
2nd Quarter 1949	2	-	921,675	-	441,141	-	-	13,154,155
3rd Quarter 1949	1	-	902,361	-	440,073	-	-	13,832,733
4th Quarter 1949	2	1	766,995	26	379,724	-	-	13,097,937
Total.....	7	1	3,214,897	26	1,591,508	-	2	51,445,673
1st Quarter 1948	-	462,528	237,993	10,415,885				
2nd Quarter 1948	5	748,031	365,285	13,125,019				
3rd Quarter 1948	2	835,642	399,212	15,057,927				
4th Quarter 1948	4	724,799	372,655	12,595,148				
Total.....	11	2,781,000	1,375,145	51,193,979				
<b>Brailiff Airways</b>								
1st Quarter 1949	122,585	43,356						2,564,269
2nd Quarter 1949	161,197	56,332						2,781,215
3rd Quarter 1949	160,990	56,910						2,923,314
4th Quarter 1949	146,704	51,216						2,718,140
Total.....	591,476	207,814						10,986,938
1st Quarter 1948	112,404	41,518						2,470,015
2nd Quarter 1948	152,819	54,638						2,685,699
3rd Quarter 1948	151,943	55,199						2,797,570
4th Quarter 1948	148,500	52,506						2,797,861
Total.....	565,666	203,861						10,751,151

TABLE II (Continued)

Operators	Accidents Total	Fatal Total	Passenger 2/ Carried/ Fatal 2		Passenger 2/ Miles (000)		Crew Fatalities Pilot Copilot Other		Revenue 2/ Plane Miles	
			Passenger	Miles						
<u>Capital Airlines (P.C.A.)</u>										
1st Quarter 1949	-	-	202,789	-	61,050	-	-	-	4,143,121	
2nd Quarter 1949	-	-	345,703	-	106,104	-	-	-	5,038,898	
3rd Quarter 1949	2	-	357,915	-	108,561	-	-	-	5,269,468	
4th Quarter 1949	1	1	284,593	4	88,147	1	1	-	4,869,963	
Total.....	3	1	1,191,000	4	363,862	1	1	-	19,321,450	
1st Quarter 1948	-	-	186,602	49,989	3,305,184					
2nd Quarter 1948	-	-	287,524	80,989	4,467,672					
3rd Quarter 1948	-	-	297,017	81,896	4,606,156					
4th Quarter 1948	2	2	250,756	74,068	4,296,156					
Total.....	2	2	1,021,899	286,942	16,675,168					
<u>Chicago &amp; Southern Air Lines</u>										
1st Quarter 1949	-	-	62,224	23,474	1,698,663					
2nd Quarter 1949	-	-	84,665	31,849	1,940,665					
3rd Quarter 1949	-	-	89,894	30,415	2,017,953					
4th Quarter 1949	-	-	76,171	26,998	1,826,441					
Total.....	-	-	312,954	112,736	7,483,722					
1st Quarter 1948	-	-	52,969	22,380	1,511,807					
2nd Quarter 1948	-	-	75,675	30,711	1,767,114					
3rd Quarter 1948	-	-	79,265	29,737	1,922,237					
4th Quarter 1948	-	-	73,529	27,344	1,873,494					
Total.....	-	-	281,438	110,172	7,074,652					
<u>Colonial Airlines</u>										
1st Quarter 1949	-	-	33,256	9,101	781,738					
2nd Quarter 1949	-	-	51,175	13,800	1,017,339					
3rd Quarter 1949	-	-	66,472	16,918	1,281,935					
4th Quarter 1949	-	-	41,337	11,002	953,051					
Total.....	-	-	192,240	50,821	4,034,063					
1st Quarter 1948	-	-	23,604	6,799	552,867					
2nd Quarter 1948	-	-	35,523	10,056	728,752					
3rd Quarter 1948	-	-	47,786	13,090	947,345					
4th Quarter 1948	-	-	25,650	9,761	847,042					
Total.....	-	-	142,563	39,706	3,076,006					

TABLE II (Continued)

Operators	Accidents		Passengers		Crew Fatalities		Plane Miles Miles
	Total	Fatal	Carried	Fatal	Pilot	Copilot	Other
<u>Continental Air Lines</u>							
1st Quarter 1949	1		34,872	19,545	1,350,531		
2nd Quarter 1949	-	1	49,371	19,136	1,475,396		
3rd Quarter 1949	1		52,250	20,894	1,486,910		
4th Quarter 1949	-	2	13,202	16,795	1,370,443		
Total.....			179,695	70,370	5,683,280		
<u>Delta Air Lines</u>							
1st Quarter 1948	-	1	30,724	11,936	1,203,814		
2nd Quarter 1948	1		43,335	16,869	1,409,619		
3rd Quarter 1948	2		48,148	18,792	1,583,159		
4th Quarter 1948	-	3	29,181	14,881	1,392,642		
Total.....			161,368	62,476	5,590,235		
<u>Eastern Air Lines</u>							
1st Quarter 1949	-	1	122,238	57,204	2,894,005		
2nd Quarter 1949	1		142,922	57,180	3,004,538		
3rd Quarter 1949	-	1	133,961	52,099	3,039,401		
4th Quarter 1949	-	1	126,718	51,404	2,981,867		
Total.....			525,839	217,887	11,919,811		
<u>Trans World Airlines</u>							
1st Quarter 1948	2	1	99,010	6	1	2	3,014,687
2nd Quarter 1948	-	1	133,273	49,935	-	-	3,053,418
3rd Quarter 1948	-	1	129,720	47,758	-	-	2,999,831
4th Quarter 1948	-	1	123,601	48,761	-	-	2,978,327
Total.....			485,604	191,730			12,046,263
<u>Midwest Airlines</u>							
1st Quarter 1948	2	1	514,544	45,276	1	1	-
2nd Quarter 1948	-	1	608,745	49,935	-	-	12,693,696
3rd Quarter 1948	2	1	560,039	47,758	1	1	12,371,416
4th Quarter 1948	1	2	524,194	48,761	1	1	12,466,056
Total.....		5	2,207,522	63	1,037,113	3	49,983,391
<u>Southwest Airlines</u>							
1st Quarter 1948	5	2	514,544	274,097	-	-	-
2nd Quarter 1948	-	1	608,745	274,181	-	-	12,452,223
3rd Quarter 1948	2	1	560,039	214,973	1	1	12,609,772
4th Quarter 1948	1	5	524,194	243,862	1	1	11,654,316
Total.....		5	2,207,522	63	1,037,113	3	47,410,263
<u>Other</u>							
1st Quarter 1948	5	2	466,083	3	1	1	12,032,051
2nd Quarter 1948	-	1	541,928	-	-	-	-
3rd Quarter 1948	-	1	498,776	-	-	-	11,609,772
4th Quarter 1948	-	2	491,998	-	-	-	11,654,316
Total.....		5	1,998,785	3	1,008,021	3	47,410,263
					- 11 -		

TABLE II (Continued)

Operators	Accidents		Passenger <sup>2/</sup>		Passenger <sup>2/</sup>		Crew Fatalities		Revenue <sup>1/</sup>	
	Total	Fatal	Carried	Fatal <sup>2/</sup>	Miles (000)	Crew Miles	Pilot	Copilot	Other	Plane Miles
<u>Inland Air Lines</u>										
1st Quarter 1949			17,477		6,052	5,771	21,907	1,853,534	551,667	
2nd Quarter 1949			21,334		8,424	7,077	28,753	2,196,554	694,463	
3rd Quarter 1949			25,837		10,102	21,533	28,488	2,300,364	805,659	
4th Quarter 1949			20,222		7,745	17,999	25,007	2,128,511	695,837	
Total.....			84,870		32,623	73,680	104,155	6,476,963	2,747,636	
1st Quarter 1948			15,366		5,771	5,771	19,244	1,651,803	2,110,237	
2nd Quarter 1948			18,782		7,077	7,077	27,329	2,175,118	586,117	
3rd Quarter 1948			21,533		8,195	8,195	26,995	2,022,585	577,854	
4th Quarter 1948			17,999		6,616	6,616	24,267	10,064,113	1,815,218	
Total.....			73,680		27,659	27,659	97,835	7,969,743	5,643,733	
<u>Mid-Continent Airlines</u>										
1st Quarter 1949	1		69,463		21,907	21,907	19,244	2,274,427	1,264,643	
2nd Quarter 1949	-		92,867		28,753	28,753	27,329	2,518,001	2,518,001	
3rd Quarter 1949	-		92,668		28,488	28,488	26,995	2,597,284	1,662,570	
4th Quarter 1949	-		82,519		104,155	104,155	183,464	2,674,101	1,815,218	
Total.....			337,517					10,064,113	5,643,733	
1st Quarter 1948			60,910		19,244	19,244	16,924	901,307	-	
2nd Quarter 1948			87,561		27,329	27,329	22,720	-	1,264,643	
3rd Quarter 1948			86,711		26,995	26,995	25,928	-	2,518,001	
4th Quarter 1948			77,919		24,267	24,267	32,477	-	2,597,284	
Total.....			313,101		97,835	97,835	98,049	-	1,662,570	
<u>National Airlines</u>										
1st Quarter 1949			80,184		51,713	51,713	16,924	-	-	
2nd Quarter 1949			73,114		44,071	44,071	22,720	-	-	
3rd Quarter 1949			71,239		42,446	42,446	25,928	-	-	
4th Quarter 1949			72,976		45,234	45,234	32,477	-	-	
Total.....			297,513					-	-	
1st Quarter 1948			30,028		16,924	16,924	16,924	-	-	
2nd Quarter 1948			36,353		22,720	22,720	22,720	-	-	
3rd Quarter 1948			44,898		25,928	25,928	25,928	-	-	
4th Quarter 1948			54,373		32,477	32,477	32,477	-	-	
Total.....			165,652		98,049	98,049	98,049	-	-	

TABLE II (Continued)

Operators	Accidents		Carried/ Fatal		Passenger <sup>2</sup>		Revenue <sup>3</sup>	
	Total	Fatal	Miles (000)	Miles (000)	Pilot Copilot Other	Plane Miles	Plane Miles	
<u>Northeast Airlines</u>								
1st Quarter 1949	-	-	54,246	-	10,978	794,858	995,137	
2nd Quarter 1949	-	-	87,449	-	17,480	1,296,922	1,296,922	
3rd Quarter 1949	1	-	115,744	-	23,235	986,625	986,625	
4th Quarter 1949	-	1	67,524	-	12,723	4,013,572	4,013,572	
Total.....	1	1	324,963	-	65,416	-	-	
1st Quarter 1948	-	-	47,876	-	9,476	690,276	827,888	
2nd Quarter 1948	-	-	68,696	-	13,809	1,059,996	1,059,996	
3rd Quarter 1948	-	-	96,478	-	19,528	787,500	787,500	
4th Quarter 1948	-	1	59,240	-	11,911	3,365,660	3,365,660	
Total.....	1	1	272,292	-	54,724	-	-	
1st Quarter 1949	-	-	118,094	-	62,512	3,661,760	4,711,785	
2nd Quarter 1949	-	-	202,733	-	119,511	5,262,307	5,262,307	
3rd Quarter 1949	1	-	227,447	-	141,224	5,059,882	5,059,882	
4th Quarter 1949	-	1	180,637	-	114,586	18,694,734	18,694,734	
Total.....	1	1	728,911	-	437,833	-	-	
1st Quarter 1948	-	-	110,422	-	59,747	3,420,792	4,400,777	
2nd Quarter 1948	-	-	178,182	-	99,381	4,821,846	4,821,846	
3rd Quarter 1948	4	-	192,138	33	107,078	2	2	
4th Quarter 1948	-	1	123,448	-	72,228	3,982,223	3,982,223	
Total.....	5	1	614,190	33	338,734	1	2	
1st Quarter 1949	-	-	261,435	-	192,923	11,155,321	12,524,283	
2nd Quarter 1949	-	-	403,671	-	287,545	12,692,935	12,692,935	
3rd Quarter 1949	-	-	401,660	-	291,458	10,215,208	10,215,208	
4th Quarter 1949	-	1	319,841	-	225,025	46,687,747	46,687,747	
Total.....	2	1	1,386,607	-	996,961	-	-	
<u>Transcontinental &amp; Western Air</u>								
1st Quarter 1949	1	-	234,769	3	195,016	11,721,619	13,054,956	
2nd Quarter 1949	-	1	330,608	1	244,005	14,210,659	14,210,659	
3rd Quarter 1949	-	-	356,149	-	257,375	13,165,022	13,165,022	
4th Quarter 1949	-	1	315,275	-	218,307	52,152,256	52,152,256	
Total.....	2	1	1,236,901	-	914,703	-	-	

- 13 -

TABLE III. (Continued)

Operators	Accidents		Passenger		Passenger		Crew Fatalities		Revenue <sup>1</sup>	
	Total	Fatal	Carried	Miles (000)	Pilot	Copilot	Other	Miles	Plane	Miles
<u>All Air Lines</u>										
1st Quarter 1949	1		464,189	212,726				10,197,927		
2nd Quarter 1949	1		607,483	360,907				12,660,759		
3rd Quarter 1949	-		672,832	393,104				13,666,001		
4th Quarter 1949	-		458,560	289,914				11,665,232		
Total.....	2		2,173,064	1,286,651				48,190,020		
1st Quarter 1948	1		-	331,664	-	193,374	-	11,590,332		
2nd Quarter 1948	1	1	523,453	39	330,216	1	2	13,992,761		
3rd Quarter 1948	1	-	598,758	-	364,508	-	-	14,973,781		
4th Quarter 1948	-	3	480,937	39	285,847	-	1	12,443,082		
Total.....	1		1,934,812	39	1,173,945		2	52,999,957		
Western Air Lines										
1st Quarter 1949			59,400	23,550				1,445,054		
2nd Quarter 1949			72,903	28,496				1,485,106		
3rd Quarter 1949			75,142	31,036				1,714,474		
4th Quarter 1949			64,524	27,024				1,693,019		
Total.....			271,979	110,136				6,337,653		
1st Quarter 1948			61,953	24,680				1,481,592		
2nd Quarter 1948			70,142	28,745				1,557,337		
3rd Quarter 1948			77,069	32,300				1,699,349		
4th Quarter 1948			65,903	25,926				1,572,216		
Total.....			275,067	111,661				6,310,494		
Grand Total - Trunk Lines										
1st Quarter 1949	6	-	2,780,362	-	1,424,758	-	-	69,180,846		
2nd Quarter 1949	5	-	3,927,007	-	1,894,910	-	-	78,891,990		
3rd Quarter 1949	9	1	4,006,951	12	1,932,236	1	1	82,498,076		
4th Quarter 1949	5	1	3,765,727	31	1,617,446	2	2	25,501,824		
Total.....	11	1	12,478,445	93	6,869,350	3	3	306,072,766		
1st Quarter 1948	11	1	4,326,912	11	1,223,432	2	2	3	66,613,814	
2nd Quarter 1948	8	1	3,331,887	39	1,647,557	1	1	77,054,574		
3rd Quarter 1948	11	1	3,562,031	33	1,718,213	1	1	82,713,433		
4th Quarter 1948	14	-	2,103,208	-	1,506,163	-	-	74,812,696		
Total.....	44	5	12,324,038	83	6,095,365	4	4	201,194,517		

1/ Revenue passengers only.  
2/ Both revenue and non-revenue.

3/ In scheduled passenger operations.

4/ Excludes propeller accidents to persons.

5/ NOTE: - 14 -

TABLE III  
TYPE OF ACCIDENT VS OPERATIONAL PHASE IN SCHEDULED DOMESTIC TRUNK, FEEDER AND TERRITORIAL AIR CARRIER PASSENGER OPERATIONS  
(Calendar Years 1949 and 1948)

Type of Accident	OPERATIONAL PHASE										Total				
	To Take Off	From Landing	Other	Run	Climb	Descent	Normal Flight	Approach	Level Off	Roll Around	Go Around	Start Engine	Idling	Other	
Ground, or water Loop															1
1949.....															2
1948.....															1
Wheels up-down															1
1949.....															3
1948.....															1
Hard landing															1
1949.....															1
1948.....															1
Clips -- retract. Landing gear															1
1949.....															9
1948.....															4
Overshoot															5
1949.....															2
1948.....															1
Undershoot															3
1949.....															2
1948.....															1
Nose up-over															1
1949.....															1
1948.....															1
Collision two aircraft															3
Airborne															5
1949.....															1
1948.....															1
Both on ground															5
1949.....															1
1948.....															1
Collision - Ground															3
1949.....															1
1948.....															1

*2a/*

TABLE III (Continued)

Type of Accident	OPERATIONAL PHASE										Ground					Total
	To Off	From Landing	Taxing	Take Off	Other	Run	Climb	Descent	Normal Flight	Approach	Level Off	Go Around	Start Engines	Landing	Other	
Collision - objects																6
1949.....	1 <sup>a/</sup>	-	-	-	-	-	-	-	-	-	-	-	-	-	-	6
1948.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3
Stall																1
1949.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1
1948.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1
Fire on ground																1
1949.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1
1948.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1
Fire in air																2
1949.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	2
1948.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	2
Airframe failure																3
1949.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3
1948.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3
Other																6
1949.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	6
1948.....	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	6
Total	1949.....	1	1	1	1	1	1	1	2	2	1	1	1	1	1	29
	1948.....	8	5	5	5	5	5	5	4	4	3	2	2	2	2	2

<sup>a/</sup> Includes 1 Feeder accident.<sup>b/</sup> Includes 2 Feeder accidents.<sup>c/</sup> Includes 1 Territorial accident.<sup>d/</sup> Prop. failure.<sup>e/</sup> One accident involved hail storm and one involved severe pitching in air.<sup>f/</sup> Two accidents involved hail storm, two involved turbulent air, one powerplant failure and one prop. failure.

Excludes propeller accidents to persons.

TYPE OF ACCIDENT VS INJURY AND DAMAGE IN SCHEDULED DOMESTIC TRUNK,  
FEEDER AND TERRITORIAL AIR CARRIER PASSENGER OPERATIONS  
(Calendar Years 1949 and 1948)

TABLE IV

Type of Accident	Injury Index			Total	Aircraft Damage		
	Fatal	Serious	Minor-None		Destroyed	Substantial	Minor-None
Ground, or water loop							
1949.....			a/ 2	1			1
1948.....			2	2			2
Hard landing							
1949.....			1	1		1	1
1948.....			1	1			
Wheels up-down							
1949.....			1	1			1
1948.....			3	3			3
Clds.-retract. landing gear							
1949.....			-	-			9
1948.....			c/ 9	9			
Overshoot							
1949.....			1	2			2
1948.....			b/ 5	5			5
Undershoot							
1949.....			2	2			2
1948.....			-	-			-
Nose up-over							
1949.....			1	1			1
1948.....			-	-			-
Collision--two aircraft							
Both airborne							
1949.....			2	2			2
1948.....			-	-			-
Both on ground							
1949.....			1	1			1
1948.....			a/ 5	5			5
Collision-ground or water							
1949.....			1	1			1
1948.....			b/ 2	2			a/ 1
Collision--objects							
1949.....			1	6			6
1948.....			b/ 7	8			b/ 6
Stall							
1949.....			2	1			1
1948.....			-	-			-
Fire on ground							
1949.....			1	1			1
1948.....			-	-			-
Fire in air							
1949.....			2	2			2
1948.....			5	5			5
Airframe failure							
1949.....			1	1			1
1948.....			a/ 2	3			2
Other							
1949.....			1	4			3
1948.....		2	3	6			4
Total							
1949.....	4	3	22	29	6	21	2
1948.....	5	2	45	52	7	43	2
Propeller accidents to persons							
1949.....	2			2			2
1948.....	-			-			-
Grand Total							
1949.....	6	3	21	31	6	21	4
1948.....	5	2	45	52	7	43	2

a/ Includes 1 Feeder accident.

b/ Includes 2 Feeder accidents.

c/ Includes 1 Feeder and 1 Territorial accident.

OPERATIONAL PHASE VS INJURY AND DAMAGE IN SCHEDULED DOMESTIC TRUNK  
FEEDER AND TERRITORIAL AIR CARRIER PASSENGER OPERATIONS  
(Calendar Years 1949 and 1948)

TABLE V

Operational Phase	Injury Index			Total	Aircraft Damage		Minor-None
	Fatal	Serious	Minor-None		Destroyed	Substantial	
<u>Taxying</u>							
To take off							
1949.....			1	1			1
1948.....			3a	8			8
From landing							
1949.....			1	1			1
1948.....			5	5			5
Other							
1949.....			-	-			-
1948.....			1	1			1
<u>Take Off</u>							
Run							
1949.....			2	2			2
1948.....			-	-			-
Climb							
1949.....			1	2			1
1948.....			3	4			3
<u>Flight</u>							
Normal							
1949.....	1	1	5	7			5
1948.....	3	2	8	13			9
<u>Landing</u>							
Approach							
1949.....	2	2	2	4			2
1948.....	1	2b	2b	3			2b
Level Off							
1949.....			1	1			-
1948.....			2	2			1
Roll							
1949.....		1	8c	9			8c
1948.....		-	12c	12			11c
Go around							
1949.....	1	-	1b	1			1b
1948.....	-		2	2			-
<u>Ground</u>							
Other							
1949.....			1	1			1
1948.....			2	2			2
<u>Total</u>							
1949.....	4	3	22	29	6	21	2
1948.....	5	2	45	52	7	43	2

a/ Includes 1 Territorial and 2 Feeder accidents.

b/ Includes 1 Feeder accident.

c/ Includes 3 Feeder accidents.

Excludes propeller accidents to persons.

PRIMARY CAUSE OF ACCIDENTS VS OPERATIONAL PHASE IN SCHEDULED DOMESTIC TRUNK, FEEDER AND TERRITORIAL AIR CARRIER PASSENGER OPERATIONS  
(Calendar Years 1949 and 1948)

TABLE VI

Primary Cause	OPERATIONAL PHASE										Total			
	To	Taxiing	From	Landing	Other	Run	Climb	Normal Flight	Discon-timed	Approach	Landings	Start Engine	Ground Idle	Other
Pilot Error														
Misuse, powerplant and controls														
1949.....														1
1948.....														-
Misuse brakes, flight controls, etc.														1
1949.....														-
1948.....														3
Failure to retract or extend gear														1
1949.....														-
1948.....														2
Selected unsuitable terrain														1
1949.....														-
1948.....														2
Misjudged distance														4
1949.....														4
1948.....														6
Failure to observe, aircraft, objects														1
1949.....														2
1948.....														4
Failed to maintain flying speed														1
1949.....														1
1948.....														2
Improper instrument operation														1
1949.....														-
1948.....														1
Operating recklessly														3
1949.....														3
1948.....														1
Other Personnel Error														2
Inadequate maintenance, aircraft														1
1949.....														1
1948.....														1

- 19 -

TABLE VI (continued)

Primary Cause	OPERATIONAL PHASE										Total
	To	Taxying From	Taxying To	To	Take Off	Take Off	Normal Flight	Landing	Ground	Idling	
	To	From	Off	From	From	Approach	Level Off	Go Around	Start Engine	Idling	Other
Other Personnel Error (Continued)											
Inproper operation, airport facilities											
1949.....											1
1948.....											1
Other	1949.....										1
1948.....											1
Pilot/plant											
Fuel system	1949.....										1
1948.....											1
Engine structure	1949.....										1
1948.....											1
Propeller and prop. accessories	1949.....										1
1948.....											1
Engine accessories	1949.....										1
1948.....											1
Undetermined	1949.....										1
1948.....											1
Airframe											
Flight-control system	1949.....										1
1948.....											1
Wings, flaps	1949.....										1
1948.....											1
Miscellaneous	1949.....										1
1948.....											1

- 20 -

TABLE VI (Continued)

Primary Cause	OPERATIONAL PHASE										Total	
	TAXIING			TAKE OFF			LANDING					
	To	From	Taxi	Run	Climb	Normal	Approach	Level	Go Around	Start Engine		
To Take off	From Landing	Landing	Other	Run	Climb	Discon-tinued	Flight	Off	Roll	Around	Ground	
<u>Landing Gear</u>												
Main landing gear assembly												
1949.....												
1948....												
Nose wheel												
1949....												
1948....												
Brakes												
1949....												
1948....												
Other												
1949....												
1948....												
<u>Equipment and Accessories</u>												
Hydraulic system												
1949....												
1948....												
Other												
1949....												
1948....												
<u>Weather</u>												
Rain - fog												
1949....												
1948....												
Snow - hail												
1949....												
1948....												
Unfavorable wind conditions for												
Landing, taxiing												
1949....												
1948....												
Turbulence in flight												
1949....												
1948....												
Downraft - updraft												
1949....												
1948....												

TABLE VI (Continued)

Primary Cause	OPERATIONAL PHASE												Total
	To	Taxying	Take Off	Landing	Ground	Start	Engine	Landing	Around	Go	Off	Normal	
	Take Off	From	Front	Other	Run	Climb	Run	Climb	timed	Flight	Approach	Flight	
<u>Airport - Terrain</u>													
Soft	1949.	-											1
Snow - Ices	1948.	-											2
1949.	-												2
Other hazard	1948.	-											1
1949.	-												1
Miscellaneous													
Bird collision	1949.	-											
1948.	-												
Other	1949.	-											
1948.	-												
Undetermined	1949.	-											
1948.	-												
<u>Small In Progress</u>													
1949.	-												2
1948.	-												1
Total	1949.	-											29
	1948.	-											52
Propeller accidents to person													
1949.	-												2
1948.	-												1
GRAND TOTAL	1949.	-											31
	1948.	-											52

a/ Includes 1 Feeder accident.  
 b/ Territorial accident.

COMPARATIVE SAFETY RECORD OF INDIVIDUAL U. S. DOMESTIC FEEDER  
AIR CARRIERS IN SCHEDULED PASSENGER OPERATIONS  
(Calendar Years 1949 and 1948 by Quarters)

TABLE VII

Operators	Accidents			Passenger		Crew Fatalities			Revenue <sup>3/</sup>
	Total	Fatal	Carried <sup>1/</sup>	Passenger Miles	Miles (000)	Pilot	Copilot	Other	Plane Miles
All American Airways, Inc. <sup>4/</sup>				809	145				40,775
1st Quarter 1949				16,876	2,435				482,259
2nd " 1949				33,961	5,008				740,981
3rd " 1949				21,785	3,384				702,229
4th " 1949				73,431	10,972				1,966,254
Total.....									
Did not carry passengers in 1948.									
Bonanza Air Lines, Inc. <sup>5/</sup>				352	106				30,658
4th Quarter 1949									
Central Airlines, Inc. <sup>6/</sup>						6			16,179
3rd Quarter 1949				56	767				336,626
4th " 1949					823	163			352,805
Total.....						169			
Challenger Airlines Co.									381,512
1st Quarter 1949				1	5,863	1,901			428,772
2nd " 1949					7,762	2,528			409,305
3rd " 1949					10,850	3,264			290,412
4th " 1949					5,320	1,799			1,526,001
Total.....					29,793	9,492			
1st Quarter 1948									308,822
2nd " 1948									351,154
3rd " 1948									371,319
4th " 1948									338,425
Total.....									1,369,790

TABLE VII (Continued)

Operators	Accidents		Passenger		Passenger		Crew Fatalities		Revenue <sup>2/</sup>
	Total	Fatal	Carried <sup>1/</sup>	Fatal <sup>2/</sup>	Miles (000)	Pilot	Copilot	Other	Plane Miles
<b>Empire Airlines</b>									
1st Quarter 1949			6,765		1,555				242,224
2nd " 1949			9,289		2,247				274,339
3rd " 1949			9,952		2,293				277,351
4th " 1949			7,756		1,924				267,884
<b>Total.....</b>			<b>33,762</b>		<b>8,019</b>				<b>1,061,798</b>
<b>1st Quarter 1948</b>									
2nd " 1948	1		2,880		762				228,704
3rd " 1948	-		6,302		1,641				251,623
4th " 1948	-		6,826		1,666				259,494
<b>Total.....</b>	<b>1</b>		<b>6,640</b>		<b>1,496</b>				<b>252,798</b>
			<b>22,648</b>		<b>5,563</b>				<b>992,619</b>
<b>Florida Airways, Inc.<sup>2/</sup></b>									
1st Quarter 1949					451				193,120
Discontinued operations									
3/28/49									
<b>1st Quarter 1948</b>									
2nd " 1948			2,291		372				20,111
3rd " 1948			4,087		587				205,745
4th " 1948			2,867		452				203,701
<b>Total.....</b>	<b>1</b>		<b>3,015</b>		<b>1,69</b>				<b>202,401</b>
			<b>12,260</b>		<b>1,880</b>				<b>817,958</b>
<b>Mid-West Airlines<sup>8/</sup></b>									
4th Quarter 1949					529				160,356
<b>Monarch Air Lines</b>									
1st Quarter 1949			4,678		1,478				389,792
2nd " 1949			8,128		2,471				442,883
3rd " 1949			10,655		3,102				468,696
4th " 1949			7,114		2,123				443,027
<b>Total.....</b>			<b>30,575</b>		<b>9,174</b>				<b>1,744,398</b>
<b>1st Quarter 1948</b>									
2nd " 1948			4,034		1,102				349,515
3rd " 1948			7,632		2,087				412,896
4th " 1948			10,171		3,017				457,778
<b>Total.....</b>			<b>6,358</b>		<b>1,892</b>				<b>430,052</b>
			<b>28,195</b>		<b>8,098</b>				<b>1,650,242</b>

- 24 -

TABLE VII (Continued)

Operators	Accidents		Passenger <sup>2</sup>		Crew Fatalities			Revenue <sup>3</sup>
	Total	Fatal	Carried <sup>1</sup>	Total <sup>12</sup>	Miles (000)	Pilot	Copilot	
<u>Piedmont Aviation, Inc.<sup>9</sup></u>								
1st Quarter 1949			12,894	2,990				604,786
2nd " 1949			22,646	5,108				761,413
3rd " 1949			26,844	6,070				823,879
4th " 1949			23,770	5,429				861,024
Total.....			86,154	19,627				3,051,202
1st Quarter 1948			938	282				53,184
2nd " 1948			8,480	2,206				411,901
3rd " 1948			16,254	3,951				578,192
4th " 1948			13,698	3,405				526,467
Total.....			39,370	9,844				1,600,044
<u>Pioneer Air Lines</u>								
1st Quarter 1949			20,110	6,000				879,721
2nd " 1949			28,490	8,389				984,758
3rd " 1949			28,089	8,376				1,008,177
4th " 1949			27,423	7,946				948,976
Total.....			104,112	30,711				3,21,632
1st Quarter 1948			14,493	4,101				581,444
2nd " 1948			25,126	7,104				828,519
3rd " 1948			26,801	7,938				998,284
4th " 1948			27,435	7,827				1,017,508
Total.....			93,855	26,870				3,425,755
<u>Purdue Aeronautics Corp.</u>								
Data not yet available.								

TABLE VII (Continued)

Operators	Revenue <sup>2/</sup>			Passenger <sup>2/</sup>			Revenue <sup>2/</sup>		
	Total	Fatal	Accident	Passenger	Miles	Crew Fatalities	Plane Miles		
				Carried	(000)	Pilot Copilot Other			
<u>Robinson Airlines, Corp.<sup>10/</sup></u>									
1st Quarter 1949	-	-	-	7,725	1,269			187,293	
2nd " 1949	1			10,943	1,775			208,096	
3rd " 1949	-			11,466	1,888			247,640	
4th " 1949	-			11,181	1,832			267,752	
Total.....	1			41,315	6,771			910,784	
				"	"			"	
1st Quarter 1948	-	-	-	-	-			16,566	
2nd " 1948	-	-	-	766	123			159,276	
3rd " 1948	-			7,407	1,209			175,842	
4th " 1948	-			8,173	1,332				
Total.....	1								
<u>Southern Airways, Inc.<sup>11/</sup></u>									
1st Quarter 1949	-	-	-	242	69			19,790	
2nd " 1949	-			4,501	989			334,242	
3rd " 1949	-			5,922	1,250			465,237	
4th " 1949	-			10,665	2,308			819,369	
Total.....	1								
				"	"			"	
Not operating in 1948									
<u>Southwest Airways</u>									
1st Quarter 1949	-	-	-	20,892	4,283			581,940	
2nd " 1949	-			32,354	6,305			607,470	
3rd " 1949	-			36,516	6,995			624,208	
4th " 1949	-			24,781	4,976			586,289	
Total.....	1			114,573	22,559			2,399,907	
				"	"			"	
1st Quarter 1948	-	-	-	14,585	3,153			479,206	
2nd " 1948	-			23,584	4,597			596,932	
3rd " 1948	-			33,351	6,312			610,366	
4th " 1948	-			25,904	5,204			603,792	
Total.....	1								
				"	"			"	
214									

TABLE VII (Continued)

Operators	Accident		Passenger		Passenger		Crew Fatalities		Revenue/ Plane Miles
	Total	Fatal	Carried	Total	Fatal	Pilot	Copilot	Other	
<u>Trans-Texas Airways</u>									
1st Quarter 1949			6,959			1,919			565,041
2nd " 1949			11,862			3,290			71,3,856
3rd " 1949			15,439			3,841			789,247
4th " 1949			15,504			3,722			811,420
Total.....			49,764			12,772			2,909,567
<u>1st Quarter 1948</u>									
2nd " 1948		1	2,389			701			321,753
3rd " 1948		-	3,972			1,102			379,645
4th " 1948		-	7,177			2,138			567,640
Total.....		-	8,731			2,404			575,248
			22,269			6,345			1,844,286
<u>Turner Airlines, Inc. 12/</u>									
Not operating 1st Quarter 1949				559		100			35,530
4th Quarter 1949									
<u>West Coast Airlines</u>									
1st Quarter 1949			10,921			1,521			276,318
2nd " 1949			19,342			2,602			326,029
3rd " 1949			24,341			3,370			359,926
4th " 1949			19,231			1,605			281,322
Total.....			65,335			9,188			1,243,395
<u>1st Quarter 1948</u>									
2nd " 1948			10,842			1,430			267,163
3rd " 1948			18,851			2,394			312,263
4th " 1948			25,728			3,489			356,259
Total.....			63,421			7,274			318,654
			68,733			9,178			1,253,356
<u>El Paso Airlines Airways 12/</u>									
1st Quarter 1949									"
2nd " 1949									"
3rd " 1949									"
4th " 1949									"
Total.....									
<u>Not operating in 1948</u>									
1st Quarter 1949									"
2nd " 1949									"
3rd " 1949									"
4th " 1949									"
Total.....									

Not operating in 1948

TABLE VII (Continued)

Operators	Accident			Passenger		Revenue <sup>2/</sup>		
	Total	Fatal	Carried	Passenger <sup>2/</sup>	Miles (000)	Crew Fatalities	Pilot	Co-pilot
<u>Wisconsin Central Airlines<sup>1/</sup></u>								
1st Quarter 1949	-	1	3,287	568	288,863			
2nd " 1949	"	1	8,514	1,406	381,081			
3rd " 1949	"	-	12,279	2,042	476,392			
4th " 1949	"	-	8,547	1,407	487,600			
Total.....			32,627	5,423	1,633,936			
1st Quarter 1948	-	-	343	73	50,345			
2nd " 1948	"	1	2,624	520	192,345			
3rd " 1948	"	1	5,052	1,034	304,470			
4th " 1948	"	-	3,366	616	250,854			
Total.....			11,395	2,243	798,014			
Grand Total — Feeder Lines								
1st Quarter 1949	1	103,929	24,080	4,631,388				
2nd " 1949	2	176,448	38,715	5,670,746				
3rd " 1949	-	225,018	47,248	6,581,385				
4th " 1949	-	172,422	37,956	7,040,812				
Total.....	3	577,817	147,999	23,924,331				
1st Quarter 1948	1	56,051	12,914	2,846,547				
2nd " 1948	2	106,057	23,877	3,943,043				
3rd " 1948	2	142,860	32,350	4,784,069				
4th " 1948	2	120,717	27,824	4,705,542				
Total.....	7	425,685	96,965	16,279,202				

<sup>1/</sup> Revenue passengers only.<sup>2/</sup> Both revenue and non-revenue.<sup>3/</sup> In scheduled passenger operations.<sup>4/</sup> Inaugurated passenger service 3/7/49.<sup>5/</sup> Inaugurated passenger service 12/19/49.<sup>6/</sup> Inaugurated passenger service 9/15/49.<sup>7/</sup> Carrier discontinued operations on 3/28/49 pursuant to Bd. order of 3/7/49.<sup>8/</sup> Inaugurated passenger service 10/21/49.<sup>9/</sup> " 2/20/48.<sup>10/</sup> " 9/19/48.<sup>11/</sup> " 6/10/49.<sup>12/</sup> " 11/12/49.<sup>13/</sup> " 9/19/49.<sup>14/</sup> " 2/24/48.

COMPARATIVE SUMMARY RECORDS OF INDIVIDUAL U. S. TERMINAL  
AIR CARRIERS IN SCHEDULED PASSENGER OPERATIONS  
(Calendar Years 1949 & 1948 by Quarters)

TABLE VIII

Operators	Accidents		Passenger <sup>2</sup>		Revenue <sup>3</sup>	
	Total	Fatal	Carried <sup>1</sup>	Fatal <sup>12</sup>	Miles (000)	Plane Miles
<u>Caribbean-Atlantic Airlines</u>						
1st Quarter 1949			23,905		1,729	158,823
2nd " 1949			21,533		1,633	153,825
3rd " 1949			19,472		1,506	142,507
4th " 1949			13,662		1,143	127,826
Total.....			78,572		6,011	58,981
1st Quarter 1948			19,823		1,249	98,296
2nd " 1948			17,511		1,106	100,424
3rd " 1948			18,745		1,212	109,778
4th " 1948			18,222		1,186	111,973
Total.....			74,401		4,753	420,471
1st Quarter 1949			71,732		10,100	610,935
2nd " 1949			79,220		10,913	646,520
3rd " 1949			86,353		11,886	729,291
4th " 1949			65,963		8,842	633,386
Total.....			303,268		41,741	2,620,132
1st Quarter 1948			77,521		10,932	660,821
2nd " 1948			84,222		11,986	727,801
3rd " 1948			106,128		15,212	922,972
4th " 1948			76,100		10,532	628,969
Total.....			343,971		48,662	2,940,563

TABLE VIII (Continued)

Operators	Accidents	Passenger <sup>2</sup>		Crew Fatalities			Revenue <sup>3</sup> Plane Miles
		Total	Fatal	Carried <sup>1</sup>	Fatal <sup>2</sup>	Pilot	Copilot
<u>Trans-Pacific Airlines, Ltd.<sup>4</sup></u>							
1st Quarter 1949	-	-	-	-	-	-	59,531
2nd " 1949	4,960	4,960	22,501	758	3,539	277,884	277,884
3rd " 1949	11,850	11,850	11,850	1,614	1,614	170,131	170,131
4th " 1949	39,311	39,311	39,311	5,941	5,941	507,546	507,546
Grand Total-Territorial Lines	-	-	-	-	-	-	-
1st Quarter 1949	95,637	95,637	105,713	11,829	13,304	859,876	859,876
2nd " 1949	128,326	128,326	128,326	16,931	16,931	1,449,682	1,449,682
3rd " 1949	91,475	91,475	91,475	11,629	11,629	931,343	931,343
4th " 1949	421,151	421,151	421,151	53,693	53,693	3,710,659	3,710,659
Total.....	-	-	-	-	-	-	-
1st Quarter 1948	97,344	97,344	101,733	12,181	13,092	828,225	828,225
2nd " 1948	-	-	124,873	-	16,424	1,032,750	1,032,750
3rd " 1948	-	-	94,422	-	11,718	740,942	740,942
4th " 1948	418,372	418,372	418,372	53,415	53,415	3,361,034	3,361,034
Total.....	-	-	-	-	-	-	-

<sup>1</sup>/ Revenue passengers only.<sup>2</sup>/ Both revenue and non-revenue.<sup>3</sup>/ In scheduled passenger operations.<sup>4</sup>/ Regularly scheduled operations, transporting passengers and property only, were inaugurated on June 6, 1949.

**COMPARATIVE SAFETY RECORD OF U. S. FLAG SCHEDULED AIR CARRIERS  
IN INTERNATIONAL PASSENGER OPERATIONS  
(Calendar Years 1948 and 1949 by Quarters)**

**TABLE IX**

Operators	Accidents		Passenger <sup>2</sup>		Revenue <sup>3</sup> /		
	Total	Fatal	Carried <sup>1</sup>	Fatal <sup>2</sup>	Miles (000)	Pilot	Copilot
<b>American Airlines</b>							
1st Quarter 1949			18,009		18,722		
2nd Quarter 1949			21,144		17,947		
3rd Quarter 1949			23,531		20,360		
4th Quarter 1949			19,437		16,482		
Total.....			82,121		73,511		
					388,012		
1st Quarter 1948	-	1	12,114		12,877		
2nd Quarter 1948	-	1	14,051		18,737		
3rd Quarter 1948	-	1	14,951		19,287		
4th Quarter 1948	-	1	14,512		18,113		
Total.....			55,628		69,044		
					1,967,945		
<b>American Overseas Airlines</b>							
1st Quarter 1949	-	-	15,658		37,967		
2nd Quarter 1949	-	-	23,777		55,160		
3rd Quarter 1949	-	-	27,829		59,047		
4th Quarter 1949	-	1	28,039		47,339		
Total.....			95,303		199,513		
					7,598,905		
1st Quarter 1948			8,490		25,087		
2nd Quarter 1948			18,937		51,817		
3rd Quarter 1948			23,588		61,974		
4th Quarter 1948			12,602		43,775		
Total.....			75,617		182,653		
					7,110,523		

TABLE IX (Continued)

Operators	Accidents		Passenger <sup>2</sup>		Revenue <sup>2</sup>	
	Total	Fatal	Carried <sup>1</sup>	Miles (000)	Crew Fatalities	Plane Miles
<u>Braniiff Airways</u> <sup>4</sup>						
1st Quarter 1949	2,408	6,511				
2nd Quarter 1949	3,683	10,304				
3rd Quarter 1949	3,557	10,177				
4th Quarter 1949	3,632	10,107				
Total.....	13,280	27,093				
1st Quarter 1948	288	619				
2nd Quarter 1948	1,939	4,285				
3rd Quarter 1948	1,900	3,889				
4th Quarter 1948	4,026	3,793				
1st Quarter 1948	5,767	6,465				
2nd Quarter 1948	6,150	7,747				
3rd Quarter 1948	6,036	9,469				
4th Quarter 1948	5,528	6,930				
Total.....	23,481	29,611				
<u>Chicago &amp; Southern Air Lines</u>						
1st Quarter 1948	1	2,909				
2nd Quarter 1948	1	2,813				
3rd Quarter 1948	1	2,269				
4th Quarter 1948	1	4,738				
Total.....	1/2	11,472				
1st Quarter 1948	2,115	2,621				
2nd Quarter 1948	2,269	3,723				
3rd Quarter 1948	4,649	2,997				
4th Quarter 1948	5,012	2,187				
Total.....	12,637	11,528				
<u>Colonial Airlines</u>						
1st Quarter 1948	3,064	2,621				
2nd Quarter 1948	4,219	3,723				
3rd Quarter 1948	3,220	2,997				
4th Quarter 1948	2,114	2,187				
Total.....	12,637	11,528				
1st Quarter 1948	4,645	3,642				
2nd Quarter 1948	5,111	4,271				
3rd Quarter 1948	4,211	3,694				
4th Quarter 1948	2,800	2,503				
Total.....	16,537	14,110				

- 32 -

TABLE IX (Continued)

Operators	Accidents		Passenger Miles		Crew Fatalities		Revenue Miles	
	Total	Fatal	Carried	(000)	Pilot	Co-pilot	Other	Miles
<u>Eastern Air Lines</u>								
1st Quarter 1949	3,340		3,950		1,277,200			
2nd Quarter 1949	4,085	1,325	4,089		1,09,280			
3rd Quarter 1949	4,105	4,456	4,105		1,05,120			
4th Quarter 1949	3,433	2,704	3,433		1,01,160			
Total.....	14,963	16,435			752,960			
1st Quarter 1948	3,906	4,089	3,906		187,320			
2nd Quarter 1948	4,039	4,246	4,039		199,280			
3rd Quarter 1948	5,016	5,268	5,016		187,236			
4th Quarter 1948	3,100	3,296	3,100		189,280			
Total.....	16,061	16,899			753,176			
<u>National Airlines</u>								
1st Quarter 1949	14,024		4,246		132,132			
2nd Quarter 1949	12,295		3,870		139,741			
3rd Quarter 1949	19,373		5,616		175,822			
4th Quarter 1949	12,915		3,878		149,014			
Total.....	58,607		17,610		596,710			
1st Quarter 1948	1,676				78,119			
2nd Quarter 1948	1,796				105,088			
3rd Quarter 1948	2,836				111,579			
4th Quarter 1948	2,356				105,028			
Total.....	3,654				399,574			
1st Quarter 1949	5,386				1,146,584			
2nd Quarter 1949	5,390				1,458,444			
3rd Quarter 1949	9,027				1,412,630			
4th Quarter 1949	7,209				1,473,375			
Total.....	27,012				5,826,033			
<u>Northwest Airlines</u>								
1st Quarter 1949	7,491		15,605		1,014,500			
2nd Quarter 1949	10,320		21,920		1,013,047			
3rd Quarter 1949	11,192		23,443		1,104,025			
4th Quarter 1949	8,984		18,605		1,402,773			
Total.....	37,967		79,573		4,534,363			
1st Quarter 1948	5,600		12,619					
2nd Quarter 1948	6,741		14,106					
3rd Quarter 1948	8,396		15,033					
4th Quarter 1948	8,210		20,650					
Total.....	28,947		65,403					

TABLE IX (Continued)

Operators	Accidents			Passenger			Passenger			Crew Fatalities			Revenue <sup>3/</sup> Plane Miles Miles
	Total	Fatal	Carried	Fatal	Carried	Miles (000)	Pilot	Copilot	Other	Pilot	Copilot	Other	
<u>Pan American Airways (All Div.)</u>													
1st Quarter 1949	1		243,693		269,342					13,294,615			
2nd Quarter 1949	-		239,953		320,142					14,143,758			
3rd Quarter 1949	1		268,827		363,915					15,348,544			
4th Quarter 1949	2		205,842		271,279					13,612,812			
Total.....	4		958,225		1,224,678					57,000,729			
1st Quarter 1948	2		233,220		-		259,693			13,506,976			
2nd Quarter 1948	3		219,931		20		295,166			14,176,137			
3rd Quarter 1948	1		254,252		-		325,211			15,111,616			
4th Quarter 1948	1		213,428		-		284,006			14,548,218			
Total.....	7		920,831		20		1,164,076			57,343,247			
Pan American Grace Airways													
1st Quarter 1949			24,287				30,903			1,342,724			
2nd Quarter 1949			22,906				27,600			1,352,318			
3rd Quarter 1949			21,977				25,674			1,444,970			
4th Quarter 1949			23,790				28,284			1,444,466			
Total.....			92,960				112,461			5,584,478			
1st Quarter 1948			24,536				27,565			1,409,653			
2nd Quarter 1948			22,908				28,032			1,397,949			
3rd Quarter 1948			22,495				26,213			1,369,100			
4th Quarter 1948			22,358				27,874			1,350,212			
Total.....			92,297				107,684			5,526,914			
Transcontinental & Western Air													
1st Quarter 1949	1		16,932				54,126			2,578,134			
2nd Quarter 1949	1		28,769				84,562			3,411,250			
3rd Quarter 1949	-		32,492				94,663			3,855,063			
4th Quarter 1949			22,499				66,392			2,973,162			
Total.....			100,692				299,743			12,817,609			
1st Quarter 1948			12,549				41,031			2,320,165			
2nd Quarter 1948			19,672				65,691			2,747,948			
3rd Quarter 1948			27,205				86,073			3,627,301			
4th Quarter 1948			22,517				72,376			2,170,176			
Total.....			81,943				265,171			11,865,590			

- 34 -

## TARIF TX (Continued)

Operators	Accidents Total	Passenger Carried Fatal	Passenger <sup>2/</sup>			Crew Fatalities			Revenue <sup>3/</sup>	
			Miles (000)	Pilot	Copilot	Other			Plane Miles	Miles
<u>United Air Lines</u>										
1st Quarter 1949	6	6,128	14,518	18,225			519,227			
2nd Quarter 1949		7,417			21,372		643,358			
3rd Quarter 1949		8,733				11,979	631,200			
4th Quarter 1949		1,718					616,879			
Total.....		27,026					2,410,664			
1st Quarter 1948	1	3,032	7,400				432,000			
2nd Quarter 1948		5,343	12,949				444,000			
3rd Quarter 1948		8,206	19,847				532,800			
4th Quarter 1948		6,278	15,271				470,400			
Total.....		22,859	55,467				1,879,200			
<u>Uraba, Medellin &amp; Central Airways</u>										
1st Quarter 1949		815	271				25,912			
2nd Quarter 1949		793	268				25,564			
3rd Quarter 1949		652	217				25,896			
4th Quarter 1949		520	174				25,232			
Total.....		2,785	930				102,604			
1st Quarter 1948		719	261				41,216			
2nd Quarter 1948		443	147				37,184			
3rd Quarter 1948		532	176				33,864			
4th Quarter 1948		546	183				25,232			
Total.....		2,240	747				137,495			
<u>Grand Total - International Carriers</u>										
1st Quarter 1949	3	361,526	465,247				23,152,557			
2nd Quarter 1949	1	385,516	575,793				24,955,544			
3rd Quarter 1949	1	431,524	640,400				27,035,945			
4th Quarter 1949	2	241,501	487,310				23,894,674			
Total.....	8	1,520,067	2,168,780				99,038,720			
1st Quarter 1948	3	317,639	397,272				21,041,759			
2nd Quarter 1948	5	1	495,160				22,906,760			
3rd Quarter 1948	1	-	573,210				25,722,105			
4th Quarter 1948	2	320,973	496,152				24,207			
Total.....	11	1	1,372,856	20			93,919,831			

<sup>1/</sup> Revenue passengers only.  
<sup>2/</sup> Both revenue and non-revenue

<sup>3/</sup> In scheduled passenger operations.  
Regular scheduled operations inaugurated 6/4/48.

TYPE OF ACCIDENT VS OPERATIONAL PHASE IN U. S. FLAG SCHEDULED AIR CARRIERS IN INTERNATIONAL PASSENGER OPERATIONS  
(Calendar Years 1949 and 1948)

TABLE X

Type of Accident	OPERATIONAL PHASE										Total		
	To Taxiing	From Take Off	To Landing	From Landing	Other	Run	Climb	Discon-timed	Normal Flight	Approach	Landing	Ground	
											Start Engines	Idling	Other
Clips - retract landing gear													
1949	-	-	-	-	-	-	-	-	-	-	-	-	-
1948	-	-	-	-	-	-	-	-	-	-	-	-	-
Undershoot													
1949	-	-	-	-	-	-	-	-	-	-	-	-	-
1948	-	-	-	-	-	-	-	-	-	-	-	-	-
Collision - two aircraft													
Airborne													
1949	-	-	-	-	-	-	-	-	-	-	-	-	-
1948	-	-	-	-	-	-	-	-	-	-	-	-	-
Collision - objects													
1949	-	-	-	-	-	-	-	-	-	-	-	-	-
1948	-	-	-	-	-	-	-	-	-	-	-	-	-
Collision - ground or water													
1949	-	-	-	-	-	-	-	-	-	-	-	-	-
1948	-	-	-	-	-	-	-	-	-	-	-	-	-
Fire in air													
1949	-	-	-	-	-	-	-	-	-	-	-	-	-
1948	-	-	-	-	-	-	-	-	-	-	-	-	-
Others													
1949	-	-	-	-	-	-	-	-	-	-	-	-	-
1948	-	-	-	-	-	-	-	-	-	-	-	-	-
Total	-	-	-	-	-	-	-	-	-	-	-	-	-
1949	-	-	-	-	-	-	-	-	-	-	-	-	-
1948	-	-	-	-	-	-	-	-	-	-	-	-	-

a/ Involved turbulent air.  
b/ Struck by bullets fired by unknown riflemen.

TYPE OF ACCIDENT VS INJURY AND DAMAGE IN U. S. FLAG SCHEDULED  
AIR CARRIERS IN INTERNATIONAL PASSENGER OPERATIONS  
(Calendar Years 1949 and 1948)

TABLE XI

Type of Accident	Injury Index			Total	Aircraft Damage		
	Fatal	Serious	Minor-None		Destroyed	Substantial	Minor-None
<u>C</u> ps. -retract. ldg. pt.				-			-
1949.....			4	4			4
1948.....			-	-			-
<u>U</u> dershoot				1	1		1
1949.....			-	-			-
1948.....			-	-			-
<u>C</u> llision - two aircraft				-			-
Airborne				1	1		1
1949.....			-	-			-
1948.....			-	-			-
<u>C</u> llision—ground or water				-			-
1949.....			-	-			-
1948.....		1	-	1	1		-
<u>C</u> llision—objects				4	4		4
1949.....			2	2	1		1
1948.....			-	-			-
<u>E</u> re in air				1	1		1
1949.....			3	3			3
1948.....			-	-			-
<u>O</u> ther				1	1		1
1949.....			-	-			-
1948.....		1	1	1	1		1
Total				7	8		7
1949.....	-	1	10	11	2		9
1948.....	1	-	-	-	-		-

PRIMARY CAUSE OF ACCIDENTS VS OPERATIONAL PHASE IN U. S. FLIG SCHEDULED AIR CARRIERS IN INTERNATIONAL PASSENGER OPERATIONS  
(Calendar Years 1949 and 1948)

TABLE XII

Primary Cause	OPERATIONAL PHASE										Total	
	Taxying			Take Off			Landing					
	To	From					Normal	Level	Go Around	Ground		
Take Off	Landing	Other	Run	Climb	BTinued	Flight	Approach	Off	Roll	Start	Idling	
										Engine	Other	
<u>Pilot Error</u>												
Misuse brakes, flight controls, ground												
1949.....											1	
1948.....											1	
Failure to retract or extend gear											1	
1949.....											1	
1948.....											1	
Misjudged distance											2	
1949.....											1	
1948.....											1	
Failure to observe aircraft, objects											1	
1949.....											1	
1948.....											1	
Improper instrument operation											1	
1949.....											1	
1948.....											1	
Other Personnel											1	
Inadequate maintenance, aircraft											1	
1949.....											1	
1948.....											1	
Other											1	
1949.....											1	
1948.....											1	
<u>Powerplant</u>											1	
Fuel system											1	
1949.....											1	
1948.....											1	
Engine structure											1	
1949.....											1	
1948.....											1	

TABLE XII (CONTINUED)

Primary Cause	OPERATIONAL PHASE										Total			
	Taxying		Take Off		Landing		Ground							
	To	From	Take Off	Landing	Other	Run	Normal Flight	Discon-tinued	Level Off	Roll	Go Around	Start Engine	Idle Engine	Other
<u>Powerplant (continued)</u>														
<u>Engine accessories</u>														
1949.....														1
1948.....														1
<u>Landing gear</u>														
<u>Nose wheel</u>														
1949.....														2
1948.....														2
<u>Weather</u>														
<u>Turbulence in flight</u>														
1949.....														1
1948.....														1
<u>Miscellaneous</u>														
<u>Other</u>														
1949.....														8
1948.....														11
<u>Total</u>														
1949.....														8
1948.....														11

OPERATIONAL PHASE VS INJURY AND DAMAGE IN U. S. FLAG SCHEDULED  
AIR CARRIERS IN INTERNATIONAL PASSENGER OPERATIONS  
(Calendar Years 1949 and 1948)


TABLE XIII

Operational Phase	Injury Index			Total	Aircraft Damage		
	Fatal	Serious	Minor-None		Destroyed	Substantial	Minor None
<u>Taxying</u>							
From landing							
1949.....			1	1			1
1948.....			1	1			1
Other							
1949.....			1	1			1
1948.....			-	-			-
<u>Take Off</u>							
Run							
1949.....			-	-			
1948.....			2	2			2
Discontinued							
1949.....			-	-			
1948.....			1	1	1		
<u>Flight</u>							
Normal							
1949.....		1	2	3			2
1948.....		-	3	3			3
<u>Landing</u>							
Approach							
1949.....	-		3	3			3
1948.....	1		-	1	-		-
Roll							
1949.....			-	-			
1948.....			3	3			3
Total							
1949.....	-	1	7	8	-	7	1
1948.....	1	-	10	11	2	9	-

CHART A

PASSENGER FATALITY RATE AND PASSENGER MILES IN DOMESTIC  
AIR CARRIER SCHEDULED PASSENGER CARRYING OPERATIONS

CALENDAR YEARS 1938 - 1949




ACCIDENT ANALYSIS DIVISION  
BUREAU OF SAFETY INVESTIGATION  
CIVIL AERONAUTICS BOARD  
JUNE - 1950

15735

CHART B

NUMBER OF AIR CARRIER ACCIDENTS IN  
SCHEDULED DOMESTIC PASSENGER CARRYING OPERATIONS  
CALENDAR YEARS 1938 - 1949



1513 f

ACCIDENT ANALYSIS DIVISION  
BUREAU OF SAFETY INVESTIGATION  
CIVIL AERONAUTICS BOARD

230

JUNE - 1960

CIVIL AERONAUTICS BOARD  
Washington 25, D. C.

Joseph J. O'Connell, Jr. - Chairman

Oswald Ryan, Vice-Chairman  
Russell B. Adams, Member

Josh Lee, Member  
Harold A. Jones, Member

Jesse W. Lankford, Chief  
Accident Analysis Division

William K. Andrews, Director  
Bureau of Safety Investigation

Ben W. Ashmead, Chief  
Statistical Analysis Section

RESUME OF U.S. AIR CARRIER ACCIDENTS  
(CALENDAR YEAR 1948)

Details of accidents in (1) scheduled, (2) irregular and (3) Alaskan air carrier operations during 1948 are contained in the following pages. The accidents are shown according to the classes of operation conducted by the three air carrier groups noted from the standpoint of date, location of accident, operator, equipment, total personnel aboard, injury division among crew and passengers and aircraft damage. Indication is made whether accident occurred at night and if fire in air or after impact was involved. A brief description of each accident is included.

June 1949

4. Commercial Domestic Operations4.1. Passenger Carrying Operations

Date	Alt.	Night	Location	Operator	Equipment	Passenger Aboard	Injury					Aircraft Damage	In Air	After Impact		
							Total	Crew	M	N	E	S	M	No.		
1/11/48			Atlanta, Georgia	FAI	DC-3	24	- - - 3	- - -	11					Subst.**		

On landing at Atlanta, the flight was given Runway 15 with wind southeast variable at 30, gusty to 40, occasionally 45. While turning onto the base leg, the flight was advised that the wind had shifted and was south-southwest with strong gusts. The flight being low, continued on into Runway 15 although the Captain at first considered pulling up and had moved the landing gear latch handle to the unlocked position. Deciding to continue on in, he attempted to lock the gear again but was unable to do so. He then placed the landing gear handle in the down position, checked the hydraulic pressure and made the landing. Again the Captain attempted to lock the gear but could not do so and so started taxying in. A 180 degree turn in gusty air was completed when the left gear folded, followed by the right gear. Investigation disclosed that the Captain had not allowed sufficient time to operate the gear by the regular procedure, as by moving the latch handle first he had placed the mechanism in the spring loaded position. Whereas he first should have placed the landing gear selector handle in the down position.

1/8/48  
Yes Birmingham, Alabama Delta  
No. 3 24 - - - 3 - - - 21 Subst.

After encountering some difficulty with the landing gear mechanism at Meridian, Mississippi, the flight continued on to Birmingham. Here the red light showed when the gear was lowered. However, as the difficulty appeared to be the same as that previously encountered, a landing was made with no brakes being used. Then almost to a stop a right turn was started but after completing about 45 degrees of the turn, the left gear collapsed and the aircraft came to rest on the left wing tip. No evidence could be found to indicate a mechanical failure although damage to the gear would prevent any definite determination. It was brought out, however, that the Captain was not thoroughly familiar with the gear mechanism and didn't realize that a turn angle not have been made under the circumstances until pins were inserted. The company also failed to furnish any instruction as this in their pilot's manual.

1/11/48  
Ridgway, Washington Boeing 247-D 7 - - - 2 - - - 5 Subst.

While taxying out for take-off, pilot failed to observe a post anchoring the door track of a small hangar off the edge of the tarmac strip and struck the post with the left wing tip of the plane.

1/13/48  
Yes Mr. Glen Hill, Md. FAI No. 3 9 2 - 1 - 3 2 1 - Destroyed

Mr. Mr. flight 572 enroute from Atlanta to Washington was cleared to Lancaster Marker with permission to descend to 2,500 feet over Bryn Mawr, Pennsylvania, as another L.M.A. flight was approaching Baltimore at this time from the northwest, flight 572 was

\* P = Fatal; S = Serious; M = Minor; N = None  
\*\* Subst. = Substantial

NO  
NOT REPRODUCIBLE

A. Scheduled Domestic Operations

1. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Total	Injury						Aircraft Damage	In Air	Fire After Impact	
					Crew	Passenger	F	S	M	N	F	S	M	N	
1/13/48		Mr. Oxon Hill, Md. (Continued)													
1/21/48	Yes	E. Boston, Mass.	EAL	Lockheed	25	—	—	5	—	5	15	Destroyed	Yes		
1/30/48	New York, New York	TWA	Boeing 307	28	—	—	3	—	—	25	Subst.				
1/31/48	While taxiing, the right side of the landing gear retracted. Examination disclosed this failure to be due to the failure of the threads of the two bolts holding the landing gear latch to the front spar of the wing, allowing the latch to pull away from the spar.	EAL	DC-3	6	—	—	3	—	—	3	Subst.				

instructed to climb to 3,500 feet. The Captain replied that he was then contact and requested the reason for climbing. At this time, the second E.A.L. flight, No. 454 reported on contact so flight 572 was again cleared on 2,500 feet. Flight 454 was picked up on the tower's surveillance radar scope and precision beam radar scope until it had landed but flight 572 was never picked up. It was learned that it had flown into the ground 5.2 miles south of the airport, crashing into wooded terrain. First contact was made when the right wing tip struck a tree 106 feet above sea level. The ship had struck on a heading straight toward the runway and in a level or slightly climbing attitude. Investigation disclosed no malfunction of aircraft or facilities. The procedure in EAL's operation manual required a minimum approach altitude of 1,500 feet when over Mt. Vernon. It is apparent that the flight was not at this altitude as it never appeared in the radar scopes. Highly variable cloud conditions were a contributing factor as the pilot attempted to remain on contact into the field and so failed to maintain sufficient altitude to clear obstructions.

1/21/48  
Yes      E. Boston, Mass.      EAL      Lockheed      25      —      —      5      —      5      15      Destroyed

6/9

On the scheduled flight from Miami to Newark, the part of it to Philadelphia was made in routine fashion. After passing Philadelphia, the flight was cleared to La Guardia instead. A position report as over Freehold, N. J. was made which later events proved to be in error by five minutes. At La Guardia the approach was missed, the plane passing  $\frac{1}{2}$  mile to the right of the designated runway after which the pilot reported the ceiling under 500 feet and requested clearance to Boston which was granted. At Boston a straight in, ILS approach was made and the plane landed on runway 4 where  $\frac{1}{2}$  inch of new fallen snow was laying. Shortly after the touchdown 2,000 feet from the approach end, the left gear struck snow drifts causing plane to turn to the left changing its direction suddenly and to crash into a large snowbank on the left. Fire broke out in the vicinity of Nos. 3 and 4 engines and spread inward to the fuselage. The occupants left from the rear door and the aircraft was practically destroyed by the fire.

1/30/48  
New York, New York      TWA      Boeing 307      28      —      —      3      —      —      25      Subst.

The flight was ready for take-off and in running up engines, roughness developed in No. 2 engine on left magneto. Plane was returned to the ramp at which time fire broke out in back of No. 2 engine. The Captain pulled fire extinguisher and fire went out. Origin of fire was not discovered.

1/31/48  
New York, New York      EAL      DC-3      6      —      —      3      —      —      3      Subst.

While taxiing, the right side of the landing gear retracted. Examination disclosed this failure to be due to the failure of the threads of the two bolts holding the landing gear latch to the front spar of the wing, allowing the latch to pull away from the spar.

No. 2 Unrepaired Domestic Operations

1. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury							Aircraft Damage	In Air Fire	After Impact Fire			
						Passenger				Crew								
						F	S	M	W	P	S	M						
2/7/48		Burnell, Florida	EAL	Lockheed	69	1	-	5	-	1	1	61	Subst.					
				649														
2/15/48	Yes	Chicago, Illinois	TWA	Boeing 307	30	-	-	-	-	5	-	-	25	Subst.	Yes			
2/16/48		Chicago, Illinois	TWA	L-049 C-46	45	-	-	-	-	4	-	-	41	Subst.				
2/24/48	Yes	Bellingham, Washington	UAI	DC-3	16	-	-	-	-	4	-	-	12	Subst.				

While cruising at 22,000 feet enroute from La Guardia for W. Palm Beach, there was a sudden loud noise and severe vibration. Power was reduced and a descent started. Depressurization of the cabin had occurred, the engine instruments were not functioning and No. 3 engine was vibrating. Soon after this, the propeller and parts of No. 3 engine dropped from the aircraft and vibration ceased. It was then discovered that parts of the propeller had been driven through the fuselage at the galley area and had killed a passenger. No. 3 engine continued operating until lack of oil froze it. As the descent continued there was a pronounced left yaw, which was partially corrected by power to engines 1 and 2. A landing under extreme difficulty was made at Burnell, Florida in which abnormal use of the left brake was necessary and the left outboard tire blew out. A fire in the right landing gear was extinguished when the plane stopped. Further study of No. 3 engine and the type of propeller engine installation being used is now being made.

Number 4 engine backfired two or three times as plane was being taxied to take-off position. Shortly after take-off, the pilot noticed that No. 4 throttle stuck for several seconds as it was being reduced and at this time the Hostess reported fire in No. 4 engine. The propeller was feathered and the fire extinguished by means of CO<sub>2</sub>. Evidence indicates that the backfires prior to take-off had caused the failure of the carburetor air scoop adaptor clamp, thus permitting flames from the backfires to ignite accumulations of fluid around carburetor. Air ramming through the air scoop increased the intensity of the fire until it burned through the hydraulic lines of the cowling flap control. The hydraulic fluid released supported combustion for several minutes. Steps were taken to prevent a repetition of this failure.

After landing, the plane was turned off the runway onto an old runway which was closed and used for parking only. Here it taxied into a parked, partially dismantled Slick Airways C-46, damaging both aircraft.

Pilot inadvertently taxied into a dead end revetment strip where he had to turn around in a narrow space. An abandoned service pit about four feet deep with no cover on it was in this area and was struck by the tail wheel which fell into the opening, damaging the aircraft tail assembly severely.

A. Scheduled Domestic Operations

1. Passenger Carrying Operations

<u>Date</u>	<u>Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury Passengers</u>						<u>Aircraft Damage</u>	<u>In Air</u>	<u>Fire</u>	<u>After Impact</u>
						<u>Crew</u>	<u>F</u>	<u>S</u>	<u>M</u>	<u>N</u>	<u>E</u>				
3/10/48	Yes	Chicago, Illinois	Delta	DC-4	13	4	-	-	8	1	-	Destroyed		Yes	
		The flight made what appeared to be a normal take-off until an altitude of 150 to 200 feet had been reached, at which point the plane assumed a very steep climbing attitude. At 500 to 800 feet the nose and right wing dropped and the plane crashed to the ground. Fire followed immediately. Extensive investigation failed to disclose any evidence of mechanical malfunctioning or structural failure of the plane. The plane was properly loaded and the weather was not conducive to the formation of ice. The probable cause must remain as loss of longitudinal control for reasons undetermined.													
3/10/48		Tulsa, Oklahoma	AA	DC-4	33	-	-	-	3	-	-	30	Subst.		
		On take-off run, the nosewheel struck a snowdrift damaging it so that it could not be raised. Pilot proceeded to Dallas where better weather conditions prevailed. Nosewheel was held off ground on landing until speed was lost. On contact, nosewheel centered itself and landing was completed without mishap. Inspection showed that steering arm support bracket had been broken.													
4/24/48	Yes	Wichita Falls, Texas	Continental	DC-3	17	-	1	-	3	-	-	1	12	Minor	
		While the flight was approaching Wichita Falls, extreme turbulence was momentarily encountered. The hostess was in the aisle at the time and was thrown across a seat, injuring her severely. An infant was thrown from its mother's lap, suffering a cut on the head. After the flight landed, a flight agent opening the door received a static electrical charge which knocked him to the ground, but he was not seriously injured.													
4/28/48		Nr. Toledo, Ohio	AA	DC-6	52	-	-	-	4	-	-	48	Subst.	Yes	
		After reaching cruising altitude all main tanks were switched to their respective alternates and the booster pumps were shut off. Immediately thereafter fuel pressure and fuel flow for No. 3 engine dropped suddenly followed by the overspeeding of the propeller. The propeller was feathered and it was found that No. 3 engine was on fire. The CO <sub>2</sub> selector for that engine was pulled, the cowl flaps opened 4 degrees and a dive was started. The fire went out and the flight was continued on to Cleveland. On the final approach the Stewardess advised that a fire existed in No. 2 zone of No. 3 engine and the CO <sub>2</sub> extinguisher for that zone was discharged. The landing was made, no fire was found and the ship was towed to the ramp and passengers deplaned. Investigation disclosed that in high blower, cutting of the tachometer range (when throttles are left in cruising auto-lean position, results in the overrevving of the propeller above the tachometer range) caused the blower at around 3300 rpm. Damage done by pieces of the blower to the intake manifold and exhaust stack allowed hot exhaust gasses to ignite gasoline in No. 1 zone and this fire passed to No. 2 zone through a hole in the diaphragm also caused by the impeller. The gasoline fire no doubt ignited oil and hydraulic fluid. Fortunately the crew was able to extinguish this fire.													

A. Scheduled Domestic Operations.

1. Passenger Carrying Operations.

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury				Aircraft Damage	In Air After Impact	Fire	
						Total	Crew	Passenger					
						E	S	M	N	F	S	W	N
5/3/48	Yes	New York, New York	AA	DC-6	37	- - -	4	- - -	33	Subst.			
5/7/48		Mr. El Paso, Texas	AA	DC-6	34	- - -	4	- - -	30	Subst.	Yes		

On the landing, normal contact was made on the main wheels. The nose, however, which had been dropping normally, continued on down past its usual level position and the warning horn began to sound. The plane was brought to a stop and the passengers quickly deplaned. Investigation failed to disclose any failure or malfunction in the gear and it is believed that inadvertent operation of the landing gear control instead of flap control may have occurred though such has not been substantiated, to date.

5/25/48		Mr. Midland, Texas	AA	DC-6	34	- - -	4	- - -	30	Subst.		
5/28/48		Galveston, Texas	Trans-Texas Airways	Two DC-3's	2	- - -	2	- - -	- - -	Subst.	(NC 17331)	
					17	- - -	2	- - -	15		(Braniff NC 21776)	
6/12/48		Harrisburg, Pennsylvania	TWA	DC-3	18	- - -	3	- - -	15	Subst.		

Flight departed El Paso and climbed to 17,000 feet. Then with alternate tank fuel booster pumps on low speed, the fuel tank selectors were changed from "main" to "alternate" and the fuel pumps turned off. At this time the fuel warning light came on and Nos. 3 and 4 engines surged. Power on these engines were reduced, propellers put into fixed pitch and the fuel pumps turned onto high speed. No. 4 propeller was feathered just as the fire warning light for No. 2 zone of No. 2 engine came on. No. 3 propeller was then feathered. The firewall shut off valve for No. 3 engine selector was pulled and the right hand CO<sub>2</sub> charge was fired. The fire warning light went off immediately although considerable smoke and flames were seen issuing from No. 3 nacelle by the cabin occupants. The flight returned to El Paso and landed without further incident, with damage being confined to the No. 3 engine. A punctured enrichment diaphragm in the carburetor of No. 3 was found, which possibly could have caused the fire by dripping fuel on the generator, combustion occurring and vaporizing the fuel in lines and carburetor causing a loss of fuel flow.

While cruising in the vicinity of Midland, Texas, sudden, severe and unpredicted hail was encountered. A left turn was made and the flight was out of the hail in a matter of minutes. Considerable damage was sustained by the aircraft as the hailstones were estimated to be about 3/4 inch in diameter. Flight descended and continued to El Paso where a safe landing was made.

NC 21776 was holding (awaiting ATC clearance) and somewhat blocked the taxi way as NC 17331 was being taxied to take-off position. Pilot in NC 17331 attempted to pass the other aircraft and in doing so, misjudged his clearance - the left wing tip was damaged on collision with right wing of NC 21776.

Encountered severe hail storm, enroute to Pittsburgh from Reading, resulting in damage to plane. Safe landing made at Harrisburg.

A. Scheduled Domestic Operations

1. Passenger Carrying Operations

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury Passengers</u>						<u>Aircraft Damage</u>	<u>Fire In Air</u>	<u>Fire After Impact</u>
						<u>Crew</u>	<u>E</u>	<u>S</u>	<u>M</u>	<u>N</u>	<u>E</u>	<u>S</u>	<u>M</u>	<u>N</u>
6/14/48	Yes	Detroit, Michigan	AA	DC-6	23	-	-	4	-	-	19	-	Subst.	Yes

The nose gear retracted a few seconds after it contacted the runway and aircraft skidded along on its nose for a considerable distance before coming to a stop. Investigation disclosed the nose wheel gear to be improperly rigged and it appears that the cumulative results of the rigging errors in turn resulted in the down latch being insecure and consequently jarred off center by the effect of nose gear spring-back. The use of insufficiently sturdy templates for precision rigging in the field is also considered as a contributing factor.

6/17/48	Mr. Mt. Carmel, Pennsylvania	VAL	DC-6	43	4	-	-	39	-	-	—	—	Destroyed	Yes

The flight known as 624 was routine from San Diego to a point west of Sunbury, Pennsylvania at which time the New York Radio Operator heard a loud call for New York and a garbled message which indicated that an emergency descent was being made and something was said concerning fire in the forward cargo pit and that a fire extinguisher had been released. No further message was received. Eye witnesses on the ground saw the plane pass over the Sunbury Airport at 400-500 feet. A wide turn to the left was made near Shamokin followed by a wide turn to the right which steepened until the plane struck a ridge and a high voltage transmission tower.

6/19/48	Yes	Amarillo, Texas	Pioneer	DC-3C	6	-	-	3	-	-	3	Subst.	Yes

The flight to Amarillo was normal and routine. After waiting until some thunderstorm activity had passed over the airport, the flight was cleared to make a VFR landing on Runway 31. A normal landing was made, but the plane continued its landing roll and when about 3/4 of the way down the runway, veered off to the right onto the sod, ran through a fence, came to a halt and was the taxied back to discharge the passengers. Investigation revealed that a windshift occurred and this together with the fact that the runway was wet and slippery reduced brake effectiveness and prevented pilot from having full control on the roll.

7/4/48	Washington, D. C.	NWA EAL	Two C-54B's	9	-	-	2	-	-	7	Subst.	(NC 95407) (NC 88812)
				34	-	-	4	-	-	30		

Pilot of NC 95407 was returning to the ramp and was under the impression NC 88812 had already started out from its warm-up position. NC 88812 had not yet moved and consequently pilot in NC 95407 realized too late that he would not have adequate clearance and applied brakes but the left wing tip collided with right tip of NC 88812.

A. Scheduled Domestic Operations

1. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury Passenger					Aircraft Damage	In Air After Impact	Fire	
						Crew	F	S	M	N	E	S	W	N
7/5/48		Minneapolis, Minnesota	Wisconsin Central	Lockheed 10A	11	-	-	-	2	-	-	9	Subst.	
7/12/48		Wenatchee, Washington	NW	Martin 202	17	-	-	-	4	-	-	13	Subst.	
7/13/48	Yes	Des Moines, Iowa	UAL	DC-3	21	-	-	-	3	-	-	18	Subst.	
7/21/48		Ocala, Florida	Florida Airways, Inc.	Beechcraft 118C	3	-	-	-	2	-	-	1	Subst.	

While on approach for landing, pilot was unable to get the right gear in full down position and all attempts to retract or fully extend the gear were unsuccessful (it was in half-down position). He then circled in vicinity of airport until fuel was nearly exhausted and made a belly landing in the sod area. Inspection revealed gear malfunction was caused by a pin shearing in the universal joint at the outer gear box. It appears this joint has no provision for lubrication and no cover for protection from grit.

While taxiing out for take-off, it was discovered that some baggage which should have been deplaned was still on board. A turn around was attempted during which time the nose wheel and right gear were permitted to get off the hard surface taxy way. Pilot applied considerable power in attempting to bring the nose wheel and right gear back on the runway and the nose gear failed allowing the plane to drop down and strike the propellers on the ground.

Enroute from Cedar Rapids to Des Moines, pilot was advised that due to a power failure the field lights at Des Moines were inoperative. However, an emergency generator provided for obstruction lights on the ILS shack and the neon approach lights. Captain contacted the Des Moines tower and was advised of a NE wind 10-15 mph, visibility 3 miles (accident occurred 9 minutes before hours of darkness); he then advised the tower he would land on runway 31. Captain states runway outline was distinguishable during approach, but after passing approach lights visibility was somewhat restricted in light rain. On contact with runway "full" flaps were applied and Captain found brakes ineffective during landing roll on wet runway. Approximately 860 feet from end of 5,700 foot runway the left wheel went off the concrete onto soft sod area and aircraft travelled over the sod 576 feet in a skidding attitude completely demolishing the ILS shack then continued another 185 feet coming to rest against a steel fence.

7/21/48

A. Scheduled Domestic Operations

1. Passenger Carrying Operations

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury Passengers</u>						<u>Aircraft Damage</u>	<u>Fire In Air</u>	<u>Fire After Impact</u>	
						Crew	F	S	M	N	F	S	M	N	
7/21/48	Yes	Nr. Hutchinson, Kansas	Continental	DC-3	17	-	1	-	2	-	-	-	14	None	
		While hostess was carrying out routine duties, the plane encountered a moderate to severe bump causing the hostess to lose her footing and she fell to the cabin floor, suffering injury. She was removed from the plane at Wichita and taken to the hospital where X-ray examination disclosed two broken vertebrae.													
8/11/48	Yes	Great Bend, Kansas	Continental	DC-3A	12	-	-	-	3	-	-	-	9	Subst.	
		While in flight between Denver, Colorado to Tulsa, Oklahoma, moderate to severe turbulence was encountered near Great Bend, Kansas, following which it was found that elevator control was affected. By the use of maximum power, sufficient control was kept to enable the pilot to effect a safe landing on the Great Bend Army Air Field. Inspection of the plane showed the right horizontal tail surfaces drooped downward from a location near the fuselage attachment. The torque tube of the elevator and the stabilizer had failed from a downward load. No other cause than excessive stresses due to turbulence could be found.													
8/19/48		Glenview, Illinois	AA	Convair CV-240	38	-	-	-	3	-	-	-	35	Subst.	
		As pilot dropped gear preparatory to landing at Chicago, lights indicated the nose gear remained in retracted position. Repeated attempts were made to lower the nose gear and when it became evident further attempts would be useless, an emergency landing was made at Glenview. A tail-low landing was made, then as speed decreased to 60 mph, the nose slowly dropped and skidded until aircraft came to a stop. Investigation revealed the locating lugs of the upper cam of steering gear centering assembly were sheared. This was followed by displacement of the nose wheel about the steering axis so that it cocked to the left and jammed against the left lower longitudinal nose wheel well beam.													
8/29/48		Nr. Winona, Minnesota	Northwest	Martin 202	37	4	-	-	3	-	-	-	33	-	Destroyed
		During flight through a thunderstorm area, a structural failure originating in the wing panel attachment fitting occurred. The aircraft then broke apart in the air resulting in fatal injury to all on board.													
8/29/48	Yes	Spokane, Washington	NWA	Martin 202	31	-	-	-	3	-	-	-	28	Subst.	
		Aircraft had just become airborne when the forward cargo door failed and blew off. Pilot immediately reverted an emergency and returned to the airport completing the landing without further incident. Considerable damage was sustained by fuselage, center section and horizontal stabilizer.													

A. Scheduled Domestic Operations

1. Passenger Carrying Operations

Date	At	Night	Location	Operator	Equipment	Total Aboard	Injury				Aircraft Damage	Fire In Air	Fire After Impact
							Total	Crew	Passenger	Injury			
							N	F	S	M	N		
8/31/48	Louisville, Kentucky	AA	Convair 240	37	- - - - -	3	- - -	3	- - -	34	Subst.		
9/8/48	Tampa, Florida	NA	DC-4	17	- - - - -	4	- - -	4	- - -	13	Subst.	Yes	
9/20/48	Burlington, Vermont	Colonial	DC-3	17	- - - 1	2	- - -	2	12	Destroyed			
10/6/48	Chattanooga, Tennessee	Delta	DC-3	10	- - - - -	3	- - -	3	- - -	7	Subst.	Yes	

The plane made a normal landing on the runway but very soon after the nose wheel contacted the surface, the nose wheel gear collapsed allowing the propeller tips, the nose wheel doors and finally the nose to contact the runway. The aircraft veered to the right and came to rest without fire or other complications resulting. Passengers were deplaned safely. Investigator disclosed that the failure in the nose gear was due to a defective brazed joint in the hydraulic retracting cylinder.

Flight '72, Miami to New Orleans via Tampa proceeded routinely until about 57 miles SE of Tampa where a descent was started. At this time it was noted that head temperatures on No. 3 engine were rising with the fuel pressure and oil pressure reading zero. Attempts were made to feather the propeller which were only partially successful. Fire was observed and the firewall shut off valves and right bank of CO<sub>2</sub> was actuated. On the final approach an explosion occurred in the nacelle and parts dropped from the engine. Fire was again apparent and the left bank of CO<sub>2</sub> was discharged. A normal landing was made in spite of a vibration and yaw to the right and the remaining fire extinguished by ground equipment. The origin of the fire in No. 3 nacelle is still being studied.

On a VFR approach the plane was brought in a little high and a little fast. The touchdown was made about half way down the runway. The brakes proved ineffective and it became apparent to the Captain that he would be unable to stop on the runway. He then attempted to take off. Three hundred feet beyond the end of the runway the plane struck a pile of earth followed by contact of the left wing with some saplings, turning the plane 90 degrees to the left and it came to a stop among the trees. Subsequent tests made on the brakes showed them to be in normal condition. There is a strong possibility that the landing was made with the flaps only 1/4 down. It is apparent that the main cause was an approach made too high and with too much speed with a wet runway being a contributing factor. The Captain's delay in applying corrective measures is also a factor.

On taking off at Chattanooga and upon becoming airborne, a loud noise was heard and rpm dropped on the right engine, and shortly following a fire was detected in the right engine. Preparations were made to land, including an attempt to feather the engine. After lining up with a runway the gear was lowered. The positive latch had to be forced into position and after the plane landed and stopped rolling, the right gear collapsed. Ground fire equipment extinguished the blaze and all personnel were safely evacuated. Investigation disclosed that the initial cause of the engine failure was a breakage of the engine pin end of the master rod.

A. Scheduled Domestic Operations

1. Passenger Carrying Operations

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	Injury Passengers						<u>Aircraft Damage</u>	<u>In Air</u>	<u>After Impact</u>	
					Total	Crew Aboard	F	S	M	N	F	S	V	N
10/6/48		Chattanooga, Tennessee (Continued)												
10/16/48		Oakland, California	TWA	DC-3	10	- - - - 3	- - - - 7							Subst. (NC 18949)
10/28/48		Rochester, New York	AA	DC-3	19	- - - - 3	- - - - 16							Subst.
11/5/48	Yes	Dallas, Texas	Delta	DC-3	22	- - - - 3	- - - - 19							Subst.

This split the No. 1 piston into two sections. Further disintegration followed tearing of the cylinder and fire followed. The landing gear failure was due, first to the fact that the landing gear was locked down before the gear had fully extended and second, by failure of the truss members to carry the load when the gear knuckled down. This may have been due in part to internal rusting of the truss members.

Pilot in NC 18949 landed and received tower clearance to taxi in to the ramp. Pilot in NC 2803N meanwhile landed on gravel area (parallel to runway) and without clearance, turned onto the taxi strip ahead of the airliner and proceeded to taxi in. Neither had, at this point, been cautioned by the tower as to their close proximity (tower operators were busy and apparently were not aware of this condition inasmuch as NC 2803N was not given taxi clearance and was expected to hold his position after landing). NC 18949 pilots did not observe the other aircraft and overtook it from the rear.

Following a normal landing the plane was being taxied into the ramp. In making a 90 degree left turn, right brake was applied to halt the turn but the brake failed to hold even though both the Captain and First Officer applied pressure. Power was applied to the left engine without noticeable effect and both brakes were applied but the crew was unable to avoid colliding with two parked Fairchild M-62A's. Investigation disclosed that the hydraulic pressure on right brake was below that required for normal operation. A check of the brake control valves showed the tuning fork to be out of alignment by 3/8 inch. Brake pressures were set for 650 p.s.i. each and taxiing tests made which showed brakes to be in normal condition.

On the take-off, airport personnel heard one of the engines cut out as the plane passed the NW boundary of the airport. The engine was feathered and clearance for an emergency landing on runway 7 was requested. On final approach the tower was advised that the landing gear was not locked down. Crash crews were placed in the most advantageous positions. A normal landing was made but after rolling over a third of the runway the aircraft veered to the right, left the runway and groundlooped 180 degrees before coming to rest. Investigation revealed that on the take-off a fine oil mist filled the cockpit covering the instruments and making breathing difficult. The Captain fearing an engine oil leak, feathered the left engine as the leak appeared to be from that source and the landing was made. The actual leak, however, was found to come from a ruptured windshield wiper line which had been installed improperly as a bend had been made in the line too close to the fitting to permit making the required flare in the line inside the fitting. Steps are being taken to prevent a repetition.

I. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury Passengers						Aircraft Damage	Fire In Air After Impact
						Grew	F S M N	E S W N	E S W N	E S W N	E S W N		
11/13/48		St. Louis, Missouri	AA	Convair 240	37	- - 1	2	- -	2	- -	2	Subst.	
11/15/48		E. Boston, Mass.	Northeast	DC-3A	23	- - -	3	- -	3	- -	20	Subst.	
11/19/48	Yes	Birmingham, Alabama	Capital	DC-3	10	- - -	4	- - -	4	- - -	6	Subst.	
11/19/48		Endicott, New York	Robinson	DC-3	12	- - -	3	- - -	3	- - -	9	Subst.	

Flight was routine including landing and taxiing in at St. Louis. Arriving at the ramp, the engines were cut, parking brakes applied and the cockpit secured. The passenger loading door was then opened, followed almost immediately by the collapse of the landing gear. Investigation disclosed that 3 green lights had shown when gear was extended and pressure was up. However, tests showed that it was possible to move handle to a position 1/2 inch above full down and get the green lights. On landing, friction from the solenoid pin probably held the gear up for a time. Changes are now being incorporated which will make it impossible to get the green lights without the landing gear primary lock being engaged.

11/19/48      E. Boston, Mass.      Northeast      DC-3A      23      - - -      3      - - -      3      - - -      20      Subst.

While taxiing out from gates, wing struck a passenger loading ramp.

11/19/48      Yes      Birmingham, Alabama      Capital      DC-3      10      - - -      4      - - -      4      - - -      6      Subst.

On the landing approach very turbulent air conditions prevailed. On the flares-out, the plane ballooned into the air and would not settle to the runway in the turbulent air. The Captain took over the controls from the co-pilot who was flying and forced the plane on the runway, put the flaps in "up" position and applied brakes. The brakes were ineffective on the wet runway and seeing that the plane would overshoot the runway, the Captain applied full left rudder and full right engine. The plane turned left but did not complete the groundloop before hitting a heavy wire fence along a creek bank. The plane bounced off the fence and headed easterly until one wheel rolled over the bank of the creek at slow speed, bringing the plane to rest.

11/19/48      Endicott, New York      Robinson      DC-3      12      - - -      3      - - -      3      - - -      9      Subst.

On a flight originating at Buffalo, New York and with final destination being Pendix Airport, New Jersey, an intermediate stop was made at Tri-Cities Airport, Endicott, New York. On the first approach visual contact was not made at 2,240 feet and the plane was climbed back to 3,500 feet. A second approach was made and this time the contact was made at 2,400 feet and a landing was made in which the plane touched down 1,785 feet from the approach end of the runway following which the plane rolled a distance of 850 feet then started a left turn, rolled off the runway and over a 10 foot embankment, nosing up. Investigation disclosed that the approach and landing was made at a greater than normal speed. This coupled with a wet runway made it impossible to stop within the length of runway remaining.

A. Scheduled Domestic Operations

1. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury Crew F S N P S M N					Aircraft Damage	Fires In Air	Fires After Impact
						Passenger							
11/19/48	Yes	New York, New York	AA	Convair 240	40	- - - 3	- - - 37				Subst.		
11/25/48		Los Angeles, Calif.	TWA	Lockheed 0-49	23	- - 1 4	- - 4	14	- -	1 4	Destroyed	Yes	
12/3/48		Columbus, New Mexico	AA	DC-6	45	- - - 4	- - 4	41	- -	4	Subst.		
12/8/48		St. Croix, Virgin Islands	Caribbean Atlantic	M-3	5	- - - 3	- - 3	2	- -	3	Subst.		
12/12/48		Yakima, Washington	Northwest Martin 202	16	- - - 3	- - 3	- - 3	13	- -	3	Subst.		

In making a landing approach through heavy rain and turbulent air the crew forgot to place the landing gear in the extended position. As the wheel was eased back and power reduced, the gear warning horn sounded, but both pilots mistook this for the stall warning indicator and applied more power. The plane landed on the belly and skidded along the runway. No fire occurred and all personnel deplaned safely.

11/25/48 Los Angeles, Calif. TWA Lockheed 0-49

Upon arrival at Los Angeles, although the weather was clear, there were patches of ground fog. In the approach as the plane was being flared out, a patch of ground fog was encountered resulting in pilots being "blind". The Captain pulled back on the wheel and the plane dropped in very hard. Both nose wheel tires blew out and other serious damage was sustained. The plane went off the runway and was turned sharp right to avoid a ditch, then came to a stop. Fire ensued and destroyed the plane but not before all occupants were deplaned with only minor injury to five.

12/3/48 Columbus, New Mexico AA DC-6

While cruising normally at 18,000 feet, a hard jolt was felt. It was seen that No. 4 engine was missing and fire was in the nacelle. Emergency procedures were followed, the fire extinguished and a safe landing accomplished on the Columbus, New Mexico Airport. The engine was found, practically intact, with one propeller blade missing. This blade was later found and all indications were that it had failed in the air. Tests revealed that the blade failure was due to an original manufacturing defect.

12/8/48 St. Croix, Virgin Islands

While taxiing, left landing gear collapsed as a right turn was made. Investigation showed that the drag strut had failed in upper end attachment bolt. The bolt had seized due to lack of lubrication with the initial failure occurring some time previously.

12/12/48 Yakima, Washington Northwest Martin 202

Snow which had fallen on the runways had been inadequately removed and as a result patches of packed snow and ice remained, which were very slippery. On the landing the touchdown was made well within the first  $\frac{1}{3}$  of the runway. On the last  $\frac{1}{4}$  of the runway, however, the wheels were observed to be sliding and deceleration had practically ceased. The pilot attempted to groundloop but the plane skidded ahead until the nose wheel struck the packed snow at the end of the runway and collapsed. The plane then skidded on its nose and main wheels in a left turn for 150 feet, coming to rest on its nose and main gear.

A. Scheduled Domestic Operations

1. Passenger Carrying Operations

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury</u>						<u>Aircraft Damage</u>	<u>Fire In Air</u>	<u>Fire After Impact</u>		
						<u>Crew</u>	<u>Passenger</u>	<u>F</u>	<u>S</u>	<u>H</u>	<u>N</u>					
12/21/48	Yes	Chicago, Illinois	Capital	DC-3	23	- - -	- 3	- -	- 20	-	-	Subst.				
Pilot of DC-3, tarrying out, failed to observe Cessna and taxied into it from the rear.																
12/24/48	Yes	Nashville, Tennessee	EAL	C-54D	35	- - -	- 5	- -	- 30	-	-	Subst.				
On a flight scheduled between Miami, Florida and St. Louis, Missouri, with intermediate stops at West Palm Beach, Jacksonville, Atlanta and Nashville, the flight was routine to Nashville except for running 1/2 hour late. After some difficulty in contacting the tower on account of precipitation static, the flight was cleared in and advised the tower it was going to land on runway 2 L. When sighted, it was to the right of runway 2 L and the flight advised that it was landing on runway 3R. The actual landing, however, was made on runway 2 R, which is short, making contact only 1,500 feet from the approach end. The plane bounced, however, and again made contact 2,100 feet from the approach end. Brakes were applied but were ineffective on the wet, black top runway. The plane went off the runway and came to rest 100 yards beyond with wheels buried in soft dirt. Investigation disclosed poor coordination between Captain and Co-pilot and confusion as to which runway was to be used. Lack of alertness on the Captain's part also played a part.																
12/28/48	Yes	Johnson City, Tennessee	Piedmont	DC-3	18	- - -	- 3	- -	- 15	-	-	Subst.				
Take-off was made from Tri-Cities airport, an intermediate stop on the route from New Penn, North Carolina to Cincinnati, Ohio. As the plane crossed the airport boundary, the right oil pressure warning light came on and pressure dropped to 40 pounds. A return to the field was made and a landing attempt made on the same runway from which take-off was made. This approach was overshoot and throttles were opened for a go-around. Altitude could not be gained and a crash landing was made 3/4 of a mile beyond the airport boundary, with wheels up. Fire started in the left engine but was quickly extinguished by CO <sub>2</sub> . Investigation disclosed that the cause of the drop in oil pressure (though not accompanied by power loss) was fuel dilution of the right engine oil, due to a change in the location of the oil dilution switch to one formerly occupied by the primer switch, the crew not having been instructed in such change. In the approach to the emergency landing, the Captain made unnecessary use of the microphones, diverting his attention and he allowed the right engine to overcool by improper use of cowl flaps, resulting in lack of power when it was needed for the go-around.																
12/31/48	Yes	Akron, Ohio	EAL	DC-3	18	- - -	- 3	- -	- 15	-	-	Subst.				
Aircraft was in a routine landing approach with gear and flaps down and airspeed 100 mph. At an altitude of about 200 feet, severe turbulence was encountered, and at 150 feet a severe downdraft occurred, which in spite of application of power, dropped the aircraft so close to the ground that the main landing gear struck an embankment just outside the boundary of the airport. The plane bounced into the air for a short distance, landed on the belly and skidded over the icy surface of the runway, finally coming to rest on the left side of the runway.																
					Total	1269	15	2	4	165	83	4	16	980		

A. Scheduled Domestic Operations

2. Other Revenue Operations

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury						Aircraft Damage	In Air After Impact	Fire	
						P	S	M	N	E	S	M			
3/23/48		Pittsburgh, Pennsylvania	All Amer. Stinson	SR10C W-3	3	-	-	-	-	3	-	-	Subst	(TWA)	
		Pilot of All American Stinson was taxying out and watching a TWA ship also taxying to take-off. Pilot failed to observe a stand-ing Douglas DC-3 with engines idling. The right wing passed under the nose of the Douglas breaking pitot mast and continued on into the propeller of the Douglas which was still turning although switches had been cut.													
11/28/48	Yes	Albuquerque, New Mexico	TWA	DC-3A	3	"	-	-	3	-	-	-	Subst.		
		On this flight, carrying cargo only, the weather was CAVU with light turbulence. At 11,000 feet the Captain adjusted his seat so his legs were straight on the rudder and loosened his seat belt. Later the dome light was turned on. Suddenly the aircraft encountered a down draft which threw the Captain up 4 or 5 inches off his seat where he could not reach the rudder pedals. The aircraft immediately went into a steep dive and right spiral. The aircraft continued down out of control until the combined efforts of Captain and Co-pilot righted it after losing 3,300 feet. A 180 degree turn was made and the plane was headed east. The Captain decided to land at Albuquerque where a landing was made. It was necessary to use brakes and power to keep rolling straight on the runway, but still ran off the right side at the end of the roll. It was then taxied in. Investigation revealed serious damage to the rudder resulting from the excessive stresses applied to it by both pilots. The action of the pilot in not keeping proper adjustment of seat belt and seat is the primary cause coupled with use of dome light instead of rheostat light during flight.													
12/26/48		San Juan, Puerto Rico	Caribbean	DC-3	2	"	-	-	2	"	-	-	Minor		
		Atlantic													
		The pilot of the Aeromexico taxied out for take-off and was holding, awaiting clearance from the control tower. While thus standing, a Caribbean Airlines Douglas DC-3 taxied along the runway and turned right straight into the Aeromexico. Pilot jumped out of his plane in time to avoid other than minor injury. Investigation disclosed the reported facts as substantially correct except that the Aeromexico may have been moving forward at the time. The outstanding factor, however, was lack of vigilance on the part of the DC-3's pilot plus the same on part of tower operator.													
3/9/48		San Francisco, California	UAL	DC-4	3	"	-	-	3	"	-	-	Subst.		
		Following take-off on a local training flight, it was discovered that the nose gear would not extend, although the main landing gear operated normally. After all efforts to get the gear to lower had been made, the plane was flown to San Francisco Municipal Airport, where after dumping excess fuel and releasing flares, the ship was landed with the nose gear retracted. Investigation disclosed that a long piece from one of the rubber chevron packings in the retracting piston, had become detached and lodged in the orifice of the tee fitting through which the hydraulic fluid for the cylinder passes, where it stayed despite pressures of 4,000 p.s.i. being applied. Changes in this installation in accordance with Douglas Service Bulletin DC-4-78 dated 9/24/47 have been made.													

12  
C1

A. Scheduled Domestic Operations

2. Non-Revenue Operations

Date	At Night	Location	Operator	Equipment	Injury						Aircraft Damage	In Air	Fire After Impact		
					Total	Crew	Passenger	F	S	M	N				
3/18/48		Ardmore, Oklahoma	AA	Convair 240	2	--	--	2	--	--	--	Subst.		Yes	
					In practicing a "low visibility approach", a descent was made at 120 mph and at 200 feet a pull-out was started. The airplane struck the ground in approximately level position on all three gears. The center section failed in torsion on both sides and further damage occurred as a result. The teaching of the "low visibility approach" has been discontinued by American Airlines, as this type of maneuver with an aircraft of high wing loading required exact judgment and timing in order to check the rate of descent in sufficient time. A fire which followed the accident was extinguished.										
4/2/48		Newark, New Jersey	Northwest	Martin 202	2	--	--	2	--	--	--	Subst.			
					Just as the aircraft left the ground on a ferry flight, the front loading door came off and struck the left propeller. The field was circled and a normal landing made on the airport. Examination indicated that probably on numerous occasions the door had been locked before the rods or "bayonettes" were lined up with the receptacles in the door frame. This caused the rod assemblies to bend or break, and only two of the bayonettes were actually holding the door at the time of the accident. Design on the door could be improved.										
5/30/48		Chicago, Illinois	Delta	C-54B	2	--	--	2	--	--	--	Subst.			
					A nose gear failure occurred as pilot sprung aircraft to left into position for engine run-up prior to take-off. Investigation disclosed the nose gear yoke end fitting had failed. Evidence indicates faulty manufacture as having contributed to this failure, i.e., imperfect radius and tool marks on highly stressed part.										
7/23/48		Los Angeles, California	VAL	C-54	3	--	--	3	--	--	--	Subst.			
					A test hop was being made for the purpose of testing a newly installed No. 1 engine. On the final approach No. 3 engine became rough accompanied by fluctuating manifold pressure indications. The engine was feathered and the landing made but while taxiing to the hangar, fire was seen coming from the lower section of ring cowling. The fire was extinguished by use of CO <sub>2</sub> and water. Examination disclosed that fire had apparently originated in the blower section of the engine for reasons not known.										
					Total	12	--	--	12	--	--	--			

4. Non-scheduled Operations (Charter, etc.)

No accidents.

B. Scheduled U. S. Flag International

1. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury Passenger						Aircraft Damage	In Air Fire	After Impact	
						Crew	F	S	M	N	E	S	M	N	
2/28/48	Yes	San Francisco, Calif.	PAA	DC-4	34	-	-	-	-	-	7	-	-	27	Subst.
															Yes

While taking off on a scheduled flight from San Francisco to the Orient, after about 2,830 feet down the runway and at an indicated speed of 85-95 mph, all three landing gears suddenly retracted. The throttles were closed and the aircraft skidded along on its belly for 2,450 feet and came to rest, still on the runway. Fire broke out in No. 3 engine nacelle which was successfully extinguished by the use of CO<sub>2</sub> bottles. Extensive investigation was made to determine where the failure may have occurred but nothing was found which could account for it. Suspicion, therefore, rests strongly on the crew and for lack of evidence to prove otherwise, it must be assumed that a member of the crew retracted the gear prematurely on the take-off run.

3/21/48	Yes	Enroute San Francisco - Honolulu	UAL	DC-6	24	-	-	-	-	-	6	-	-	28	Subst.	Yes
While cruising at 12,000 feet, No. 4 engine became very rough, although instruments were showing normal indications. Then No. 1 zone fire warning light came on followed by Nos. 2 and 3 zone fire warning lights. The propeller was feathered and the CO <sub>2</sub> selector valve was set for No. 4 engine. CO <sub>2</sub> was not discharged however, as the warning lights went out and a visual check showed the fire had been extinguished. The remainder of the trip was made at 10,000 feet with No. 4 engine feathered. The cause of the trouble was found to be due to the failure of the No. 8 master rod piston pin.																
3/24/48		Accra, Gold Coast, Africa	PAA	Lockheed 49	41	-	-	-	-	-	10	-	-	31	Subst.	
4/15/48	Yes	Shannon, Eire	PAA	Lockheed 49-46	31	10	-	-	-	-	20	-	-	1	Destroyed	Yes

Flight was from La Guardia Field, New York to Johannesburg, South Africa, with six intermediate stops enroute. The flight was routine to Santa Maria where a crew change was made. Upon arrival at Lisbon, some difficulty was experienced in extending the nose wheel gear which was overcome by applying a few strokes to the emergency extension handle. At Dakar the same trouble was again experienced and after landing, an inspection was made. The flight continued, however, and at Accra, the nose wheel again refused to extend and this time all measures taken were of no avail. The aircraft was finally belly landed off the runway with the nose gear actuating cylinder. The piston in the cylinder was found to lack the standard 45 degree chamfered edge resulting in the edge being peened over and cutting off chips and scoring the cylinder. Bottoming of the piston against the cylinder and the chips resulted in further peening and chipping until seizure of the piston finally occurred. Steps have been taken to inspect and replace, if necessary, similar pistons on this type of actuating assembly.

Pan American flight 1-10 scheduled to fly westward from San Francisco to New York was routine on its trip via Calcutta (where aircraft was changed), Damascus, Syria, Istanbul. On the approach at Brussels, Peldquin, the fluorescent lighting on the pilot's side went out. This happened again at London but as no spare rheostat switch, the cause of the trouble, was available, the chart

## 1. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Injury Passengers			Aircraft Damage			Fire In Air After Impact		
					Total Aboard	Crew F	S E M N	Passenger F S M N	Damage F S M N	Fire In Air	After Impact		

4/24/48

Shannon, Erie (Continued)

Light was used instead. On the approach to Shannon Airport, using the instrument landing system, one "missed approach" was reported by the flight which was observed by the tower through a break in the clouds. On the second approach the flight reported that it was approaching the marker and then acknowledged a communication from the tower regarding weather. In the approach, however, the flight descended below minimum altitude until it struck the ground 2,280 feet short of the end of the runway. Fire broke out immediately. Investigation failed to disclose any probability of mechanical malfunction other than the possibility of failure of the pilot's fluorescent instrument panel light and it can only be concluded that the probable cause was continuation of the instrument approach to an altitude insufficient to clear the terrain. Failure of the fluorescent instrument light may have been a contributing factor.

4/25/48

St. Louis, Missouri Chicago and Southern

Flight departed Havana, Cuba and proceeded to New Orleans where a crew change was made. On flight to Memphis, No. 3 generator became inoperative and the fire warning light for No. 4 engine came on a time or two, but was disregarded. The generator control box was changed and the flight continued toward St. Louis although the generator was still inoperative. From Memphis to St. Louis, the fire warning signal came on several times, but no action was taken and no examination was made at St. Louis. Seven minutes out of St. Louis the oil pressure gauges for Nos. 1 and 2 engines dropped below allowable limits and the flight started a return to St. Louis. The fuel pressure gauge for No. 3 engine rose rapidly and smoke appeared in the cockpit. An emergency landing at Springfield, Illinois was contemplated until the source of the smoke was found to be an overheated transformer in an electrical junction box in the cargo compartment, which burned out and the smoke subsided, leaving fuel oil and manifold pressure gauges inoperative. The flight returned to St. Louis and landed without further incident. It was found on examination that the No. 4 exhaust pipe had parted due to improper installation of the clamp ring. The hot gases had burned through the stainless steel shroud, deflected off the firewall and charred the electric wires in the main electric conduit thus creating a high resistance and overloading the transformer which burned out. Heat from the flame operated the fire detector signal, which was disregarded as crew did not realize that this detector was of a new type, more reliable than an older type previously used. Had the flight continued much further, there is little doubt that a serious fire would have occurred.

4/29/48

San Jose, Costa Rica PAA DC-3A

Total - - - 4 - - - 47 Subst.

Aircraft was fired upon by riflemen as it was taking off from San Jose. A tire was blown out, several bullets went into or through the cabin and a hole was made in one blade of the No. 2 propeller. No personal injuries were inflicted. It was assumed that the firing was intended for one of the passengers, a Communist leader in Costa Rica but the identity of the assailants could not be determined. Aircraft was not damaged sufficient to affect airworthiness and flight continued to destination.

B. Scheduled U. S. Flag International

1. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury						Aircraft Damage	In Air Fire	After Impact
						Crew F S E N	Passenger M F S M N	Passenger L S M N	Passenger U S M N	Passenger I S M N	Passenger O S M N			
5/17/48		Seattle, Washington	PAA	DC-4,	24	- - - 7	- - - 17	- - - 17	- - - 17	- - - 17	- - - 17	Subst.		
5/27/48	Yes	Tamzin, Mexico	AA	DC-6	21	- - - 4	- - - 17	- - - 17	- - - 17	- - - 17	- - - 17	Subst.	Yes	
7/24/48	Yes	Havana, Cuba	PAA	Convair 240	44	- - - 4	- - - 40	- - - 40	- - - 40	- - - 40	- - - 40	Subst.		
12/9/48		Havana, Cuba	PAA	Convair 240	44	- - - 1	- - - 3	- - - 3	- - - 3	- - - 3	- - - 3	Subst.	Yes	

While taxiing in to the ramp, a small customs building was passed. A runway crew supervisor was in attendance and directed the pilot to continue to taxi. Just before coming to rest at the blocks, the left wing tip struck a stack on top of the building, crushing the leading edge of the wing. Approaching darkness and inadequate lighting on the building were factors as well as poor coordination between the Captain and ramp signalman.

Flight 90, Los Angeles to Mexico City, Mexico, made a routine flight as far as Monterrey, Mexico after a stop at El Paso, Texas. After departing Monterrey and reaching 10,000 feet, Nos. 1, 2 and 3 engines were shifted to high blower. No. 4 high blower was discarded "inoperative" and was not used. At 18,000 feet, Nos. 1 and 4 engines were changed to the alternate tanks with propellers at fixed position. Shortly thereafter No. 2 engine surged to a very high rpm accompanied by a loud explosion and fire around the nacelle. Fire warning lights came on, indicating fire in zones 1, 2 and 3 of "C" 2 engine. No. 2 propeller was immediately feathered, the oil and fuel selector valves shut off and the left tank of CO<sub>2</sub> discharged. The fire went out. The Captain then decided to land at Tamzin and make an instrument approach. The flight broke out at 1,300 feet and a landing was made in which the pilot could not stop the aircraft until within 400 feet of the end of the runway where a 15 degree left turn was made causing three tires to blow out. Tests conducted on overspeeding have established that by following certain procedures in the engine operation, overspeeding may be avoided. Further research and testing is being done with a view to elimination of this troublesome problem.

A normal landing was made with all indicators showing gear down and locked. However, during the landing roll the nose gear partially retracted and aircraft skidded on the nose until brought to a stop. Investigation disclosed the failure of a defective braze joint in the nose wheel retracting cylinder which allowed nose gear to retract.

On the take-off run, approximately 2,500 feet was used up without the plane becoming airborne. The Captain reduced power and applied brakes without effect. The plane continued off the end of the runway, struck a ditch shearing off left main gear, nose gear and right wing and engine, and came to rest on its belly. The right wing and engine which had separated completely from the plane caught on fire. Investigation revealed that an unidentified vibration had occurred on the take-off. The Captain was tardy in discontinuing the run resulting in brakes being applied while aircraft was nearly airborne. This wore through two of the aircraft's main tires and braking action on the remaining two was insufficient to stop the plane. A contributing factor is believed

B. Scheduled U. S. Flag International

1. Passenger Carrying Operations

Date	At	Night	Location	Operator	Equipment	Total	Injury			Aircraft Damage	Passenger Damage	In Air	After Impact
							Crew	S	M				
2/9/48			Javana, Cuba (Continued)				- - -	- - -	- - -	- - -	- - -	- - -	- - -

to be engine malfunctioning and vibration during take-off due to failure of the water injection regulator vent line check valve to function resulting in upsetting the mixture.

2/13/48 New Orleans, Louisiana Chicago and C-54B Southern

After effecting a normal ILS approach and landing, and following a short roll, the nose of the plane started to drop. The horn started blowing and the red light came on. After losing speed, the nose contacted the runway and the plane skidded along for 1,800 feet coming to rest on the nose and wheels. Investigation disclosed that the retraction of the gear was due to the failure of the First Officer to place the landing gear handle in the full down and locked position, possibly due to confusing the handle with the flap control handle.

Total 345 10 - 1 52 20 - 1 261

2. Other Revenue Operations

No accidents.

3. Non-revenue Operations (Test, Ferrying, Training, Check, Publicity, Familiarization, Company Flights, etc.)

Date	At	Operator	Equipment	Total	Crew	S	M	N	E	S	M	N	In Air	After Impact
1/27/48	Miami, Florida	PAA	C-54B		- - -	- - -	- - -	- - -	- - -	- - -	- - -	- - -	- - -	- - -

While taxiing out for take-off on a pilot training flight, a normal right turn onto the runway was started at which time several loud sharp reports were heard from the direction of the nose wheel assembly. The rate of turn sharply increased and the nose wheel collapsed to the left. Investigation disclosed that the cause was the failure of the right nose gear end fitting. It is considered likely that the strength of the subject type fittings is marginal.

Date	At	Operator	Equipment	Total	Crew	S	M	N	E	S	M	N	In Air	After Impact
2/8/48	New York, New York	PAA	Lockheed 49		- - -	- - -	- - -	- - -	- - -	- - -	- - -	- - -	- - -	- - -

During a test flight, fumes and the odor of burning material were noticed. Heater inverters and generators were turned off and the tower was notified that an emergency landing would be made on the airport. A straight in approach and landing on runway 31 was approved. Landing check off was completed and plane touched down between 110 and 120 mph. Propellers were reversed and the aircraft veered to the right. Pilot was unable to stop this turn with left brake and the plane left the runway, catapulted an embankment, went into the Bay and came to rest about 50 feet beyond embankment, partially submerged in the water. Investigation disclosed that failure occurred in the electrical power source resulting in only two propellers reversing. Loss of directional control occurred primarily as a result of the pilot's failure to have all three gears on the ground in the landing roll. During

B. Scheduled U. S. Flag International

2. Non-revenue Operations (Test, Ferrying, Training, Check, Publicity, Familiarization, Company Flights, etc.)

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury						Aircraft Damage	In Air After Impact	Fire In Air After Impact
						Total	Crew	Passenger E S M N F S M N	Injury	Passenger E S M N F S M N	Aircraft Damage			
5/8/48		New York, New York (Continued)												
10/27/48	Yes	Nr. Edmonton, Alberta, Northwest	DC-4		5	2	2	1	-	-	-	Destroyed		
		Canada												
		The flight departed Edmonton, Alberta, Canada where a stop had been made on a ferry flight to Tokyo, Japan from Minneapolis. No radio contacts were made after take-off and it was later determined that the plane had crashed and burned 10 minutes after taking off at a point 35 miles NW of Edmonton. Investigation indicated that the plane had been flying very low and had struck a tree 3,000 feet east of the final stopping point. It also indicated the probability that the Captain was giving instruction to the Co-pilot with one and two engines feathered and allowed the plane to descend to such a point that it was too late to avoid the tree.												
3/12/48	Yes	Mt. Sanford, Alaska	Northwest	DC-4	30	6	-	-	24	-	-	Destroyed		
		As part of a charter flight from Shanghai, China to New York, take-off was made from Anchorage, Alaska. Position reports were made over the Wasilla intersection at Sheep Mountain and Gulkana. From here a direct course was set for Skag, Yukon. On this course, 42 miles from Gulkana, 15 Mt. Sanford, 16,208 feet elevation. No further communication was heard from the flight and a fire was reported on Mt. Sanford. Search finally located the wreckage on the west slope of the mountain at an elevation of 8,500 feet. Investigation disclosed that ordinarily under good visibility conditions, Mt. Sanford could easily be seen and skirted, but on this occasion the aurora borealis was particularly brilliant and it is thought probable that a thin layer of clouds capping the mountain may have acted as a reflector for the lights and thus obscured the crew's view of the mountain until too late to avoid crashing into it.												
		Total			42	8	2	2	6	24	-	-		

C. Irregular Domestic Operations

1. Passenger Carrying Operations

At Date	Night	Location	Operator	Equipment	Injury							Aircraft Damage	Fire In Air	Fire After Impact	
					Total	Crew	G	S	M	N	F	S	V		
1/7/48		Savannah, Georgia	Coastal Air Lines	DC-3	27	1	1	-	-	17	8	-	-	Destroyed	

Enroute, between Charleston and Savannah, on a flight from Newark, New Jersey to Miami, Florida, the Co-pilot left the cockpit for navigation charts and while in the cabin heard one or both engines run roughly. By the time he returned to his seat, they were operating normally but a few minutes later both engines stopped and the fuel pressure gauges were seen to read zero and pressure could not be restored with the wobble pump, placing of crossfeed valves in "on" position, or changing of fuel selector valves. When it became apparent that the engines could not be started, the Captain instructed the Co-pilot to proceed to the passenger cabin to see that their safety belts were fastened, in preparation for a landing in a marsh. While thus engaged, he felt the airplane turn steeply and he started back to the cockpit but was forced to the floor by centrifugal force. The aircraft shuddered as though in a stall and crashed. Investigation failed to disclose definite evidence of malfunction other than the strong probability that the fuel selector valves were positioned so that both engines were supplied fuel from only one of the auxiliary tanks until fuel was exhausted, then if the crossfeed valve was placed in the "on" position, air would enter the system and result in inability to restart the engines, bringing on the forced landing in which the pilot, unassisted, lost control of the plane and allowed it to stall.

1/28/48	Coalings, California	Airline Transport Carriers	IC-3C	32	3	-	-	29	-	-	-	Destroyed	Yes
The crew scheduled to use NC 79055, certificated for 32 passengers, made a mistake and took NC 36480, certificated for 26 passengers, and which was 7 hours overdue for a 100 hour inspection. The flight to Oakland was routine but here 28 Mexican Nationals were enplaned, leaving three sitting on luggage without safety belts. While cruising south at 5,000 feet, smoke was observed streaming from the left engine; followed about a minute later by flames. A dull explosion was heard after which the left wing and left engine dropped free of the aircraft which then crashed out of control. Investigation disclosed that the gasket in the engine driven left fuel pump was broken and the four studs holding the castings of the pump together were loose. Tests showed that under pressure, gasoline would spray from the pump. This spray probably became ignited from the exhaust and the intense fire thus generated burned through the main spar back of the left engine.													
2/2/48	Lanai, T. H.	Andrew Flying Service, Ltd.	Cessna 0-73	2	-	-	-	1	-	-	-	1	Subst.

In landing approach apparently pilot failed to maintain sufficient airspeed and when a downdraft was encountered, ship stalled out and struck ground hard.

C. Irregular Domestic Operations

1. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury						Aircraft Damage	In Air Fire	After Impact		
						Crew	Passenger F	Passenger S	Passenger M	Passenger E	Passenger N					
2/3/48		San Juan, Puerto Rico	Argonaut Airways	DC-3C	2	- - -	2	-	-	-	-	Subst.				
						On the level-off for the landing a sudden deluge of rain came down reducing visibility to zero. Turning on the windshield wipers failed to improve matters. The ship stalled and touched the right wing tip and end of the right aileron on the runway. The rain stopped immediately and the pilot was able to straighten the ship up and continue on down the runway without further difficulty.										
3/29/48	Yes	Mana Kauai, Hawaii	Cockett: Beechcraft C-18S Airlines		1	- - -	1	-	-	-	-	Subst.				
						On the landing roll the right wheel locked due to the shearing of a special hex head bolt from the brake drum. Right tire blew out and plane skidded to a stop on the propeller hubs and nose section.										
4/24/48	Yes	Annette Island, Alaska	Arctic-Pacific	Curtiss C-46D	7	- - -	4	-	-	-	-	3	Subst.			
						The president of Arctic-Pacific, Inc. was acting as co-pilot in the right side while Pilot Bredehoft was acting captain, although apparently not in actual command of the plane. The approach was made too high. The acting Co-pilot applied power but the Captain was apparently so sure that he could make the landing that he cut the power off by pulling back the throttles and pulled back on the control wheel. The tail went down almost 60 degrees without touching and the aircraft stalled violently. Some recovery was effected by use of power but damage occurred as the ship dropped in hard. Glare from field lights may have been a contributing factor.										
4/26/48		Potts Camp, Mississippi	Southern Beechcraft 35	Airways	4	- - -	1	-	-	-	-	3	Subst.			
						On a charter flight from Memphis, Tennessee to Columbus, Mississippi, failure of the engine occurred while cruising. The plane was landed wheels up in an open field with no injury to occupants resulting. The engine was shipped to the Continental Factory without ascertaining the exact cause of the failure but the evidence indicated strongly that the trouble was in the lubrication system.										
6/3/48	Yes	El Morro, New Mexico	Aero-Van Express Corp.	DC-3C	31	- - -	3	-	-	-	-	28	Destroyed			
						While in normal cruise, pilot detected a vibration in the aircraft and suspecting icing, applied carburetor heat which only tended to increase the vibration. He then identified the left engine as the offender and immediately feathered the propeller and initiated single engine procedure making a VFR approach to a nearby auxiliary airport. Pilot overshot the runway on his first attempt to land and elected to make a 90 degree right turn crossing the head of the runway then another 270 degree right turn thus lining up on the runway for final approach. While executing this maneuver, pilot undershot and was unable to maintain sufficient altitude										

C. Irregular Domestic Operations

1. Passenger Carrying Operations

Date	At Night	Location	Operator	Equipment	Injury						Aircraft Damage	In Air Fire	After Impact	
					Total	Aboard	Crew	F	S	M	N			
6/3/48		El Morro, New Mexico (Continued)												
6/20/48	Yes	Irig Delta, Alaska	Artic Airlines	IR-34	23	-	-	2	-	-	2	29	Subst.	
9/21/48	Yes	Everett, Washington	Golden North Airways	Curtiss C-46A	10	-	-	3	-	-	7	Subst.		
9/29/48	Yes	Cordova, Alaska	Trans-Alaskan Airlines	DC-3C	10	-	1	1	-	-	3	5	-	Subst.

on the single engine to reach the runway - aircraft continued to settle in despite full power on the one engine and contacted rough terrain with the wheels retracted and in level flight attitude. Aircraft skidded a considerable distance, turned and skidded sideways before coming to rest. Investigation revealed the following facts: (1) The No. 12 cylinder of left engine had broken off at the No. 4 and No. 5 fin, but did not swallow the valve. The rear spark plug was dirty with carbon and apparently not delivering full fire power. Examination of the cylinder head showed signs of scorching and overheating. Since an explosion occurred immediately after carburetor heat was applied, indications are, a detonation condition existed in the No. 12 cylinder and the application of heat intensified the detonation which blew off the cylinder head; (2) Aircraft was overladen on take-off and else during landing; (3) Generally poor maintenance was indicated in that aircraft and engines were dirty; and (4) Pilot did not use the 1st-down procedure for the airport being used - the field was lighted and radio station was operating.

The flight had departed from Juneau, an intermediate stop on an instrument flight plan, for Fairbanks. In the vicinity of Big Delta while en route, the pilot saw a mountain directly ahead. A steep pull-up was made and a crash was heard. The aircraft was climbed to 9,300 feet, flown to Fairbanks and safely landed. It was found that one blade tip of a propeller was bent and the tail wheel strut was also bent causing considerable damage to the fuselage bulkheads. Some damage in the cabin also occurred due to a sudden forward leveling off with some passenger's seat belts not being fastened. Investigation disclosed no malfunction of plane or radio range facilities which could have contributed to the accident and it is concluded that navigational pilot error was the primary cause.

The right propeller governor was out and rpm was being controlled by use of the manual control. However, the manual control also malfunctioned and being in the vicinity of Everett (where pilot knew C-46 maintenance was available) pilot elected to land rather than continue through bad weather on to Seattle. Pilot made a straight in approach on a crosswind runway touching down at approximately the halfway point. Aircraft ran off the runway and pilot groundlooped to avoid running off a 15 foot drop. The tail dropped over the edge of this bank and struck a tree. Runway was wet from a recent rain.

A landing was made in heavy rain with excess speed. It became apparent to the pilot that he would be unable to stop within the remaining runway and he attempted to groundloop but was only partially successful. The aircraft went into a deep ditch at a speed of approximately 30 mph. Investigation disclosed that the aircraft had been landed partly downwind in an 18 mph wind, the

C. Irregular Domestic Operations

1. Passenger Carrying Operations

Date	At	Night	Location	Operator	Equipment	Injury						Aircraft Damage	Firs In Air	Firs After Impact
						Total Aboard	F	S	M	N	E			
9/29/48			Cordova, Alaska (Continued)											

resultant "assault" being in the neighborhood of 11 mph. Weather sequence reports received in flight indicated an easterly surface wind and although it was actually ENE at the time of approach, the landing was made to the west. There is a possibility that the landing was made downwind purposely as the approach from the east is much clearer and the pilot was not very familiar with the surrounding terrain.

10/4/48 Yes Haines Cay, Bahamas Is., New England DC-3 23 - - - 4 - - - 19 Destroyed

Berry Is. Group Air Express

The flight departed Teterboro, New Jersey on a direct flight to Miami, an intermediate stop before San Juan, Puerto Rico. The U. S. coast was left at about Atlantic City and was not sighted again thereafter. Cross checks were made on the Washington, D. C.; Cherry Point, North Carolina; and Charleston, South Carolina ranges. After crossing the Melbourne, Florida range, it was expected that the mainland would be sighted, but failing to do so the flight was headed west. Lights were sighted which proved to be a large island. Turned in Nassau range, picked up a leg and was following it in when fuel in right main tank became exhausted. Switched to left main and found that only 30 gallons remained, insufficient to reach Nassau. Islands were sighted which were identified as the Berry Group and a landing, wheels-up was made on the beach with only minor damage resulting. The surf later damaged the plane beyond repair. Though there is no factual evidence to support it, a probability exists that the crew were asleep during part of the flight and the auto pilot precessed and turned the plane leftward.

10/19/48 Anchorage, Alaska Columbia Air DC-3 5 - - - 3 - - - 2 Subst.

Cargo, Inc.

On a flight from Portland, Oregon, an intermediate stop was made at Annette Airport where fuel was taken on and some cargo un-loaded. The flight continued using the original weight and balance sheet. At Anchorage, 505 pounds of cargo was unloaded and the aircraft refueled to 600 gallons. After about three hours on the ground here, a take-off was attempted after brushing off accumulated snow on the wings with brooms. On this take-off it was seen that the plane used up the entire 3,960 foot runway, becoming airborne to about 10 feet after leaving the hard surfaced area. The plane banked to the left about 30 degrees and dragged through a copse of small trees and brush. Unable to gain altitude, a landing was made in the brush. Investigation disclosed that the cargo on board plus fuel and two passengers with baggage aggregated gross load of 27,403 pounds. Although the C. G. was still within limits, the cargo exceeded by 2,076 pounds, the amount listed on the balance form. The cargo was inadequately secured and had shifted somewhat. Further, it was found that the snow had not been completely cleared from the wings before take-off. This was the pilot's first trip as Captain.

C. Irregular Domestic Operations

1. Passenger Carrying Operations

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Aircraft</u>	<u>Injury</u>						<u>Fire</u>			
						Total	Aboard	Crew	F	S	M	N			
10/23/48	Yes	Teterboro, New Jersey	Modern Air Transport	Two DC-3's	23	- - - 2 - - - 21							Subst.		
						When gear was placed in down position, it was noticed that there was no hydraulic pressure. Gear was secured and locked in down position and landing made. Safety pins were placed in the gear to taxi in and brake pressure was maintained by manual operation of hydraulic emergency pumps. As the ramp was approached, both brakes failed to operate despite use of the hydraulic emergency pump. Unable to stop, a collision ensued with a parked American Air Transport DC-3. The plane was finally stopped by heading into the wind on the ramp apron away from other airplanes and buildings. It was found that the failure of the brakes were due to complete loss of all hydraulic fluid through a break in one of the left engine hydraulic lines.									
11/4/48		Nr. Cape Spencer, Alaska	Pacific Alaska	DC-3C	17	2 - - 15 - - -							Destroyed		
			Air Express			The flight departed Yakutat, Alaska for Annette, Alaska as one leg of an Anchorage-Seattle trip. A position report was received by the Gustavus Radio that the flight had passed Cape Spencer and was estimating being over Sitka at 1544. Nothing further was heard from the flight and an extensive search failed to locate it.									
12/23/48	Yes	Between San Juan, P.R. and Miami, Florida	Airborne Transport, Inc.	DC-3	32	3 - - 29 - - -							Destroyed		
						Although some trouble was present in the electrical system and the batteries were nearly discharged, the plane was cleared for the return trip of a round trip flight from Miami to San Juan providing contact with the tower could be made after take-off for the purpose of filing an IFR plan. This was not done. However, the flight proceeded toward Miami without a clearance and overloaded by 116 pounds. Further contact with the plane could not be made by San Juan. Contact, however, was made with Miami, the flight reporting it was cruising at 8,500 feet. New Orleans intercepted a message from the plane later stating it was 50 miles south of Miami. Nothing further was heard from the flight and a search failed to locate it. Investigation showed that the most probable cause of the plane's disappearance was a navigational error by which the pilot believed the flight to be east of the Florida Peninsula whereas it had actually crossed the Keys and was west of the peninsula. He was unable to make radio contacts due to electrical trouble and discharged batteries and so flew west over the Gulf of Mexico until land could not be reached before the fuel was exhausted. A northeast wind was a factor in this.									
10-12-48		Annette Island, Alaska	Arnold Air Service	DC-3	8	- - - 2 - - 1½ - 6							Miror		

Service

Plane was being taxied on the side of the runway with the wing overhanging a nearby gravel road which ran parallel to the runway. A road grader operated by a CAA employee was being driven on the gravel road in the same direction the airplane was moving. The right wing of the aircraft collided with the grader cab knocking it off the grader and injuring its driver. The pilot states that the tail wheel was in locked position because of gusty conditions and he was unable to unlock it in time to avoid the grader

Total 257 9 2 1 28 90 11 7 109

a/ Bystander seriously injured not counted in totals.

N  
CO

C. Irregular Domestic Operations

2. Other Revenue Operations

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury</u>				<u>Aircraft Damage</u>	<u>Fire In Air</u>	<u>Fire After Impact</u>
						<u>Gross</u>	<u>Passenger</u>	<u>F S M N</u>	<u>E S M N</u>			
2/25/48	Yes	Columbus, Ohio	Bruning Aviation, Inc.	DC-3	2	1	1	-	-	Destroyed	Yes	
3/2/48		Newark, New Jersey	Meteor Air Transport	DC-3	2	-	-	2	-	-	Subst.	
3/23/48		Santa Maria, California	Flying Tiger Line, Inc.	C-54	2	-	-	2	-	-	Subst.	
4/7/48	Yes	Miami, Florida	Continental Charters	DC-3	2	-	-	2	-	-	Subst.	

Flight was enroute from Pittsburgh to Columbus on instrument clearance. The Co-pilot flew until the instrument approach was started at which time the Captain took over. The flight was cleared to the Hilliard fan marker located 9.8 miles west of the Columbus Radio Range Station. The last communication from the flight was received when it was 23 miles east of the airport at 2,600 feet. Then the Captain took over the controls, he descended to 1,600 feet, the minimum for that part of the instrument approach to Columbus. He continued to let down below this altitude although the Co-pilot remonstrated with him. The descent was continued until trees were observed, into which the aircraft flew and after striking several, crashed and burned 1,150 feet from the first point of impact. Death resulted to the pilot but the co-pilot escaped with serious injuries. The point at which the impact occurred was 1,140 feet elevation.

Enroute Detroit to Newark, the aircraft was exposed to icing conditions for approximately forty minutes. Newark was contacted for an emergency landing, which was approved. After one approach was missed, a "missed approach" procedure was applied and a second approach made. This time, visual contact was made and the aircraft approached runway 6. As it passed over the approach lights, the plane stalled, shearing off the light supports and the right wing of the aircraft. The plane continued on in flight attitude, bounced onto the end of the runway, continued down the runway under control and was taxied in to a parking area.

After taxiing into position for an engine run-up before take-off, the runway surface suddenly gave way under the left wheel and the master switch and idle cut off were immediately used, preventing further damage. A ditch running across one end of the runway was apparently improperly filled and improperly covered. Recent rains had undermined the runway.

While running up engines, the left magneto was out on the right engine although right magneto was okay. A recheck on the left magneto gave a bad backfire and fire broke out in the engine. The CO<sub>2</sub> bottles and plane extinguisher were of no avail and the fire was finally extinguished by an Army jeep equipped with a large bottle, and the fire department. Investigation disclosed the probability that during the actuation of the inverter switch the carburetor de-icing switch had been inadvertently contacted and discharged a certain amount of de-icer fluid into the air scoop. This, combined with the severe backfire, may have caused the fire. The Co-pilot recalls having turned on the inverter switch.

2. Irregular Domestic Operations

2. Other Revenue Operations

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury Passengers</u>					<u>Aircraft Damage</u>	<u>Fire In Air After Impact</u>
						<u>Crew</u>	<u>F</u>	<u>S</u>	<u>M</u>	<u>N</u>		
4/28/48	Yes	Burbank, California	Flying Tiger Line, Inc.	DC-3C	2	-	-	-	2	-	-	Subst.

A normal take-off was made on runway 15. After becoming airborne and at about 50 feet altitude, the plane started a gentle turn to the left which the Captain corrected by control action and by retarding the right throttle, this resulting in the ship reversing and entering a steep right bank and turn. All power was reduced as the Captain attempted to roll out of the steep turn. The right wing tip and right landing wheel struck the ground. Control was finally regained, however, and the airplane rolled to a stop without further damage. Immediately after this, the wing de-icer boots were found to be operating. The left engine was run and it was found that there was definite loss of power. The removal of the electrical harness revealed an excessive amount of water due to flying through rain previously. Correction of this condition resulted in normal operation. The Captain had been flying heavier equipment and stated that he possibly had not attained the necessary safe airspeed as he had not flown this type for over a month.

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury Passengers</u>					<u>Aircraft Damage</u>	<u>Fire In Air After Impact</u>
						<u>Crew</u>	<u>F</u>	<u>S</u>	<u>M</u>	<u>N</u>		
5/4/48	No	Chicago, Illinois	Flying Tiger Line, Inc.	C-54	2	-	-	-	2	-	-	Subst.

Over arrival at Chicago from St. Louis, the flight was cleared to make an ILS approach. It missed the approach and with tower approval, chose two circling approaches, the last one to runway 18R on which it landed. The plane, however, failed to decelerate normally and continued on of the end of the runway where it swerved to avoid a concrete abutment, narrowly missing a parked DC-4 with its right wing. The right flap struck the top of a parked truck and the nose gear failed on striking a slightly raised gravel area. Investigation failed to disclose any mechanical malfunction and it is evident that under the conditions of reduced visibility and a wet runway that the Captain made his touchdown so far into the runway (1/4 of the way) and with such speed that stopping within the limits of the runway was not possible.

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury Passengers</u>					<u>Aircraft Damage</u>	<u>Fire In Air After Impact</u>
						<u>Crew</u>	<u>F</u>	<u>S</u>	<u>M</u>	<u>N</u>		
5/16/48	Yes	Columbus, Ohio	Slick Airways	Curtiss C-46	2	-	-	-	-	-	Destroyed	Yes

Enroute from Newark to Chicago the flight requested cancellation of its instrument clearance and proceeded to Columbus, Ohio to land. There they reported that they were experiencing trouble with controls and after missing two approaches, stalled on a go-around, crashed and burned. Investigation indicates that as a probable result of being flown through an area of very severe turbulence, one half hour before the accident, the rivets and fuselage skin immediately beneath the vertical fin failed, allowing the fin to rock across its longitudinal axis until the fuselage carry-in structure beneath the fin failed completely, causing complete loss of control. All models of this aircraft, following recommendation of the manufacturer, are to be reinforced around the skin and fuselage sand-bulkhead frames beneath the vertical fin.

C. Irregular Domestic Operations

2. Other Revenue Operations

Date	At Night	Location	Operator	Equipment	Total Aboard	Crew F S M N	Passenger E S M N F S M N				Aircraft Damage	Fire In Air	Fire After Impact
							Injury						
6/12/48	Yes	Eloy, Arizona	Eagle Air Freight	DC-3C	2	- - - 2	- - - 2	- - - 2	- - - 2	- - - 2	Destroyed	Yes	
6/16/48		Dallas, Texas	Slick Air - Ways, Inc.	Curtiss C-46E	4	- - - 2	- - - 2	- - - 2	- - - 2	- - - 2	Subst.		
7/15/48		Seattle, Washington	Eagle Air Freight	DC-3	2	- - - 2	- - - 2	- - - 2	- - - 2	- - - 2	Subst.		
12/31/48		Cleveland, Ohio	Air Cargo Express	DC-3C	2	- - - 2	- - - 2	- - - 2	- - - 2	- - - 2	Subst.		
												Total 24 3 1 - 18 - - - 2	
												- 28 -	

While in flight enroute from Burbank, California to El Paso, Texas, fire broke out in the left engine. The fuel flow was cut, CO<sub>2</sub> discharged and the propeller feathered. It was first decided to attempt a landing at Tucson after smoke which had filled the cockpit had cleared and recovery had been made from an uncontrolled spiral which had occurred when power on the right engine was reduced. However, since the left engine had fallen from the plane, right wing heaviness became more pronounced as an attempt was made to maneuver the plane into position for a landing. It was then decided to land at Eloy, Arizona which has a private airport. However, the actual landing was made in a stubble field and the crew escaped through the cockpit hatch. The missing engine has never been found although an intensive search was made and the definite cause of the fire cannot be established. The maintenance of the air carrier was found to be below reasonable safety standards for this type of operation. Contributing factors were; the fact that the Captain was asleep at the time of the fire discovery and failed to follow correct emergency procedures.

Shortly after refueling the aircraft, an attempt was made to start the engines. The right engine backfired (the exhaust consisting of a large ball of flame) and was immediately followed by an explosion within the right wing. The expansion which resulted from ballooning effect of explosion raised leading edge skin from the ribs and was sufficient to cause the collapse of nose ribs throughout the wing with exception of wing tip - fuel tank was not damaged. Investigation revealed fuel leakage at filler neck base, which was loose where fastened to the right tank, which would permit gasoline to drip into leading edge of outer wing panel and into lower portion of fairing where attached to center section. Evidence indicates explosion resulted when exhaust fire came near fuel dripping out of the fairing.

Shortly after take-off, pilot noted failure of right gear to retract and several unsuccessful attempts were made to get it up. He

returned to the airport and landed, after having placed gear handle in down position and holding all pressure possible on the gear. Aircraft was nearing end of landing roll when the right gear collapsed and aircraft made a 180 degree wild groundloop. It appears that gear malfunction was due to failure of hydraulic landing gear retracting strut.

On the take-off climb and at an altitude of 30-40 feet, the left engine began malfunctioning. Fuel pressure fell off to 4 pounds and would not come up despite operation of the wobble pump. Left propeller was feathered and a shallow left turn started in an attempt to line up with a runway. In this turn, which was made toward the dead engine, the plane rapidly lost altitude until it struck the ground on the left wing. The plane then slid over the ground finally coming to rest inside the boundary of the airport. Investigation disclosed that the main fuel strainer of the left engine was full of solid ice, as well as the fuel line from the wobble pump to the inlet of the strainer. Also some accumulation of ice was found on the leading edges of the wings and a considerable accumulation on the trailing edges of the horizontal stabilizers. The cross-feed was not used on the take-off.

C. Irregular Domestic Operations

2. Non-revenue Operations (Test, Ferrying, Training, Check, Publicity, Familiarization, Company Flights, etc.)

Date	At Night	Location	Operator	Equipment	Injury						Aircraft Damage	Fire In Air	Fire After Impact	
					Total	Passenger Crew	F	S	M	N				
1/19/48	Yes	Madison, Wisconsin	Wisconsin Central Airlines	Lockheed 10A	2	-	-	2	-	-	-	Subst.		

While making a landing during transition training, contact was made normally 200 feet from end of runway but the ship gradually veered to the left. Control was regained with left throttle and right brake, but a slight jar was felt and after getting stopped, an examination showed that left lower fin had been damaged probably from contact with a snowbank. Wind was 10 mph and 20 degrees off runway from the left.

3/8/48	Yes	Mt. Hamilton, California	Eagle Air Freight	DC-3C	2	2	-	-	-	-	-	Destroyed	Yes
--------	-----	--------------------------	-------------------	-------	---	---	---	---	---	---	---	-----------	-----

After being cleared for a straight in approach the flight reported leaving the Moffet Radio Range Station and 4,000 feet. No further contact was made. The wreckage was discovered in a canyon on the west side of Mt. Hamilton. Investigation disclosed no indication of fire or malfunction in the air. It did indicate, however, that the crew had deviated from their clearance and approved instrument procedure. It is possible that they were attempting to descend through a break in the overcast, but the flight path from Moffet to the scene of the accident cannot be determined.

8/9/48	Yes	Pohakulos, Hilo, Hawaii	Crockett Air Lines	Beechcraft C-18S	1	-	1	-	-	-	-	Destroyed	Yes
--------	-----	-------------------------	--------------------	------------------	---	---	---	---	---	---	---	-----------	-----

Pilot took off from Hilo on return flight to Honolulu - his VFR flight plan estimating elapsed time enroute of one hour, thirty minutes with available fuel supply as three hours. Upon reaching the north shore of Island of Hawaii, he positioned himself near Upolu Point by lights on the ground and shifted his radio receiver to Maui Radio Range and picked up the range signals. Shortly thereafter the radio became erratic and his efforts to contact Maui Radio were unsuccessful. Pilot flew around for forty minutes in an attempt to find either the Island of Maui or Kahoolawe - steering various headings - and being unable to find either island reversed his heading, planning a reciprocal course back to Hilo. Back over the Island of Hawaii, pilot recognized two mountains and positioned himself on the saddle between them thus establishing the shortest distance to Hilo, as one tank was empty and the fuel low in the other. The engines suddenly lost power and being unable to revive them, a wheels-up landing was made on a rough lava bed. Aircraft was demolished, as it skidded over the rough lava, and the entire forward section, back as far as passenger's cabin door, was consumed by fire. From available evidence it is believed pilot had been lost and while returning to point of take-off the engines cut out due to fuel exhaustion.

9/20/48	Yes	Miami, Florida	American Air Export Co.	DC-3C	3	-	-	1	-	-	2	Subst.	
---------	-----	----------------	-------------------------	-------	---	---	---	---	---	---	---	--------	--

The left gear collapsed during take-off run quickly followed by the right gear and investigation failed to reveal any cause for malfunction or failure of the landing gear. It appears pilot had attempted to raise the gear prematurely.

C. Irregular Domestic Operations

3. Non-revenue Operations (Test, Ferrying, Training, Check, Publicity, Familiarization, Company Flights, etc.)

Date	At	Night	Location	Operator	Equipment	Total Aboard	Injury				Aircraft Damage	Fires In Air	Fires After Impact	
							Total	Crew	Passenger E S M N	F S M N				
9/27/43	Miami, Florida		Nationwide Air Transport Service	DC-3A	2	- - - 2 - - -					Subst.	Yes		
			Pilot returned to airport after the right engine began to run rough and backfire. Coming in on final approach, fire was observed in the left engine; pilot completed the landing and upon turning off runway discharged the CO <sub>2</sub> in that engine, which together with aid of airport crash crew, extinguished the fire in two minutes. Later, inspection disclosed a loose, improperly connected fuel pump hose connection. Fuel had escaped into the lower section of engine nacelle and had apparently been ignited by engine exhaust torching as power was reduced during landing.											
10/14/43	Miami, Florida		Inter-American Airways	Lockheed 18-50	3	- - - 2 - - - 1					Subst.			
			The plane was being flown on a test flight following rewiring of the ignition harness on both engines. Shortly after take-off, at an altitude of 1,000 feet, the right engine suddenly failed, followed by the left engine. An emergency landing was at once made on the Miami Navy Master Airport. During the landing roll, the right landing gear collapsed and the right wing settled to the runway. Investigation disclosed that the right gear down latch had failed to engage although the left gear and wing flaps were in the full down position. Further investigation disclosed that the cause of engine failure was water in the fuel system of the plane, possibly placed there by a disgruntled former employee, although definite proof of this could not be established. The failure of the right gear to engage is believed to be due to the inadequate capacity of the hydraulic system accumulator with which this type is equipped, when both gear and flaps are extended simultaneously.											
12/13/43	New Milford, New Jersey		Arrow Airways	VC-3	2	- - - 2 - - -					Subst.			
			During the course of a six month proficiency check for the Captain, and while in a steep bank to the left, the airplane suddenly assumed an extreme nose down attitude, accompanied with violent vibration. Control was difficult to maintain. A wheels-up emergency landing was made in a weeded field. Examination disclosed that the rear cargo door had come open in flight and had torn away from its hinges and had lodged securely against the leading edge of the port horizontal stabilizer. Preceding this, the passenger's step-down door had come open as the rear cargo door cannot open until the step-down door is opened. It is believed that the step-down door had not been securely latched.											
					Total	15	2	1	-	9	- - -	3		
					GRAND TOTAL	296	14	4	1	55	90	21	7	114

**D. Irregular International Operations.**

**1. Passenger Carrying Operations**

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Injury</u>						<u>Aircraft Damage</u>	<u>Fire In Air</u>	<u>Fire After Impact</u>	
					<u>Crew</u>	<u>Passengers</u>	<u>F</u>	<u>S</u>	<u>M</u>	<u>N</u>				
9/30/48		Basra, Iraq	Skyways Interna- tional Trading & Transport Co.	Curtiss C-46F	41	- - - 4 - - -					37	Subst.		

On the take-off at Basra with the plane loaded to near allowable load and with hot, still air conditions prevailing, the plane was lousy and failed to get off. The pilot cut the throttles and applied brakes, but was forced to groundloop to avoid going into the Tigris River. On the groundloop a ditch was struck. The evidence shows no specific cause, other than general doubtful technique of the pilot and poor maintenance and operations due to the financial disintegration of the company.

**2. Other Revenue Operations**

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Crew</u>	<u>Passenger</u>	<u>F</u>	<u>S</u>	<u>M</u>	<u>N</u>	<u>E</u>	<u>S</u>	<u>M</u>	<u>N</u>	
1/27/48	Yes	Honolulu, T. H.	Transocean Air Lines	C-54	6	- - - 6 - - -										Subst.

Aircraft was enroute from Honolulu to Wake Island at 8,500 feet when a sharp jar was felt and the Third Pilot brought word to the cockpit that the cabin door had broken away and had hit and stuck to the leading edge of the left horizontal stabilizer. A return to Honolulu was immediately started. Gasoline was dumped and crash preparations made upon arrival as the plane was heavily loaded. A fast but successful landing was made and pilot was able to brake the plane to a stop before reaching the end of the runway. The cause of the door coming loose has not been reported but it seems likely that the emergency release handle had been inadvertently moved, though this cannot be substantiated.

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Crew</u>	<u>Passenger</u>	<u>F</u>	<u>S</u>	<u>M</u>	<u>N</u>	<u>E</u>	<u>S</u>	<u>M</u>	<u>N</u>	
12/7/48		Maracaibo, Zulia, Venezuela	Miami Airlines	DC-3	2	- - - 2 - - -										Subst.

Pilot failed to correct adequately for drift on the landing and a groundloop ensued.

<u>Total</u>	<u>8</u>	<u>- - - 8 - - -</u>
<b>GRAND TOTAL</b>	<b>49</b>	<b>- - - 12 - - -</b>

**3. Non-revenue Operations (Test, Ferrying, Training, Check, Publicity, Familiarization, Company Flights, etc.)**

No accidents.

E. Alaskan Air Carriers

1. Passenger Carrying

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Injury</u>						<u>Aircraft Damage</u>	<u>In Air</u>	<u>Fire After Impact</u>
					Total Aboard	Crew	Passenger E	Passenger S	Passenger M	Passenger N			
5/26/48	Koyuk, Alaska	Northern Consolidated Airlines	Stinson SR-5E	2	- 1 - - 1 - -	-	-	-	-	-	Destroyed		
9/3/48	Mr. Ketchikan, Alaska	Alaska Coastal Airlines	Gruuman G-21A	8	- - - 1 - - -	-	-	-	-	-	Subst.		

While in cruising flight, the left tank was turned off and the right one on. About a minute later the engine quit. A forced landing was made in tall trees. Occupants were rescued by local Indians. Cause of engine failure undetermined.

While in normal flight over Ernest Sound, Alaska at 500 feet altitude, the right engine cowling became detached and struck the right stabilizer shearing off a large portion as well as a smaller portion of the right elevator. As the pilot was able to regain control following a short dive and the plane handled well, he decided to continue on to Ketchikan where a normal and uneventful landing was made. As the failure occurred over deep water, recovery of the missing parts was impossible, but inspection of the remaining engine cowling disclosed a broken turnbuckle trunion and it is believed that a similar failure occurred on the right cowling. The felt padding between the cowling and metal ring to which it was attached was found to be old and hard, necessitating considerable tightening of the turnbuckles, thus increasing the strain on them.

9/7/48      Woodchopper, Alaska      Wien Alaska Airlines      Stinson SR-9C

All engine instruments checked normally on the ground run-up, but on the take-off the rpm dropped off and aircraft started clipping the tops of trees. A landing was made and the plane was wrecked by striking stumps. The operators feel that the difficulty was due to the propeller counterweights being out of adjustment. Investigator corroborates this, but cites additional facts; that plane was loaded to gross limits and was being flown from a comparatively short runway with probable downdrafts existing.

12/11/48      Nation, Alaska      Alaska Airlines Pilgrim 100-B

In taxiing out, struck a pile of dirt, crumpling gear and nosing plane up.

12/18/48      Yes      Anchorage, Alaska      Reeve Aleutian Airways      U-3

Prior to take-off, a check was made for ice on the wing and control surfaces. The upper surfaces were all free of ice except the wing de-icing boots which had a thin layer, about 1/4 inch in thickness. This was not removed, however. On the take-off, 43 inches HG was used and as the plane became airborne the gear was retracted. The plane began to settle and finally contacted the ground 324 feet from west end of runway after striking three parked aircraft with the wing tips. The plane came to rest 411 feet beyond end of runway. The Captain's failure to have all ice removed and to utilize higher manifold pressures on the take-off are the outstanding causative factors present.

E. Alaskan Air Carriers

1. Passenger Carrying.

<u>Date</u>	<u>At Night</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury</u>				<u>Aircraft Damage</u>	<u>Fire In Air</u>	<u>After Impact</u>
						<u>Crew</u>	<u>Passenger</u>	<u>F</u>	<u>S</u>			
12/19/48	Yes	Minneapolis, Minnesota	Alaska Airlines	DC-4	39	- - -	3	-	-	36	Subst.	

On an instrument approach with reduced visibility and ice on the runway made braking action ineffective. Went off the end of the runway at a speed of 15-20 mph and turned to avoid an approach light but caught it with the underside of the left wing. The plane was then taxied to the ramp.

<u>Date</u>	<u>At</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury</u>	<u>Aircraft Damage</u>	<u>Fire In Air</u>	<u>After Impact</u>
12/21/48		Fairbanks, Alaska	Lavery Airways	DC-3	11	- - -	2	-	9 Subst.

On the take-off, plane lifted from ground at an indicated speed of 75 mph. Immediately after becoming airborne, however, the left wing dipped and the plane veered 45 degrees to the left. The landing gear collided with a six foot embankment and the plane settled into the snow 300 feet from the embankment. Passengers were quickly evacuated. The evidence indicates that pilot pulled aircraft off too soon and failed to utilize the runway ahead to gain sufficient speed.

Total 89 - 1 2 9 - 1 - 76

2. Other Revenue Operations

<u>Date</u>	<u>At</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury</u>	<u>Aircraft Damage</u>	<u>Fire In Air</u>	<u>After Impact</u>
2/6/48		Candle, Alaska	Alaska Airlines	Stinson SR-9	1	- - -	1	-	- Subst.

Pilot was making a take-off from a frozen river. A barrel was buried in the ice and covered with snow, being almost impossible to see. Just as plane was airborne the left ski hit the barrel snapping the landing gear leg off. Pilot proceeded to an airport where he states that a landing was made without further damage.

<u>Date</u>	<u>At</u>	<u>Location</u>	<u>Operator</u>	<u>Equipment</u>	<u>Total Aboard</u>	<u>Injury</u>	<u>Aircraft Damage</u>	<u>Fire In Air</u>	<u>After Impact</u>
4/6/48		Cordova, Alaska	Alaska Airlines	C-54	4	- - -	3	-	1 Subst.

As flight taxied up to ramp and the nose wheel was straightened up preparatory to stopping, it was noted that unusually heavy pressure was needed on the wheel. Almost immediately the warning horn blew, red light came on, the green nose wheel went off and the nose wheel started to collapse. The switches were cut and the forward motion was stopped before the propellers dug into the cement. Investigation showed failure to be due primarily to deterioration of the composition chevrons in the piston of the nose wheel retracting cylinder. A change in the location of the restrictive orifice in the nose wheel retraction return line had not been complied with in accordance with a service bulletin which had been issued. The evidence indicates, however, that the trouble did not originate at this point.

2. Alaskan Air Carriers.

2. Other Revenue Operations.

Date	At Night	Location	Operator	Equipment	Total Aboard	Injury				Aircraft Damage	In Air	Fire After Impact	
						Crew	S	M	N	Passenger's			
6/8/48	Beaver, Alaska	Alaska Airlines	Noorduyn UC-64A	Noorduyn	1	- - -	1	-	-	-	Destroyed	Yes	
						While attempting to start the engine, Pilot, through over priming and improper use of throttle, caused an excessive amount of fuel to be present in the intake manifold and carburetor air-scoop. He again energized and engaged the starter (after two failures to start engine) when the engine backfired setting fire to the unvaporized fuel in the manifold and air-scoop. Pilot was unable to control the fire with extinguishing equipment available, resulting in aircraft and a considerable amount of U. S. mail being destroyed.							
8/10/48	Taylor, Alaska	Alaska Airlines 100-A	Pilgrim	1	- - -	1	-	-	-	-	Destroyed	Yes	
						Aircraft was nearing end of landing roll when it started to groundloop. Pilot states brakes are not effective when this aircraft is landed and before he could recover and straighten out with power, the aircraft ran over an abrupt 10 foot bank. Aircraft hit on its nose and immediately caught fire.							
12/11/48	Koyuk, Alaska	Alaska Airlines	Stinson SR-9	2	- - -	2	-	-	-	-	Subst.		
						On taking off, plane hit a snow drift about 10 inches high and the axle sheared off.							
12/12/48	Boundary, Alaska	Alaska Airlines	Stinson SR-9C	1	- - -	1	-	-	-	-	Subst.		
						On taking off, the left ski hit a small mound of frozen dirt which was covered with snow. Left gear collapsed and plane nosed up.							
5/14/48	Fairbanks, Alaska	Lavery Airlines	Noorduyn UC-64A	1	- - -	1	-	-	-	-	Subst.		
						On take-off climb at 300 feet, engine quit and fuel pressure was noted to be at zero. Switching tanks and using wobble pump failed to correct this and a landing was made in a willow patch. Investigation disclosed fuel stoppage to be cause of the engine failure due to a defective selector valve which having no click or centering feel when turned to different positions and having considerable back lash, was in partially closed position causing engine to starve.							



**REGISTRATION OF U. S. AIR CARRIER ACCIDENTS**  
 (Calendar Year 1948)

Type of Operation	Total Accidents	Aircraft Damage			Injury of Crew			Injury of Passenger			Injury of Minor Pass.			Abnormal Flight			After Impact			See Page
		Fatal Accidents	Partially Destroyed	Substantial	None	Fatal	Serious	Minor	Fatal	Serious	Minor	Fatal	Serious	Minor	Fatal	Serious	Minor	Fatal	Serious	
Scheduled Domestic	53	5	7	44	2	15	2	4	165	63	4	16	920	1269	5	5	5	1	1-13	
Passenger Carrying....									16	5	-	-	-	-	-	-	-	-	14	
Other Revenue....	5	-	-	5	1	-	-	-	12	-	-	-	-	-	-	-	-	-	15	
Non-revenue....									-	-	-	-	-	-	-	-	-	-	14-15	
Non-scheduled....									-	-	-	-	-	-	-	-	-	-	15	
Sub-Total.....	61	5	7	51	3	15	2	4	187	89	4	16	945	1206	5	6	6	2	2	
Scheduled International	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	16-19	
Passenger Carrying....	11	1	1	10	-	10	-	1	22	20	-	1	201	345	3	2	2	-	1	
Other Revenue....	-	-	-	-	-	-	-	-	2	2	-	-	-	-	-	-	-	-	19	
Non-revenue....	3	1	1	2	-	2	-	2	6	-	-	-	-	-	-	-	-	-	20	
Non-scheduled....	1	1	1	1	-	6	-	-	24	-	-	-	-	-	-	-	-	-	20	
Sub-Total.....	15	3	3	12	-	18	2	3	58	44	-	1	261	347	3	5	5	-	-	
Irregular Domestic	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	21-25	
Passenger Carrying....	17	4	6	10	2	9	2	1	28	90	11	7	109	257	1	2	2	1	1	
Other Revenue....	11	2	3	8	-	3	1	1	18	-	-	-	-	-	-	-	-	-	26-28	
Non-revenue....									9	-	-	-	-	-	-	-	-	-	29-30	
Sub-Total.....	35	7	11	23	1	14	4	1	55	90	11	7	114	296	3	4	4	1	1	
Irregular International	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	31	
Passenger Carrying....	1	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	31	
Other Revenue....	2	-	-	2	-	-	-	-	-	-	-	-	-	-	-	-	-	-	31	
Non-revenue....									-	-	-	-	-	-	-	-	-	-	-	
Sub-Total.....	3	-	-	3	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
Alaskan Air Carriers	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	32-33	
Passenger Carrying....	7	-	2	5	-	-	-	-	1	2	0	-	-	-	-	-	-	-	32-33	
Other Revenue....	6	-	2	4	-	-	-	-	1	2	0	-	-	-	-	-	-	-	33-34	
Non-revenue....	3	-	-	3	-	-	-	-	2	2	1	-	-	-	-	-	-	-	34-35	
Sub-Total.....	16	-	4	12	-	-	-	-	1	2	21	-	-	-	-	-	-	-	34-35	
Total																				
Passenger Carrying....	89	10	16	70	3	34	5	3	258	193	16	24	1463	2001	9	8	1	1	1	
Other Revenue....	22	2	5	16	1	3	1	1	45	-	-	-	-	-	-	-	-	2	2	
Non-revenue....	18	2	3	15	-	4	3	2	30	-	-	-	-	-	-	-	-	4	4	
Non-scheduled....	1	1	1	1	-	6	-	-	24	-	-	-	-	-	-	-	-	1	1	
Grand Total.....	130	15	25	101	4	47	9	10	16	24	1472	2130	11	16	4	4	4	4	4	