

TECHNICAL REPORT STANDARD TITLE PAGE

| | | | |
|---|--|---|----------|
| 1. Report No. NTSB-AAS-76-4 | 2.Government Accession No. | 3.Recipient's Catalog No. | |
| 4. Title and Subtitle Special Study - General Aviation Accidents Involving Aerobatics, 1972-1974 | | 5.Report Date July 20, 1976 | |
| 7. Author(s) | | 6.Performing Organization Code | |
| 9. Performing Organization Name and Address National Transportation Safety Board Bureau of Aviation Safety Washington, D. C. 20594 | | 8.Performing Organization Report No. | |
| 10. Work Unit No. 1813-A | | 11.Contract or Grant No. | |
| 12.Sponsoring Agency Name and Address NATIONAL TRANSPORTATION SAFETY BOARD Washington, D. C. 20594 | | 13.Type of Report and Period Covered Special Study | |
| 14.Sponsoring Agency Code | | | |
| 15.Supplementary Notes | | | |
| 16.Abstract This report contains a discussion of the 105 accidents involving aerobatics which occurred in various small, fixed wing, U. S. general aviation airplanes during the period 1972 through 1974. Detailed statistical information is given regarding the number of injuries, kind of flying, type of accident, accident causes, and pilot experience. The study evaluates the adequacy and applicability of airworthiness standards relating to aerobatic certification, the fundamental importance of proper aerobatic training and orientation, and regulatory controls applicable to airshows. The several most significant types of accidents associated with aerobatics--stalls and spins; collisions with ground/water, wires/poles, trees; and airframe failure in flight--are reviewed in detail. The study concludes with a number of recommendations to the Federal Aviation Administration intended to reduce accidents involving aerobatics. | | | |
| 17.Key Words <u>Aerobatics</u> , Aerobic Accidents, Airplane Accidents, Aviation Safety, General Aviation, Bureau of Aviation Safety | | 18.Distribution Statement | |
| 19.Security Classification (of this report) UNCLASSIFIED | 20.Security Classification (of this page) UNCLASSIFIED | 21.No. of Pages 102 | 22.Price |

TABLE OF CONTENTS

| | Page |
|---|------|
| INTRODUCTION..... | 1 |
| AEROBATIC ACCIDENT STATISTICS..... | 2 |
| Stalls and Spins..... | 2 |
| Collisions With Ground/Water, Wires/Poles, Trees..... | 12 |
| Airshow Aerobatics..... | 12 |
| Airframe Failure In Flight..... | 13 |
| AIRWORTHINESS STANDARDS..... | 19 |
| Airplane Categories..... | 19 |
| Limit Maneuvering Load Factors..... | 20 |
| Spinning..... | 21 |
| Operational Considerations..... | 22 |
| AEROBATIC TRAINING..... | 25 |
| CONCLUSIONS..... | 27 |
| RECOMMENDATIONS..... | 28 |
| APPENDIX A: List of Accidents Involving Aerobic In-flight Phase of Operation..... | 33 |
| APPENDIX B: Briefs of Accidents..... | 41 |
| APPENDIX C: Tables | 85 |
| 1. Injuries..... | 85 |
| 2. Kind of Flying by Injury Index..... | 87 |
| 3. Type of Accident by Injury Index..... | 89 |
| 4. Broad Cause/Factor..... | 91 |
| 5. Detailed Cause/Factor..... | 93 |
| APPENDIX D: Aerobatic Regulations (CFR 91 - General Operating and Flight Rules)..... | 99 |
| APPENDIX E: FAA Flight Instructor Bulletin No. 18 - Airplane Spinning..... | 103 |

NATIONAL TRANSPORTATION SAFETY BOARD
Washington, D. C. 20594
SPECIAL STUDY

Adopted July 20, 1976

GENERAL AVIATION ACCIDENTS INVOLVING AEROBATICS, 1972-1974

INTRODUCTION

The National Transportation Safety Board was prompted to study aerobatic accidents because of the continued occurrence in recent years of significant numbers of fatal or serious accidents involving aerobatics. For example, from 1972 through 1974, 105 such accidents resulted in 107 fatalities and 21 serious injuries. The Safety Board believes that in view of the growing interest in sport aerobatics and the continuing manufacture of airplanes certificated for aerobatic operation, an effort should be made to reduce the number of aerobatic accidents. This study isolates those problems which require remedial action.

The term aerobatics, as defined in 14 CFR 91.71, is "an intentional maneuver involving an abrupt change in an aircraft's attitude, an abnormal attitude, or abnormal acceleration, not necessary for normal flight." Aerobatics include snap rolls, chandelles, loops, aileron rolls, lazy eights, and numerous other precision maneuvers, all of which can be performed safely within specified design limits in airplanes certificated for these operations. The primary risk associated with aerobatics is largely a function of pilot competence, proficiency, and judgment. Therefore, pilots must understand and adhere to the aerobatic limitations of their airplanes, operate within the limits of their abilities and experience, and exercise good judgment in all operational matters relating to the performance of aerobatic maneuvers.

During the barnstorming era of the 1920's and 1930's, aerobatics, stunt flying, and other aerial displays effectively conjured up in the public's mind thoughts of inextricable danger. This interpretation of the sport may have resulted because of operational or airworthiness limitations of the aircraft of that era, and because of the sensationalism associated with air circuses and airshows of that day. While the events and circumstances of those days may have provided some justification for this viewpoint, such a viewpoint is not justified in today's environment.

The maneuvers or circumstances surrounding most of the 105 accidents evaluated in this report were not related to the performance of professional or precision aerobatics because they lacked approved or prescribed operational objectives, related expertise, organization, and planning. In many accidents, the fundamentals of aerobatics--steep turns and pull-ups--are involved only incidentally, while other accidents involved nondescript combinations of aerobatic maneuvers. While these operations may be technically defined as aerobatics, based on the broader definition given above, they are more appropriately referred to as stunt flying, skylarking, or careless and reckless operation.

The aerobatic training manual published by the Cessna Aircraft Company explains that "stunt flying is a situation where the airplane is doing radical maneuvering and nobody (particularly the pilot) knows what is going on or what will be happening next. Precision aerobatic pilots practice hour after hour and know what is going to happen three and seven-tenths maneuvers from now." The high percentage of pilots involved in the cause of aerobatic accidents and the nature of their involvement (attempted operation beyond experience/ability level; failed to follow approved procedures, directives; exercised poor judgment) further substantiate this point. Moreover, professional or competitive aerobatics are conducted only in airplanes designed and approved for aerobatic flight while a number of accidents in this study involved airplanes in which aerobatic operation was prohibited.

AEROBATIC ACCIDENT STATISTICS

The Safety Board's records reveal that there were 105 aerobatic accidents from 1972 through 1974. Seventy-eight aerobatic accidents (74 percent) were fatal and represented 3.76 percent of the 2,071 fatal accidents. One hundred and seven persons lost their lives in aerobatic accidents; 21 persons were injured seriously and 10 persons were injured slightly.

Seventy-eight aerobatic accidents occurred in "noncommercial" kinds-of-flying--58 in pleasure flying, 16 in practice flying, and 4 in other noncommercial flying. Fourteen aerobatic accidents occurred in the "miscellaneous" kind-of-flying category, 9 of which involved airshows. Eight aerobatic accidents occurred during "instructional" flying--five in instructional dual flying and three during instructional solo flight. The remaining five aerobatic accidents occurred in "commercial" flying--four during aerial application or crop control-related flights and one during power or pipeline patrol.

The 105 accidents include the following specific first accident types: Twenty-seven controlled collisions with ground or water; 6 uncontrolled collisions with ground or water; 9 collisions with wires, poles, or trees; 13 stalls; 36 spins; and 10 airframe failures in flight.

The two most significant broad cause/factor categories for aerobatic accidents are "pilot" and "terrain." The pilot was cited as a cause in 97 accidents and as a causal factor in 15 accidents. (More than one cause or factor may be cited in a single accident.) Terrain was a cause of two accidents and a factor in nine accidents. (See Tables 1, 2, 3, and 4.)

Stalls and Spins

Forty-nine of the 105 accidents involved a stall or a spin (36 spins and 13 stalls). Most of these were unintentional and were related to the performance of other aerobatic maneuvers at low altitudes--altitudes which made recovery from the accidental stall or spin either difficult or impossible. Flights at these altitudes were in violation of 14 CFR 91.9, "Careless or Reckless Operation," and 14 CFR 91.71(d), "Aerobatic Flight" (except for those flights associated with airshows where the FAA had issued a waiver or letter of competence). The latter prohibits aerobatics below 1,500 feet above the surface. Accident-prevention efforts, therefore, should be focused primarily on enforcement--an intensive and rigorous campaign by the FAA in which the certificate of any person found guilty of violating these provisions would be suspended or revoked. The conspicuous posting of notices to this effect at general aviation airports throughout the country might be effective. In addition, a regulation to restrict the performance of aerobatic maneuvers to persons holding an appropriate endorsement and the distribution of educational materials should also be considered as a solution to this problem.

On the other hand, some of the spins were intentional and were initiated at altitudes which would normally have been sufficient to permit recovery. Recovery in these cases, however, was not effected either because of inadequate spin recovery techniques at normal recovery altitudes, or because the spin was otherwise prolonged to the point that insufficient altitude remained in which to recover. In some cases, the airplane hit the ground before the spin rotation stopped; in other cases, the airplane crashed after spin rotation had stopped, but before a pullup from the ensuing dive could be completed. Persons involved in these types of accidents had some previous spin instruction, but their overall knowledge and proficiency in spins is believed to have been minimal. For example, they probably were not fully aware of all of the adverse spin characteristics that could be induced through improper use

TABLE 1

("PILOT" and "TERRAIN" CATEGORIES, "MISCELLANEOUS ACTS, CONDITIONS")
 AEROBATICS - INFLIGHT PHASE OF OPERATION
 U. S. GENERAL AVIATION
 1972 - 1974

| <u>FATAL AND NONFATAL ACCIDENTS</u> | | | |
|--|---------------|--------------|------------|
| <u>CAUSE</u> | <u>FACTOR</u> | <u>TOTAL</u> | |
| <u>PILOT</u> | | | |
| Attempted operation w/known deficiencies in equipment | 1 | 1 | |
| Attempted operation beyond experience/ability level | 14 | 15 | |
| Exceeded design stress limits of aircraft | 3 | 3 | |
| Failed to see and avoid objects or obstructions | 2 | 2 | |
| Failed to obtain/maintain flying speed | 33 | 33 | |
| Misjudged speed, altitude, or clearance | 2 | 2 | |
| Failed to follow approved procedures, directives, etc. | 4 | 17 | |
| Improper operation of flight controls | 13 | 29 | |
| Inadequate preflight preparation and/or planning | 3 | 3 | |
| Lack of familiarity with aircraft | 2 | 2 | |
| Mismanagement of fuel | 1 | 1 | |
| Exercised poor judgment | 29 | 31 | |
| Operated carelessly | 2 | 2 | |
| Misjudged speed and altitude | 3 | 4 | |
| Misjudged altitude and clearance | 10 | 10 | |
| Misjudged altitude | 28 | 28 | |
| Misjudged clearance | 1 | 1 | |
| Incapacitation | 1 | 1 | |
| Physical impairment | 3 | 9 | |
| Subtotal | 178 | 16 | 194 |

TABLE 1 CONT.

| <u>TERRAIN</u> | <u>CAUSE</u> | <u>FACTOR</u> | <u>TOTAL</u> |
|-------------------|--------------|---------------|--------------|
| Wet, soft ground | 1 | 1 | 1 |
| Snow-covered | | 1 | 1 |
| High Obstructions | 1 | 8 | 8 |
| Other | 1 | 1 | 1 |
| Subtotal | 2 | 9 | 11 |

"Miscellaneous acts and conditions" are often given to supplement other causal information such as the above. These were recorded as follows:

| <u>MISCELLANEOUS ACTS, CONDITIONS</u> | <u>CAUSE</u> | <u>FACTOR</u> | <u>TOTAL</u> |
|---|--------------|---------------|--------------|
| Disregard of good operating practice | 1 | 1 | 2 |
| Seatbelt not fastened | | 2 | 2 |
| Unwarranted low flying | 33 | 16 | 49 |
| Correcting lenses-not used | | 1 | 1 |
| Fatigue fracture | 1 | 1 | 1 |
| Separation in flight | | 3 | 3 |
| Corroded/corrosion | | 1 | 1 |
| Fuel exhaustion | 1 | 1 | 1 |
| Alcoholic impairment of efficiency and judgment | 3 | 5 | 8 |
| Improperly loaded aircraft-weight-and/or CG | | 3 | 3 |
| Interference with flight controls | 1 | 1 | 1 |
| Aircraft came to rest in water | | 10 | 10 |
| Overload failure | 1 | 2 | 3 |
| Material failure | 2 | 1 | 2 |
| Disconnected | 1 | 1 | 1 |
| Flutter | | 1 | 1 |
| Jammed | | 1 | 1 |

TABLE 2

**PILOT AGE BY PILOT CERTIFICATE
AEROBATICS - INFILIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION**

PILOT CERTIFICATE

| AGE | STUDENT | PRIVATE | COMMERCIAL | TRANSPORT | COMMERCIAL | AIRLINE | AIRLINE | NONE (UNCERTIFIED OR EXPIRED) | TOTAL |
|---------------|---------|---------|------------|-----------|--|--|--|-------------------------------------|-------|
| | | | | | WITH FLIGHT INSTRUCTOR CERTIFICATE | WITH FLIGHT INSTRUCTOR CERTIFICATE | WITH FLIGHT INSTRUCTOR CERTIFICATE | | |
| 20-24 | | 1 | | | 3 | | 3 | | 13 |
| 25-29 | | 1 | | | 4 | | 8 | 1 | 21 |
| 30-34 | | | | | 5 | 1 | 6 | | 17 |
| 35-39 | 3 | | 1 | 9 | | | | | 13 |
| 40-44 | | | 3 | 4 | 1 | | 2 | 1 | 12 |
| 45-49 | | | 3 | 5 | 3 | | 2 | | 13 |
| 50-54 | | | 3 | 3 | | | 1 | | 7 |
| 55-59 | | | 2 | 2 | | | 1 | | 5 |
| 60 or more | | 1 | 2 | | | | 1 | | 4 |
| | 5 | 31 | 37 | 5 | 24 | 1 | | | 105 |

TABLE 3

PILOT TOTAL TIME BY PILOT CERTIFICATE
AEROBATICS - INFLIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972 - 1974

PILOT CERTIFICATE

TABLE 4

**PILOT TIME IN TYPE BY PILOT CERTIFICATE
AEROBATICS - INFILIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION**

PILOT CERTIFICATE

| TIME IN TYPE | STUDENT | PRIVATE | COMMERCIAL | COMMERCIAL | | INSTRUCTOR CERTIFICATE | NONE (UNCERTIFIED OR EXPIRED) | TOTAL |
|--------------------------|---------|---------|------------|----------------------|--|---------------------------|-------------------------------------|-------|
| | | | | AIRLINE TRANSPORT | WITH FLIGHT INSTRUCTOR CERTIFICATE | | | |
| LESS THAN 100 hr | 4 | 19 | 10 | 3 | 6 | | 1 | 42 |
| 100- 299 | 1 | 4 | 9 | | 8 | | 23 | |
| 300- 599 | | 1 | 5 | | 2 | | 8 | |
| 600- 899 | | | 1 | | 1 | | 2 | |
| 900-1199 | | | | | 2 | | | |
| 1200-1499 | | | | | | | | 2 |
| 1500-1799 | | | | | | | | |
| 1800-2099 | | | | | | | | |
| 2100-2399 | | | | | | | | |
| 2400-2699 | | | | | | | | |
| 2700-2999 | | | | | | | | |
| 3000 or More | | | | | | | | |
| Unknown/ Not Reported | 6 | 11 | 1 | 4 | | | 2 | 24 |
| | 5 | 31 | 37 | 5 | | | 2 | 105 |

of the flight or power controls, or both, or of the essential need to use a precise technique appropriate to their particular airplane in order to optimize the recovery.

The fatal spin accident, which involved a commercial flight instructor and a passenger in a Cessna Model 150J on November 24, 1974, near Morganton, North Carolina, typifies the above circumstances. A witness estimated that the spin continued for at least five turns. Apparently, the airplane had stopped rotating, but struck the ground in a near vertical attitude (File No. 3-3837).

A number of accidents which include the above circumstances involved spins which were apparently initiated at altitudes that allowed little margin for error, such as inept application of recovery controls or a delayed recovery because a pilot misjudged his altitude or became disoriented. This situation is particularly hazardous in the case of the novice or relatively inexperienced pilot. The fatal spin accident on January 28, 1974, just offshore, near Melbourne, Florida, for example, involved a private pilot with less than 100 flight-hours who had been given several hours of aerobatic instruction (File No. 3-0118). He was flying a Cessna Model A150L. A witness who saw the airplane in a spin said the spin continued to a relatively low altitude. The pilot was observed to bail out and his parachute deployed satisfactorily; however, he drowned in rough seas.

Another case involving two commercial pilots further illustrates the potential hazards of initiating spins at relatively low altitudes (File No. 3-3937). The probable cause of this fatal spin accident is cited as "pilot-in-command - misjudged altitude." An excerpt from the factual report describes the circumstances:

At approximately 1600 c.s.t., a pilot and his companion were observed to board N8344M and depart the airport. Before departure the pilot had made the comment to persons at the airport that he intended to demonstrate spins to his companion.

At approximately 1630 c.s.t., a witness, who was also a commercial pilot, saw an aircraft in flight from a point about one mile northeast of the crash site. The witness saw the aircraft do a series of wing-over maneuvers. After completing one of these maneuvers, the aircraft made a climb and went into a spin, rotating to the left. The aircraft was seen as it continued in a spin until it disappeared from the witness' view behind some trees. This witness estimated the aircraft's altitude to be approximately 3,500 feet when it began to spin.

A second witness, who was watching the aircraft in flight stated that the aircraft turned or spun seven times before it crashed in an open field. Both occupants of the aircraft were found in the cockpit with their seatbelts fastened and wearing back-type parachutes.

Investigation disclosed no evidence of an in-flight malfunction or failure. All aircraft control surfaces and extremities were found within the immediate wreckage area.

The weather in the area was described as clear of clouds with good visibility.

Both occupants held commercial pilot certificates. The pilot was enrolled in a 10-hour acrobatic course and at the time of the accident had received 7.2 hours of dual instruction including spins and spin recovery.

In one accident which resulted during an intentional spin, the airplane's spin characteristics or lack of response may have been a factor in thwarting the pilot's recovery efforts. On September 24, 1972, at Larkspur, Colorado, a Beechcraft Model C-23 airplane failed to recover from a spin despite repeated recovery efforts by a commercial flight instructor and his student. Both parachuted from the airplane. Airworthiness Directive 74-14-05 was issued subsequently to "prevent in-flight situations in which prompt spin recovery may not be assured." The AD applied to Beechcraft Models B-19 and C-23 which were originally approved in the acrobatic category and to intentional spins in the utility and acrobatic categories. The AD prohibited intentional spins in these airplanes and required that all placards pertaining to intentional spins and acrobatic flight be removed. In place thereof, a placard was required which prohibited intentional spins and acrobatic maneuvers except chandelles, lazy eights, steep turns, and stalls (except whip stalls). A Beech spin-improvement kit must be installed for these operating restrictions to be removed.

Several flight instructors have complained of difficulty in recovering from spins in Cessna Model 150 airplanes. Detailed investigation by the FAA, however, disclosed that the problems were related to operational vagaries or anomalies, inadequate knowledge regarding the precise spin recovery procedures necessary for the airplane, improper application or misapplication of recovery controls, apprehension, and confusion. As a result of these incidents and past spin accidents, the initiation of spins at higher, conservative altitudes is being emphasized. For example, the 1976 pilot's operating handbook for the Cessna 150 Aerobat recommends that :

"Where feasible, entries be accomplished at high enough altitude that recoveries are completed 4,000 feet or more above ground level. At least 1,000 feet of altitude loss should be allowed for a 1-turn spin and recovery, while a 6-turn spin and recovery may require somewhat more than twice that amount. For example, the recommended entry altitude for a 6-turn spin would be 6,000 feet above ground level. In any case, entries should be planned so that recoveries are completed well above the minimum 1,500 feet above ground level required by FAR 91.71. Another reason for using high altitudes for practicing spins is that a greater field of view is provided which will assist in maintaining pilot orientation."

While the frequency of spin accidents involving the operational circumstances described above is not unusually high, these accidents occur regularly and usually are fatal. Furthermore, in view of the expanding aerobatic interest in spins, the frequency of these accidents can be expected to increase unless steps are taken to prevent their recurrence.

Based on the provisions of 14 CFR 91.71(d), on airplane spin mechanics and recovery requirements, and on the human potential for error, the Board believes that a supplemental schedule of minimum initial spin altitudes should be incorporated into 14 CFR 91.71. For example, no spin, regardless of duration or number of turns, should be permitted to begin below 3,500 feet above the surface and spins initiated at this altitude should not exceed a designated number of turns before recovery is begun. A conservative increment in altitude should be required for each additional spin turn or fraction thereof.

In years past, spins and spin-recovery procedures have been oversimplified. Only recently have precise recovery procedures been emphasized for a particular airplane. There are, moreover, various operational circumstances which stem from confusion, apprehension, disorientation, and the misapplication of flight controls which may hamper the recovery process. Because some of the knowledge regarding spins and spin-recovery techniques has been attained only recently, flight instructors may not be aware of many of the operational implications.

To disseminate recent spin information, the FAA's Central Region, in cooperation with the Cessna Aircraft Company, devoted most of its "Flight Instructor Bulletin" of August 1975 to spins, particularly as they relate to the Cessna Models 150, A150, 172, and 177. (See Appendix F.)

The FAA's Central Region also initiated a spin indoctrination program relating to the spinning characteristics of typical general aviation airplanes, particularly those used extensively for training. On August 16 and 17, 1975, the first of a series of stall/spin clinics was held at St. Louis, Missouri. The clinic was held to brief flight instructors on the precise spin characteristics of the Cessna 150 and, through actual flight demonstrations, provide appropriate operational indoctrination. A subsequent clinic dealt with the spin characteristics of Piper Cherokee airplanes.

Collisions With Ground/Water, Wires/Poles, Trees

There were four types of collisions which were associated with 42 (40 percent) of the 105 accidents: Twenty-seven were controlled collisions with the ground or water, six were uncontrolled collisions with the ground or water, two were collisions with wires or poles, and seven were collisions with trees. Again, many of these accidents reflect the hazards of performing aerobatics at low altitudes. While a few of these collisions occurred during an authorized airshow, most involved flights conducted in violation of one or more of the provisions of 14 CFR 91.71. Safety Board records show that some of the more significant causes or causal factors relating to these accidents are as follows:

- o Exercised poor judgment.
- o Misjudged altitude.
- o Unwarranted low flying.
- o Attempted operation beyond experience/ability level.
- o Failed to follow approved procedures, directives, etc.
- o Alcoholic impairment of efficiency and judgment.
- o Misjudged altitude and clearance.
- o Improper operation of flight controls.

The remedial action necessary to reduce these types of accidents is identical to that previously discussed in connection with stalls and spins--an intensive enforcement campaign by FAA.

Airshow Aerobatics

Before conducting an airshow, the sponsor of the airshow must obtain a certificate of waiver or authorization from the Federal Aviation Administration. The operations authorized and the waived regulations are specified thereon such as aerobatic flights associated with an airshow, waiver of Part 91.71(c) (flight within a control zone or Federal airway), and waiver of Part 91.71(d) (acrobatic flight below an altitude of 1,500 feet above the surface). The certificate is accompanied by a list of special provisions pertinent to the operations

authorized and any participating pilot, if he is to operate below 1,500 feet above the surface, must also possess a current letter of competency indicating that he has demonstrated satisfactorily his ability to perform aerobatics for public airshows. This letter may contain limitations relating to minimum operating altitude, permissible maneuvers, and type of aircraft.

As previously noted, there were nine accidents directly associated with the actual performance of aerobatics at airshows; three of these were fatal, five involved serious injuries, and one involved minor injuries. In addition, 7 of the 16 accidents which occurred in non-commercial practice flying were related indirectly to an airshow since their associated flight purposes involved the practice of maneuvers to be performed at an airshow at some future time. Six of the seven accidents were fatal; one involved serious injuries. (See Table 5.)

The aerobatic maneuvers being performed included rolls or inverted flight at low altitude, snap rolls, and spins at low altitude.

Airframe Failure In Flight

Airframe failure in flight is one of the several primary types of accidents relating to aerobatic mishaps and was evidenced in 10 of the 105 aerobatic accidents. Five airplanes involved were experimental or amateur-built, three were certificated in the aerobatic category, one was certificated in the normal category, and one was uncertificated. (See Table 6.)

The avoidance of such a failure is of special interest to aerobatic pilots since an adequate understanding and respect for an airplane's structural limitations are fundamental prerequisites for the performance of aerobatic maneuvers. To avoid exceeding an airplane's design stress limits, the aerobatic pilot knows he must stay within two structural limitations: One pertaining to airspeed, the other to load factor. Normally, the airspeed indicator is monitored routinely and, as an aid to the pilot in observing airspeed limits, a radial red line has been painted on the instrument to designate Vne--the never-exceed airspeed. The following comments regarding the never exceed airspeed and limit load factor are excerpted from the Citabria Owners Manual:

"The never-exceed speed is equivalent to the limit load factor--it is the maximum speed expected in service. It is shown by a red line on the airspeed indicator, and, as the name implies, should never be exceeded.

"NOTE: In a Citabria, a slightly nose-low attitude when inverted will allow a rapid buildup of speed. Watch the airspeed indicator when inverted to prevent exceeding the never-exceed speed.

TABLE NO. 5
 AIRSHOW AEROBATICS
 CAUSE/FACTOR SUMMARY
 AEROBATICS-INFLIGHT PHASE OF OPERATION
 U. S. GENERAL AVIATION
 1972-1974

| FILE NO. | AIRCRAFT | CAUSE/FACTOR DATA | REMARKS |
|----------|-------------------|--|--|
| 3-2127 | Bellanca 8KCAB | PILOT-IN-COMMAND - misjudged altitude and clearance, improper operation of flight controls. Weather - downdraft, updrafts. <u>1/</u> | Complex low altitude roll maneuver. |
| 3-3306 | Bellanca 8KCAB | PILOT-IN-COMMAND - failed to obtain/maintain flying speed, improper operation of flight controls. <u>2/</u> | Authorization limited 500 ft. above ground level. After spin rotation stopped aircraft observed half twist before almost vertical descent. |
| 3-3099 | Bellanca 8KCAB | PILOT-IN-COMMAND - failed to follow approved procedures, directives, etc., misjudged altitude and clearance. <u>2/</u> | Letter of competence - minimum altitude 100 ft. above surface. Two successive rolls, left wing hit ground second roll. |
| 3-2967 | CESSNA A150K | PILOT-IN-COMMAND - misjudged altitude, improper operation of flight controls, failed to follow approved procedures, directives, etc. | |
| 3-1913 | N. American SNJ-5 | PILOT-IN-COMMAND - Misjudged altitude. | |

1/ Weather Briefing - No briefing received.

2/ Fire after impact.

TABLE 5 CONT.

| | | | |
|--------|----------------|---|---|
| 3-3673 | Piper J-3 | PILOT-IN-COMMAND - misjudged altitude. | Pilot entered intentional spin at 500 ft. Did not recover fully before striking ground. |
| 3-3095 | WACO UPF-7 | PILOT-IN-COMMAND - failed to obtain/maintain flying speed. Terrain - high obstructions. | Aircraft hit trees. |
| 3-2056 | Starduster T00 | PILOT-IN-COMMAND - Failed to obtain/maintain flying speed. <u>2/</u> | Wooded swamp. Pilot lost control at insufficient altitude to recover during authorized low level acrobatics in airshow. |
| 3-3399 | Zimmerman S-1C | PILOT-IN-COMMAND - misjudged altitude | Spin demonstration, late recovery. Stopped rotation, hit ground during recovery. |

- 15 -

TABLE NO. 6
AIRFRAME FAILURE IN FLIGHT
CAUSE/FACTOR SUMMARY
AEROBATICS-INFLIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972-1974

| FILE NO. | AIRCRAFT | CAUSE/FACTOR DATA | REMARKS |
|-------------|-----------------------|--|--|
| 3-4120 | Avion Mudry CAP10B | PILOT-IN-COMMAND - inadequate preflight preparation and/or planning. MISCELLANEOUS - foreign material affecting normal operations. SYSTEMS - flight control systems: elevator and elevator tab control system. MISCELLANEOUS ACTS, CONDITIONS - jammed. | Preflight, cable tension tool inadvertently left on rudder cable jammed elevator bellcrank. Parachuted OK. |
| 3-3704 | Bellanca 7GBC | PILOT-IN-COMMAND - improper operation of flight controls, exceeded designed stress limits of aircraft. MISCELLANEOUS ACTS, CONDITIONS - over-load failure. | Entered acrobatic maneuver at too low altitude to effect safe recovery. Right wing failed. |
| 3-1676 | Bellanca 8KCAB | PILOT-IN-COMMAND - exceeded designed stress limits of aircraft, - incapacitation. | Pilot stated he blacked out during high g loads. Both wings deformed. Pilot landed OK. |
| 3-1184 | Erco 415-C | PILOT-IN-COMMAND - exercised poor judgment, improper operation of flight controls. MISCELLANEOUS ACTS, CONDITIONS - unwarranted low flying. AIRFRAME - flight control surfaces: aileron surfaces, attachments. MISCELLANEOUS ACTS, CONDITIONS - corroded/corrosion, flutter, separation in flight. | Right aileron counter weight separated in flight during low level aerobatics over pilot's home. |

TABLE 6 CONT.

| | | | |
|--------|----------------------|--|---|
| 3-2334 | Jeanies Teenie | SYSTEMS - flight control systems rudder and rudder tab control system. MISCELLANEOUS ACTS, CONDITIONS - disconnected. PERSONNEL - maintenance, servicing, inspection: inadequate maintenance and inspection. MISCELLANEOUS - unqualified person operated aircraft. | Rod end bearing attach push-pull torque tube to rudder control horn failed. Aircraft and pilot uncertificated. |
| 3-2076 | May Flybaby 1 | PILOT-IN-COMMAND - exceeded designed stress limits of aircraft, failed to follow approved procedures, directives, etc. AIRFRAME - wings, spars. MISCELLANEOUS ACTS, CONDITIONS - overload failure, separation in flight. | Right wing separated during prohibited loop maneuvers. |
| 3-0152 | Pitts S-1S | AIRFRAME - wings, other. MISCELLANEOUS ACTS, CONDITIONS - material failure, separation in flight. ^{1/} | Lower right wing disintegrated during low level practice for air show, cause of material failure not determined. |
| 3-1997 | BEDE BD-5J | AIRFRAME - fuselage: windshields, windows, canopies. MISCELLANEOUS ACTS, CONDITIONS - material failure. | Steep descent - 230KTS(Vne 250KTS). Canopy failed hitting pilot in head. Aircraft subjected to approximately 15g. |
| 3-1545 | Hazard-Turn T-40H | AIRFRAME - wing spars. PERSONNEL - production design personnel, substandard quality control. MISCELLANEOUS ACTS, CONDITIONS - overload failure. | Right wing main spar at right strut attach point weakened by misslocated drilled holes. |

1/ Fire after impact.

TABLE 6 CONT.

3-1132 Pitts Spcl S-2A AIRFRAME - flight control surfaces: horizontal stabilizer, attachments. MISCELLANEOUS ACTS, CONDITIONS - Fatigue fracture. TERRAIN - wet soft ground. 2/ Right horizontal stabilizer forward attach tube failed during two point roll. Pilot had to land fast in plowed field.

2/ EMERGENCY CIRCUMSTANCES - Forced landing off airport on land. Suspected or known aircraft damage.

"If you should ever get into a position from which you cannot recover without exceeding either the never-exceed speed or the limit load factor, it is usually best to recover without exceeding the limit load factor, even if airspeed exceeds the never-exceed speed."

Despite the emphasis placed on the critical importance of observing an airplane's limit load factors during the performance of aerobatic maneuvers, accelerometers (instruments which measure load factor) are not required on most aerobatic airplanes. An accelerometer is required in Bellanca's Champion Model 8KCAB (the Decathlon), which has limit load factors of -5g and +6g, but not in predecessor Bellanca models, such as the 7ECA, which have limit load factors of only -2g and +5g.

Accelerometers are useful for indicating not only the immediate load factor, but also for temporarily recording the maximum and minimum load factors induced during a maneuver or series of maneuvers. This capability provides a means of assessing or calibrating the adequacy and precision of certain maneuvers or combinations of maneuvers (e.g., loops and immelmanns).

As pointed out in studies conducted by the National Aeronautics and Space Administration, stick forces are not necessarily a reliable indication of load factor, particularly negative load factor, nor do they pose any significant physical constraint to the generation of excessive load factors. While aerobatic pilots may acquire capability for sensing the approximate load factor, critical dependence on this means alone to assure operation within precise limits does not appear justified.

While installation of an accelerometer does not assure that an airplane will not be overloaded, repeated indications to a pilot that he is inducing load factors which approach or exceed structural limits would prompt him to alter or discontinue his actions, or at least to exercise more caution. While it is important to avoid exceeding limit load factors, it is equally important to know when these load factors have been exceeded.

AIRWORTHINESS STANDARDS

Airplane Categories

The operations or maneuvers which may be performed in airplanes currently certificated in accordance with 14 CFR 23 are given in Part 23.3, "Airplane categories":

(a) The normal category is limited to airplanes intended for nonacrobatic operation. Nonacrobatic operation includes -

- (1) Any maneuver incident to normal flying;
- (2) Stalls (except whip stalls); and
- (3) Lazy eights, chandelles, and steep turns, in which the angle of bank is not more than 60 degrees.

(b) The utility category is limited to airplanes intended for limited acrobatic operation. Airplanes certificated in the utility category may be used in any of the operations covered under paragraph (a) of this section and in limited acrobatic operations. Limited acrobatic operation includes -

- (1) Spins (if approved for the particular type of airplane); and
- (2) Lazy eights, chandelles, and steep turns, in which the angle of bank is more than 60 degrees.

(c) The acrobatic category is limited to airplanes intended for use without restrictions other than those shown to be necessary as a result of required flight tests.

(d) Small airplanes may be certificated in more than one category if the requirements of each requested category are met.

Limit Maneuvering Load Factors

The related structural limitations associated with the above categories are given in Part 23.337, "Limit maneuvering load factors":

(a) The positive limit maneuvering load factor may not be less than -

- (1) $2.1 + \frac{24,000}{W+10,000}$ for normal category airplanes,
except that n need not be more than 3.8
- (2) 4.4 for utility category airplanes; or
- (3) 6.0 for acrobatic category airplanes.

(b) The negative limit maneuvering load factor may not be less than -

- (1) 0.4 times the positive load factor for the normal and utility categories; or
- (2) 0.5 times the positive load factor for the acrobatic category.

- (c) Maneuvering load factors lower than those specified in this section may be used if the airplane has design features that make it impossible to exceed these values in flight.

Spinning

The spin requirements for each category are contained in Part 23.221, "Spinning":

- (a) Normal category. A single-engine, normal category airplane must be able to recover from a one-turn spin or a 3-second spin, whichever takes longer, in not more than one additional turn, with the controls used in the manner normally used for recovery. In addition -

- (1) For both the flaps-retracted and flaps-extended conditions, the applicable airspeed limit and positive limit maneuvering load factor may not be exceeded;
- (2) There may be no excessive back pressure during the spin or recovery; and
- (3) It must be impossible to obtain uncontrollable spins with any use of the controls.

For the flaps-extended condition, the flaps may be retracted during recovery.

- (b) Utility category. A utility category airplane must meet the requirements of paragraph (a) of this section or the requirements of paragraph (c) of this section.

- (c) Acrobatic category. An acrobatic category airplane must meet the following requirements:

- (1) The airplane must recover from any point in a spin, in not more than one and one-half additional turns after normal recovery application of the controls. Prior to normal recovery application of the controls, the spin test must proceed for six turns or 3 seconds, whichever takes longer, with flaps retracted, and one turn or 3 seconds, whichever takes longer, with flaps extended. However, beyond 3 seconds, the spin may be discontinued when spiral characteristics appear with flaps retracted.

- (2) For both the flaps-retracted and flaps-extended conditions, the applicable airspeed limit and positive limit maneuvering load factor may not be exceeded. For the flaps-extended condition, the flaps may be retracted during recovery, if a placard is installed prohibiting intentional spins with flaps extended.
- (3) It must be impossible to obtain uncontrollable spins with any use of the controls.
- (d) AIRPLANES "Characteristically incapable of spinning". If it is desired to designate an airplane as "characteristically incapable of spinning" this characteristic must be shown with -
- (1) A weight five percent more than the highest weight for which approval is requested;
 - (2) A center of gravity at least three percent aft of the rearmost position for which approval is requested;
 - (3) An available elevator up-travel four degrees in excess of that to which the elevator travel is to be limited for approval; and
 - (4) An available rudder travel seven degrees, in both directions, in excess of that to which the rudder travel is to be limited for approval.

The above airplane categories are defined in essentially the same way in both CFR 23 and Part 3 of the Civil Air Regulations (CAR 3). This latter regulatory part was the basis for certification before CFR 23 became effective. The limit maneuvering load factor and spin requirements in these parts are the same except that the spin requirements in CAR 3 were applicable to all airplanes of 4,000 pounds or less maximum weight while those in Part 23 apply only to single-engine airplanes.

Operational Considerations

Applications for airplane certification received between November 13, 1945, and February 1, 1965, were processed in accordance with the airworthiness standards in CAR 3; those received before November 13, 1945, were governed by Part 4a or Part 04 of the Civil Air Regulations, or Aeronautics Bulletin No. 7-a. A substantial number of older airplanes operating today such as the Aeronca Champion, Cessna 120/140, Luscombe, Piper J-3, and Taylorcraft, were certificated under CAR 4a or CAR 04.

An applicant who certificated an airplane in accordance with CAR 04 or CAR 4a could elect to do so in the normal, acrobatic, or transport categories depending on the intended use of the airplane. The airworthiness standards for the normal and acrobatic categories under these parts, however, including those relating to maneuvering load factors, were the same. Additionally, the operational category of some airplanes certificated under these parts is not specified on the type certification data sheets. Neither is there an approved flight manual nor approved operating limitations governing their use. Consequently, from a regulatory point of view, these airplanes may engage in aerobatics with no restrictions as to type of maneuvers which may be performed.

The regulatory requirements for certification in the acrobatic category have been improved and expanded somewhat over the years with respect to structural standards which distinguish between type of airplane operation, demonstration of maneuvers for which certification is requested, specifications regarding approved types of acrobatic maneuvers, and entry speeds. One significant difference in the aerobatic criteria between Part 23 and CAR Parts 04 and 4a is in regard to the limit maneuvering load factor. As noted above, Part 23 requires that the limit maneuvering load factor envelope extend from -3g to +6g. In contrast, the Citabria, a present-day aerobatic airplane certificated in accordance with Part 4a (because it was derived from the normal category, Aeronca Champion originally certificated under this Part), has an operational envelope that extends from -2g to +5.2g. The manufacturer of the Citabria also builds the aerobatic Decathlon, an airplane which was certificated under Part 23 in the early 1970's. This airplane has an operational limit load factor envelope extending from -5g to +6g and is capable of performing many of the more complex inverted competitive type aerobatics.

The National Aeronautics and Space Administration has studied the actual flight loads on a number of general aviation airplanes for comparison with their design flight envelopes, including accelerations measured during individual practice, and competitive aerobatics. As a result, one of the conclusions contained in a 1968 NASA report entitled "Initial Report on the Operational Experiences of General Aviation Aircraft" pointed out that "A limited sample of data from aerobatic operations shows significant exceedances of the minimum negative limit load factor required by FAR 23 for certification in the aerobatic category when obligatory groups of maneuvers are performed." A joint program was subsequently undertaken between NASA and the Champion Aircraft Corp. to investigate aerobatic loading conditions in more detail. Data were taken on a test airplane which participated in national aerobatic competition. This program resulted in the 1970 NASA report entitled "Loading Conditions Measured During Aerobatic Maneuvers" and substantiated the aerobatic findings in the previous report.

The following excerpt from this report points out the potential for exceeding the limit maneuvering load factors:

"For the maneuvers in which the negative normal load factor exceeded a value of -3, the maximum stick push forces ranged 15-44 lb, depending primarily on the elevator trim tab position. The pilot control force, therefore, would not be a reliable indication of the negative normal load factor, nor would the control force be a physical limit for load factors that exceeded the minimum required negative load factor.

"The largest positive normal load factors occurred during pullout and pullup portions of various maneuvers as the pilot was trying to turn a square corner. The load factor for two of these maneuvers came very close to the positive limit maneuver envelope. The maximum stick pull force for one maneuver was 55 lb; therefore it would appear that exceeding the positive limit maneuver envelope is not limited by the physical capabilities of the pilot. It seems quite probable that the positive limit maneuver load factor would be exceeded occasionally, particularly during competitive conditions."

The Safety Board realizes that the airworthiness standards in 14 CFR 23 are only minimum standards and that certification in the aerobatic category does not necessarily mean that all types of aerobatic maneuvers may be performed. Moreover, if those aerobatic maneuvers approved for a particular airplane were always flown by experienced aerobatic pilots, the potential for exceeding the design flight envelope would be remote. Professional aerobatic pilots, however, tend to fly higher strength, higher performance airplanes with relatively few restrictions while the novice aerobatic pilots routinely fly the more restricted airplanes. Also, the label "certified for aerobatics" often results in a false sense of security since it implicitly conveys an operational or structural capacity which may not exist. This is particularly true in light of the significant differences in structural limitations between various aerobatic airplanes. Additionally, the actual strength of an aerobatic airplane designed to the standards of CAR 4a may not be significantly greater than that of an airplane certificated in the utility category under 14 CFR 23.

In view of the above information, the expanded interest in aerobatics in recent years, and the performance of increasingly sophisticated aerobatic maneuvers by relatively inexperienced pilots, there is an increasing need to assure complete understanding of all of the operational implications associated with the performance of aerobatics and a margin of safety compatible with the potential consequence of operational error in maneuvers flown by these pilots.

AEROBATIC TRAINING

A course on the fundamentals of aerobatics is usually programmed for a minimum of 10 to 12 hours of flight instruction. The course generally is for a particular airplane, such as the Cessna 150 Aerobat, the Bellanca Citabria, or the Bellanca Decathlon. The specific maneuvers taught include most or all of those approved for these airplanes--spins, loops, aileron rolls, Immelmanns, and snap rolls.

Except in an isolated case or two involving an FAA-approved aerobatic course, there are no regulations which relate directly to the aerobatic curriculum or to pilot flight proficiency or experience since there are no certification tests or airman ratings required in connection with the performance of aerobatics. Consequently, although the operator of a pilot school could apply for FAA approval of an aerobatic course under 14 CFR 141, there are generally no economic or operational reasons for him to do so.

The lack of regulation prompts some concern regarding the quality of aerobatic instruction and the unrestricted performance of aerobatic maneuvers by pilots lacking adequate training or experience in such maneuvers. For example, a flight instructor holding only an "airplane" rating cannot instruct in the capacity of an instrument flight instructor even though he holds an instrument rating. He must pass both an additional written and a practical test before doing so. By contrast, although the operating implications and safety aspects of aerobatics are no less critical, there is no similar prerequisite or criterion to assure instructor competence in this area. Even though a flight instructor may have compiled substantial flight experience, it is essential that, as an aerobatic instructor, he be thoroughly familiar with all of the approved flight maneuvers, specialized operational techniques, and performance flight characteristics of each make and model airplane used. Since there are no aerobatic certification tests or related airman ratings, it is not feasible to require aerobatic instructor ratings. The FAA, however, should consider the issuance of a "letter of competence" or its equivalent. A potential aerobatic instructor would then be required to demonstrate, in the airplane make and model he intends to use, all aerobatic maneuvers approved for that make and model. In place of the demonstration, a certificate would be presented to that instructor indicating that he has completed satisfactorily an aerobatic instructor's orientation course given by the manufacturer or its distributors.

All aerobatic maneuvers approved for a particular make and model airplane can be performed safely by pilots who have been adequately trained in these maneuvers--those who have received comprehensive dual instruction from a qualified flight instructor and have practiced such

maneuvers under his supervision. Conversely, these maneuvers, particularly those involving inverted flight, cannot be performed safely without this type of training. Regardless of a pilot's flight experience, the ability to perform aerobatics safely does not stem automatically from such experience and the acquisition of aerobatic proficiency is not necessarily a natural extension of his overall flying abilities. The following excerpts from the respective Cessna and Bellanca aerobatic training manuals emphasize this point:

- o "Of course, no aerobatic maneuvers should be attempted without first having received dual instruction from a qualified aerobatic instructor. Just as you didn't read a book entitled How To Fly, jump in an airplane and proceed to teach yourself to get the machine off the ground and back again. You will agree that had you done just that, you would have been in for a surprising experience. In addition, had you achieved such a feat . . . only bad habits and poor techniques would have developed."
- o "Never attempt to do aerobatics unless you are qualified as evidenced by a certificated flight instructor. Only then can you be assured the safety of not exceeding design limitations."

Despite these precautionary notes and in the absence of regulations restricting his performance, the novice aerobatic pilot may perform any of the aerobatic maneuvers approved for his airplane, regardless of their complexity or criticality. Moreover, there is no assurance that dual instruction alone or the completion of an aerobatics course will result in the student's attaining an adequate measure of aerobatic proficiency, particularly since there are no established operational or experience prerequisites for such a course of instruction. The only way to assure that the student has attained this proficiency is to have his aerobatic flight instructor endorse his logbook to this effect in those cases where he believes the student's demonstrated performance warrants it. This endorsement could relate to any or all of the aerobatic maneuvers approved for a particular airplane. Pilots should be prohibited from performing any critical aerobatic maneuver without first obtaining such an endorsement. Although they are sometimes considered as aerobatics, from a technical point of view, chandelles, lazy eights, and other coordination exercises and maneuvers normally practiced and developed during the course of training for airman certification tests need not be included within the context of this endorsement.

CONCLUSIONS

- o Since there are no certification tests or airman ratings required in connection with the performance of aerobatics, there are no regulations which relate directly to the aerobatic training curriculum or to the flight instructors' or novice pilots' aerobatic flight proficiency or experience.
- o The majority of accidents involving aerobatics are unrelated to precision or professional aerobatics. Many such accidents are merely the result of careless and reckless operation by pilots lacking aerobatic knowledge, training, or proficiency.
- o Over the years, regulatory requirements for aircraft certification in the aerobatic category have been improved and expanded somewhat with respect to structural criteria based on type of airplane operation, demonstration of maneuvers for which certification is requested, and approved types of aerobatic maneuvers.
- o The operational category (normal or aerobatic) of some older airplanes certificated under Parts 4a or 04 of the Civil Air Regulations is not specified on the type certification data sheet. Neither is there an approved flight manual nor approved operating limitations governing their use. Consequently, from a regulatory point of view, these airplanes may engage in aerobatics with no restrictions as to type of maneuvers which may be performed.
- o Flight evaluation studies by the National Aeronautics and Space Administration in one particular aerobatic airplane disclosed that the minimum negative limit load factor required by FAR 23 was exceeded significantly when obligatory (competitive) groups of aerobatic maneuvers were performed; stick forces, it was learned, were not necessarily a reliable indication of load factor, nor was exceeding the limit load factor significantly limited by the physical capabilities of the pilot.
- o The aerobatic maneuvers being performed during airshow or airshow-related accidents generally included rolls or inverted flight, snap rolls, and spins at low altitude.
- o The majority of the stalls and spins involved in aerobatic-related accidents were unintentional and occurred at low altitudes--altitudes which made recovery from the stall or spin difficult or impossible. Those accidents directly associated

with intentional spins (some of which also occurred because of a lack of altitude sufficient for a complete spin recovery) generally related to lack of pilot experience or proficiency, poor judgment, improper or inadequate spin recovery techniques, etc.

- o Because of operational vagaries or anomalies, improper or inadequate application of recovery controls, apprehension, confusion, or disorientation, the initiation of spins at higher altitudes is being increasingly emphasized. Moreover, to obtain consistent, optimum spin recovery results may require use of precise spin recovery techniques.
- o Aerobatic accidents involving controlled and uncontrolled collisions with the ground or collisions with wires, poles, or trees, like many of the aerobatic-related stall/spin accidents, merely reflect the hazards of performing aerobatics at low altitude. Most such accidents involved flights conducted in violation of one or more of the provisions of FAR 91.71, "Acrobatic Flight," particularly FAR 91.7(d) which prohibits the operation of an aircraft in acrobatic flight below an altitude of 1,500 feet above the surface.
- o Five of the ten airplanes involved in the aerobatics-related, in-flight airframe failures accidents reviewed herein were experimental or amateur built; three were certificated in the aerobatic category; one was certificated in the normal category; and one was uncertificated.
- o Despite the emphasis placed on the critical importance of observing an airplane's limit load factor and the operational usefulness of recording load factors induced during a maneuver or series of maneuvers, accelerometers (instruments which measure load factor) are not required on some aerobatic airplanes.

RECOMMENDATIONS

As a result of this Special Study, the National Transportation Safety Board has recommended that the Federal Aviation Administration:

"Expand the presentation of flight instructor stall/spin indoctrination clinics patterned after the one initially held in FAA's Central Region on August 15-17, 1975, to include all FAA Regions and various popular make and model airplanes. (Class II--Priority Followup.) (A-76-105).

"Require a commercial flight instructor to hold a 'letter of competence' or its equivalent before providing aerobatic instruction other than that routinely required during the normal course of training for airman certification tests. (Class III--Longer-Term Followup.) (A-76-106).

"Require that pilots obtain a logbook endorsement from an aerobatic flight instructor before performing aerobatic maneuvers other than those required in connection with airman certification tests. (Class III--Longer-Term Followup.) (A-76-107).

"Issue an Advisory Circular explaining the operational considerations, airworthiness requirements, and safety aspects associated with the performance of aerobatics. (Class II--Priority Followup.) (A-76-108).

"Require that all airplanes subsequently certificated in the aerobatic category, including those previously certificated in another category under a Regulatory Part other than 14 CFR 23, conform with the currently applicable structural criteria in Subpart C of FAR 23, particularly the provisions relating to limit maneuvering load factors. (Class II--Priority Followup.) (A-76-109).

"Evaluate the feasibility of specifying stick force gradient requirements uniquely applicable to aerobatic airplanes in 14 CFR 23.155, 'Elevator Control Force in Maneuvers.' (Class III--Longer-Term Followup.) (A-76-110).

"Amend 14 CFR 91.71, 'Aerobatic Flight' to include a schedule of minimum initial spin altitudes. (Class II--Priority Followup.) (A-76-111).

"Conduct an intensive accident prevention campaign to emphasize and enforce effectively the provisions of 14 CFR 91.71, 'Aerobatic flight' and 14 CFR 91.9, 'Careless or Reckless Operation.' (Class II--Priority Followup.) (A-76-112).

"Require the installation of accelerometers in all aerobatic airplanes. (Class III--Longer-Term Followup.) (A-76-113).

"Amend 14 CFR 23.337, 'Limit Maneuvering Load Factor,' to increase the minimum required, negative limit maneuvering load factor for aerobatic airplanes from -3.0 to -4.5. (Class III--Longer-Term Followup.) (A-76-114).

JL

"Amend 14 CFR 23.333, 'Flight Envelope' to require that the negative maneuvering load factor specified in 14 CFR 23.337 for the aerobatic category remain constant between III--Longer-Term Followup.) (A-76-115)."

BY THE NATIONAL TRANSPORTATION SAFETY BOARD

/s/ WEBSTER B. TODD, JR.
Chairman

/s/ KAY BAILEY
Vice Chairman

/s/ FRANCIS H. McADAMS
Member

/s/ PHILIP A. HOGUE
Member

/s/ WILLIAM R. HALEY
Member

July 20, 1976

LI

APPENDIX A
LIST OF ACCIDENTS INVOLVING AEROBATIC IN-FLIGHT PHASE OF OPERATION

LIST OF ACCIDENTS INVOLVING
ACROBATICS INFLIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972 - 1974
SORTED BY AIRCRAFT MAKE AND MODEL

| FILE NUMBER | AIRCRAFT REGIST. | DATE | LOCATION | AIRCRAFT MAKE | AIRCRAFT MODEL | INJURY INDEX |
|-------------|------------------|--------|--------------------|---------------|----------------|--------------|
| 3 4120 | N80DE | 122174 | VERBANK, NY | AVION MUDRY | CAP10B | MINOR |
| 3 3704 | N36034 | 100673 | MORRIS, ILL | BELLANCA | 7GCBC | FATAL |
| 3 2944 | N9003L | 092273 | JACKSONVILLE, ARK | CHAMPION | 7KCAB | FATAL |
| 3 2276 | N2043A | 072973 | ROCK SPRINGS, WYO | AERONCA | 7BCM | MINOR |
| 3 2262 | N8237Z | 072274 | STUTTGART, ARK | AERONCA | 7AC | FATAL |
| 3 0405 | N90918 | 021074 | CANON CITY, COLO | BELLANCA | 7KCAB | FATAL |
| 3 3963 | N112Z | 120873 | SOUTH HAVEN, MICH | CHAMPION | 7GCAA | FATAL |
| 3 1847 | N8953 | 072874 | ARCHDALE, NC | BELLANCA | 7GCBC | FATAL |
| 3 1033 | N2536F | 033174 | XENIA, OHIO | CHAMPION | 7ECA | FATAL |
| 3 0276 | N9027L | 031773 | MADERA, CALIF | CHAMPION | 7KCAB | FATAL |
| 3 0204 | N85401 | 013073 | SLOUGHHOUSE, CALIF | AERONCA | 7AC | SERIOUS |
| 3 3705 | N1623G | 080772 | MCCORDSVILLE, IND | CHAMPION | 7ECA | FATAL |
| 3 3618 | N9881Y | 110572 | HONESDALE, PA | CHAMPION | 7GCB | FATAL |
| 3 2888 | N5136X | 070872 | SAN RAMON, CALIF | CHAMPION | 7KCAB | FATAL |
| 3 1176 | N6398N | 081272 | SHERRILLS FORD, NC | CHAMPION | 7GCAA | FATAL |
| 3 1091 | N7564F | 073072 | WINDSOR, VA | CHAMPION | 7KCAB | FATAL |
| 3 0284 | N5081X | 011872 | SANGER, TEX | CHAMPION | 7GCBC | FATAL |
| 3 2759 | N41806 | 081874 | PAPILLION, NEBR | BELLANCA | 8KCAB | FATAL |
| 3 1709 | N68559 | 052474 | SCOTTSVILLE, VA | BELLANCA | 8KCAB | FATAL |
| 3 1676 | N41817 | 052474 | NGTLROY, CALIF | BELLANCA | 8KCAB | NONE |
| 3 3127 | N31295 | 100674 | NEW CASTLE, IND | BELLANCA | 8KCAB | SERIOUS |
| 3 3306 | N36033 | 111873 | SANTA FE, N. MEX | BELLANCA | 8KCAB | FATAL |
| 3 3099 | N86589 | 090874 | S. Weymouth, MASS | BELLANCA | 8KCAB | FATAL |
| 3 2527 | N9473H | 091273 | WIDDENITE, NC | FAIRCHILD | M-62C | NONE |
| 3 0908 | N54112 | 060272 | MADISON, MISS | FAIRCHILD | M-62A | FATAL |
| 3 3656 | N9785L | 092472 | LARKSPUR, COLO | BEECH | C23 | SERIOUS |

APPENDIX A

LIST OF ACCIDENTS INVOLVING
ACROBATICS INFLIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972 - 1974
SORTED BY AIRCRAFT MAKE AND MODEL

| FILE NUMBER | AIRCRAFT REGIST. | DATE | LOCATION | AIRCRAFT MAKE | AIRCRAFT MODEL | INJURY INDEX | FI NIJM |
|-------------|------------------|--------|---------------------|---------------|----------------|--------------|---------|
| 3 3276 | N66489 | 100774 | SOMERVILLE, TENN | BOEING | 75 | FATAL | 3 0 |
| 3 3018 | N5118N | 090174 | WAYNESVILLE, NC | BOEING | A75L3 | FATAL | 3 0 |
| 3 1610 | N7773V | 061474 | NHOYT, COLO | CALLAIR | A-9B | SERIOUS | 3 1 |
| 3 3439 | N7238V | 062074 | STEPHEN, MINN | CALLAIR | A-9 | SERIOUS | 3 4 |
| 3 3818 | N2124V | 121974 | NWASCO, OREG | CESSNA | 120 | FATAL | 3 0 |
| 3 0047 | N75J | 012372 | FREEPORT, TEX | CESSNA | 140 | FATAL | 3 1 |
| 3 3937 | N8344M | 110472 | WENTZVILLE, MO | CESSNA | A150K | FATAL | 3 1 |
| 3 0141 | N18521 | 030273 | YORK, NY | CESSNA | 150 | FATAL | 3 3 |
| 3 1898 | N7217S | 073173 | HAMPTON, IOWA | CESSNA | 150H | FATAL | 3 0 |
| 3 2765 | N5904G | 100973 | MELBOURNE, FLA | CESSNA | 150K | FATAL | 3 1 |
| 3 1881 | N19279 | 061573 | KEY WEST, FLA | CESSNA | 150L | FATAL | 3 1 |
| 3 2886 | N8441M | 051372 | METAMORA, MICH | CESSNA | A150 | FATAL | 3 1 |
| 3 2967 | N8313M | 101473 | MCARTHUR, OHIO | CESSNA | A150K | MINOR | 3 4 |
| 3 0388 | N6285G | 012672 | TOPSAIL, NC | CESSNA | 150 | NONE | 3 2 |
| 3 3014 | N6047J | 092373 | HOLLY, MICH | CESSNA | A150L | FATAL | 3 1 |
| 3 0118 | N5930J | 012874 | NMELBOURNE, FLA | CESSNA | A150L | FATAL | 3 3 |
| 3 2303 | N19266 | 062974 | FAYETTEVILLE, NC | CESSNA | 150L | FATAL | 3 3 |
| 3 0831 | N6062J | 042374 | RIO RANCHO, N MEX | CESSNA | A150L | FATAL | 3 2 |
| 3 3837 | N60581 | 112474 | MORGANTON, NC | CESSNA | 150J | FATAL | 3 2 |
| 3 2708 | N11958 | 091974 | PARKIN, ARK | CESSNA | 150L | FATAL | 3 1 |
| 3 0638 | N7284T | 031474 | SILVER CITY, N MEX | CESSNA | 172A | FATAL | 3 2 |
| 3 2795 | N9325B | 072772 | PORT CHARLOTTE, FLA | CESSNA | 175 | SERIOUS | 3 0 |
| 3 0452 | N7869A | 032373 | LIVERMORE, CALIF | CESSNA | 180A | FATAL | 3 1 |
| 3 2283 | N9321T | 071274 | NTACOMA, WASH | CESSNA | 180C | FATAL | 3 3 |
| 3 0394 | N1628T | 022074 | LEBANON, MO | CESSNA | 414 | FATAL | 3 2 |
| 3 1143 | N44090 | 080572 | SYLVESTER, GA | CESSNA | A188A | FATAL | 3 2 |

APPENDIX A

LIST OF ACCIDENTS INVOLVING
ACROBATICS INFLIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972 - 1974
SORTED BY AIRCRAFT MAKE AND MODEL

| FILE NUMBER | AIRCRAFT REGIST. | DATE | LOCATION | AIRCRAFT MAKE | MODEL | INJURY INDEX |
|----------------|---------------------|--------|-------------------|------------------|--------|-----------------|
| 3 0462 | N9936G | 060372 | NSOUTH BEND,IND | CESSNA | 188A | FATAL |
| 3 0875 | N6346L | 042173 | ERIE,COLO | AMER AVCO | AA1 | FATAL |
| 3 1865 | N9507L | 060473 | FAIRFIELD,CALIF | AMER AVCO | AA1-B | FATAL |
| 3 4023 | N9443L | 122974 | NNEWARK,CALIF | AMER AVCO | AA1-A | FATAL |
| 3 0126 | N39860 | 013073 | AURORA,COLO | BELLANCA | 17-31A | FATAL |
| 3 1894 | N8867V | 071573 | PINETOPS,NC | BELLANCA | 17-30A | FATAL |
| 3 1184 | N94031 | 070472 | MCDONALD,PA | ERCO | 415-C | FATAL |
| 3 3513 | N28741 | 091672 | OGDEN,UT | LUSCOMBE | 8C | SERIOUS |
| 3 0665 | N626N | 040872 | CHANDLER,ARIZ | HARVARD | MARKIV | FATAL |
| 3 1719 | N3194G | 073172 | KINGMAN,KANS | N. AMERICAN | SNJ-5 | FATAL |
| 3 1672 | N7056C | 070672 | THIEF RVR FL,MINN | N. AMERICAN | SNJ-4 | FATAL |
| 3 1913 | N1042C | 061773 | SHELBY,OHIO | N. AMERICAN | SNJ-5 | FATAL |
| 3 4197 | N4703M | 122174 | NBRIUNSWICK,OHIO | PIPER | PA-11 | FATAL |
| 3 2468 | N35258 | 081874 | KANKAKEE,ILL | PIPER | J3C-65 | FATAL |
| 3 1376 | N92304 | 041674 | CORNELIUS,OREG | PIPER | J3C-65 | FATAL |
| 3 3673 | N1504N | 111174 | FAIRVIEW,OKLA | PIPER | J-3 | SERIOUS |
| 3 3031 | N1822P | 100474 | HUNTINGTON,W VA | PIPER | PA-22 | FATAL |
| 3 2152 | N8826L | 081674 | GOLFAX,LA | PIPER | PA-25 | FATAL |
| 3 2992 | N4293T | 091074 | NJACKSONVILLE,FLA | PIPER | PA-28 | FATAL |
| 3 1916 | N36240 | 060472 | WARDEN,WASH | TAYLORCRAFT | BC1265 | SERIOUS |
| 3 2321 | N5016M | 070272 | LOVINGTON,N MEX | TAYLORCRAFT | BC12-D | FATAL |
| 3 0345 | N3262K | 012873 | DESERT CNTR,CALIF | GLOBE | GC-1B | FATAL |
| 3 1703 | N3342K | 071374 | PLUM ISLAND,MASS | GLOBE | GC-1B | FATAL |
| 3 3095 | N29949 | 081972 | VANCOUVER,WASH | WACO | UPF-7 | SERIOUS |
| 3 2334 | N31JT | 082373 | HOMER,NY | JEANIES | TEENIE | FATAL |
| 3 2597 | N1269 | 070173 | NMONMOUTH,OREG | STORY | MK-7 | SERIOUS |

APPENDIX A

LIST OF ACCIDENTS INVOLVING
ACROBATICS INFLIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972 - 1974
SORTED BY AIRCRAFT MAKE AND MODEL

| FILE NUMBER | AIRCRAFT REGIST. | DATE | LOCATION | AIRCRAFT MAKE | AIRCRAFT MODEL | INJURY INDFX | F NU -- |
|----------------|---------------------|--------|-------------------|------------------|-------------------|-----------------|---------------|
| 3 4170 | N7J | 122373 | LFFESBURG,FLA | PITTS | S1C | FATAL | 3 |
| 3 4154 | N2703B | 031372 | CARSON CITY,NEV | PITTS | SC-1 | FATAL | |
| 3 2483 | N3192 | 051773 | ATHENS,GA | PITTS | S1C | FATAL | |
| 3 1103 | N7JG | 052774 | WESTERLO,NY | GILMORE | 3D | NONE | |
| 3 2076 | N93003 | 052774 | SALEM,OREG | MAY FLYBABY | 1 | FATAL | |
| 3 2979 | N701D | 101973 | COMMERCE,TEX | JUNGMEISTER | BUCKER | MINOR | |
| 3 1061 | N6733C | 041474 | NCLEAR LAKE,CALIF | STITS | SA6B | FATAL | |
| 3 0924 | N50WP | 041474 | SANTA PAULA,CALIF | STARDUSTER | SA-100 | FATAL | |
| 3 2056 | N3650 | 052872 | ALABASTER,ALA | STARDUSTER | T00 | SERIOUS | |
| 3 0487 | N591T | 061572 | CRYSTAL LAKE,ILL | LOWERS | BIRD | FATAL | |
| 3 0152 | N98X | 051072 | MERCED,CALIF | PITTS | S-1S | FATAL | |
| 3 2630 | N7021 | 090874 | HIGHGROVE,CALIF | PITTS SPL | S-1C | FATAL | |
| 3 0151 | N1151H | 051272 | WOODLAKE,CALIF | PITTS | S-1S | FATAL | |
| 3 0453 | N1494 | 052172 | ADELANTO,CALIF | STARDUSTER | T00 | FATAL | |
| 3 3399 | N5191 | 081874 | WASFCA,MINN | ZIMMERMAN | S-1C | SERIOUS | |
| 3 3231 | N1276 | 091174 | CLAXTON,GA | BREEZY | DP2 | NONE | |
| 3 0459 | N513W | 052972 | DERRY,PA | PITTS SPCL | S-1 | MINOR | |
| 3 0446 | N14257 | 051072 | PERRIS,CALIF | STARDUSTER | SA-300 | FATAL | |
| 3 3090 | N10BA | 100973 | FRANKLIN,IND | CORBIN | B-ACE | FATAL | |
| 3 2849 | N3477 | 090273 | SAN LEON,TEX | ZLIN | Z526 | SERIOUS | |
| 3 2077 | N25C | 072074 | MT.PLEASANT,TEX | KNIGHT TWST | 85B | FATAL | |
| 3 1997 | N152BD | 071774 | NEWTON,KANS | BEDE | BD-5J | SERIOUS | |
| 3 1545 | N13HH | 061873 | GONZALES,CALIF | HAZARD-TURN | T-40H | FATAL | |
| 3 3542 | N80022 | 111773 | BOGALUSA,LA | PITTS | S-2A | FATAL | |
| 3 4122 | N22XP | 090973 | HOMESTEAD,FLA | PITTS | S-1S | FATAL | |
| 3 1132 | N8028 | 080372 | MIAMI,FLA | PITTS SPCL | S-2A | NONE | |

APPENDIX A

LIST OF ACCIDENTS INVOLVING
ACROBATICS INFLIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972 - 1974
SORTED BY AIRCRAFT MAKE AND MODEL

| FILE NUMBER | AIRCRAFT REGIST. | DATE | LOCATION | AIRCRAFT MAKE | AIRCRAFT MODEL | INJURY INDEX |
|----------------|---------------------|--------|-----------------|------------------|-------------------|-----------------|
| ----- | ----- | ----- | ----- | ----- | ----- | ----- |
| 3 3848 | N80029 | 121673 | LETOHATCHEE,ALA | PITTS | S-2A | MINOR |

APPENDIX B
BRIEFS OF ACCIDENTS

NATIONAL TRANSPORTATION SAFETY BOARD

WASHINGTON, D. C. 20594

BRIEFS OF ACCIDENTS

ACROBATIC-INFLIGHT PHASE OF OPERATION

1ST TYPE ACCIDENT-STALL/SPIN

U.S. GENERAL AVIATION

1972 THRU 1974

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | | PILOT DATA |
|--|------------------|----------------|----------------------|---------------------|------------------------------------|--------|---|
| | | | | | CR- | PX- | |
| 3-0047 | 1/23/72 | FREERPORT, TEX | CESSNA 140 N75J | CR- 2 0 PX- 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANSP | COMMERCIAL, AGE 27, 297 TOTAL HOURS, 226 IN TYPE, NOT INSTRUMENT RATED. |
| | TIME - 1300 | | DAMAGE-DESTROYED | | | | |
| | DEPARTURE POINT | VICTORIA, TEX | INTENDED DESTINATION | | | | |
| | TYPE OF ACCIDENT | STALL | LAFAYETTE, LA | | | | |
| | | | PHASE OF OPERATION | | | | |
| | | | IN FLIGHT ACROBATICS | | | | |
| PROBABLE CAUSE(S) | | | | | | | |
| PILOT IN COMMAND - EXERCISED POOR JUDGMENT | | | | | | | |
| PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED | | | | | | | |
| MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | | |
| REMARKS - LOW PASS ABOUT 20-30 FT ABOVE EDGE OF BEACH. STALLED FROM WG OVER TYPE MANEUVER. | | | | | | | |
| PROBABLE CAUSE(S) | | | | | | | |
| PILOT IN COMMAND - EXERCISED POOR JUDGMENT | | | | | | | |
| PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED | | | | | | | |
| FACTOR(S) | | | | | | | |
| MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | | |
| REMARKS - HAMMER-HEAD STALL AFTER BUZZING CAMP SITE ABOUT 20 FT AGL. | | | | | | | |

APPENDIX B

- 42 -

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|--------------------------|---|------------|--------|--------|---------------------------|--|
| | | | | F | S | M/N | | |
| 3-0459 | 5/29/72 | DERRY, PA TIME - 1615 | PITTS SPCL S-1 N613W DAMAGE-DESTROYED | CR- PX- | 0 0 | 1 0 | NONCOMMERCIAL PRACTICE | COMMERCIAL, FL•INSTR• AGE 43, 3334 TOTAL HOURS, 43 IN TYPE, INSTRUMENT RATED. |

DEPARTURE POINT
LATROBE, PA
TYPE OF ACCIDENT
STALL SPININTENDED DESTINATION
LOCAL
PHASE OF OPERATION
IN FLIGHT ACROBATICS

PROBABLE CAUSE(S)

PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
 PILOT IN COMMAND - MISJUDGED ALTITUDE
 PILOT IN COMMAND - MISJUDGED ALTITUDE
 REMARKS- ENTERED INVERTED FLAT SPIN FROM ATTEMPT AT OUTSIDE SNAP ROLL. UNABLE TO RECOVER. PLT BAILED OUT.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|--------|-------------------------------|---|------------|--------|--------|---|---|
| | | | | F | S | M/N | | |
| 3-0665 | 4/8/72 | CHANDLER, ARIZ TIME - 1241 | HARVARD MARKIV N626N DAMAGE-DESTROYED | CR- PX- | 2 0 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRANSP | COMMERCIAL, AGE 40, 600 TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. |

NAME OF AIRPORT - GOODYEAR AUX 6
DEPARTURE POINT
MESA, ARIZ
TYPE OF ACCIDENT
STALL SPININTENDED DESTINATION
LOCAL
PHASE OF OPERATION
IN FLIGHT ACROBATICS

PROBABLE CAUSE(S)
 PILOT IN COMMAND - EXERCISED POOR JUDGMENT
 PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
 PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN LOW FLYING
 MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
 FIRE AFTER IMPACT
 REMARKS- LOST CTL IN LOW ALT ROLL AND SPUN IN.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|--------|------------------------------|---|------------|--------|--------|---------------------------|--|
| | | | | F | S | M/N | | |
| 3-0908 | 6/2/72 | MADISON, MISS TIME - 1310 | FAIRCHILD M-62A N54112 DAMAGE-DESTROYED | CR- PX- | 1 1 | 0 0 | NONCOMMERCIAL BUSINESS | COMMERCIAL, FL•INSTR• AGE 25, 5746 TOTAL HOURS, 10 IN TYPE, INSTRUMENT RATED. |

NAME OF AIRPORT - BRUCE CAMPBELL
DEPARTURE POINT
MADISON, MISS
TYPE OF ACCIDENT
STALL SPININTENDED DESTINATION
LOCAL
PHASE OF OPERATION
IN FLIGHT ACROBATICS

PROBABLE CAUSE(S)
 PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
 FACTOR(S)
 PILOT IN COMMAND - LACK OF FAMILIARITY WITH AIRCRAFT
 MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER
 REMARKS- PLT FAILED TO RECOVER FROM INTNL SPIN.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|--------|------------------------------|---|------------|--------|--------|---------------------------------------|---|
| | | | | F | S | M/N | | |
| 3-1143 | 8/5/72 | SYLVESTER, GA TIME - 0940 | CESSNA 188A N44090 DAMAGE-DESTROYED | CR- PX- | 1 0 | 0 0 | COMMERCIAL ASSOC CROP CTL ACTIVITY | COMMERCIAL, FL•INSTR• AGE 27, 3940 TOTAL HOURS, 200 IN TYPE, NOT INSTRUMENT |

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--------|------------------------|--|--|------------------------|--|--|
| 3-1143 | 8/5/72 TIME - 0940 | SYLVESTER, GA DEPARTURE POINT SYLVESTER, GA TYPE OF ACCIDENT STALL SPIN | CESSNA A188A N4409Q DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | COMMERCIAL ASSOC CROP CIL ACTIVITY | COMMERCIAL, FL INSTR. AGE 27, 3940 TOTAL HOURS, 200 IN TYPE, NOT INSTRUMENT RATED. |
| | | NAME OF AIRPORT - JACKS STRIP INTENDED DESTINATION LOCAL | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED FACTOR(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT | | | | |
| | | SPECIAL DATA TOTAL HOURS IN CROP CONTROL - UNKNOWN/NOT REPORTED KIND OF CROP - TOBACCO PILOT'S SEAT BELT - FASTENED-PROPERLY GOOGLES - NOT USED COCKPIT CRASHPAD - NOT INSTALLED TANK/HOPPER-LOCATION - FORWARD OF PILOT REMARKS- PLT FLEW ACROSS STRIP AND DID CHANDELLE TO L. ACFT ENTERED SPIN. CRASHED DURING RECOVERY. | | | KIND OF OPERATION - SPRAYING CROPS TYPE OF CHEMICAL USED - LIQUID CHEMICAL-TOXIC GLOVES - NOT USED CRASH HELMET - AVAILABLE-USED CRASH BAR - INSTALLED | |
| 3-1719 | 7/31/72 TIME - 0947 | KINGMAN, KANS DEPARTURE POINT KINGMAN, KANS TYPE OF ACCIDENT STALL | N-AMERICAN SNJ-5 N3194G DAMAGE-DESTROYED | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | COMMERCIAL, AGE 38, UNK/NR TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED. |
| | | NAME OF AIRPORT - KINGMAN INTENDED DESTINATION INDEPENDENCE, MO | | | TRANSP PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING REMARKS- LOST CTL IN L CHANDELLE SHORTLY AFTER T/O. | | | | |

APPENDIX B

- 44 -

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | FLIGHT PURPOSE | PILOT DATA |
|--------|--------|--------------|---|----------------|-----|------------------------------------|---|
| | | | | F | S | | |
| 3-1916 | 6/4/72 | WARDEN, WASH | TAYLORCRAFT BC1265 N36240 TIME - 0745 DAMAGE-DESTROYED | CR- 0 PX- 0 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANSP AGE 28, 1250 TOTAL HOURS, 800 IN TYPE, NOT INSTRUMENT RATED. |

NAME OF AIRPORT - WARDEN
DEPARTURE POINT
WARDEN, WASH
TYPE OF ACCIDENT
STALL SPIN

PROBABLE CAUSE(S)

PILOT IN COMMAND - EXERCISED POOR JUDGMENT
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
REMARKS- ENTERED SPIN AFT HAMMERHEAD STALL AT LOW ALT.

NAME OF AIRPORT - ALABASTER, ALA
DEPARTURE POINT
TIME - 1450
ALABASTER, ALA
TYPE OF ACCIDENT
STALL SPIN

PROBABLE CAUSE(S)
PILOT IN COMMAND - EXERCISED POOR JUDGMENT
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
REMARKS- ENTERED SPIN AFT HAMMERHEAD STALL AT LOW ALT.

NAME OF AIRPORT - SHELBY COUNTY
DEPARTURE POINT
TIME - 1450
ALABASTER, ALA
TYPE OF ACCIDENT
STALL SPIN

PROBABLE CAUSE(S)
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
FIRE AFTER IMPACT
REMARKS- WOODED SWAMP. PLT LOST CONTROL AT INSUF ALT TO RECOVER DURG AUTHZD LOWLVL ACROBATICS IN AIRSHOW.

NAME OF AIRPORT - PORT CHARLOTTE, FLA
DEPARTURE POINT
TIME - 1355
PUNTA GORDA, FLA
TYPE OF ACCIDENT
STALL

PROBABLE CAUSE(S)
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
FACTORS
MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER

NAME OF AIRPORT - CHARLOTTE COUNTY
DEPARTURE POINT
TIME - 1355
PUNTA GORDA, FLA
TYPE OF ACCIDENT
STALL

PROBABLE CAUSE(S)
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
FACTORS
MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|----------------|---------------|----------|---|----------------|----------------------|
| | | | | F | S | | |
| 3-2886 | 5/13/72 | METAMORA, MICH | CESNA A150 | CR- 1 | 0 | NONCOMMERCIAL | PRIVATE, AGE 27, 113 |

| | | BRIEFS OF ACCIDENTS | | PILOT DATA | |
|---------|------------------------|--|--|------------------------|--|
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | FLIGHT PURPOSE |
| 3-28886 | 5/13/72 TIME - 1609 | METAMORA, MICH NAME OF AIRPORT - COUNTRY VIEW DEPARTURE POINT - PONTIAC, MICH TYPE OF ACCIDENT - STALL | CESNA A150 N8441M DAMAGE-DESTROYED | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRNSP |
| | | INTENDED DESTINATION LOCAL | | | PRIVATE, AGE 27, 113 TOTAL HOURS, 16 IN TYPE, NOT INSTRUMENT RATED. |
| | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G. REMARKS- ENTERED SPIN FROM LOW ACROBATIC MANEUVER. ABOUT 42 LBS OVER MAX GROSS WT ON DEP. | | | |
| 3-28888 | 7/8/72 TIME - 1530 | SAN RAMON, CALIF NAME OF AIRPORT - OAKLAND, CALIF TYPE OF ACCIDENT - STALL | CHAMPION 7KLAB N5136X DAMAGE-DESTROYED | CR- 2 0 0 PX- 0 0 0 | INSTRUCTIONAL DUAL |
| | | INTENDED DESTINATION LOCAL | | | COMMERCIAL, FL. INSTR., AGE 30, 974 TOTAL HOURS, 185 IN TYPE, INSTRUMENT RATED. |
| | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING MISCELLANEOUS ACTS, CONDITIONS - INTERFERENCE WITH FLIGHT CONTROLS MISCELLANEOUS ACTS, CONDITIONS - INWARRANTED LOW FLYING FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - SEAT BELT NOT FASTENED MISCELLANEOUS ACTS, CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G. REMARKS- IP SEAT BELT NOT FASTENED. OVER MAX GROSS WT AT T/O ABOUT 150 LBS. AFT CG. LOW LEVEL AEROBATICS. | | | |
| 3-3095 | 8/19/72 TIME - 1215 | VANCOUVER, WASH NAME OF AIRPORT - EVERGREEN DEPARTURE POINT - VANCOUVER, WASH TYPE OF ACCIDENT - STALL | WACO UPF-7 N29949 DAMAGE-SURSTANTIAL | CR- 0 1 0 PX- 0 0 0 | MISCELLANEOUS AIR SHOW/RACING |
| | | INTENDED DESTINATION LOCAL | | | COMMERCIAL, AGE 60, 20200 TOTAL HOURS, 450 IN TYPE, INSTRUMENT RATED. |
| | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED FACTOR(S) TERRAIN - HIGH OBSTRUCTIONS REMARKS- ACFT HIT TREES. | | | |

APPENDIX B

- 46 -

BRIEFS OF ACCIDENTS

| FILE | | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|--------------------------|-----------------------|------------------------|------------------------------------|-------------------|--|
| 3-3513 | 9/16/72 | OGDEN, UT TIME - 1530 | LUSCUMBE 8C N28741 | CR- 0 1 0 PX- 0 1 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANSP | COMMERCIAL, AGE 21, 275 TOTAL HOURS, 80 IN TYPE, INSTRUMENT RATED. |

DEPARTURE POINT LOCAL
OGDEN, UT
TYPE OF ACCIDENT STALL
REMARKS- UN RCVR FROM SPIN.RCVRD 9/17/72.

PROBABLE CAUSE(S)
PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL
PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
PILOT IN COMMAND - OPERATED CARELESSLY
PILOT IN COMMAND - LATER RECOVERED
MISSING AIRCRAFT - LATER RECOVERED
REMARKS- ACFT OBSRVD EXECUTING EITHER WNG-OVR OR SNAP-ROLL DRG CLMB OUT.ACFI APRX 110LBS OVR GWT.

| NAME OF AIRPORT | | CHERRY RIDGE | INTENDED DESTINATION | PHASE OF OPERATION | PILOT DATA | | |
|-----------------|---------------|------------------------------|-------------------------|------------------------------------|--|--------|---|
| DEPARTURE POINT | HONESDALE, PA | LOCAL | IN FLIGHT AEROBATICS | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 46, 500 TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. | | |
| 3-3618 | 11/5/72 | HONESDALE, PA TIME - 1115 | CHAMPION 76CB N9881Y | CR- 1 0 0 PX- 0 1 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANSP | CUMMERCIAL, F. INSTR. AGE 29, 840 TOTAL HOURS, 22 IN TYPE, INSTRUMENT RATED. |

DEPARTURE POINT LOCAL
HONESDALE, PA
TYPE OF ACCIDENT SPIN
STALL

PROBABLE CAUSE(S)
PILOT IN COMMAND - MISJUDGED ALTITUDE
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
FACTOR(S)
MISCELLANEOUS ACTS, CONDITIONS - IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR C.G.
REMARKS- ACFT OBSRVD EXECUTING EITHER WNG-OVR OR SNAP-ROLL DRG CLMB OUT.ACFI APRX 110LBS OVR GWT.

| DEPARTURE POINT | | LARKSPUR, COLO | INTENDED DESTINATION | PHASE OF OPERATION | PILOT DATA | |
|------------------|---------|--|--|------------------------------------|-----------------------|--|
| TYPE OF ACCIDENT | STALL | UNCONTROLLED COLLISION WITH GROUND/WATER | IN FLIGHT AEROBATICS IN FLIGHT UNCONTROLLED DESCEND | NONCOMMERCIAL PLEASURE/PERSONAL | TRANSP | |
| 3-3656 | 9/24/72 | TIME - 0910 | REFECH C23 N9785L | CR- 0 1 1 PX- 0 0 0 | INSTRUCTIONAL DUAL | CUMMERCIAL, F. INSTR. AGE 48, 2100 TOTAL HOURS, 22 IN TYPE, INSTRUMENT RATED. |

DEPARTURE POINT LOCAL
LARKSPUR, COLO
TYPE OF ACCIDENT STALL
REMARKS- UNABLE TO RECOVER FROM SPIN.PROPER RECOVERY PROCEDURES USED ACCORDING TO INSTNR PLT.

PROBABLE CAUSE(S)
MISCELLANEOUS - UNDETERMINED
FIRE AFTER IMPACT
REMARKS- UNABLE TO RECOVER FROM SPIN.PROPER RECOVERY PROCEDURES USED ACCORDING TO INSTNR PLT.

| DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--------|---------------------------------------|------------------------|------------------------|------------------------------------|---|
| 3-3937 | 11/4/72 MENTZVILLE, MO TIME - 1630 | CESSNA A150K N8344M | CR- 2 0 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANSP COMMERCIAL, F. INSTR., AGE 48, 2100 TOTAL HOURS, UNK/NR IN TYPE, INSTRU- MENT RATED. |

DEPARTURE POINT INTENDED DESTINATION

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--|---------|-----------------------------------|---|---------------------|--|---|
| 3-3937 | 11/4/72 | WENTZVILLE, MO TIME - 1630 | CESNA A150K N8344M DAMAGE-DESTROYED | CR- PX- 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | COMMERCIAL, FL. INSTR., * AGE 48, 2100 TOTAL HOURS, UNKNR IN TYPE, INSTRU- MENT RATED. |
| DEPARTURE POINT WENTZVILLE, MO TYPE OF ACCIDENT STALL SPIN | | INTENDED DESTINATION LOCAL | | | TRANS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE REMARKS- INTENTIONAL SPIN. | | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| 3-0141 | 3/2/73 | YORK, NY TIME - 1335 | CESNA 150 N18521 DAMAGE-DESTROYED | CR- PX- 0 0 | INSTRUCTIONAL SOLD | STUDENT, AGE 25, 26 TOTAL HOURS, ALL IN TYPE, NOT INSTRUMENT RATED. |
| DEPARTURE POINT LE ROY, NY TYPE OF ACCIDENT STALL SPIN | | INTENDED DESTINATION LOCAL | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS | | | | | | |
| 3-0204 | 1/30/73 | SLOUGHHOUSE, CALIF TIME - 1130 | AERONCA TAC N85401 DAMAGE-SUBSTANTIAL | CR- PX- 0 1 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 24, 230 TOTAL HOURS, 113 IN TYPE, NOT INSTRUMENT RATED. |
| DEPARTURE POINT CLARKSBURG, CALIF TYPE OF ACCIDENT STALL SPIN | | INTENDED DESTINATION LOCAL | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE REMARKS- RECOVERY TOO LATE. | | | | | | |
| 3-0345 | 1/28/73 | DESERT CNTR, CALIF TIME - 1105 | GLOBE GC-1B N3262K DAMAGE-DESTROYED | CR- PX- 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 55, 837 TOTAL HOURS, 267 IN TYPE, NOT INSTRUMENT RATED. |
| NAME OF AIRPORT - DESERT CENTER DEPARTURE POINT DESERT CNTR, CALIF TYPE OF ACCIDENT STALL | | INTENDED DESTINATION LOCAL | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS FACTOR(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | |

APPENDIX B

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|----------------------------------|---|------------|--------|--------|---|---|
| | | | | F | S | M/N | | |
| 3-0875 | 4/21/73 | ERIE, COLO TIME - 1800 | AMER AVCO AAI N63466 DAMAGE-SUBSTANTIAL | CR- PX- | 1 0 | 0 0 | N/INC COMMERCIAL PLEASURE/PERSONAL TRNSP | COMMERCIAL • FL. INSTR. • AGE 24, 887 TOTAL HOURS, 40 IN TYPE, INSTRUMENT RATED. |
| | | DEPARTURE POINT BOULDER, COLO | INTENDED DESTINATION DENVER, COLO | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |

PROBABLE CAUSE(S)
 PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL
 PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
 MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
 REMARKS- ACFT ENTERED A SPIN. THEN WENT INTO A FLAT SPIN.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|--------|--------------------------------------|---|------------|--------|--------|--|---|
| | | | | F | S | M/N | | |
| 3-1865 | 6/4/73 | FAIRFIELD, CALIF TIME - 1330 | AMER AVCO AAI-B N9507L DAMAGE-DESTROYED | CR- PX- | 1 0 | 1 0 | INSTRUCTIONAL DUAL | COMMERCIAL • FL. INSTR. • AGE 57, 2244 TOTAL HOURS, 126 IN TYPE, INSTRUMENT RATED. |
| | | DEPARTURE POINT SAN RAFAEL, CALIF | INTENDED DESTINATION VACAVILLE, CALIF | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |

PROBABLE CAUSE(S)
 PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.
 PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
 REMARKS- ACFT PLACARDED-SPINS PROHIBITED. PLT FAILED TO USE ESTARD SPIN RECOVERY TECHNIQUE.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|----------------------------------|---|------------|--------|--------|--|---|
| | | | | F | S | M/N | | |
| 3-1881 | 6/15/73 | KEY WEST, FLA TIME - 1313 | CESSNA 150L N19279 DAMAGE-DESTROYED | CR- PX- | 1 0 | 0 0 | INSTRUCTIONAL SOLID | STUDENT, AGE 39, 20 TOTAL HOURS, ALL IN TYPE, NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT KEY WEST, FLA | INTENDED DESTINATION LOCAL | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |

PROBABLE CAUSE(S)
 PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
 MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
 REMARKS- ACFT CONTACTED GND IN A STEEP NOSE ON ATTITUDE.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|------------------------------|---|------------|--------|--------|------------------------------|--|
| | | | | F | S | M/N | | |
| 3-1898 | 7/31/73 | JAMPTON, IOWA TIME - 1458 | CESSNA 150H N721TS DAMAGE-DESTROYED | CR- PX- | 1 0 | 0 0 | COMMERCIAL POWER/PIPELINE | COMMERCIAL • FL. INSTR. • AGE 25, 2600 TOTAL HOURS, 2100 IN TYPE, INSTRUMENT RATED. |

| FILE | DATE | LOCATION | AIRCRAFT DATA | | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--|---------|--|---------------------------|------------|---------------------|--|--|
| | | | F | S | | | |
| 3-1898 | 7/31/73 | HAMPTON, IOWA TIME - 1458 | CESSNA 150H N7217S | CR- PX- | 1 0 0 0 | COMMERCIAL POWER/PIPELINE | COMMERCIAL FL. INSTR. AGE 25, 2600 TOTAL HOURS. 2100 IN TYPE. INSTRUMENT RATED. |
| DEPARTURE POINT MASSON CITY, IOWA TYPE OF ACCIDENT STALL SPIN | | INTENDED DESTINATION WATERLOO, IOWA | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - FAILED TO OBTAIN/Maintain FLYING SPEED MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING FIRE AFTER IMPACT REMARKS- LOST CTL DURING LOW LEVEL AEROBATIC MANEUVER. | | | | | | | |
| 3-1773 | 5/17/73 | ATHENS, GA TIME - 0606 | PITTS S1C N3192 | CR- PX- | 1 0 0 0 | NONCOMMERCIAL PRACTICE | COMMERCIAL AGE 24, 774 TOTAL HOURS, 14 IN TYPE, INSTRUMENT RATED. |
| NAME OF AIRPORT - ATHENS MUNICIPAL DEPARTURE POINT ATHENS, GA TYPE OF ACCIDENT STALL SPIN | | INTENDED DESTINATION LOCAL | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS PILOT IN COMMAND - FAILED TO OBTAIN/Maintain FLYING SPEED REMARKS- 10-15MIN CONT AEROBATICS.DRG VERT SNAP ROLL ENTRD SPIN, 2 TURNS 1 DIR REVERSED SPUN IN GTR DIR. | | | | | | | |
| 3-2483 | | | | | | | |
| 3-2527 | 9/12/73 | NR.HIDDENITE, NC TIME - 1715 | FAIRCHILD M-62C N9443H | CR- PX- | 0 0 0 1 | NONCOMMERCIAL PLEASURE/PERSONAL TRNSP | PRIVATE, AGE 25, 310 TOTAL HOURS, 54 IN TYPE, NOT INSTRUMENT RATED. |
| DEPARTURE POINT STATESVILLE, NC TYPE OF ACCIDENT STALL MUSH | | INTENDED DESTINATION BURNSVILLE, NC | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS PILOT IN COMMAND - FAILED TO OBTAIN/Maintain FLYING SPEED REMARKS- ACFT MUSHED INTO THE GND DURING WINGOVER.DAMAGED/PROP, BECAME AIRBORNE UN CONST FLT LNDG IN TREES. | | | | | | | |

APPENDIX B

- 50 -

| BRIEFS OF ACCIDENTS | | | | | | | | | |
|---------------------|---------|---|--|------------------------|------------------------------------|-------|---|------------|--|
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | | | PILOT DATA | |
| 3-2765 | 10/9/73 | MELBOURNE, FLA TIME - 1015 | CESSNA 150K N59046 DAMAGE-DESTROYED | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANS | PRIVATE, AGE 25, 86 TOTAL HOURS, 59, IN TYPE, NOT INSTRUMENT RATED. | | |
| | | DEPARTURE POINT MELBOURNE, FLA | INTENDED DESTINATION LOCAL | | | | | | |
| | | TYPE OF ACCIDENT STALL | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS PILOT IN COMMAND - FAILED TO OBTAIN/M AINTAIN FLYING SPEED | | | | | | | |
| | | FACTOR(S) PILOT IN COMMAND - MISJUDGED SPEED AND ALTITUDE | | | | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER | | | | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - ACFT CRASHED OFF-SHORE, NOT RCVRD. | | | | | | | |
| | | REMARKS- LO LVL ACROBATICS, ACFT | | | | | | | |
| 3-2849 | 9/2/73 | SAN LEON, TEX TIME - 1230 | ZLIN 7526 N3477 DAMAGE-SUBSTANTIAL | CR- 0 1 0 PX- 0 0 0 | NONCOMMERCIAL PRACTICE | TRANS | COMMERCIAL, AGE 46, 1200 TOTAL HOURS, 30 IN TYPE, NOT INSTRUMENT RATED. | | |
| | | DEPARTURE POINT LA PORTE, TEX | INTENDED DESTINATION LOCAL | | | | | | |
| | | TYPE OF ACCIDENT STALL SPIN | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE | | | | | | | |
| | | FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - DISREGARD OF GOOD OPERATING PRACTICE | | | | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER | | | | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - ALT EST 1200-1500FT IN PROCESS OF PULLING UP WHEN STRUCK WATER. | | | | | | | |
| | | REMARKS- ACFT ENTRD HI SPEED SPINNING STALL, ALT EST 1200-1500FT IN PROCESS OF PULLING UP WHEN STRUCK WATER. | | | | | | | |
| 3-3014 | 9/23/73 | HOLLY, MICH TIME - 1530 | CESSNA A150L N6047J DAMAGE-DESTROYED | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANS | PRIVATE, AGE 23, 130 TOTAL HOURS, 3 IN TYPE, NOT INSTRUMENT RATED. | | |
| | | DEPARTURE POINT SALEM, MICH | INTENDED DESTINATION LOCAL | | | | | | |
| | | TYPE OF ACCIDENT STALL SPIN | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL | | | | | | | |
| | | PILOT IN COMMAND - FAILED TO OBTAIN/M AINTAIN FLYING SPEED | | | | | | | |
| | | PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS | | | | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - LOW ALT ROLL NEAR RELATIVES HOUSE. | | | | | | | |
| | | REMARKS- LOST CTL DRG LOW ALT ROLL NEAR RELATIVES HOUSE. | | | | | | | |
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | | | PILOT DATA | |
| 4 3-3090 | 10/9/73 | FRANKLIN, IND TIME - 1250 | CORBIN B-ACE N10BA DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PRACTICE | TRANS | COMMERCIAL, FL. INSTR. AGE 22, 2050 TOTAL HOURS, 10 IN TYPE, INSTRUMENT RATED. | | |

BRIEFS OF ACCIDENTS

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | PHASE OF OPERATION | PILOT DATA |
|--------|----------|--|--|------------|--------|--------|----------------------------------|---|
| | | | | F | S | M/N | | |
| 3-3090 | 10/9/73 | FRANKLIN, IND TIME - 1250 | CORBIN B-ACE N10BA DAMAGE-DESTROYED | CR- PX- | 1 0 | 0 0 | NONCOMMERCIAL PRACTICE | COMMERCIAL, FL INSTR. AGE 22, 2050 TOTAL HOURS, 10 IN TYPE, INSTRUMENT RATED. |
| | | NAME OF AIRPORT - FRANKLIN FIELD DEPARTURE POINT FRANKLIN, IND | INTENDED DESTINATION LOCAL | | | | | |
| | | TYPE OF ACCIDENT STALL SPIN | | | | | IN FLIGHT AEROBATICS | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - CORRECTING LENSES-NOT USED REMARKS- ACFT-AEROBATICS PROHIBITED. LOOP OBSV'D FOLLOWED BY SNAP ROLL. ACFT CONT ROTATING NOSE DOWN TO IMPACT. | | | | | | |
| 3-3306 | 11/18/73 | SANTA FE, N MEX TIME - 1159 | BELLanca 8KCAB N36033 DAMAGE-DESTROYED | CR- PX- | 1 0 | 0 0 | MISCELLANEOUS AIR SHOW/RACING | AIRLINE TRANSPORT, AGE 46, 9700 TOTAL HOURS, UNK/NR IN TYPE, INSTRU- MENT RATED. |
| | | NAME OF AIRPORT - SANTA FE COUNTY DEPARTURE POINT SANTA FE, N MEX | INTENDED DESTINATION LOCAL | | | | IN FLIGHT AEROBATICS | |
| | | TYPE OF ACCIDENT STALL SPIN | | | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS FIRE AFTER IMPACT REMARKS- COMPLEX LOW ALT ROLL MANEUVER | | | | | | |
| 3-3848 | 12/16/73 | LETOHATCHEE, ALA TIME - 1245 | PITTS S-2A N80029 DAMAGE-DESTROYED | CR- PX- | 0 0 | 1 0 | NONCOMMERCIAL PRACTICE | COMMERCIAL, AGE 41, 2900 TOTAL HOURS, 54 IN TYPE, NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT MONTGOMERY, ALA | INTENDED DESTINATION LOCAL | | | | IN FLIGHT AEROBATICS | |
| | | TYPE OF ACCIDENT STALL SPIN | | | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS REMARKS- INTENTIONAL SPIN PLT DID NOT WAIT LONG ENOUGH WITH RECOVERY CTLS. GR DUG INTO GND DRG RCVR. | | | | | | |

APPENDIX B

- 52 -

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|---|--|------------|-------------|-------------|--|--|
| | | | | F | S | M/N | | |
| 3-3963 | 12/8/73 | SOUTH HAVEN, MICH TIME - 1723 | CHAMPION 7CAA N1122 DAMAGE-DESTROYED | CR- PX- | 1 0 0 | 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRNSP | COMMERCIAL, AGE 37, AD10, TOTAL HOURS. 10 IN TYPE, NOT INSTRUMENT RATED. |
| | | NAME OF AIRPORT - SOUTH HAVEN DEPARTURE POINT SOUTH HAVEN, MICH TYPE OF ACCIDENT STALL SPIN | INTENDED DESTINATION LOCAL | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |

PROBABLE CAUSE(S) - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.

PILOT IN COMMAND - MISJUDGED ALTITUDE

PILOT IN COMMAND - PHYSICAL IMPAIRMENT

PILOT IN COMMAND - UNWARRANTED LOW FLYING
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGEMENT
REMARKS - BLOOD ALCOHOL LVL 0.23 PCT. ACFT ALT EST FM 750F1 TO 1400FT. OWNERS MANUAL - 1000FT ACT LUST 3 TURNS.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|--------|-------------------------------|---|------------|-------------|-------------|---------------------------|--|
| | | | | F | S | M/N | | |
| 3-4122 | 9/9/73 | HOMESTEAD, FLA TIME - 1530 | PITTS S-1S N22XP DAMAGE-DESTROYED | CR- PX- | 1 0 0 | 0 0 0 | NONCOMMERCIAL PRACTICE | PRIVATE, AGE 34, 2200 TOTAL HOURS. ALL IN TYPE, NOT INSTRUMENT RATED. |

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|------|------|---|-------------------------------|----------|---|-----|--|------------|
| | | | | F | S | M/N | | |
| | | NAME OF AIRPORT - CURTIS PITTS DEPARTURE POINT HOMESTEAD, FLA TYPE OF ACCIDENT STALL SPIN | INTENDED DESTINATION LOCAL | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |

PROBABLE CAUSE(S)
PILOT IN COMMAND - MISJUDGED ALTITUDE
REMARKS - PLT ATMD PULL OUT AT LOW ALT.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|-----------------------------------|--|------------|-------------|-------------|-----------------------|---|
| | | | | F | S | M/N | | |
| 3-0118 | 1/28/74 | NR. MELBOURNE, FLA TIME - 1400 | CESSNA A150L N5930J DAMAGE-DESTROYED | CR- PX- | 1 0 0 | 0 0 0 | INSTRUCTIONAL SOLO | PRIVATE, AGE 22, 98 TOTAL HOURS. ALL IN TYPE, NOT INSTRUMENT RATED. |

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|------|------|---|-------------------------------|----------|---|-----|--|------------|
| | | | | F | S | M/N | | |
| | | DEPARTURE POINT MELBOURNE, FLA TYPE OF ACCIDENT STALL SPIN | INTENDED DESTINATION LOCAL | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |

PROBABLE CAUSE(S)
MISCELLANEOUS - UNDETERMINED
FACT(S)
PERSONNEL - OPERATIONAL SUPERVISORY PERSONNEL INADEQUATE GROUND TRAINING-PROCEDURES
MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO RESI IN WATER
REMARKS - MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO RESI IN WATER
ACFT OBSV'D SPIN INTO OCEAN NOT RCVRD. PLT PARACHUTED DRAGGED ACROSS WAVES WIND FILLED CHUTE-DRUNKEN

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|----------------------------|--|------------|-------------|-------------|----------------------------|---|
| | | | | F | S | M/N | | |
| 3-0394 | 2/20/74 | LEBANON, MD TIME - 0754 | CESSNA 414 N1628T DAMAGE-DESTROYED | CR- PX- | 1 0 0 | 0 0 0 | NONCOMMERCIAL CORP/EXEC | COMMERCIAL, AGE 31, 6380 TOTAL HOURS, 3200 IN TYPE. INSTRUMENT RATED. |

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|---|---|------------------------|--|---|
| | | | F S M/N | F | S M/N | |
| 3-0394 | 2/20/74 | LEBANON, MO TIME - 0754 | CESSNA 414 N1628T DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL CORP/EXEC | COMMERCIAL, AGE 31, 6380 TOTAL HOURS, 3200 IN TYPE, INSTRUMENT RATED. |
| | | NAME OF AIRPORT - LEBANON MUNICIPAL DEPARTURE POINT - LEBANON, MO TYPE OF ACCIDENT - STALL | | | | |
| | | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS PILOT IN COMMAND - FAILED TO OBTAIN/Maintain FLYING SPEED MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | |
| | | FACTOR(S) PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. FIRE AFTER IMPACT REMARKS- LOW LVL ACROBATICS OVER AIRPORT. STALL FOLLOWING RECOVERY FM RDLL. RETURN FM CORP/EXEC PSGR FLT. | | | | |
| 3-0831 | 4/23/74 | RIO RANCHO, N MEX TIME - 1624 | CESSNA A150L N6062J DAMAGE-DESTROYED | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 27, 150 TOTAL HOURS, 45 IN TYPE, NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT - ALBUQUERQUE, N MEX TYPE OF ACCIDENT - STALL | INTENDED DESTINATION LOCAL | | TRANSP | |
| | | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS PILOT IN COMMAND - FAILED TO OBTAIN/Maintain FLYING SPEED | | | | |
| 3-1033 | 3/31/74 | XENIA, OHIO TIME - 1605 | CHAMPION 7ECA N2536F DAMAGE-DESTROYED | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 23, 93 TOTAL HOURS, 67 IN TYPE, NOT INSTRUMENT RATED. |
| | | NAME OF AIRPORT - GREEN COUNTY DEPARTURE POINT - XENIA, OHIO TYPE OF ACCIDENT - STALL SPIN | INTENDED DESTINATION LOCAL | | TRANSP | |
| | | | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - FAILED TO OBTAIN/Maintain FLYING SPEED MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | |
| | | FACTOR(S) PILOT IN COMMAND - PHYSICAL IMPAIRMENT REMARKS- LOW ALT ACROBATICS. ENTERED SPIN, IN RCVR. PLT BLOOD ALCOHOL LVL 100MG%. | | | | |

APPENDIX B

- 54 -

| BRIEFS OF ACCIDENTS | | | | | | | | | |
|---------------------|---------|--|---|-------------------------------|--|---|--|--|--|
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA | | | |
| 3-1061 | 4/14/74 | NR.CLEAR LAKE, CALIF TIME - 1345 | STITS SA6B N6733C DAMAGE-DESTROYED INTENDED DESTINATION LOCAL | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRANSPO | PRIVATE, AGE 60, 461 TOTAL HOURS, 19 IN TYPE, NOT INSTRUMENT RATED. | | | |
| | | DEPARTURE POINT LOWER LAKE, CALIF TYPE OF ACCIDENT STALL | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED FACTOR(S), PILOT IN COMMAND - PHYSICAL IMPAIRMENT MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER REMARKS- LOW LEVEL ACROBATICS OVR LAKE. ACFT SANK. PLTS URINE ALCOHOL LVL 0.14%. | | | | | | | |
| 3-1103 | 5/27/74 | WESTERLO, NY TIME - 1330 | GILMORE 3D N7JG DAMAG-E-SUBSTANTIAL | CR- 0 0 1 PX- 0 0 0 | NONCOMMERCIAL PRACTICE | COMMERCIAL, FL-INSTR. AGE 64, 7000 TOTAL HOURS, 180 IN TYPE, NOT INSTRU- MENT RATED. | | | |
| | | NAME OF AIRPORT - DELP DEPARTURE POINT WESTERLO, NY TYPE OF ACCIDENT STALL SPIN | | INTENDED DESTINATION LOCAL | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE PILOT IN COMMAND - EXERCISED POOR JUDGMENT FACTOR(S), TERRAIN - HIGH OBSTRUCTIONS REMARKS- PLANNED 10 TURN SPIN FM 3300FT MSL WITH RCVRY AT 3000FT AGL HIT TREES DRG PULL-UP. | | | | | | | |
| 3-2077 | 7/20/74 | Mt.PLEASANT, TEX TIME - 0830 | KNIGHT TWST 85B N25C DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRANSPO | COMMERCIAL, FL-INSTR. AGE 43, UNK/NR TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED. | | | |
| | | DEPARTURE POINT Mt.PLEASANT, TEX TYPE OF ACCIDENT STALL SPIN | | INTENDED DESTINATION LOCAL | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED | | | | | | | |
| BRIEFS OF ACCIDENTS | | | | | | | | | |
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA | | | |
| 3-2152 | 8/16/74 | COLFAX, LA TIME - 0713 | PIPER PA-25 N8826L DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL FERRY | COMMERCIAL, AGE 33, 3631 TOTAL HOURS, 2566 IN TYPE, NOT INSTRUMENT RATED. | | | |
| | | DEPARTURE POINT | | | | | | | |

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--|-------------------------------|--------------------------------|---|------------------------|--|--|
| 3-2152 | 8/16/74 TIME - 0713 | COLFAX, LA | PIPER PA-25 N826L DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | MISCELLANEOUS FERRY | COMMERCIAL, AGE 33, 3631 TOTAL HOURS, 2566 IN TYPE, NOT INSTRUMENT RATED. |
| DEPARTURE POINT COLFAX, LA | INTENDED DESTINATION LOCAL | TYPE OF ACCIDENT STALL SPIN | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED FACTOR(S) PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS | | | | | | |
| PILOT IN COMMAND - EXERCISED POOR JUDGMENT MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | |
| 3-2262 | 7/22/74 TIME - 1525 | STUTTGART, ARK | AERONCA 7AC N82372 DAMAGE-DESTROYED | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL AERIAL SURVEY | NO CERTIFICATE, AGE 29, UNK/NR TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. |
| DEPARTURE POINT STUTTGART, ARK | INTENDED DESTINATION LOCAL | TYPE OF ACCIDENT STALL SPIN | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | |
| REMARKS- EXPIRED MED/STUDENT PLT CERTIFICATE. LOW LVL ACROBATICS. | | | | | | |
| 3-2303 | 6/29/74 TIME - 1805 | FAYETTEVILLE, NC | CESSNA 150L N19266 DAMAGE-SUBSTANTIAL | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRANSIT | COMMERCIAL, AGE 26, 369 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED. |
| DEPARTURE POINT FAYETTEVILLE, NC | INTENDED DESTINATION LOCAL | TYPE OF ACCIDENT STALL | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING FACTOR(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED | | | | | | |
| PILOT IN COMMAND - PHYSICAL IMPAIRMENT MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER | | | | | | |
| REMARKS- BLOOD ALCOHOL LVL 80 MG %. ACFT OBSV'D 2ND PASS. 90DEG L RANK. | | | | | | |

APPENDIX B

- 56 -

BRIEFS OF ACCIDENTS

| BRIEFS OF ACCIDENTS | | | PILOT DATA | | |
|---------------------|---------|---|--|------------------------|--|
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE |
| 3-2468 | 8/18/74 | KANKAKEE, ILL | PIPER J3C-65 N35258 DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PRACTICE |
| | | NAME OF AIRPORT - KOERNER DEPARTURE POINT KANKAKEE, ILL | INTENDED DESTINATION LOCAL | | PRIVATE, AGE 43, 705 TOTAL HOURS, 72 IN TYPE, NOT INSTRUMENT RATED. |
| | | TYPE OF ACCIDENT STALL SPIRAL | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. | | | |
| | | FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | |
| | | REMARKS- LOW LVL ACROBATICS, PRACTICING AIR SHOW. | | | |
| 3-3018 | 9/11/74 | WAYNESVILLE, NC | BOEING AT5L3 N5118N DAMAGE-DESTROYED | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL |
| | | NAME OF AIRPORT - JONATHAN CREEK DEPARTURE POINT WAYNESVILLE, NC | INTENDED DESTINATION LOCAL | TRANS TRANSP | COMMERCIAL, AGE 35, 1000 TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. |
| | | TYPE OF ACCIDENT STALL SPIN | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PILOT IN COMMAND - MISJUDGED ALTITUDE | | | |
| | | FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | |
| | | REMARKS- DEMONSTRATING ACROBATICS INCLUDING INTENTIONAL SPINS | | | |
| 3-3231 | 9/11/74 | CLAXTON, GA | AREZY NP2 N1276 DAMAGE-SUBSTANTIAL | CR- 0 0 1 PX- 0 0 0 | NONCOMMERCIAL PRACTICE |
| | | DEPARTURE POINT CLAXTON, GA | INTENDED DESTINATION LOCAL | | PRIVATE, AGE 43, 1000 TOTAL HOURS, 40 IN TYPE, NOT INSTRUMENT RATED. |
| | | TYPE OF ACCIDENT STALL SPIN | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED | | | |
| | | FACTOR(S) PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS | | | |
| | | REMARKS- PILOT ATMD L SPIN ACFT SPUN R. ACFT ENTRD FLAT SPIN ORG RCVRY. | | | |
| BRIEFS OF ACCIDENTS | | | PILOT DATA | | |
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE |
| 3-3276 | 10/7/74 | SIMERVILLE, TENN | BOEING 75 | CR- 1 0 0 | NONCOMMERCIAL |
| | | | | | COMMERCIAL, FL-INSTR. |

ARTICLES OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | FLIGHT PURPOSE | PILOT DATA |
|--------|-------------------------|---|-------------------------------|------------------------|--|---|
| | | | F S M/N | F S | | |
| 3-3276 | 10/7/74 TIME - 1455 | SOMERVILLE, TENN | BOEING 75 N66489 | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | COMMERCIAL, FL. INSTR. AGE 30, 450 TOTAL HOURS, 200 IN TYPE, INSTRUMENT RATED. |
| | | NAME OF AIRPORT - OZIER FIELD | DAMAGE-DESTROYED | | TRANS | |
| | | DEPARTURE POINT SOMERVILLE, TENN | INTENDED DESTINATION LOCAL | | | |
| | | TYPE OF ACCIDENT STALL SPIN | | | PHASE OF OPERATION IN FLIGHT AEROBATICS | |
| | | PROBABLE CAUSE(S) | | | | |
| | | PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED REMARKS- ACFT OBSV'D TO SPIN OUT OF A LOOP.PRIOR TO GND IMPACT NOSE RAISED ABV LVL ATTITUDE, THEN DROPPED. | | | | |
| 3-3673 | 11/11/74 TIME - 1330 | FAIRVIEW, OKLA | PIPER J-3 N1564N | CR- 0 1 0 PX- 0 0 0 | MISCELLANEOUS AIR SHOW/RACING | COMMERCIAL, AGE 57, 470 TOTAL HOURS, 300 IN TYPE, NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT FAIRVIEW, OKLA | DAMAGE-DESTROYED | | | |
| | | TYPE OF ACCIDENT STALL SPIN | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT AEROBATICS | |
| | | PROBABLE CAUSE(S) | | | | |
| | | PILOT IN COMMAND - MISJUDGED ALTITUDE REMARKS- PLT ENTRD INTNL SPN AT 500FT. DIDNT RECDVR FULLY BEFR STRKNG GRND. | | | | |
| 3-4023 | 12/29/74 TIME - 1530 | NR. NEWARK, CALIF | AMER AVCO AA1-A N9443L | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | STUDENT, AGE 39, 74 TOTAL HOURS, 3 IN TYPE, NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT SAN CARLOS, CALIF | DAMAGE-DESTROYED | | TRANS | |
| | | TYPE OF ACCIDENT STALL | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT AEROBATICS | |
| | | PROBABLE CAUSE(S) | | | | |
| | | PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING FACTORS | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER REMARKS- LOST CTL DRG LOW ALT WING DVR.CRASHED IN SALT EVAPORATIVE TANK. | | | | |

APPENDIX B

- 58 -

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|----------|---|---|------------|--------|--------|------------------------------------|---|
| | | | | F | S | M/N | | |
| 3-4197 | 12/21/74 | NR. BRUNSWICK, OHIO TIME - 1115 | PIPER PA-11 N4703M DAMAGE-DESTROYED | CR- PX- | 1 1 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 43, 225 TOTAL HOURS, 66 IN TYPE, NOT INSTRUMENT RATED. |
| | | NAME OF AIRPORT - BRUNSWICK DEPARTURE POINT VALLEY CITY, OHIO | INTENDED DESTINATION LOCAL | | | | TRANSP | |

PHASE OF OPERATION
IN FLIGHT ACROBATICS

PROBABLE CAUSE(S)

PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
PILOT IN COMMAND - FAILED TO OBTAIN/MAINTAIN FLYING SPEED
PILOT IN COMMAND - UNWARRANTED LOW FLYING

MISCELLANEOUS ACTS, CONDITIONS

TERRAIN - SNOW-COVERED
REMARKS - PERFORMED LOOP AFTER RECOVERY ENTERED SPIN FM ABT 500FT AGL.

NATIONAL TRANSPORTATION SAFETY BOARD

WASHINGTON, D.C. 20594

BRIEFS OF ACCIDENTS

ACROBATIC-INFLIGHT PHASE OF OPERATION

1974 AIRCRAFT ACCIDENT REPORTS

WASHINGTON, D.C. 20594

BRIEFS OF ACCIDENTS

ACROBATIC-INFLIGHT PHASE OF OPERATION

1ST TYPE ACCIDENT-AIRFRAME FAILURE IN FLIGHT

U.S. GENERAL AVIATION

1972 THRU 1974

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | FLIGHT PURPOSE | PILLOT DATA |
|--------|------------------------|--|--|------------|----------------|--|
| | | | F S M/N | F | S M/N | |
| 3-0152 | 5/10/72 TIME - 1720 | MERCED, CALIF | PITTS S-1S N98X DAMAGE-DESTROYED | CR- PX- | 1 0 0 0 | NONCOMMERCIAL PRACTICE |
| | | NAME OF AIRPORT - MERCED DEPARTURE POINT MERCED, CALIF | INTENDED DESTINATION LOCAL | | | COMMERCIAL, AGE 42, 3000 TOTAL HOURS, 100 IN TYPE, INSTRUMENT RATED. |
| | | TYPE OF ACCIDENT AIRFRAME FAILURE IN FLIGHT COLLISION WITH GROUND/WATER | PHASE OF OPERATION IN FLIGHT ACROBATICS IN FLIGHT UNCONTROLLED DESCENT | | | |
| | | PROBABLE CAUSE(S) AIRFRAME - WINGS OTHER MISCELLANEOUS ACTS, CONDITIONS - MATERIAL FAILURE | | | | |
| | | FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - SEPARATION IN FLIGHT | | | | |
| | | FIRE AFTER IMPACT | | | | |
| | | REMARKS- LWR R WING DISINTEGRATED DURG LOW LVL PRACT FOR AIR SHOW, CAUSE OF MAIL FAILURE NOT DETERMINED. | | | | |
| 3-1132 | 8/3/72 TIME - 1534 | MIAMI, FLA | PITTS SPCL S-2A N8028 DAMAGE-SUBSTANTIAL | CR- PX- | 0 0 0 0 | INSTRUCTIONAL DUAL |
| | | DEPARTURE POINT MIAMI, FLA | INTENDED DESTINATION LOCAL | | | COMMERCIAL, FL. INSTR. AGE 34, 2550 TOTAL HOURS, 253 IN TYPE, INSTRUMENT RATED. |
| | | TYPE OF ACCIDENT AIRFRAME FAILURE IN FLIGHT NOSE OVER/DOWN | PHASE OF OPERATION IN FLIGHT ACROBATICS LANDING ROLL | | | |
| | | PROBABLE CAUSE(S) AIRFRAME - FLIGHT CONTROL SURFACES HORIZONTAL STABILIZER, ATTACHMENTS | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - FATIGUE FRACTURE | | | | |
| | | TERRAIN - WET, SOFT GROUND | | | | |
| | | EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND | | | | |
| | | REMARKS- R HORIZ STAB FWD ATTACH TIRE FAILED DURING 2 PT ROLL. PLT HAD TO LND FAST IN PLOWED FLD. | | | | |

APPENDIX B

- 60 -

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|--------|-----------------------------|--|-----------|---------------|-----|---|------------|
| | | | | F | S | M/N | | |
| 3-1184 | 7/4/72 | MCDONALD, PA TIME - 1225 | ERCO 415-C N94031 DAMAGE-DESTROYED | CR- 1 0 0 | NONCOMMERCIAL | | PRIVATE, AGE 26, UNK/NR TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. | |

NAME OF AIRPORT - CAMPBELLS
DEPARTURE POINT - UNKNOWN/NOT REPORTED
BRIDGEVILLE, PA
TYPE OF ACCIDENT - AIRFRAME FAILURE IN FLIGHT
AIRFRAME WITH GROUND/WATER UNCONTROLLED

PROBABLE CAUSE(S)

PILOT IN COMMAND - EXERCISED POOR JUDGMENT
PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING

FACTORS(S)

AIRFRAME - FLIGHT CONTROL SURFACES, AILERON SURFACES, ATTACHMENTS
MISCELLANEOUS ACTS, CONDITIONS - CORRODED/CORROSION

MISCELLANEOUS ACTS, CONDITIONS - FLUTTER

MISCELLANEOUS ACTS, CONDITIONS - SEPARATION IN FLIGHT
REMARKS- R AILERON COUNTER WEIGHT SEPARATED IN FLT DURING LOW LEVEL AEROBATICS OVER PLTS HOME.

| | | | | | | |
|--------|---------|--------------------------------------|--|-----------|--|--|
| 3-1545 | 6/18/73 | GONZALES, CALIF TIME - 1545 | HAZARD-TURN T-40H N13HH DAMAGE-DESTROYED | CR- 2 0 0 | MISCELLANEOUS | COMMERCIAL, AGE 38, 3567 TOTAL HOURS, 4 IN TYPE, INSTRUMENT RATED. |
| | | | | PX- 0 0 0 | TEST | |
| | | DEPARTURE POINT MINTERY, CALIF | INTENDED DESTINATION UNKNOWN/NOT REPORTED | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | TYPE OF ACCIDENT AIRFRAME FAILURE | IN FLIGHT | | | |

PROBABLE CAUSE(S)

AIRFRAME - WINGS, SPARS

PERSONNEL - PRODUCTION-DESIGN-PERSONNEL

FACTORS(S)

MISCELLANEOUS ACTS, CONDITIONS - OVERLOAD FAILURE

REMARKS- R WG MN SPAR AT R STRUT ATTACH PT WEAKENED BY MISLOCATED DRILLED HOLES.

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|----------|---------------|----------|----------------|------------|
| 3-2334 | 8/23/72 | UNKN ... | | | | |

| BRIEFS OF ACCIDENTS | | | | | | | | | | | | | | | |
|---|---------|--|--|--|------------------------------------|-----------------|--|--|--|--|--|--|--|--|--|
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F M/N | FLIGHT PURPOSE | | PILOT DATA | | | | | | | | |
| 3-2334 | 8/23/73 | HOMER, NY TIME - 1830 | JEANIES TEENIE N31JT DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANS TRANSP | NO CERTIFICATE, AGE 41. UNK/NR TOTAL HOURS, UNK/NR IN TYPE. NOT INSTRUMENT RATED. | | | | | | | | |
| NAME OF AIRPORT - BERD DEPARTURE POINT HOMER, NY | | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | | | | | | | | | |
| TYPE OF ACCIDENT AIRFRAME FAILURE | | IN FLIGHT | | | | | | | | | | | | | |
| PROBABLE CAUSE(S) SYSTEMS - FLIGHT CONTROL SYSTEMS RUDDER AND RUDDER TAB CONTROL SYSTEM MISCELLANEOUS ACTS, CONDITIONS - DISCONNECTED PERSONNEL - MAINTENANCE, SERVICING, INSPECTION INADEQUATE MAINTENANCE AND INSPECTION | | | | | | | | | | | | | | | |
| FACTORS MISCELLANEOUS - UNQUALIFIED PERSON OPERATED AIRCRAFT REMARKS - ROD END BEARING ATTACH PUSH-PULL TORQUE TUBE TO RUDDER CTL HORN FAILED. PLT UNCERTIFICATED. | | | | | | | | | | | | | | | |
| 3-3704 | | 10/6/73 MORRIS, ILL TIME - 1100 | BELLanca 7GCBC N36334 DAMAGE-DESTROYED | CR- 1 0 0 PX- 1 0 0 | NONCOMMERCIAL BUSINESS | TRANS TRANSP | PRIVATE, AGE 28, 303 TOTAL HOURS, 12 IN TYPE, NOT INSTRUMENT RATED. | | | | | | | | |
| DEPARTURE POINT MORRIS, ILL | | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | | | | | | | | | |
| TYPE OF ACCIDENT AIRFRAME FAILURE | | IN FLIGHT | | | | | | | | | | | | | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS PILOT IN COMMAND - EXCEEDED DESIGNED STRESS LIMITS OF AIRCRAFT MISCELLANEOUS ACTS, CONDITIONS - OVERLOAD FAILURE REMARKS - ENTERED ACRORATIC MANEUVER AT TOO LOW ALT TO EFFECT SAFE RECOVERY. R WING FAILED. | | | | | | | | | | | | | | | |
| 3-1676 | | 5/24/74 NR.GILDROY, CALIF TIME - 1700 | BELLanca 8KCAB N41817 DAMAGE-SUBSTANTIAL | CR- 0 0 1 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANS TRANSP | COMMERCIAL FL. INSTR. AGE 30, 2968 TOTAL HOURS, 8 IN TYPE, INSTRUMENT RATED. | | | | | | | | |
| NAME OF AIRPORT - SOUTH COUNTY DEPARTURE POINT SAN JOSE, CALIF | | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | | | | | | | | | | |
| TYPE OF ACCIDENT AIRFRAME FAILURE | | IN FLIGHT | | | | | | | | | | | | | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - EXCEEDED DESIGNED STRESS LIMITS OF AIRCRAFT PILOT IN COMMAND - INCAPACITATION REMARKS - PLT STATED HE BLACKED OUT DRG HI G LOADS. BOTH WGS DEFORMED. PLT LND OK. | | | | | | | | | | | | | | | |

APPENDIX B

- 62 -

BRIEFS OF ACCIDENTS

| | | PILOT DATA | | | |
|--------|---|---|---------------------|--|---|
| FILE | DATE | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | |
| 3-1997 | 7/17/74 TIME - 1330 | BEDE BD-5J N152BD INTENDED DESTINATION LOCAL | CR- 0 1 PX- 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | COMMERCIAL. AGE 27. 4592 TOTAL HOURS. 79 IN TYPE. INSTRUMENT RATED. |
| | DEPARTURE POINT NEWTON, KANS | TYPE OF ACCIDENT AIRFRAME FAILURE | IN FLIGHT | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | | | | PROBABLE CAUSE(S) AIRFRAME - FUSELAGE WINDSHIELDS, WINDSHIELDS, CANOPIES MISCELLANEOUS ACTS, CONDITIONS - MATERIAL FAILURE REMARKS - STEEP DESCENT-230KTS (VNE 250KTS). CANOPY FAILED HITTING PLT IN HEAD. ACFT SUBJECT TO APPROX 15G. |
| 3-2076 | 5/27/74 TIME - 1141 | MAY FLYBABY 1 N93003 DAMAGE-DESTROYED | CR- 1 0 PX- 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 54. 1925 TOTAL HOURS. 3 IN TYPE. NOT INSTRUMENT RATED. |
| | NAME OF AIRPORT - PRIVATE STRIP DEPARTURE POINT SALEM, OREG | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | TYPE OF ACCIDENT AIRFRAME FAILURE | IN FLIGHT | | | |
| | | | | | PROBABLE CAUSE(S) PILOT IN COMMAND - EXCEEDED DESIGNED STRESS LIMITS OF AIRCRAFT PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. |
| | | | | | FACTOR(S) AIRFRAME - WINGS SPARS MISCELLANEOUS ACTS, CONDITIONS - OVERLOAD FAILURE MISCELLANEOUS ACTS, CONDITIONS - SEPARATION IN FLIGHT MISCELLANEOUS ACTS, CONDITIONS - PROHIBITED LOOP MANEUVERS. |
| | | | | | REMARKS - RIGHT WING SEPARATED DURING PROHIBITED LOOP MANEUVERS. |
| 3-4120 | 12/21/74 TIME - 1415 | AVION MUDRY CAPTOR N80DE DAMAGE-DESTROYED | CR- 0 0 PX- 0 0 | INSTRUCTIONAL DUAL | COMMERCIAL. FL. INSTR.** AGE 26. 730 TOTAL HOURS. 300 IN TYPE. NOT INSTRUMENT RATED. |
| | DEPARTURE POINT VERBANK, NY | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | TYPE OF ACCIDENT AIRFRAME FAILURE | IN FLIGHT | | | |
| | | | | | PROBABLE CAUSE(S) PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING MISCELLANEOUS - FOREIGN MATERIAL AFFECTING NORMAL OPERATIONS SYSTEMS - FLIGHT CONTROL SYSTEMS, ELEVATOR AND ELEVATOR TAB CONTROL SYSTEM MISCELLANEOUS ACTS, CONDITIONS - JAMMED REMARKS - PREFLT, CARLIE TENSION TOOL INADVERTENTLY LEFT ON RUDDER CABLE JAMMED ELEV BELLCRANK. PARACHUTED OK. |

NATIONAL TRANSPORTATION SAFETY BOARD

WASHINGTON, D. C. 20594

BRIEFS OF ACCIDENTS

NATIONAL TRANSPORTATION SAFETY BOARD

WASHINGTON, D. C. 20594

BRIEFS OF ACCIDENTS

ACROBATIC-INFLIGHT PHASE OF OPERATION

1ST TYPE ACCIDENT-COLLISION WITH GROUND/WATER,

WIRES/POLES AND TREES

U.S. GENERAL AVIATION

1972 THRU 1974

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | FLIGHT PURPOSE | PILOT DATA |
|--------|--|-----------------|---|------------------------|--|--|
| | | | F S M/N | F S M/N | | |
| 3-0151 | 5/12/72 | WOODLAKE, CALIF | PIITTS S-1S N1151H | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PRACTICE | COMMERCIAL, AGE 43, 2200 TOTAL HOURS, 150 IN TYPE, NOT INSTRUMENT RATED. |
| | TIME - 1900 | | DAMAGE-DESTROYED INTENDED DESTINATION LOCAL | | | |
| | DEPARTURE POINT WOODLAKE, CALIF | | | | PHASE OF OPERATION IN FLIGHT AEROBATICS | |
| | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | | CONTROLLED | | | |
| | PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE | | | | | |
| | FIRE AFTER IMPACT | | | | | |
| | REMARKS- PRACTICING FOR AIR SHOW. HIT GND DURING RECOVERY FROM AEROBATIC MANEUVER. | | | | | |
| 3-0284 | 1/18/72 | SANGER, TEX | CHAMPION 76CAC N5081X | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | AIRLINE TRANSPORT, AGF IN TYPE, INSTRUMENT RATED. |
| | TIME - 1740 | | DAMAGE-DESTROYED INTENDED DESTINATION LOCAL | | | |
| | DEPARTURE POINT SANGER, TEX | | | | PHASE OF OPERATION IN FLIGHT AEROBATICS | |
| | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | | CONTROLLED | | | |
| | PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE | | | | | |
| | REMARKS- ACFT ENTERED SPIN APPROX 1500FT AGL, SPIN WAS ARRESTED TWO LOW-HIT GND IN STEEP NOSE-DOWN ATTITUDE. | | | | | |

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|---|--|------------------------|--|---|
| 3-0446 | 5/10/72 | PERRIS, CALIF TIME - 1410 | STARDUSTER SA-300 N14257 DAMAGE-SUBSTANTIAL | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PRACTICE | COMMERCIAL, AGE 52, UNK/NR TOTAL HOURS, 200 IN TYPE, NOT INSTRUMENT RATED. |
| | | NAME OF AIRPORT - PERRIS VALLEY DEPARTURE POINT - PERRIS, CALIF TYPE OF ACCIDENT - COLLISION WITH GROUND/WATER REMARKS - AT GRND, AT ALMOST LEVEL ALTITUDE DURING LOW ALT SPLITS RECOVERY, PRACTICE FOR FUTURE AIR SHOW. | INTENDED DESTINATION LOCAL COLLISION WITH GROUND/WATER CONTROLLED | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |

PROBABLE CAUSE(S)

PILOT IN COMMAND - MISJUDGED ALTITUDE

REMARKS - AT GRND, AT ALMOST LEVEL ALTITUDE DURING LOW ALT SPLITS RECOVERY, PRACTICE FOR FUTURE AIR SHOW.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--------|--------|--|--|------------------------|--|--|
| 3-0462 | 6/3/72 | MR. SOUTH BEND, IND TIME - 1755 | CESSNA 188A N9936G DAMAGE-SUBSTANTIAL | CR- 1 0 0 PX- 0 0 0 | COMMERCIAL AERIAL APPLICATION | COMMERCIAL, AGE 46, 12000 TOTAL HOURS, 451 IN TYPE, NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT - NEW CARLISLE, IND TYPE OF ACCIDENT - COLLISION WITH GROUND/WATER REMARKS - AT GRND, AT ALMOST LEVEL ALTITUDE DURING LOW ALT SPLITS RECOVERY, PRACTICE FOR FUTURE AIR SHOW. | INTENDED DESTINATION LOCAL COLLISION WITH GROUND/WATER UNCONTROLLED | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |

PROBABLE CAUSE(S)

PILOT IN COMMAND - EXERCISED POOR JUDGMENT

FACTORS - PILOT IN COMMAND - PHYSICAL IMPAIRMENT

MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT

MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING

SPECIAL DATA

TOTAL HOURS IN CROP CONTROL - 9000

KIND OF CROP - BEANS

PILOT'S SEAT BELT - FASTENED-PROPERLY

GOGGLES - USED

COCKPIT CRASHPAD - INSTALLED

TANK/HOPPER-LOCATION - FORWARD OF PILOT

ELEVATION-AREA BEING TREATED-FEET - 285

REMARKS - PLT ATTEMPTED LOW ALT ROLL AFTER SEEDING COMPLETED. BLOOD ALCOHOL LEVEL 0.076 PCT.

KIND OF OPERATION - SEEDING CROP
 TYPE OF CHEMICAL USED - UNKNOWN,
 GLOVES - USED
 CRASH HELMET - AVAILABLE-USED
 CRASH BAR - INSTALLED
 TERRAIN-TYPE - LEVEL, FLAT
 SWATH RUN-TOW FLOWN - DOWN
 SWATH RUN-TOW FLOWN - DOWN
 SWATH RUN-TOW FLOWN - DOWN
 REMARKS - PLT ATTEMPTED LOW ALT ROLL AFTER SEEDING COMPLETED. BLOOD ALCOHOL LEVEL 0.076 PCT.

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|----------------------------------|--|------------------------|---------------------------|---|
| 3-0487 | 6/15/72 | CRYSTAL LAKE, ILL TIME - 1155 | LOWERS BIRD N591T DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PRACTICE | 4191 TOTAL HOURS, 27 IN TYPE, INSTRUMENT RATED. |

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA | |
|----------|---------------------|---|---|---------------------|--|--|--|
| | | | | | | CR- | PX- |
| 3-0487 | 6/15/72 TIME - 1155 | CRYSTAL LAKE, ILL | LOWERS BIRD N591T DAMAGE-DESTROYED | 0 0 0 0 0 0 | NONCOMMERCIAL PRACTICE | AIRLINE TRANSPORT, AGE 30, IN TYPE, INSTRUMENT RATED. | AIRLINE TRANSPORT, AGE 30, 4191 TOTAL HOURS, ?7 IN TYPE, INSTRUMENT RATED. |
| | | NAME OF AIRPORT - CRYSTAL LAKE DEPARTURE POINT CRYSTAL LAKE, ILL | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | |
| | | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | CONTROLLED | | | | |
| | | PROBABLE CAUSE(S) FACTORS) | PILOT IN COMMAND - MISJUDGED ALTITUDE | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | MISSING AIRCRAFT - LATER RECOVERED | | | | |
| | | REMARKS- OBS SAW ACFT ROLLING IN 45 DEG DIVE. DIDNT SEE IMPACT. RECOVERED FROM SWAMP 6/15/72. CHUTE NOT USED | | | | | |
| 3-1091 | 7/30/72 TIME - 1845 | WINDSOR, VA | CHAMPION 7KCAB N7564F DAMAGE-DESTROYED | 0 0 0 0 1 0 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 22, 500 TOTAL HOURS, 100 IN TYPE, NOT INSTRUMENT RATED. | |
| | | DEPARTURE POINT WAKEFIELD, VA | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | |
| | | TYPE OF ACCIDENT COLLIDED WITH TREES | | | | | |
| | | PROBABLE CAUSE(S) FACTORS) | PILOT IN COMMAND - EXERCISED POOR JUDGMENT | | | | |
| | | PILOT IN COMMAND - MISJUDGED ALTITUDE | MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | |
| | | REMARKS- OBS SAW PLT PERFORM 2 LOW ALT ROLLS AND LOOPS. THEN PLT SPUN FROM HAMMERHEAD. HIT TREES ON RECOVERY. | | | | | |
| ✓ 3-1176 | 8/12/72 TIME - 1345 | SHERRILLS FORD, NC | CHAMPION 7GCAA N6398N DAMAGE-DESTROYED | 0 0 0 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | COMMERCIAL, AGE 39, 1873 TOTAL HOURS, 63 IN TYPE, INSTRUMENT RATED. | |
| | | NAME OF AIRPORT - LONG ISLAND | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | |
| | | DEPARTURE POINT HICKORY, NC | | | | | |
| | | TYPE OF ACCIDENT COLLIDED WITH TREES | | | | | |
| | | PROBABLE CAUSE(S) FACTORS) | PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE | | | | |
| | | REMARKS- PLT MEDICAL RESTRICTION-GLASSES FOR DISTANT VISION. NO CORRECTING LENSES FOUND. RECOVERY FROM SPIRAL | | | | | |

APPENDIX B

- 66 -

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | | | INJURIES | | FLIGHT PURPOSE | | PILOT DATA |
|---|--------|--------------------|------------------------------|------------|--------|----------|------------------------------------|----------------|--|--|
| | | | F | M | N | CR- | 1 | 0 | NONCOMMERCIAL | |
| 3-1672 | 7/6/72 | THIEF RVR FL, MINN | N AMERICAN SNJ-4 N7056C | CR- PX- | 1 0 | 0 0 | PLEASURE/PERSONAL | TRANS P | COMMERCIAL, AGE 38, | 8020 TOTAL HOURS. 250 IN TYPE, INSTRUMENT RATED. |
| NAME OF AIRPORT - THIEF RIVER FALLS DEPARTURE POINT - THIEF RVR FL, MINN TYPE OF ACCIDENT - COLLISION WITH GROUND/WATER REMARKS - DAMAGE-DESTROYED | | | | | | | | | | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - MISJUDGED SPEED AND ALTITUDE MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING REMARKS - LOW LEVEL AEROBATICS. | | | | | | | | | | |
| 3-2321 | 7/2/72 | LOVINGTON, N MEX | TAYLORCRAFT BC12-D N501GM | CR- PX- | 1 0 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANS P | PRIVATE, AGE 34. | 440 TOTAL HOURS. 63 IN TYPE, NOT INSTRUMENT RATED. |
| NAME OF AIRPORT - LEA CNTY-LOVINGTON DEPARTURE POINT - LOVINGTON, N MEX TYPE OF ACCIDENT - COLLISION WITH GROUND/WATER REMARKS - SLOW ROLL OVR RWY, OUTSIDE AERD AREA. | | | | | | | | | | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - MISJUDGED ALTITUDE FACTOR(S), PILOT IN COMMAND - LACK OF FAMILIARITY WITH AIRCRAFT REMARKS - BARREL ROLL, LONG SLOW ROLL, APRX 700-1600FT AGL. | | | | | | | | | | |
| 3-3705 | 8/7/72 | MCCORDSVILLE, IND | CHAMPION 7EC N16236 | CR- PX- | 1 0 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANS P | COMMERCIAL, FL. INSTR. AGE 24, 1693 TOTAL HOURS, 349 IN TYPE, INSTRUMENT RATED. | |
| NAME OF AIRPORT - BROOKSIDE DEPARTURE POINT - GREENWOOD, IND TYPE OF ACCIDENT - COLLISION WITH GROUND/WATER REMARKS - | | | | | | | | | | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - MISJUDGE ALTITUDE FACTOR(S), PILOT IN COMMAND - LACK OF FAMILIARITY WITH AIRCRAFT REMARKS - BARREL ROLL, LONG SLOW ROLL, APRX 700-1600FT AGL. | | | | | | | | | | |

✓

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | | | INJURIES | | FLIGHT PURPOSE | | PILOT DATA |
|--------|---------|------------------|-----------------------|------------|--------|----------|---------------|----------------|---------------------|--------------------------------|
| | | | F | M | N | F | S | M/N | PRACTICE | |
| 3-4154 | 3/13/72 | CARSON CITY, NEV | PITTS SC-1 N70703R | CR- PX- | 1 0 | 0 0 | NONCOMMERCIAL | TRANS P | COMMERCIAL, AGE 31, | 3599 TOTAL HOURS. UNK/NR TN |

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|---|--|----------|--------|--|--|
| | | | | F | S | | |
| 3-4154 | 3/13/72 | CARSON CITY, NEV TIME - 1010 | PITTS SC-1 N203R DAMAGE-DESTROYED | CR- 0 | 1 0 | NONCOMMERCIAL PRACTICE | COMMERCIAL, AGE 31, 3599 TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT CARSON CITY, NEV | INTENDED DESTINATION LOCAL | | | | |
| | | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | UNCONTROLLED | | | PHASE OF OPERATION IN FLIGHT AEROBATICS | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING REMARKS- DURING LOW LEVEL AEROBATICS ACFT DOVE TO GND IN VERT NOSE DOWN ATT. | | | | | |
| 3-0126 | 1/30/73 | AURORA, COLO TIME - 1800 | BELLanca 17-31A N3960 DAMAGE-DESTROYED | CR- 0 | 2 0 | MISCELLANEOUS DEMONSTRATION | PRIVATE, AGE 29, 64 TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT BROOMFIELD, COLO | INTENDED DESTINATION RETURN | | | LAST ENROUTE STOP LITTLETON, COLO | |
| | | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | CONTROLLED | | | PHASE OF OPERATION IN FLIGHT AEROBATICS | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - MISJUDGED CLEARANCE FACTOR(S) MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING MISSING AIRCRAFT - LATER RECOVERED | | | | | |
| | | REMARKS- HIT GRND R WG FIRST IN HI SPEED ROLLING TYPE MANEUVER. RECOVERED 1/31/73. | | | | | |
| 3-0276 | 3/17/73 | MADERA, CALIF TIME - 1240 | CHAMPION 7KCAB N9027L DAMAGE-DESTROYED | CR- 0 | 1 0 | NONCOMMERCIAL PLEASURE/PERSONAL | COMMERCIAL, AGE 55, 14301 TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. |
| | | NAME OF AIRPORT - MADERA MADERA, CALIF | INTENDED DESTINATION LOCAL | | | | |
| | | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | CONTROLLED | | | PHASE OF OPERATION IN FLIGHT AEROBATICS | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - MISJUDGED ALTITUDE REMARKS- ATTEMPTED AEROBATICS AT LOW ALTITUDE. | | | | | |

APPENDIX B

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|----------|------------------------|---|---|------------|--------|--------|-----------------------------------|--|
| | | | | F | S | M/N | | |
| ✓ 3-0452 | 3/23/73 TIME - 1747 | LIVERMORE, CALIF NAME OF AIRPORT - LIVERMORE DEPARTURE POINT LIVERMORE, CALIF TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | CESSNA 180A N7869A DAMAGE-DESTROYED | CR- PX- | 1 0 | 0 0 | MISCELLANEOUS PARAJUMP (SPORT) | COMMERCIAL, AGE 50, 4803 TOTAL HOURS, 4 IN TYPE, NOT INSTRUMENT RATED. |
| | | | | | | | | |
| | | | | | | | | |

PROBABLE CAUSE(S)
 PILOT IN COMMAND - EXERCISED POOR JUDGMENT
 PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
 MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
 FACTOR(S)
 MISCELLANEOUS ACTS, CONDITIONS - SEAT BELT NOT FASTENED
 REMARKS- FOLLOWED PARACHUTISTS TO GRND, BUZZED DROP ZONE, THEN LOST CTL IN LOW ALT AEROBATICS MANEUVER.

| | | | | | | | | | |
|--------|------------------------|---|---|------------|--------|--------|------------------------------------|--------|--|
| 3-1894 | 7/15/73 TIME - 1330 | PINETOPS, NC NAME OF AIRPORT - PINETOPS-HEDGEDEPTH DEPARTURE POINT PINETOPS, NC TYPE OF ACCIDENT COLLIDED WITH TREES | BELLanca 17-30A N8867V DAMAGE-DESTROYED | CR- PX- | 1 3 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANSP | PRIVATE, AGE 52, 1800 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED. |
| | | | | | | | | | |
| | | | | | | | | | |

PROBABLE CAUSE(S)
 MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
 PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
 FACTOR(S)
 TERRAIN - HIGH OBSTRUCTIONS
 FIRE AFTER IMPACT
 REMARKS- ACFT SLIPPED, LOST ALT IN LOW LEVEL VERTICLE BANK.

| | | | | | | | | |
|--------|------------------------|--|---|------------|--------|--------|----------------------------------|---|
| 3-1913 | 6/17/73 TIME - 1408 | SHELBY, OHIO NAME OF AIRPORT - SHELBY DEPARTURE POINT SHELBY, OHIO TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | N. AMERICAN SNJ-5 N1042C DAMAGE-DESTROYED | CR- PX- | 1 0 | 0 0 | MISCELLANEOUS AIR SHOW/RACING | AIRLINE TRANSPORT, AGE 45, 21000 TOTAL HOURS, 600 IN TYPE, INSTRUMENT RATED. |
| | | | | | | | | |
| | | | | | | | | |

PROBABLE CAUSE(S)
 PILOT IN COMMAND - MISJUDGED ALTITUDE

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | | FLIGHT PURPOSE | PILOT DATA |
|--------|------------------------|---|--|------------|--------|--------|------------------------------------|--|
| | | | | F | S | M/N | | |
| 3-2276 | 7/29/73 TIME - 1745 | ROCK SPRINGS, WYO NAME OF AIRPORT - AERONCA 7RCM DEPARTURE POINT AERONCA 7RCM TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | AERONCA 7RCM N2043A DAMAGE-DESTROYED | CR- PX- | 0 0 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 47, 1600 TOTAL HOURS, 403 IN TYPF, |
| | | | | | | | | |

BRIEFS OF ACCIDENTS

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|------|------|----------|---------------|---------------------|-------------------|------------|
|------|------|----------|---------------|---------------------|-------------------|------------|

3-2276 7/29/73 ROCK SPRINGS, WYO
TIME - 1745
DEPARTURE POINT
ROCK SPRINGS, WYO
TYPE OF ACCIDENT
COLLIDED WITH WIRES/POLES
TERRAIN - HIGH OBSTRUCTIONS

PROBABLE CAUSE(S)
PILOT IN COMMAND - FAILED TO SEE AND AVOID OBJECTS OR OBSTRUCTIONS
PILOT IN COMMAND - OPERATED CARELESSLY
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
FACTOR(S)

AERONCA 7BCM
N2043A
DAMAGE-SUBSTANTIAL
INTENDED DESTINATION
LOCAL

CR- 0 0 1 NONCOMMERCIAL
PX- 0 0 0 PLEASURE/PERSONAL TRANS
PHASE OF OPERATION
IN FLIGHT ACROBATICS

PRIVATE, AGE 47, 1600
TOTAL HOURS, 403 IN TYPE,
NOT INSTRUMENT RATED.

3-2944 9/22/73 JACKSONVILLE, ARK
TIME - 1640
DEPARTURE POINT
N. LITTLE ROCK, ARK
TYPE OF ACCIDENT
COLLISION WITH GROUND/WATER
CONTROLLED

CHAMPION 7KCAB
N9003L
DAMAGE-DESTROYED
INTENDED DESTINATION
LOCAL

CR- 2 0 0 NONCOMMERCIAL
PX- 0 0 0 PLEASURE/PERSONAL TRANS
PHASE OF OPERATION
IN FLIGHT ACROBATICS

COMMERCIAL, AGE 39,
15000 TOTAL HOURS, 500 IN
TYPE, INSTRUMENT RATED.

PROBABLE CAUSE(S)
PILOT IN COMMAND - EXERCISED POOR JUDGMENT
PILOT IN COMMAND - MISJUDGED ALTITUDE
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING

3-2967 10/14/73 MCARTHUR, OHIO
TIME - 1430
NAME OF AIRPORT - VINTON COUNTY
DEPARTURE POINT
MCARTHUR, OHIO
TYPE OF ACCIDENT
COLLISION WITH GROUND/WATER
CONTROLLED

CESNA A150K
N8313M
DAMAGE-DESTROYED
INTENDED DESTINATION
LOCAL

CR- 0 0 1 MISCELLANEOUS
PX- 0 0 0 AIR SHOW/RACING
PHASE OF OPERATION
IN FLIGHT ACROBATICS

COMMERCIAL, FL-INSTR.,
AGE 34, 3367 TOTAL HOURS,
1285 IN TYPE, INSTRUMENT
RATED.

PROBABLE CAUSE(S)
PILOT IN COMMAND - MISJUDGED ALTITUDE
PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.
REMARKS- LETTER OF COMPETENCE-MINIMUM ALTITUDE 100FT ABV SFC.2 SUCCESSIVE ROLLS L WING HIT GND 2ND ROLL.

APPENDIX B

- 70 -

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA | |
|--------|----------|--|-------------------------------|---------------------|--|--|------------|
| | | | | | | CR- PX- | 0 0 0 0 |
| 3-2979 | 10/19/73 | COMMERCE, TEX TIME - 0800 | JUNGMEISTER BUCKER N701D | 1 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 21, 371 TOTAL HOURS, 24 IN TYPE NOT INSTRUMENT RATED. | |
| | | NAME OF AIRPORT - COMMERCE DEPARTURE POINT COMMERCE, TEX | INTENDED DESTINATION LOCAL | | | | |
| | | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | CONTROLLED | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. PILOT IN COMMAND - MISJUDGED ALTITUDE MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING REMARKS- PLT ATTEMPTED A SNAP ROLL 300 FT AGL IN A 3/4 SCALE MODEL JUNGMEISTER ACFT. | | | | | |

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA | |
|--------|----------|--|-------------------------------|---------------------|--|--|------------|
| | | | | | | CR- PX- | 1 0 0 0 |
| 3-3542 | 11/17/73 | BOGALUSA, LA TIME - 1525 | PITTS S-2A N80022 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | PRIVATE, AGE 59, 1000 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED. | |
| | | NAME OF AIRPORT - CARR MEMORIAL DEPARTURE POINT BOGALUSA, LA | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | |
| | | TYPE OF ACCIDENT COLLIDED WITH TREES | | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL PILOT IN COMMAND - MISJUDGED SPEED AND ALTITUDE FACTOR(S) TERRAIN - HIGH OBSTRUCTIONS MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING REMARKS- LO ALT ACROATIC FLT.HI-SPD SPLIT-S RECOVERY FM INVERTED FLT.HIT TREES. | | | | | |

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA | |
|--------|----------|--|-------------------------------|---------------------|--|--|------------|
| | | | | | | CR- PX- | 1 0 0 0 |
| 3-4170 | 12/23/73 | LEESBURG, FLA TIME - 1607 | PITTS S1C N71J | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | COMMERCIAL, AGE 49, 2600 TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. | |
| | | NAME OF AIRPORT - LEESBURG MUNI DEPARTURE POINT LEESBURG, FLA | INTENDED DESTINATION LOCAL | | PHASE OF OPERATION IN FLIGHT ACROBATICS | | |
| | | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | CONTROLLED | | | | |
| | | PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE PILOT IN COMMAND - IMPROPER OPERATION OF FLIGHT CONTROLS MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING FIRE AFTER IMPACT REMARKS- ACFT ROLLED TO INVERTED PSN ART 250FT AGL. ALT LOST, ROLL RVRS'D HIT GND BFR REACHING WING LVL FLT. | | | | | |

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA | |
|--------|---------|----------------------------------|--------------------------|---------------------|------------------------------------|---|------------|
| | | | | | | CR- PX- | 1 0 0 0 |
| 3-0405 | 2/10/74 | CANNON CITY, COLO TIME - 0820 | RELLANCA 7KCAB N90918 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | COMMERCIAL, FL, INSTR, AGE 30, 3013 TOTAL HRS. | |
| | | | | | | | |

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | FLIGHT PURPOSE | PILOT DATA |
|--------|------------------------|--|--|---------------------------------|--|--|
| | | | F S M/N | F S M/N | | |
| 3-0405 | 2/10/74 TIME - 0820 | CANON CITY, COLO | BELLanca 7KCAB N90918 DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRNSP | COMMERCIAL, FL. INSTR. AGE 30. 3013 TOTAL HOURS. 280 IN TYPE. INSTRUMENT RATED. |
| | | NAME OF AIRPORT - FREMONT COUNTY DEPARTURE POINT - CANON CITY, COLO | INTENDED DESTINATION - LITTLETON, COLO | PHASE OF OPERATION IN FLIGHT | ACROBATICS | |

PROBABLE CAUSE(S)

PILOT IN COMMAND - EXERCISED POOR JUDGMENT
PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL

MISCELLANEOUS ACTS, CONDITIONS - DISREGARD OF GOOD OPERATING PRACTICE

FACTORS(S)
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING

FIRE AFTER IMPACT
REMARKS - LOW LEVEL ROLL INITIATED FM 100FT AGL. UN TO COMPLETE RECOVERY BEFORE IMPACT.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | FLIGHT PURPOSE | PILOT DATA |
|--------|------------------------|---------------------------------|---|---------------------------------|--|--|
| | | | F S M/N | F S M/N | | |
| 3-0638 | 3/14/74 TIME - 1525 | SILVER CITY, N MEX | CESSNA 172A N7284T DAMAGE-DESTROYED | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRNSP | COMMERCIAL, FL. INSTR. AGE 46, 1327 TOTAL HOURS. 1213 IN TYPE. NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT - DEMING, N MEX | INTENDED DESTINATION - SILVER CITY, N MEX | PHASE OF OPERATION IN FLIGHT | ACROBATICS | |

PROBABLE CAUSE(S)

PILOT IN COMMAND - EXERCISEN POOR JUDGMENT

PILOT IN COMMAND - PHYSICAL IMPAIRMENT

MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT

MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING

PILOT IN COMMAND - FAILED TO SEE AND AVOID OBJECTS OR OBSTRUCTIONS

FACTORS(S)
TERRAIN - HIGH OBSTRUCTIONS

REMARKS - LO LVL ACROBATICS. HIT LIGHT POLE ON RCVRY. BLOOD ALC LVL 174MG%.

APPENDIX B

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|-----------------------------------|--|----------|-------|---|--|
| | | | | F | S M/N | | |
| 3-0924 | 4/14/74 | SANTA PAULA, CALIF TIME - 1120 | STARDUSTER SA-100 N50WP DAMAGE-DESTROYED | CR- 1 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRAVEL | COMMERCIAL, FL. INSTR. AGE 51, 5362 TOTAL HOURS, UNK/NR IN TYPE, INSTRUMENT RATED. |

NAME OF AIRPORT - SANTA PAULA

DEPARTURE POINT - INTENDED DESTINATION

SANTA PAULA, CALIF

TYPE OF ACCIDENT - COLLISION WITH GROUND/WATER

COLLISION WITH GROUND/WATER CONTROLLED

PROBABLE CAUSE(S)

PILOT IN COMMAND - MISJUDGED DISTANCE, SPEED, ALTITUDE OR CLEARANCE

PILOT IN COMMAND - EXERCISED POOR JUDGMENT

MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING

FIRE AFTER IMPACT

REMARKS - ACFT OBSV IN LOW ALT AEROBATIC MANEUVERS PRIOR TO IMPACT.

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|--------------------------------|------------------------|----------|-------|---|--|
| | | | | F | S M/N | | |
| 3-1376 | 4/16/74 | CORNELIUS, OREG TIME - 1815 | PIPER J3C-65 N92304 | CR- 1 | 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRAVEL | COMMERCIAL, FL. INSTR. AGE 26, 337 TOTAL HOURS, 212 IN TYPE, NOT INSTRUMENT RATED. |

NAME OF AIRPORT - SKYPORT

DEPARTURE POINT - LOCAL

CORNELIUS, OREG

TYPE OF ACCIDENT - COLLISION WITH GROUND/WATER

COLLISION WITH GROUND/WATER CONTROLLED

PROBABLE CAUSE(S)

PILOT IN COMMAND - MISJUDGED ALTITUDE

REMARKS - ACFT TOO LOW TO EFFECT RECOVERY FROM SPIN. PRACTICING AEROBATIC MANEUVERS INCLUDING, SPINS.

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|------------------------------|-----------------------|----------|-------|---------------------------------------|--|
| | | | | F | S M/N | | |
| 3-1610 | 6/14/74 | NR-HOYT, COLO TIME - 0845 | CALLAIR A-9B N773V | CR- 0 | 1 0 | COMMERCIAL ASSOC CROP CTL ACTIVITY | AIRLINE TRANSPORT, AGE 46, 14200 TOTAL HOURS, 21 |

BRIEFS OF ACCIDENTS

FILE DATE LOCATION AIRCRAFT DATA INJURIES FLIGHT PILOT DATA

3-1610 6/14/74 NR-HOYT+COLD
TIME - 0845 CALAIR A-9B CR- 0 1 0 COMMERCIAL AIRLINE TRANSPORT. AGE
N7773V PX- 0 0 ASSOC CROP CTL ACTIVITY 46, 14200 TOTAL HOURS. 31
DAMAGE-DESTROYED IN TYPE, INSTRUMENT
RATED.

DEPARTURE POINT BRIGHTON+COLD

TYPE OF ACCIDENT COLLISION WITH GROUND/WATER

INTENDED DESTINATION HOYT+COLD

PHASE OF OPERATION IN FLIGHT ACROBATICS

PROBABLE CAUSE(S)

PILOT IN COMMAND - MISJUDGED SPEED AND ALTITUDE
PILOT IN COMMAND - EXERCISED POOR JUDGMENT
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING

SPECIAL DATA
TOTAL HOURS IN CROP CONTROL - 2500
KIND OF CROP - GRAIN FIELDS
PILOT'S SEAT BELT - FASTENED-PROPERLY
GOOGLES - NOT USED
COCKPIT CRASHPAD - INSTALLED
TANK/HOPPER-LOCATION - FORWARD OF PILOT
ELEVATION-AREA BEING TREATED-FEET - 5200
REMARKS- LOW ALT ACROBATICS. RETURNING FRM AG FLT.

KIND OF OPERATION - FERRY
TYPE OF CHEMICAL USED - LIQUID CHEMICAL-NONTOXIC
GLOVES - USED
CRASH HELMET - AVAILABLE-USED
CRASH BAR - INSTALLED
TERRAIN-TYPE - LEVEL,FLAT

NAME OF AIRPORT - PLUM ISLAND
DEPARTURE POINT PLUM ISLAND MASS

INTENDED DESTINATION LOCAL

PHASE OF OPERATION IN FLIGHT ACROBATICS

PROBABLE CAUSE(S)

PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING
PILOT IN COMMAND - MISJUDGED ALTITUDE
REMARKS- ACFT OBSV'D PERFORMING AEROBATIC MANEUVERS AT EST ALT 3-500FT AGL. VCNTRY PLUM ISLAND ARPT.

NAME OF AIRPORT - GLOBE GC-18
DEPARTURE POINT N3342K

INTENDED DESTINATION LOCAL

PHASE OF OPERATION IN FLIGHT ACROBATICS

PROBABLE CAUSE(S)

PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL
PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.
MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING

PILOT IN COMMAND - MISJUDGED ALTITUDE
REMARKS- ACFT OBSV'D PERFORMING AEROBATIC MANEUVERS AT EST ALT 3-500FT AGL. VCNTRY PLUM ISLAND ARPT.

APPENDIX B

| BRIEFS OF ACCIDENTS | | | | | | | | | |
|--|--------|--|--|------------------------|---|---|--|------------|--|
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | | | PILOT DATA | |
| 3-2630 | 9/8/74 | HIGHGROVE, CALIF. TIME - UNK/NR | PILOTS SPL S-IC N7021 DAMAGF-SUBSTANTIAL | CR- 1 0 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRANSF | COMMERCIAL, AGE 29, TOTAL HOURS, UNK/NR IN TYPE. NOT INSTRUMENT RATED. | | | |
| DEPARTURE POINT RUBIDOUX, CALIF. | | | | | | | | | |
| | | INTENDED DESTINATION | | | | | | | |
| | | LOCAL | | | | | | | |
| TYPE OF ACCIDENT COLLIDED WITH TREES | | | | | | | | | |
| | | | | | | | | | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | | | | |
| | | TERRAIN - HIGH OBSTRUCTIONS | | | | | | | |
| | | MISSING AIRCRAFT - LATER RECOVERED | | | | | | | |
| | | REMARKS - DOING AEROBATICS & DISAPPEARED FROM SIGHT. ACFT WRECKAGE FOUND NEXT DAY IN AREA LAST SEEN. | | | | | | | |
| 3-2708 9/19/74 PARKIN, ARK TIME - 1200 | | | | | | | | | |
| | | CESSNA 150L N11958 | | | | | | | |
| | | DAMAGE-DESTROYED | | | | | | | |
| | | INTENDED DESTINATION | | | | | | | |
| | | LOCAL | | | | | | | |
| DEPARTURE POINT PARKIN, ARK | | | | | | | | | |
| | | | | | | | | | |
| TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | | | | | | | | | |
| | | CONTROLLED | | | | | | | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. PILOT IN COMMAND - FAILED TO OBTAIN/Maintain FLYING SPEED | | | | | | | | | |
| | | MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | | |
| | | REMARKS - ATTEMPTD LOW ALT WING OVER. | | | | | | | |
| 3-2759 8/18/74 PAPILLION, NEBR TIME - 1125 | | | | | | | | | |
| | | BELLANCA 8KCAB N41806 | | | | | | | |
| | | DAMAGE-DESTROYED | | | | | | | |
| | | INTENDED DESTINATION | | | | | | | |
| | | LOCAL | | | | | | | |
| DEPARTURE POINT PAPILLION, NEBR | | | | | | | | | |
| | | | | | | | | | |
| TYPE OF ACCIDENT COLLIDED WITH TREES | | | | | | | | | |
| | | | | | | | | | |
| PROBABLE CAUSE(S) PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | | | | | | |
| | | | | | | | | | |
| | | PILOT IN COMMAND - PHYSICAL IMPAIRMENT | | | | | | | |
| | | REMARKS - MEDICAL EVIDENCE INDICATES PLT HAD MODERATE TO SEVEREATHEROSCLEROSIS. | | | | | | | |

APPENDIX B

- 76 -

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|---|---|------------|------------|--|--------------------------------|
| | | | | F | S M/N | | |
| 3-2992 | 9/10/74 | NR. JACKSONVILLE, FLA TIME - 1540 | PIPER PA-28 N4293T DAMAGE-DESTROYED | CR- PX- | 1 0 0 1 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANS NOT INSTRUMENT RATED. |
| | | DEPARTURE POINT TAMPA, FLA | INTENDED DESTINATION CHARLESTON, SC | | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | UNCONTROLLED | | | | |
| | | REMARKS- PLT BLOOD ALCOHOL LEVEL 0.24 PERCENT. PLT ANNOUNCED TO PAX HE WOULD DEMONSTRATE ACFT CAPABILITIES. | | | | | |

PROBABLE CAUSE(S)

PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE

PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.

PILOT IN COMMAND - PHYSICAL IMPAIRMENT OF EFFICIENCY AND JUDGMENT

MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT

FACT(S) MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER

REMARKS- PLT BLOOD ALCOHOL LEVEL 0.24 PERCENT. PLT ANNOUNCED TO PAX HE WOULD DEMONSTRATE ACFT CAPABILITIES.

| FILE | DATE | NAME OF AIRPORT - NEWTON FIELD DEPARTURE POINT HUNTINGTON, W VA TIME - 1830 | PIPER PA-22 N1822P DAMAGE-DESTROYED | CR- PX- | 1 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANS NOT INSTRUMENT RATED. | PILOT DATA |
|--------|---------|--|---|------------|------------|------------------------------------|-----------------------------------|------------|
| | | | | | | | | |
| 3-3091 | 10/4/74 | HUNTINGTON, W VA TIME - 1830 | PIPER PA-22 N1822P DAMAGE-DESTROYED | CR- PX- | 1 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL | TRANS NOT INSTRUMENT RATED. | PILOT DATA |

NAME OF AIRPORT - NEWTON FIELD

DEPARTURE POINT
HUNTINGTON, W VA
TIME - 1830INTENDED DESTINATION
LOCAL
TYPE OF ACCIDENT
COLLIDED WITH TREES

PROBABLE CAUSE(S)

PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE

FACTOR(S)

PILOT IN COMMAND - PHYSICAL IMPAIRMENT OF EFFICIENCY AND JUDGMENT

MISCELLANEOUS ACTS, CONDITIONS - ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT

TERRAIN - HIGH OBSTRUCTIONS

REMARKS- BLOOD ALCOHOL LVL 70 MG PCT. STRUCK TREES DRG PULL UP FM SPLIT S.

| FILE | DATE | NAME OF AIRPORT - NAAS S WEYMOUTH DEPARTURE POINT S. WEYMOUTH, MASS TIME - 1315 | BELLANCA 8KCAR N86589 DAMAGE-SUBSTANTIAL | CR- PX- | 1 0 0 0 | MISCELLANEOUS AIR SHOW/RACING | PILOT DATA |
|--------|--------|--|--|------------|------------|----------------------------------|---|
| | | | | | | | |
| 3-3099 | 9/8/74 | INTENDED DESTINATION LOCAL | | | | | COMMERCIAL, AGE 31+ 562 TOTAL HOURS, 233 IN TYPE. NOT INSTRUMENT RATED. |

PROBABLE CAUSE(S)

PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.

PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE

FIRE AFTER IMPACT

REMARKS- AUTH. LTD. SOONFT AGL. AFTR SPIN ROTATION STRIPPED ACFT NRSDV HALF TWIST BFR ALMOST VERT USCNFT.

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | | FLIGHT PURPOSE | PILOT DATA |
|--------|---------|--------------------------------|--|------------|------------|----------------------------------|---|
| | | | | F | S M/N | | |
| 3-3127 | 10/6/74 | NEW CASTLE, IND TIME - 1300 | BELLANCA 8KCAB N31295 DAMAGE-DESTROYED | CR- PX- | 0 1 0 0 | MISCELLANEOUS AIR SHOW/RACING | COMMERCIAL, AGE 45+ 3590 TOTAL HOURS, 127 IN TYPE. |

BRIEFS OF ACCIDENTS

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PHASE OF OPERATION | IN FLIGHT AEROBATICS | PITCH DATA |
|--------|---|---|--------------------------|-------------------------|-------------------------|--------------------|----------------------|--|
| | | | | | | | | COMMERCIAL, AGE 45, 3690 TOTAL HOURS, 122 IN TYPE, NO INSTRUMENT RATED. |
| 3-3127 | 10/6/74 | NEW CASTLE, IND | BELLanca 8KCAB N31295 | CR- 0 1 0 MISCELLANEOUS | PX- 0 0 AIR SHOW/RACING | | | |
| | TIME - 1300 | DAMAGE-DESTROYED | | | | | | |
| | NAME OF AIRPORT - NEW CASTLE, IND | DEPARTURE POINT | LOCAL | | | | | |
| | TYPE OF ACCIDENT | COLLISION WITH GROUND/WATER | CONTROLLED | | | | | |
| | PROBABLE CAUSE(S) | Pilot in command - misjudged altitude and clearance | | | | | | |
| | FACTORS | Pilot in command - improper operation of flight controls | | | | | | |
| | WEATHER | DOWNDRAFT, UPDRAFTS | | | | | | |
| | WEATHER BRIEFING | - NO BRIEFING RECEIVED | | | | | | |
| | WEATHER FORECAST | - UNKNOWN/NOT REPORTED | | | | | | |
| | SKY CONDITION | Ceiling at accident site | | | | | | |
| | BROKEN | 10000 | | | | | | |
| | VISIBILITY AT ACCIDENT SITE | PRECIPITATION AT ACCIDENT SITE | | | | | | |
| | 5 OR OVER | NONE | | | | | | |
| | OBSTRUCTIONS TO VISION AT ACCIDENT SITE | RELATIVE BEARING (OF WIND) | | | | | | |
| | NONE | RIGHT QUARTERING TAIL WIND 113-157 DEGREES | | | | | | |
| | TEMPERATURE-F | WIND DIRECTION-DEGREES | | | | | | |
| | 73 | 220 | | | | | | |
| | WIND VELOCITY-KNOTS | TYPE OF WEATHER CONDITIONS | | | | | | |
| | 12 | VFR | | | | | | |
| | TYPE OF FLIGHT PLAN | | | | | | | |
| | NONE | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| 3-3399 | 8/18/74 | WASECA, MINN | ZIMMERMAN S-1C N5191 | CR- 0 1 0 MISCELLANEOUS | PX- 0 0 AIR SHOW/RACING | | | AIR, FLIGHT INSTR., AGE 40, 13200 TOTAL HOURS, 100 IN TYPE, INSTRUMENT RATED. |
| | TIME - 1325 | DAMAGE-SUBSTANTIAL | | | | | | |
| | NAME OF AIRPORT - WASECA, MINN | DEPARTURE POINT | LOCAL | | | | | |
| | TYPE OF ACCIDENT | COLLISION WITH GROUND/WATER | CONTROLLED | | | | | |
| | PROBABLE CAUSE(S) | Pilot in command - misjudged altitude | | | | | | |
| | REMARKS | SPIN DEMO, LATE RECOVERY, STOPPED ROTATION, HIT GND ORG RECOVERY. | | | | | | |

APPENDIX B

- 78 -

| BRIEFS OF ACCIDENTS | | | | | | PILOT DATA |
|---------------------|--|---|---|---|---|------------|
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | |
| 3-3439 | 6/20/74 STEPHEN, MINN TIME - 1655 | CATAIR A-9 N7238V INTENDED DESTINATION LOCAL | CR- PX- 0 0 | 0 1 0 COMMERCIAL CROP CTL ACTIVITY ASSOC CROP CTL ACTIVITY | COMMERCIAL, AGE 22, 766 TOTAL HOURS, 350 IN TYPE, NOT INSTRUMENT RATED. | |
| | | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | CONTROLLED | | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | SPECIAL DATA | | KIND OF OPERATION - SPRAYING CROPS TYPE OF CHEMICAL USED - LIQUID CHEMICAL-NON TOXIC GOGGLES - NOT USED COCKPIT CRASHPAD - INSTALLED TANK/HOPPER-LOCATION - FORWARD OF PILOT ELEVATION-AREA REING TREATED-FEEI - 850 | | |
| | | PROBABLE CAUSE(S) | | REMARKS- ACFT OBSERVED MAKING LOOP AT LOW ALTITUDE. PLT HAD COMPLETED SPRAYING AND WAS RETURNING TO BASE. | | |
| | | PILOT IN COMMAND - EXERCISED POOR JUDGMENT PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE MISCELLANEOUS ACTS, CONDITIONS - UNWARRANTED LOW FLYING | | | | |
| 3-3818 | 12/19/74 NR-WASCO, OREG TIME - 1230 | CESSNA 120 N2124V INTENDED DESTINATION LOCAL | CR- PX- 1 0 0 0 0 0 | NONCOMMERCIAL PLEASURE/PERSNL TRANSP | STUDENT, AGE 24, 22 TOTAL HOURS, ALL IN TYPE, NOT INSTRUMENT RATED. | |
| | | DEPARTURE POINT WASCO, OREG | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | CONTROLLED | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | SPECIAL DATA | | | | |
| | | PROBABLE CAUSE(S) | | | | |
| | | PILOT IN COMMAND - MISJUDGED ALTITUDE AND CLEARANCE PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL | | | | |
| | | FACTORS | | | | |
| | | PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. PERSONNEL - FLIGHT INSTRUCTOR INADEQUATE TRAINING OF STUDENT PERSONNEL - PLT OWNED ACFT. CRASHED DURING RECOVERY FROM ACROBATIC MANEUVER. | | | | |
| 3-3837 | 11/24/74 MORGANTON, NC TIME - 1730 | CESSNA 150J N60581 INTENDED DESTINATION LOCAL | CR- PX- 2 0 0 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRANSP | COMMERCIAL, FL-INSTRL. AGE 28, 3000 TOTAL HOURS, UNKNOWN IN TYPE, INSTRUMENT RATED. | |
| | | DEPARTURE POINT MORGANTON, NC | TYPE OF ACCIDENT COLLISION WITH GROUND/WATER | CONTROLLED | PHASE OF OPERATION IN FLIGHT ACROBATICS | |
| | | SPECIAL DATA | | | | |
| | | PROBABLE CAUSE(S) | | | | |
| | | PILOT IN COMMAND - MISJUDGED ALTITUDE FACTOR(S) | | | | |
| | | PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC. MISCELLANEOUS ACTS, CONDITIONS, ETC. - UNKNOWN COLLISION WITH GROUND/WATER | | | | |

NATIONAL TRANSPORTATION SAFETY BOARD

WASHINGTON, D. C. 20594

BRIEFS OF ACCIDENTS

NATIONAL TRANSPORTATION SAFETY BOARD

WASHINGTON, D. C. 20594

BRIEFS OF ACCIDENTS

ACCRIDATIC-INFLIGHT PHASE OF OPERATION

1ST TYPE ACCIDENT-ENGINE FAILURE OR MALFUNCTION

U.S. GENERAL AVIATION

1972 THRU 1974

| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES F S M/N | FLIGHT PURPOSE | PILOT DATA |
|--------|------------------------|-------------|--|---------------------|---|---|
| 3-0388 | 1/26/72 TIME - 1245 | TUPSALE, NC | CESSNA 150 N6285G DAMAGE-SUBSTANTIAL | CR- 0 0 PX- 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRAVEL | PRIVATE, AGE 31, 186 TOTAL HOURS, ALL IN TYPE, NOT INSTRUMENT RATED. |

DEPARTURE POINT WILMINGTOM, NC
INTENDED DESTINATION LOCAL

PHASE OF OPERATION
IN FLIGHT ACROBATICS
LANDING ROLL

TYPE OF ACCIDENT
ENGINE FAILURE OR MALFUNCTION
COLLIDED WITH OBJECT

PROBABLE CAUSE(S)
PILOT IN COMMAND - INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING
PILOT IN COMMAND - MISMANAGEMENT OF FUEL
MISCELLANEOUS ACTS, CONDITIONS - FUEL EXHAUSTION
TERRAIN - OTHER

COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE
EMERGENCY CIRCUMSTANCES - FORCED LANDING OFF AIRPORT ON LAND

REMARKS- PRACTICE STALL-SPIN FLT. EXHA DURG SPIN. LNDD ON RD, WING HI RD SIGN.

APPENDIX B

| BRIEFS OF ACCIDENTS | | | | | | PILOT DATA |
|---------------------|--------|--------------------|------------------------------------|------------------------|---|---|
| FILE | DATE | LOCATION | AIRCRAFT DATA | INJURIES | FLIGHT PURPOSE | |
| | | | F S M/N | F S M/N | | |
| 3-2597 | 7/1/73 | NR. MONMOUTH, OREG | STORY MK-7 N1269 TIME - 1100 | CR- 0 1 0 PX- 0 0 0 | NONCOMMERCIAL PLEASURE/PERSONAL TRANS | COMMERCIAL AGE 36, UNK/NR TOTAL HOURS, UNK/NR IN TYPE, NOT INSTRUMENT RATED. |

NAME OF AIRPORT - FETTER
DEPARTURE POINT LOCAL
MONMOUTH, OREG

INTENDED DESTINATION
LOCAL

PHASE OF OPERATION
IN FLIGHT ACROBATICS
IN FLIGHT ACROBATICS

TYPE OF ACCIDENT
ENGINE FAILURE OR MALFUNCTION
COLLISION WITH GROUND/WATER CONTROLLED

PROBABLE CAUSE(S)

PILOT IN COMMAND - MISJUDGED DISTANCE, SPEED, ALTITUDE OR CLEARANCE

PILOT IN COMMAND - EXERCISED POOR JUDGMENT

PILOT IN COMMAND - EXERCISED POOR JUDGMENT

POWERPLANT - ENGINE STRUCTURE OTHER

FACTOR(S)

PILOT IN COMMAND - FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES, ETC.

PILOT IN COMMAND - ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL

PILOT IN COMMAND - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE

COMPLETE POWER LOSS - COMPLETE ENGINE FAILURE/FLAMEOUT-1 ENGINE

REMARKS- PLT ATMD LOOP. ENG NOT EQPD FOR INVERTED FLT. ENGF AILED AT TOP OF LOOP.

LIST OF ABBREVIATIONS USED IN BRIEFS

| ABBREVIATION | MEANING |
|--------------------|--------------------------|
| AERIAL ADVERTISING | AERIAL ADVERTISING |
| ATR, FLIGHT INSTR. | ATR INF TRANSDCT INSTRUM |

LIST OF ABBREVIATIONS USED IN BRIEFS

| ABBREVIATION | MEANING |
|---------------------------|--|
| AERIAL ADVERTISE | AERIAL ADVERTISING |
| AIR FLIGHT INSTR. | AIRLINE TRANSPORT INSTRUCTOR |
| AIR SHOW-RACING | AIR SHOW/AIR RACING |
| AIR TAXI-CARGO | AIR TAXI-CARGO OPERATIONS |
| AIR TAXI-PASSG | AIR TAXI-PASSENGER OPERATIONS |
| APPROACH CTL-DEPARTURE | APPROACH CONTROL-DEPARTURE |
| APR CTL-TW ENR CTL SRV | APPROACH CONTROL-TOWER EN ROUTE CONTROL SERVICE |
| ASSOC CROP CTL ACTIVITIES | ASSOCIATED CROP CONTROL ACTIVITIES |
| ASSOC FIRE CTL ACTIVITIES | ASSOCIATED FIRE CONTROL ACTIVITIES |
| COMMERCIAL FLIGHT-INSTR. | COMMERCIAL FLIGHT INSTRUCTOR |
| CORP/EXEC | CORPORATE/EXECUTIVE |
| CR- | CREW |
| CTR CARGO-D | CONTRACT/CHARTER-CARGO-DOMESTIC |
| CTR CARGO-I | CONTRACT/CHARTER-CARGO-INTERNATIONAL |
| CTR PASSG-D | CONTRACT/CHARTER-PASSENGER-DOMESTIC |
| CTR PASSG-I | CONTRACT/CHARTER-PASSENGER-INTERNATIONAL |
| LAST ENROUTE STOP | LAST PLANNED EN ROUTE LANDING POINT |
| MAPPING/PHOTO | AERIAL MAPPING/PHOTOGRAPHY |
| MIL CONTRACT CARGO INTL | MILITARY CONTRACT-CARGO-INTERNATIONAL |
| MIL CONTRACT PASSG INTL | MILITARY CONTRACT-PASSENGER-INTERNATIONAL |
| MILITARY CTR CARGO DOM | MILITARY CONTRACT-CARGO-DOMESTIC |
| MILITARY CTR PASSG DOM | MILITARY CONTRACT-PASSENGER-DOMESTIC |
| MIL/CTR CARGO | MILITARY CONTRACT-CARGO |
| MIL/CTR PASSG | MILITARY CONTRACT-PASSENGER |
| NR* | NEAR |
| NS CTR CARGO | NONSCHEDULED/CHARTER REVENUE CARGO-INTRA-STATE |
| NS CTR PASSG | NONSCHEDULED/CHARTER REVENUE PASSENGER-INTRA-STATE |
| NS/CTR REVENUE CARGO DOM | NONSCHEDULED/CHARTER REVENUE CARGO-DOMESTIC |
| NS/CTR REVENUE CARGO INTL | NONSCHEDULED/CHARTER REVENUE CARGO-INTERNATIONAL |
| NS/CTR REVENUE PASSG DOM | NONSCHEDULED/CHARTER REVENUE PASSENGER-DOMESTIC |
| NS/CTR REVENUE PASSG INTL | NONSCHEDULED/CHARTER REVENUE PASSENGER-INTERNATIONAL |
| OT- | OTHER AIRCRAFT AND GROUND |
| PARAJUMP | PARAJUMP |
| PRIVATE,FL.INSTR. | PRIVATE FLIGHT INSTRUCTOR |
| PX- | PASSENGERS |
| RADAR CTL/SURVEILLANCE | RADAR CONTROL/SURVEILLANCE |
| SCHED CARGO SRV | SCHEDULED CARGO SERVICE |
| SCHED DOM CARGO SRV | SCHEDULED DOMESTIC CARGO SERVICE |
| SCHED DOM PASSG SRV | SCHEDULED DOMESTIC PASSENGER SERVICE |
| SCHED INTERNL CARGO SRV | SCHEDULED INTERNATIONAL CARGO SERVICE |
| SCHED INTERNL PASSG SRV | SCHEDULED INTERNATIONAL PASSENGER SERVICE |
| S-D | SCHEDULED-PASSENGER SERVICE |
| S-I | SCHEDULED-DOMESTIC |
| UNK/NR | UNKNOWN/NOT REPORTED |

APPENDIX C

TABLES

Table 1

ACROBATICS - INFLIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972 - 1974

| | INJURIES | | | | | TOTAL |
|-----------------|----------|---------|-------|------|---------|-------|
| | FATAL | SERIOUS | MINOR | NONE | UNKNOWN | |
| PILOT | 77 | 13 | 8 | 6 | | 104 |
| COPILOT | 7 | | | | | 7 |
| DUAL STUDENT | | | | | | |
| CHECK PILOT | 1 | 2 | 1 | 1 | | 5 |
| FLIGHT ENGINEER | 1 | | | | | 1 |
| NAVIGATOR | | | | | | |
| CABIN ATTENDANT | | | | | | |
| EXTRA CREW | | | | | | |
| PASSENGERS | 21 | 6 | 1 | 1 | | 29 |
| TOTAL | 107 | 21 | 10 | 8 | ABOARD | 146 |
| OTHER AIRCRAFT | | | | | | |
| OTHER GROUND | | | | | | |
| GRAND TOTAL | 107 | 21 | 10 | 8 | | 146 |

INVOLVES 105 TOTAL ACCIDENTS
INVOLVES 78 FATAL ACCIDENTS

Table 2

KIND OF FLYING BY INJURY INDEX
 ACROBATICS-INFLIGHT PHASE OF OPERATION
 U.S. GENERAL AVIATION
 1972 - 1974

APPENDIX C

Table 2 (cont.)

TRA 427

Table 3

FIRST TYPE OF ACCIDENT BY INJURY INDEX
ACROBATICS - INFIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972 - 1974

TRA 427

APPENDIX C

Table 3 (cont.)

| TRA 106 | NONE | F | C | M | N | Z | OTHER | RECORDS ACCIDENTS | | INVOLVES IN VOLVES | 10 7 |
|-------------------------------|------|----|---|---|---|---|-------|-------------------|-----------|-----------------------|--------------------|
| | | | | | | | | RECORDS | ACCIDENTS | | |
| OTHER | | | | | | | | | | | |
| BIRD STRIKE | | | | | | | | 13 | 13 | | |
| STALL | | 11 | 2 | | | | | | | 36 | 36 |
| SPIN | | 25 | 7 | 2 | 2 | | | | | 1 | 1 |
| SPIRAL | | | 1 | | | | | | | 1 | 1 |
| MUSH | | | | | | 1 | | | | | |
| FIRE OR EXPLOSION | | | | | | | | | | | PILOT |
| IN FLIGHT | | | | | | | | | | | PERSONNEL |
| ON GROUND | | | | | | | | | | | AIRFRAME |
| AIRFRAME FAILURE | | | | | | | | | | 10 | 10 |
| IN FLIGHT | | 6 | 1 | 1 | 2 | | | | | | LANDING GEAR |
| ON GROUND | | | | | | | | | | | |
| ENGINE TEARAWAY | | | | | | | | | | 2 | 2 |
| ENGINE FAILURE OR MALFUNCTION | | | 1 | | | 1 | | | | | SYSTEMS |
| PROPELLER/ROTOR FAILURE | | | | | | | | | | | INSTRUMENTS/E |
| PROPELLER | | | | | | | | | | | |
| TAIL ROTOR | | | | | | | | | | | ROTORCRAFT |
| MAIN ROTOR | | | | | | | | | | | |
| PROP ROTOR ACNT TO PERSON | | | | | | | | | | | AIRPORTS/AIR |
| JET INTAKE/EXH ACNT TO PERS | | | | | | | | | | | WEATHER |
| PROPELLER/JET/ROTOR BLAST | | | | | | | | | | | TERRAIN |
| TURBULENCE | | | | | | | | | | | MISCELLANEOUS |
| HAIL DAMAGE TO AIRCRAFT | | | | | | | | | | | UNDETERMINED |
| LIGHTNING STRIKE | | | | | | | | | | | |
| EVASIVE MANEUVER | | | | | | | | | | | |
| UNCONTROLLED ALT DEVIATION | | | | | | | | | | | |
| DITCHING | | | | | | | | | | | THE FIG OF ACCI |
| MISSING ACFT NOT RECOVERED | | | | | | | | | | | |
| MISCELLANEOUS/OTHER | | | | | | | | | | | * |
| UNDETERMINED | | | | | | | | | | | / |
| OTHER | | | | | | | | | | | CATEGDR |
| RECORDS | 78 | 15 | 6 | 6 | | | | | | 105 | |
| ACCIDENTS | 78 | 15 | 6 | 6 | | | | | | 105 | |

Table 4

CAUSE/FACTOR TABLE

ACROBATICS - INFLIGHT PHASE OF OPERATION

U. S. GENERAL AVIATION

1972 - 1974

EXCLUDES ACCIDENTS WITH NO CAUSAL DETERMINATION

INVOLVES 105 TOTAL ACCIDENTS
 INVOLVES 78 FATAL ACCIDENTS

| BROAD CAUSE/FACTOR | FATAL ACCIDENTS | | | NONFATAL ACCIDENTS | | | ALL ACCIDENTS | | |
|---------------------------------------|-----------------|-------------|-------------|--------------------|------------|-------------|---------------|-------------|-------------|
| | CAUSE | FACTOR | TOTAL* | CAUSE | FACTOR | TOTAL* | CAUSE | FACTOR | TOTAL* |
| PILOT | 73 93.59 | 14 17.95 | 73 93.59 | 24 88.89 | 1 3.70 | 24 88.89 | 97 92.38 | 15 14.29 | 97 92.38 |
| PERSONNEL | 2 2.56 | 2 2.56 | 4 5.13 | .00 | .00 | .00 | 2 1.90 | 2 1.90 | 4 3.81 |
| AIRFRAME | 2 2.56 | 2 2.56 | 4 5.13 | 2 7.41 | .00 | 2 7.41 | 4 3.81 | 2 1.90 | 6 5.71 |
| LANDING GEAR | .00 | .00 | .00 | .00 | .00 | .00 | .00 | .00 | .00 |
| POWERPLANT | .00 | .00 | .00 | 1 3.70 | .00 | 1 3.70 | 1 .95 | .00 | 1 .95 |
| SYSTEMS | 1 1.28 | .00 | 1 1.28 | 1 3.70 | .00 | 1 3.70 | 2 1.90 | .00 | 2 1.90 |
| INSTRUMENTS/EQUIPMENT AND ACCESSORIES | .00 | .00 | .00 | .00 | .00 | .00 | .00 | .00 | .00 |
| ROTORCRAFT | .00 | .00 | .00 | .00 | .00 | .00 | .00 | .00 | .00 |
| AIRPORTS/AIRWAYS/FACILITIES | .00 | .00 | .00 | .00 | .00 | .00 | .00 | .00 | .00 |
| WEATHER | .00 | .00 | .00 | .00 | 1 3.70 | 1 3.70 | .00 | 1 .95 | 1 .95 |
| TERRAIN | .00 | 6 7.69 | 6 7.69 | 2 7.41 | 3 11.11 | 5 18.52 | 2 1.90 | 9 8.57 | 11 10.48 |
| MISCELLANEOUS | .00 | 1 1.28 | 1 1.28 | 1 3.70 | .00 | 1 3.70 | 1 .95 | 1 .95 | 2 1.90 |
| UNDETERMINED | 2 2.56 | .00 | 2 2.56 | 1 3.70 | .00 | 1 3.70 | 3 2.86 | .00 | 3 2.86 |

THE FIGURES OPPOSITE EACH CAUSAL CATEGORY REPRESENT THE NUMBER AND PERCENT OF ACCIDENTS IN WHICH THAT PARTICULAR CAUSAL CATEGORY WAS ASSIGNED

* IF AN ACCIDENT INCLUDES BOTH A CAUSE AND RELATED FACTOR IN THE SAME CAUSAL CATEGORY, THE ACCIDENT IS REPRESENTED ONCE UNDER THE TOTAL FOR THAT CATEGORY

Table 5
CAUSE/FACTOR TABLE

ACROBATICS - INFLIGHT PHASE OF OPERATION
U. S. GENERAL AVIATION
1972 - 1974
EXCLUDES ACCIDENTS WITH NO CAUSAL DETERMINATION

INVOLVES 105 TOTAL ACCIDENTS
INVOLVES 78 FATAL ACCIDENTS

| DETAILED CAUSE/FACTOR | FATAL ACCIDENTS | | | NONFATAL ACCIDENTS | | | ALL ACCIDENTS | | |
|---|-----------------|--------|-------|--------------------|--------|-------|---------------|--------|-------|
| | CAUSE | FACTOR | TOTAL | CAUSE | FACTOR | TOTAL | CAUSE | FACTOR | TOTAL |
| ** PILOT ** | | | | | | | | | |
| PILOT IN COMMAND | | | | | | | | | |
| ATTEMPTED OPERATION W/KNOWN DEFICIENCIES IN EQUIPMENT | 1 | | 1 | | | | 1 | | 1 |
| ATTEMPTED OPERATION BEYOND EXPERIENCE/ABILITY LEVEL | 12 | | 12 | 2 | 1 | 3 | 14 | 1 | 15 |
| EXCEEDED DESIGN STRESS LIMITS OF AIRCRAFT | 2 | | 2 | 1 | | 1 | 3 | | 3 |
| FAILED TO SEE AND AVOID OBJECTS OR OBSTRUCTIONS | 1 | | 1 | | | 1 | 2 | | 2 |
| FAILED TO OBTAIN/MAINTAIN FLYING SPEED | 28 | | 28 | 5 | | 5 | 33 | | 33 |
| MISJUDGED SPEED, ALTITUDE OR CLEARANCE | 1 | | 1 | | | 1 | 2 | | 2 |
| FAILED TO FOLLOW APPROVED PROCEDURES, DIRECTIVES ETC | 11 | 3 | 14 | 2 | 1 | 3 | 13 | 4 | 17 |
| IMPROPER OPERATION OF FLIGHT CONTROLS | 22 | | 22 | 7 | | 7 | 29 | | 29 |
| INADEQUATE PREFLIGHT PREPARATION AND/OR PLANNING | 1 | | 1 | 2 | | 2 | 3 | | 3 |
| LACK OF FAMILIARITY WITH AIRCRAFT | | | 2 | | | 2 | | 2 | 2 |
| MISMANAGEMENT OF FUEL | | | 2 | | | 2 | | 1 | 1 |
| EXERCISED POOR JUDGMENT | 24 | 2 | 26 | 5 | | 5 | 29 | 2 | 31 |
| OPERATED CARELESSLY | | | | 2 | | 2 | 2 | | 2 |
| MISJUDGED SPEED AND ALTITUDE | 2 | 1 | 3 | 1 | | 1 | 3 | 1 | 4 |
| MISJUDGED ALTITUDE AND CLEARANCE | 8 | | 8 | 2 | | 2 | 10 | | 10 |
| MISJUDGED ALTITUDE | 20 | | 20 | 8 | | 8 | 28 | | 28 |
| MISJUDGED CLEARANCE | 1 | | 1 | | | 1 | 1 | | 1 |
| INCAPACITATION | | | | | | 1 | | | |
| PHYSICAL IMPAIRMENT | 3 | 6 | 9 | | | 1 | | 3 | 6 |
| SUBTOTAL | 137 | 14 | 151 | 41 | 2 | 43 | 178 | 16 | 194 |
| ** PERSONNEL ** | | | | | | | | | |
| FLIGHT INSTRUCTOR | | | | | | | | 1 | 1 |
| INADEQUATE TRAINING OF STUDENT | | | 1 | 1 | | | | 1 | 1 |
| MAINTENANCE, SERVICING, INSPECTION | | | | | | | | 1 | 1 |
| INADEQUATE MAINTENANCE AND INSPECTION | 1 | | 1 | | | | | 1 | 1 |
| OPERATIONAL SUPERVISORY PERSONNEL | | | | | | | | 1 | 1 |
| INADEQUATE GROUND TRAINING-PROCEDURES | | | 1 | 1 | | | | 1 | 1 |
| WEATHER PERSONNEL | | | | | | | | 1 | 1 |
| TRAFFIC CONTROL PERSONNEL | | | | | | | | 1 | 1 |
| AIRPORT SUPERVISORY PERSONNEL | | | | | | | | 1 | 1 |
| AIRWAYS FACILITIES PERSONNEL | | | | | | | | 1 | 1 |
| PRODUCTION-DESIGN-PERSONNEL | | | | | | | | 1 | 1 |
| SUBSTANDARD QUALITY CONTROL | 1 | | 1 | | | | 1 | | 1 |
| MISCELLANEOUS-PERSONNEL | | | | | | | | 1 | 1 |
| THIRD PILOT | | | | | | | | 1 | 1 |
| FLIGHT ENGINEER | | | | | | | | 1 | 1 |
| FLIGHT PERSONNEL | | | | | | | | 1 | 1 |
| DISPATCHING (AIR CARRIER ONLY) | | | | | | | | 1 | 1 |
| OTHER | 2 | 2 | 4 | 2 | | 2 | 4 | 2 | 6 |
| DISPATCHING | | | | | | | | 1 | 1 |
| DISPATCHED AIRCRAFT IMPROPERLY EQUIPPED FOR FLIGHT | 1 | 1 | 2 | | | | 1 | | 2 |
| SUBTOTAL | 5 | 5 | 10 | 2 | | 2 | 7 | 5 | 12 |
| ** AIRFRAME ** | | | | | | | | | |
| WINGS | | | | | | | | | |
| SPARS | 1 | 1 | 2 | | | | 1 | 1 | 2 |
| OTHER | 1 | | 1 | | | | 1 | 1 | 1 |
| FUSELAGE | | | | | | | | | |
| WINDSHIELDS, WINDOWS, CANOPIES | | | | 1 | | 1 | 1 | | 1 |
| LANDING GEAR | | | | | | | | | |
| FLIGHT CONTROL SURFACES | | | | | | | | | |
| AILERON, SURFACES ATTACHMENTS | 1 | 1 | 1 | | | 1 | 1 | 1 | 1 |
| HORIZONTAL STABILIZER, ATTACHMENTS | | | | | | | | 1 | 1 |
| SUBTOTAL | 2 | 2 | 4 | 2 | | 2 | 4 | 2 | 6 |

Table 5 (cont.)

CAUSE/FACTOR TABLE

APPENDIX C

POWERPLANT (CONTINUED)

| FATAL ACCIDENTS | | | NONFATAL ACCIDENTS | | | ALL ACCIDENTS | | |
|-----------------|--------|-------|--------------------|--------|-------|---------------|--------|-------|
| CAUSE | FACTOR | TOTAL | CAUSE | FACTOR | TOTAL | CAUSE | FACTOR | TOTAL |
| | | | | | | | | |

** POWERPLANT **

ENGINE STRUCTURE
 OTHER
 IGNITION SYSTEM
 FUEL SYSTEM
 LUBRICATING SYSTEM
 COOLING SYSTEM
 PROPELLER AND ACCESSORIES
 EXHAUST SYSTEM
 ENGINE ACCESSORIES
 ENGINE CONTROLS-COCKPIT
 POWERPLANT-INSTRUMENTS
 MISCELLANEOUS
 REDUCTION GEAR ASSEMBLY
 COMPRESSOR ASSEMBLY
 COMBUSTION ASSEMBLY
 TURBINE ASSEMBLY
 ACCESSORY DRIVE ASSEMBLY
 LUBRICATING SYSTEM
 FUEL SYSTEM
 SAFETY SYSTEM
 IGNITION SYSTEM
 TORQUEMETER
 AIR BLEED
 EXHAUST SYSTEM
 THRUST REVERSER
 PROPELLER SYSTEM
 CONSTANT SPEED DRIVE
 POWER LEVER
 PROPELLER LEVER
 REVERSE THRUST LEVER
 ENGINE INDICATING EQUIPMENT
 ENGINE INSTALLATION

1 1 1 1 1

SUBTOTAL

** SYSTEMS **

ELECTRICAL SYSTEM
 HYDRAULIC SYSTEM
 FLIGHT CONTROL SYSTEMS
 ELEVATOR AND ELEVATOR TAB CONTROL SYSTEM
 RUDDER AND RUDDER TAB CONTROL SYSTEM
 ANTI-ICING, DE-ICING SYSTEMS
 AIR CONDITION, HEATING AND PRESSURIZATION
 AUTO PILOT
 FIRE WARNING SYSTEM
 FIRE EXTINGUISHER SYSTEM
 OXYGEN SYSTEM
 OTHER SYSTEMS

1 1 1 1 1 1

SUBTOTAL

** WEATHER **

DOWNDRAFTS, UPDRAFTS

1 1 1 1

SUBTOTAL

** TERRAIN **

WET, SOFT GROUND
 SNOW-COVERED
 HIGH OBSTRUCTIONS
 OTHER

1 1 1 1 1 1
 5 5 3 3 8 8
 1 1 1 1 1 1

SUBTOTAL

** MISCELLANEOUS **

UNQUALIFIED PERSON OPERATED AIRCRAFT
 FOREIGN MATERIAL AFFECTING NORMAL OPERATIONS

1 1 1 1 1 1

MISCELLANEOUS

UNDETERMINED

SUBTOTAL

GRAND TOTAL

** MISCELLANEOUS

DISREGARD
 SEAT BELT
 UNWARRANTED
 CORRECTING
 FATIGUE FROM
 SEPARATION
 CORRODED/CORRODED
 FUEL EXHAUST
 ALCOHOLIC
 IMPROPERLY
 INTERFERED
 AIRCRAFT CONTROL
 OVERLOAD FUEL
 MATERIAL FAILURE
 DISCONNECTED
 FLUTTER
 JAMMED

DIRECT CAUSAL

Table 5 (cont.)

CAUSE/FACTOR TABLE

MISCELLANEOUS (CONTINUED)

| | FATAL ACCIDENTS | | | NONFATAL ACCIDENTS | | | ALL ACCIDENTS | | |
|---|-----------------|--------|-------|--------------------|--------|-------|---------------|--------|-------|
| | CAUSE | FACTOR | TOTAL | CAUSE | FACTOR | TOTAL | CAUSE | FACTOR | TOTAL |
| UNDETERMINED | 2 | | 2 | 1 | | 1 | 3 | | 3 |
| SUBTOTAL | 2 | 1 | 3 | 2 | | 2 | 4 | 1 | 5 |
| GRAND TOTAL | 147 | 28 | 175 | 51 | 6 | 57 | 198 | 34 | 232 |
| ** MISCELLANEOUS ACTS, CONDITIONS ** | | | | | | | | | |
| DISREGARD OF GOOD OPERATING PRACTICE | 1 | | 1 | | | 1 | 1 | 1 | 2 |
| SEAT BELT NOT FASTENED | | 2 | 2 | | | | 2 | 2 | |
| UNWARRANTED LOW FLYING | 28 | 16 | 44 | 5 | | 5 | 33 | 16 | 49 |
| CORRECTING LENSES-NOT USED | | 1 | 1 | | | | 1 | 1 | |
| FATIGUE FRACTURE | | | | 1 | | 1 | | 3 | 3 |
| SEPARATION IN FLIGHT | | 3 | 3 | | | | 1 | 1 | |
| CORRODED/CORROSION | | 1 | 1 | | | | 1 | 1 | |
| FUEL EXHAUSTION | | | | | | | 1 | 1 | |
| ALCOHOLIC IMPAIRMENT OF EFFICIENCY AND JUDGMENT | 3 | 5 | 8 | | | 1 | 1 | | 1 |
| IMPROPERLY LOADED AIRCRAFT-WEIGHT-AND/OR CG | | 3 | 3 | | | | 3 | 5 | 8 |
| INTERFERENCE WITH FLIGHT CONTROLS | 1 | | 1 | | | | 1 | 3 | 3 |
| AIRCRAFT CAME TO REST IN WATER | | 8 | 8 | | 2 | 2 | 1 | 10 | 10 |
| OVERLOAD FAILURE | 1 | 2 | 3 | | | | 1 | 2 | 3 |
| MATERIAL FAILURE | 1 | | 1 | 1 | | 1 | 2 | | 2 |
| DISCONNECTED | 1 | | 1 | | | | 1 | | 1 |
| FLUTTER | | | 1 | | | | 1 | | 1 |
| JAMMED | | | 1 | | | 1 | 1 | | 1 |

DIRECT ENTRY CAUSES ARE CARRIED UNDER THEIR APPROPRIATE
CAUSAL CATEGORIES AND ARE INCLUDED IN THE TOTALS

APPENDIX D

AEROBATIC REGULATIONS
(CFR 91 - General Operating and Flight Rules)

There are several regulations under the General Operating and Flight Rules of Part 91 which relate directly or indirectly to flight operations involving aerobatics. These include:

CFR 91.9 CARELESS OR RECKLESS OPERATION

No person may operate an aircraft in a careless or reckless manner so as to endanger the life or property of another.

CFR 91.9.15 PARACHUTES AND PARACHUTING

(a) No pilot of a civil aircraft may allow a parachute that is available for emergency use to be carried in that aircraft unless it is an approved type and-

(1) If a chair type (canopy in back), it has been packed by a certificated and appropriately rated parachute rigger within the preceding 120 days; or

(2) If any other type, it has been packed by a certificated and appropriately rated parachute rigger within the preceding 60 days.

(b) Except in an emergency, no pilot-in-command may allow, and no person may make, a parachute jump from an aircraft within the United States except in accordance with Part 105 of this chapter.

(c) Unless each occupant of the aircraft is wearing an approved parachute, no pilot of a civil aircraft, carrying any person (other than a crewmember) may execute any intentional maneuver that exceeds-

(1) A bank of 60 degrees relative to the horizon; or

(2) A nose-up or nose-down attitude of 30 degrees relative to the horizon.

(d) Paragraph (c) of this section does not apply to-

(1) Flight tests for pilot certification or rating; or

(2) Spins and other flight maneuvers required by the regulations for any certificate or rating when given by-

(i) A certificated flight instructor; or

(ii) An airline transport pilot instructing in accordance with paragraph 61.163 of this chapter.

APPENDIX D

(e) For the purposes of this section, "approved parachute" means-

- (1) A parachute manufactured under a type certificate or a technical standard order (C-23 series); or
- (2) A personnel-carrying military parachute identified by an NAF, AAF, or AN drawing number, an AAF order number, or any other military designation or specification number.

CFR 91.63 WAIVERS

(a) The Administrator may issue a certificate of waiver amay issue a certificate of waiver authorizing the operation of aircraft in deviation of any rule of this subpart if he finds that the proposed operation can be safely conducted under the terms of that certificate of waiver.

(b) An application for a certificate of waiver under this section is made on a form and in a manner prescribed by the Administrator and may be submitted to any FAA office.

(c) A certificate of waiver is effective as specified in that certificate.

CFR 91.71 ACROBATIC FLIGHT

No person may operate an aircraft in acrobatic flight-

- (a) Over any congested area of a city, town, or settlement;
- (b) Over an open air assembly of persons;
- (c) Within a control zone or Federal airway;
- (d) Below an altitude of 1,500 feet above the surface; or

(e) When flight visibility is less than 3 miles. For the purpose of this section, acrobatic flight means an intentional maneuver involving an abrupt change in an aircraft's attitude, an abnormal attitude or abnormal acceleration, not necessary for normal flight.

APPENDIX E

FAA FLIGHT INSTRUCTOR BULLETIN NO. 18--AIRPLANE SPRINNING




No. 18

- 103 -

FLIGHT INSTRUCTOR BULLETIN

APPENDIX E



FIB 8/75

DEPARTMENT OF TRANSPORTATION - FEDERAL AVIATION ADMINISTRATION - CENTRAL REGION

This month's Flight Instructor Bulletin is devoted entirely to excellent information regarding spins contributed by the Cessna Aircraft Company. Hopefully, we will be able to present information regarding flight characteristics of other aircraft in future issues.

The subject of airplane spinning is a complex one, which is often oversimplified during hangar-flying sessions. There are increasing numbers of pilots, including flight instructors, who, because of the structure of present pilot certification requirements, have had little or no training in spins and spin recovery. This has resulted in some confusion and misunderstanding over the behavior of airplanes in spinning flight, and it appears that this lack of understanding may have contributed to some serious accidents. In the interest of expanding each pilot's knowledge and increasing the safety of his operations, we will discuss some factors influencing spin behavior as it pertains to the Cessna Models 150, A150, 172, and 177 which are approved for intentional spins.

The following list summarizes important safety points relative to the performance of intentional spins.

BASIC GUIDELINES FOR INTENTIONAL SPINS


- (1) KNOW YOUR AIRCRAFT THOROUGHLY.
- (2) PRIOR TO DOING SPINS IN ANY MODEL AIRCRAFT, OBTAIN THOROUGH INSTRUCTION IN SPINS FROM AN INSTRUCTOR FULLY QUALIFIED AND CURRENT IN SPINNING THAT MODEL.
- (3) BE FAMILIAR WITH THE PARACHUTE, AIRSPACE AND WEATHER REQUIREMENTS OF FAR 91.15 and 91.71 AS THEY AFFECT YOUR FLIGHT.
- (4) CHECK THE AIRCRAFT WEIGHT AND BALANCE TO BE SURE YOU ARE WITHIN THE APPROVED ENVELOPE FOR SPINS.
- (5) SECURE OR REMOVE ALL LOOSE COCKPIT EQUIPMENT PRIOR TO TAKEOFF.
- (6) BE SURE THE AREA TO BE USED IS SUITABLE FOR SPINS AND IS CLEAR OF OTHER TRAFFIC.

APPENDIX E

- (7) ENTER EACH SPIN AT A HIGH ALTITUDE. PLAN RECOVERIES TO BE COMPLETED WELL ABOVE THE MINIMUM LEGAL ALTITUDE OF 1500 FEET ABOVE THE SURFACE.
- (8) CONDUCT ALL ENTRIES IN ACCORDANCE WITH THE PROCEDURES RECOMMENDED BY THE MANUFACTURER.
- (9) LIMIT YOURSELF TO 2-TURN SPINS UNTIL COMPLETELY FAMILIAR WITH THE CHARACTERISTICS OF YOUR AIRPLANE.
- (10) USE THE FOLLOWING RECOVERY PROCEDURES FOR THE CESSNA MODELS 150, 172, AND 177:
 - (a) VERIFY THAT THE THROTTLE IS IN IDLE AND AILERONS ARE NEUTRAL.
 - (b) APPLY AND HOLD FULL RUDDER OPPOSITE TO THE DIRECTION OF ROTATION.
 - (c) JUST AFTER THE RUDDER REACHES THE STOP, MOVE THE CONTROL WHEEL BRISKLY FORWARD FAR ENOUGH TO BREAK THE STALL. Full down elevator may be required at aft center of gravity loadings in some airplane models to assure optimum recoveries.
 - (d) HOLD THESE CONTROL INPUTS UNTIL ROTATION STOPS. Premature relaxation of the control inputs may extend the recovery.
 - (e) AS THE ROTATION STOPS NEUTRALIZE RUDDER AND MAKE A SMOOTH RECOVERY FROM THE RESULTING DIVE.

For the purpose of this discussion, we will divide the spin into three distinct phases. These are the entry, incipient, and steady phases. These are illustrated in the figure. The basic cause of a spin is a difference in lift and drag between the two wings with the airplane operating in essentially stalled flight. Entry to this condition is initiated, intentionally or otherwise, when the airplane is stalled in uncoordinated flight. This causes one wing to reach a higher angle of attack than the other. Beyond stall angles of attack, lift begins decreasing while drag rises rapidly. This causes a sustained autorotation to begin because of the decreased lift and increased drag of one wing half as compared to the other.

Here, in the entry phase, recovery from or prevention of the spin is as simple as normal stall recovery since, in fact, at this point that's all we are really faced with. Coordinated use of rudder and aileron to oppose any tendency to roll should be applied with emphasis on the rudder due to its generally more powerful influence at this point. This should be accompanied by relaxation of elevator back pressure to reduce the angle of attack below that of the stall. Coordinated use of all controls should then be applied to return to normal



APPENDIX E

level flight. During this entry phase recovery of control (or prevention of loss of control) will normally be instantaneous for all practical purposes as soon as the stall is broken.

The second or incipient phase covers that period of time from the spin entry to the fully stabilized spin. During this period the yaw being produced by a deflected rudder while the airplane is stalled is supplemented by the differences in lift and drag between the two wing panels. These parameters cause the rotating motion of the airplane to begin to increase.

During this incipient phase, spin recoveries in those airplanes approved for intentional spins are usually rapid, and, in some airplanes, may occur merely by relaxing the pro-spin rudder and elevator deflections. However, positive spin recovery control inputs should be used regardless of the phase of the spin during which recovery is initiated. Briefly, these control inputs should be 1) power off, 2) full rudder opposite to the direction of rotation, 3) just after the rudder reaches the stop, elevator briskly forward to break the stall, and 4) as rotation stops, neutralize the controls and recover from the resulting dive. Using these procedures, recoveries are typically accomplished in form 1/8 to 1/2 turn during the incipient phase.

The final phase is the fully developed "steady" phase. Here, a more-or-less steady state spin results where the autorotational aerodynamic forces (Yaw due to rudder deflection, lift and drag differences across stalled wing) are balanced by the centrifugal and gyroscopic forces on the airframe produced by the rotating motion. Due to the attitude of the airplane in a spin the total motion is made up of rolling and usually pitching motions as well as the predominant yawing motions. Movement of the airplane flight controls affects the rate of motion about one of the axes. Because of the strong gyroscopic influences in the spin, improper aerodynamic control inputs can have an adverse affect on the spin motion.

Aileron variations from neutral can cause a different balance between the aerodynamic, inertia and gyroscopic forces and cause some delay in recoveries. Typically even a slight inadvertent aileron deflection in the direction of the spin will speed up rotation and delay recoveries. Moving the elevator control forward while maintaining pro-spin rudder deflection may not provide a recovery with some airplanes. In fact, reversing the sequence of rudder-elevator inputs or even just slow, rather than brisk, inputs may lengthen recoveries. Finally, it is important, particularly in this steady spin phase, in addition to using the correct control application and the proper sequence of control application, to HOLD THIS APPLICATION UNTIL THE RECOVERIES OCCUR. In extreme cases, this may require a full turn or more with full down elevator deflection.

The proper recovery control inputs to obtain optimum recovery characteristics in Cessna single engine airplanes are repeated here and amplified somewhat from those listed under the incipient phase.

- (1) VERIFY THAT THE THROTTLE IS IN IDLE AND AILERONS ARE NEUTRAL.

The
inci
inci
to a
or n
tior
in s
CONT

Some
beha
buti

Dist
spin
grav
This
weig
reco
to ol
extre
a mon
well
in g
sligt

High
provi
does

Airpl
eleva
and a
can a
reduc
recov

APPENDIX E

- (2) APPLY AND HOLD FULL RUDDER OPPOSITE TO THE DIRECTION OF ROTATION.
- (3) JUST AFTER THE RUDDER REACHES THE STOP, MOVE THE CONTROL WHEEL BRISKLY FORWARD FAR ENOUGH TO BREAK THE STALL. Full down elevator may be required at aft center of gravity loadings in some airplane models to assure optimum recoveries.
- (4) HOLD THESE CONTROL INPUTS UNTIL ROTATION STOPS. Premature relaxation of the control inputs may extend the recovery.
- (5) AS THE ROTATION STOPS NEUTRALIZE RUDDER AND MAKE A SMOOTH RECOVERY FROM THE RESULTING DIVE.

The emphasis added to these steps differentiates the steady phase from the incipient phase. The most important difference in the steady phase is an increase in the length of recoveries in this phase for some airplanes, and to a lesser extent the amount of control input needed. Up to a full turn or more to recover is not unusual in this phase. Full down elevator deflection will sometimes be needed to assure optimum recoveries at aft loadings in some airplanes. Therefore IT IS VERY IMPORTANT TO APPLY THE RECOVERY CONTROLS IN THE PROPER SEQUENCE AND THEN HOLD THEM UNTIL RECOVERY OCCURS.

Some of the additional factors which have (or may have) an effect on spin behavior and spin recovery characteristics are aircraft loading (distribution, center of gravity and weight), altitude, power, and rigging.

Distribution of the weight of the airplane can have a significant effect on spin behavior. The addition of weight at any distance from the center of gravity of the airplane will increase its moment of inertia about two axes. This increased inertia independent of the center of gravity location or weight will tend to promote a less steep spin attitude and more sluggish recoveries. Forward location of the c.g. will usually make it more difficult to obtain a pure spin due to the reduced elevator effectiveness. Conversely, extremely aft c.g. locations will tend to promote lengthened recoveries since a more complete stall can be achieved. Changes in airplane gross weight as well as its distribution can have an affect on spin behavior since increases in gross weight will increase inertia. Higher weights may extend recoveries slightly.

High altitudes will tend to lengthen recoveries since the less dense air provides less "bite" for the controls to oppose the spin. However, this does not suggest the use of low altitudes for spin practice.

Airplane rigging can have a strong influence on spin characteristics. Improper elevator and rudder deflection stops can alter the depth of entry into a spin and also can alter the amount of recovery control available. Low cable tensions can alter the amount of travel available at the control surface and may thus reduce the control power available for either entry to an intentional spin or recovery.

APPENDIX E

Power can affect the spinning attitude. If power is carried in the spin the airplane attitude may be less nose down. In addition the propeller will tend to add some gyroscopic inputs which will be reversed between left and right spins. The effect of leaving power on during a spin may lengthen recoveries on some airplanes.

The foregoing areas have been considered in the design and certification of an airplane. If the airplane is maintained and operated within manufacturers approved limitations, then spin characteristics and recoveries will be acceptable although the trends mentioned above may be evident.

The next several paragraphs will briefly describe the typical spin characteristics of recent Cessna models approved for spins.

150F through 150L - A150K through A150L

Entries at an aft c.g. will be positive from a power off unaccelerated stall. At more forward c.g. locations, a slightly higher deceleration rate may be necessary.

The incipient phase rotation will be rapid and the nose will progress to an average 60° to 70° nose down attitude in the vicinity of two turns.

At aft c.g. loadings at $2\frac{1}{2}$ to 3 turns as the airplane enters the steady phase, there may be evident some change in character of the spin. The nose attitude may become less steep and rise to approximately 45° to 50° below the horizon. In addition some change in sideslip will be felt and rotation rates will change some. As the c.g. is moved forward this tendency to change character will disappear and spiral tendencies may appear.

Recoveries during the entry and incipient phases will vary from $1/4$ to $1/2$ turn typically at aft c.g. loadings to practically instantaneous at forward c.g. loadings. Recoveries from extended spins will vary from in excess of a full turn at aft c.g. to $1/2$ turn typically at forward c.g. locations.

150M - A150M

Spin characteristics for this model are similar to those of the earlier models except as follows. Entries at forward c.g. loadings will be more difficult to accomplish without more rapid deceleration.

The incipient phase will be almost the same as for the older models but the character change upon entering the stable phase will be subdued but still evident at aft c.g. loadings. The nose attitude change may not be evident at all, although some variation in rotation rate and sideslip may be noted.

Recoveries will be similar to those of the earlier models from all phases although a slight reduction in recovery turns ($1/8$ to $1/4$) may be evident.

APPENDIX E

172H through 172L (1971)
Utility Category Only

Entries at an aft c.g. (utility aft) will be positive. At forward c.g. locations, more rapid deceleration or some power will be necessary to obtain an entry.

The airplane will pass rapidly through the incipient phase into the steady phase with little change to note.

Recoveries in the entry and incipient phases will be up to 1/8 of a turn at aft c.g. locations to almost instantaneous at forward c.g.'s. The steady phase recoveries will take up to 1/2 turn at aft c.g. and to about 1/8 turn at forward c.g. locations.

172L (1972) through 172M (Utility Category Only)

Entries at all utility loadings will be difficult to obtain unless some power and a slight amount of aileron toward the desired spin direction are applied.

Throughout the incipient phase, spiral tendencies will be evident and the airplane will usually spiral out of the spin by 2-1/2 to 3-1/2 turns even at aft c.g. loadings (utility aft).

There is no real steady phase with this model. Recoveries initiated at any point in the spin at any loading will result in practically instantaneous recoveries.

177 through 177B (Utility Category Only)

Entries are positive although some added deceleration or power may be necessary at forward loadings.

In incipient phase, nose attitude may cycle beyond vertical during the first 2 turns.

In the steady phase spiralling tendencies will be evident especially at forward loadings. Nose attitude will be in the area of 60° nose down. Recoveries during the entry and incipient phases will take no more than 1/4 turn and during the steady phase up to 3/4 turn regardless of loading.

For the purpose of training in spins and spin recoveries, a one or two turn spin will normally provide all that is necessary. All of the characteristic motions and control inputs required will have been experienced. Longer spins, while acceptable as a maneuver in appropriately certified airplanes, provide little additional insight to a student in the area of spin recovery since the prime reason for conducting a spin is to learn how to avoid an inadvertent entry in the first place and then how to recover if one should develop.

APPENDIX E

It is recommended that, where feasible, entries be accomplished at high enough altitude that recoveries are completed 4000 feet or more above ground level. In any case, entries should be planned so that recoveries are conducted well above the minimum 1500 feet above ground level required by FAR 91.71.

Another reason for using high altitudes for practicing spins is that a greater field of view is provided which will assist in maintaining pilot orientation. However, if disorientation does occur and precludes a visual determination of the direction of rotation, the symbolic airplane of the turn coordinator or the needle of the turn and bank indicator (not the ball) may be referred to for this information.

Finally, a pilot planning to spin a new model for the first time or after a long absence from this type of maneuver should first fly with a qualified instructor pilot who can point out key points in the spin and recovery procedure for this particular type of airplane. The weight and balance should be checked carefully to assure that the spins will be conducted at an approved loading. As previously stated, plenty of altitude should be maintained at all times. Owner's manual procedures for the spin and spin recovery should be rigorously followed for the optimum and most repeatable characteristics.

Understanding of the information provided in this bulletin and adherence to the recommendations will assure each pilot the utmost safety of his flight.

#

CAUTION

Certain makes of Emergency Locator Transmitters utilize Lithium batteries. If these batteries are subjected to rapid discharge such as when they become shorted, they quite quickly release a quantity of Sulfur Dioxide. If the concentration of this gas becomes high, it irritates the eyes and can virtually incapacitate a pilot.

Luckily this gas has a very "loud" odor like burning sulfur or rotten eggs and is easily detected.

At the first indication of the presence of sulfur dioxide in your aircraft ventilate the cabin to the maximum degree possible. If oxygen is available, breathing 100% oxygen will help, as will the use of well fitted smoke glasses.

Indications are that if the ELT is within the cabin area and has several cells in it, the batteries can release enough sulfur dioxide to pose a serious problem.

#

SAFETY IS EVERYONE'S BUSINESS