

National Transportation Safety Board

**FACTUAL REPORT**

AVIATION

NTSB ID: ATL04FA038

Aircraft Registration Number: N4482S

Occurrence Date: 11/21/2003

Most Critical Injury: Fatal

Occurrence Type: Accident

Investigated By: NTSB

**Location/Time**

Nearest City/Place	State	Zip Code	Local Time	Time Zone	
Griffin	GA	30224	1245	EST	
Airport Proximity: Off Airport/Airstrip		Distance From Landing Facility: 1		Direction From Airport: 290	

**Aircraft Information Summary**

Aircraft Manufacturer	Model/Series	Type of Aircraft
Beech	55	Airplane

**Sightseeing Flight:** No**Air Medical Transport Flight:** No**Narrative**

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

**HISTORY OF FLIGHT**

On November 21, 2003, at 1245 eastern standard time, a Beech Baron 55, N4482S, registered and operated by River Chase Development Aviation Co. collided with a building during climb-out at Spaulding County Airport, Griffin, Georgia. Visual meteorological conditions prevailed at the time of the accident and no flight plan was filed. The airplane was substantially damaged and the pilot was fatally injured. The flight departed Spaulding County Airport on November 21, 2003 at 1240.

According to the company's chief maintenance inspector, the purpose of the flight was to conduct a maintenance test flight of the airplane on recently installed equipment the pilot/ mechanic had just completed. Before engine start-up the pilot/ mechanic conducted a pre-flight of the airplane, and then taxied out to the ramp and ran the engine up to full rpm three consecutive times before the test flight. The pilot taxied to runway 32, and proceeded to add full power for take-off. As the airplane began to rotate for climb out the engines sounded like they began to "backfire". The engines continued to make this sound as it climbed out. The airplane climbed approximately 200 feet and the left wing pitch down. The airplane descended under the tree line and a "loud explosion" was heard.

According to other witnesses, as the airplane flew overhead the engines sounded as though they were "sputtering" as it climbed out. The airplane began to roll into a left bank, and descended below the tree line. Shortly after a "loud explosion" was heard.

There was no distress call heard from the pilot at time of the accident. The airplane collided with building mile from the departure end of runway 32.

**PERSONNEL INFORMATION**

Review of pilot records revealed the pilot was issued a commercial pilot certificate on May 14, 1982, with ratings for airplane single-engine land, multiengine land, instrument airplane, and glider aero tow. Review of records revealed the pilot held an aircraft mechanic certificate with ratings for airframe and power plant. The pilot held a second-class medical certificate issued on April 22, 2003, valid when wearing corrective lenses. Review of the pilot experience form indicated that the pilot accumulated a total of 2,500 flight hours. The pilot's logbook was not recovered for review.

(Continued on next page)

National Transportation Safety Board

**FACTUAL REPORT****AVIATION**

NTSB ID: ATL04FA038

Occurrence Date: 11/21/2003

Occurrence Type: Accident

**Narrative (Continued)****AIRCRAFT INFORMATION**

Review of airplane logbooks indicated the last recorded annual inspection was conducted on November 04, 2002; the total tachometer time was 1690. The altimeter system, static pressure system, and transponder were inspected on April 24, 2001 and were found in compliance.

**METEOROLOGICAL INFORMATION**

The nearest weather reporting facility at the time of the accident was Macon, Georgia. The 1253 surface weather observation was: clear, visibility 10 miles, temperature 22 degrees Celsius, dew point temperature 04 degrees Celsius, winds calm, altimeter reading of 30.13.

**WRECKAGE AND IMPACT INFORMATION**

Examination of the wreckage site revealed, the airplane came to rest on top of a commercial building approximately mile from the end of runway 32. The wreckage debris path extended approximately 60 feet in length along the top of the roof. The initial point of impact was approximately 30 feet high at the edge of the commercial building. Approximately 30 feet along the wreckage debris path a vent duct displayed six propeller slash marks followed by a hole in the roof of the building where the right engine came to rest. Approximately 25 feet forward of the propeller damaged vent duct the airplane fuselage came to rest on the roof of the building. Wreckage debris was spread over an area of approximately 25 yards in diameter.

Post-accident examination of the cabin section of the airplane, and the main fuselage revealed that they were fire damaged. All flight control and communication instruments were fire damaged.

Post-accident examination of the right wing assembly revealed the right wing was connected to the fire damaged fuselage by the main spar. The outboard section of the right wing assembly was distorted aft. A six-foot section of the left wing assembly came to rest in the parking lot of the building. The left wing section was distorted and fire damaged. The left wingtip was located approximately 25 feet aft of the initial impact point. The left and right horizontal stabilizers, and vertical stabilizer were fire damaged. Flight control cables were fire damaged and located within the wreckage debris. Cable ends with the respective flight control cables were attached. The flight control chains for the elevator trim and control wheel interconnect chains were found intact.

Post-accident examination of the left engine revealed that it was fire damaged. The left propeller and crankshaft-mounting flange were broken free of the crankshaft. The crankshaft was turned through approximately 290-degrees of rotation. Gear and valve train continuity was confirmed. Compression and suction was obtained on all cylinders. The external examination of the left engine revealed that all external components were fire damage. Post-accident examination of the spark plug revealed that they were intact and the barrels were fire damaged. The top spark plug electrodes were normal when compared to the Champion Aviation Check-A-Plug.

Post-accident examination of the right engine revealed that the external components of the engine were intact, and sustained damage. The engine was examined, and it was determined that it would be prepared for a field test run. The engine was started and ran at idle. After warm up, the throttle was advanced to 1700 rpm and a magneto grounding check was performed. The throttle was advanced to full power, reduced to

(Continued on next page)

National Transportation Safety Board


**FACTUAL REPORT**  
**AVIATION**

NTSB ID: ATL04FA038

Occurrence Date: 11/21/2003

Occurrence Type: Accident

**Narrative (Continued)**

idle and shut down with the mixture. At the conclusion of the field test run the no mechanical anomalies were noted that would have prevented the engine from developing power prior to the accident. The engine was also test run at the factory test cell. Throughout the test phase, the engine accelerated normally without any hesitation, stumbling or interruption in power, and demonstrated the ability to produce rated horsepower. No mechanical anomalies were noted at the conclusion of the factory test run.

Post-accident examination of blades from both propeller assemblies revealed rotational scoring. Post-accident examination of the propellers revealed both propellers were rotating and not in the feathered position. There were no pre-impact mechanical anomalies noted with the propeller blades.

**MEDICAL AND PATHOLOGICAL INFORMATION**

The Division of Forensic Sciences Georgia Bureau of Investigation State of Georgia conducted postmortem examination of the pilot, on November 22, 2003. The cause of death was fire-related injuries including smoke inhalation. The Forensic Toxicology Research Section, Federal Aviation Administration, Oklahoma City, Oklahoma performed postmortem toxicology of specimens from the pilot. The results were negative for carbon monoxide, cyanide, and ethanol.

**ADDITIONAL INFORMATION**

Review of the Beechcraft Baron B55 pilot operating manual emergency procedures section states: After Engine failure on lift-off and in-flight; requires immediate pilot response of the following procedures in order to continue flight.

1. Landing Gear and Flaps- UP
2. Throttle (inoperative engine)- Closed
3. Propeller (inoperative engine)- Feather
4. Power (operative engine)- As Required
5. Airspeed- Maintain speed at engine failure (100 KTS (115 mph) max.) until obstacles are cleared.

Review of the maintenance work order revealed that a Shadin Digilfo-L fuel flow indicator and fuel flow transducers on the right and left engines were installed by the pilot/mechanic prior to the flight. The fuel flow transducers were installed in accordance with supplemental type certificate (STC) SA579GL and SE552GL.

Post examination of left fuel flow transducer serial number 130436 revealed it was charred, and the inlet hose coupler was not as tight as the outlet hose coupler. Fuel was poured into the inlet side of the transducer, and the outlet flow was restricted. The fitting on the inlet side was removed and the inlet was inspected. Debris was found around the inlet orifice. The debris was inspected and was similar to that of the connecting hose. After removing the debris from the Fuel flow transducer, fuel was again poured into the inlet and fuel exited the outlet without restriction to flow.

Post examination of the right fuel flow transducer serial number 130437 revealed it was intact with no visible damage, and both hose couplers were tight. Fuel was poured into the inlet side of the transducer, and the fuel exited the outlet side of the transducer without visible restriction to flow.

The wreckage of N4482S was released to International loss Management on July 2, 2004.

National Transportation Safety Board


**FACTUAL REPORT  
AVIATION**

NTSB ID: ATL04FA038

Occurrence Date: 11/21/2003

Occurrence Type: Accident

**Landing Facility/Approach Information**

Airport Name Griffin Spalding Airport	Airport ID: 6A2	Airport Elevation Ft. MSL	Runway Used 32	Runway Length 3701	Runway Width 75
--	--------------------	------------------------------	-------------------	-----------------------	--------------------

Runway Surface Type: Asphalt

Runway Surface Condition: Dry

Type Instrument Approach: NONE

VFR Approach/Landing: None

**Aircraft Information**

Aircraft Manufacturer Beech	Model/Series 55	Serial Number TC-1882
--------------------------------	--------------------	--------------------------

Airworthiness Certificate(s): Normal

Landing Gear Type: Retractable - Tricycle

Homebuilt Aircraft? No	Number of Seats: 6	Certified Max Gross Wt. 4500 LBS	Number of Engines: 2
------------------------	--------------------	----------------------------------	----------------------

Engine Type: Reciprocating	Engine Manufacturer: Continental	Model/Series: IO-470L-21B	Rated Power: 260 HP
-------------------------------	-------------------------------------	------------------------------	------------------------

**- Aircraft Inspection Information**

Type of Last Inspection Annual	Date of Last Inspection 12/4/2002	Time Since Last Inspection 90 Hours	Airframe Total Time 1960 Hours
-----------------------------------	--------------------------------------	--	-----------------------------------

**- Emergency Locator Transmitter (ELT) Information**

ELT Installed? Yes	ELT Operated? No	ELT Aided in Locating Accident Site? No
--------------------	------------------	---

**Owner/Operator Information**

Registered Aircraft Owner River Chase Development Aviation Co.	Street Address 30 Old Rudnick Ln		
	City Dover	State DE	Zip Code 19901
Operator of Aircraft River Chase Development Aviation Co.	Street Address 30 Old Rudnick Ln.		
	City Dover	State DE	Zip Code 19901

Operator Does Business As:	Operator Designator Code:
----------------------------	---------------------------

**- Type of U.S. Certificate(s) Held: None**

Air Carrier Operating Certificate(s):

Operating Certificate:	Operator Certificate:
------------------------	-----------------------

Regulation Flight Conducted Under: Part 91: General Aviation

Type of Flight Operation Conducted: Flight Test

National Transportation Safety Board

## FACTUAL REPORT

AVIATION

NTSB ID: ATL04FA038

Occurrence Date: 11/21/2003

Occurrence Type: Accident

## First Pilot Information

Name	City	State	Date of Birth	Age
John R Bennaman	Fayetteville	GA	On File	47

Sex: M	Seat Occupied: Left	Principal Profession: Aircraft Mechanic	Certificate Number: On File
--------	---------------------	---	-----------------------------

Certificate(s): Commercial

Airplane Rating(s): Multi-engine Land; Single-engine Land

Rotorcraft/Glider/LTA: Glider

Instrument Rating(s): Airplane

Instructor Rating(s): None

Type Rating/Endorsement for Accident/Incident Aircraft? No Current Biennial Flight Review?

Medical Cert.: Class 2 Medical Cert. Status: With Waivers/Limitations Date of Last Medical Exam: 4/22/2003

- Flight Time Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Multi-Engine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	2500		1350		350	300	100			
Pilot In Command(PIC)										
Instructor										
Last 90 Days	50									
Last 30 Days										
Last 24 Hours										

Seatbelt Used? Yes Shoulder Harness Used? Yes Toxicology Performed? Yes Second Pilot? No

## Flight Plan/Itinerary

Type of Flight Plan Filed: None

Departure Point	State	Airport Identifier	Departure Time	Time Zone
Same as Accident/Incident Location		6A2	1240	EST

Destination	State	Airport Identifier
Same as Accident/Incident Location		6A2

Type of Clearance: VFR

Type of Airspace: Class E

## Weather Information

Source of Briefing: Unknown

Method of Briefing: Unknown

National Transportation Safety Board

**FACTUAL REPORT****AVIATION**

NTSB ID: ATL04FA038

Occurrence Date: 11/21/2003

Occurrence Type: Accident

**Weather Information**

WOF ID	Observation Time	Time Zone	WOF Elevation	WOF Distance From Accident Site	Direction From Accident Site
FFC	1253	EST	808 Ft. MSL	10 NM	270 Deg. Mag.
Sky/Lowest Cloud Condition: Clear				Ft. AGL	Condition of Light: Day
Lowest Ceiling: None			Ft. AGL	Visibility: 10 SM	Altimeter: 30.13 "Hg
Temperature: 22 °C	Dew Point: 4 °C	Wind Direction: 0		Density Altitude: 1635 Ft.	
Wind Speed: Calm	Gusts:	Weather Conditions at Accident Site: Visual Conditions			
Visibility (RVR): Ft.	Visibility (RVV) SM	Intensity of Precipitation:			
Restrictions to Visibility: None					
Type of Precipitation: None					

**Accident Information**

Aircraft Damage: Destroyed	Aircraft Fire: Ground	Aircraft Explosion: None
----------------------------	-----------------------	--------------------------

Classification: U.S. Registered/U.S. Soil

- Injury Summary Matrix	Fatal	Serious	Minor	None	TOTAL
First Pilot	1				1
Second Pilot					
Student Pilot					
Flight Instructor					
Check Pilot					
Flight Engineer					
Cabin Attendants					
Other Crew					
Passengers					
- TOTAL ABOARD -	1				1
Other Ground					
- GRAND TOTAL -	1				1

National Transportation Safety Board

  
**FACTUAL REPORT**  
**AVIATION**

NTSB ID: ATL04FA038

Occurrence Date: 11/21/2003

Occurrence Type: Accident

**Administrative Information**

Investigator-In-Charge (IIC)

Eric H Alleyne

Additional Persons Participating in This Accident/Incident Investigation:

Jose E. Gueits  
Aviation Safety Inspector  
Atlanta FSDO  
1701 Columbia Ave.  
College Park, GA 30337

Brain Cassidy

## National Transportation Safety Board

**Docket Contents****Project Information**

Project ID (mkey) Mode

**58382 Aviation**

NTSB Accident ID

**ATL04FA038**

Occurrence Date

**Nov 21, 2003**

Location

**Griffin, GA, United States****Docket Information**

Creation Date

**Jul 20, 2004**

Last Modified

**May 31, 2005 17:13**

Public Release Date &amp; Time

**May 31, 2005 17:15**

Comments

**List of Contents****Results 1 through 15 of 15****Total Pages 98/Photos 0**

Document	Filing Date	Document Title	Pages	Photo
1	Oct 04, 2004	Engine Log- Left	5	
2	Oct 04, 2004	Engine Log- Right	9	
3	Oct 04, 2004	FAA Form 337 & STC Attachments	9	
4	Oct 04, 2004	Hartzell Propeller Report	11	
5	Oct 04, 2004	Inspection Report	2	
6	Oct 04, 2004	Propeller Log- Left	3	
7	Oct 04, 2004	Propeller Log- Right	5	
8	Oct 04, 2004	STC SA579GL	15	
9	Oct 04, 2004	STC SE443GL	16	
10	Oct 04, 2004	STC SE552GL	11	
11	Oct 04, 2004	Toxicological Report	1	
12	Oct 04, 2004	Witness Statements	4	
13	Oct 04, 2004	Work Order	4	
14	Oct 04, 2004	Release of Aircraft Wreckage, NTSB Form 6120.15	2	
15	May 31, 2005	Emergency Procedures	1	

LEFT

# REBUILT ENGINE LOG

N44825

AIRCRAFT N NUMBER

I0470 L-21B

ENGINE MODEL NUMBER

297519R

ENGINE SERIAL NUMBER

USE ONLY  
FUEL  
CONFORMING  
TO ASTM D910.

USE OF AUTOMOTIVE  
GAS IS NOT  
APPROVED.

Left Hand

OWNERS NAME \_\_\_\_\_  
ADDRESS \_\_\_\_\_ CITY \_\_\_\_\_ STATE \_\_\_\_\_

[illegible]

**ENGINE 1 NO**

DATE	DESCRIPTION	SIGNATURE	LICENSE NUMBER
	<p>TSMOH 0</p> <p>Teledyne Continental: IO-470-L S/N 297519-R CS</p> <p>10/18/2002</p> <p>Engine overhauled this date in accordance with Federal Aviation Administration Regulations, Manufacturer's Overhaul Manual and Parts Manual. New parts include: oil seals, cylinder base seals, gaskets, packings, circlips, lockplates, retaining-rings, Crankshaft blade bushings, counterweight bushings, pistons (STD) R, piston rings, piston pins, rocker shafts, exhaust valves, exhaust valves, intake valves and seats (as needed), bearing inserts - rods and mains (STD), ball bearings, roller bearings, rubber couplings, cotter pins, lockwashers, and spark-plugs. All steel magnifluxed by Aircraft Specialties - Tulsa, OK. All hardware plated by United Plating - Tulsa, OK. Crankshaft polished rods and mains (STD) and ultrasonic by Aircraft Specialties. Camshaft reground by Aircraft Specialties. Hydraulic Lifters reconditioned by Rock Aviation - Bourne, TX. Cylinders reworked and honed to a ring finish std steel bore. Magnetos overhauled. Fuel System overhauled by Mike's Fuel Metering - Tulsa, OK. Engine test run by Custom Airmotive - Tulsa, OK. Engine is approved for return to service.</p> <p><i>Thomas H. Cifer</i></p> <p>Sky Tech International, Inc.</p>		

**BROUG**

DATE TIME	R.P.M.	TIME ON GROUND	
	Ground	Air	Hrs. Min.

**GARDNER AVIATION SERVICE**  
**LOG ID# 937    04-December**  
**N4482S    S/N TC-1882**

ENGINE AND PROPELLER WAS INTERNATIONAL REINSTALLED.  
PHC-C3YF-2UF SN:E85395B.

I CERTIFY THAT THIS ENGINE DETERMINED TO BE IN AIRWORTHINESS.

*(Signature)*  
JOHN BENNAMAN

BROUGHT FORWARD			
TOTALS			

Sky-Tech International, Inc.

PO Box 912

Broken Arrow, OK 74013

SERVIEABLE PART

Customer Doug Turner W.O. No. 2409

Qty. 1 Type Teledyne Cont S/N 297519-RD

Part Name Engine P/N 10-470-L

Work done Overhauled

by Tom Aft

Date 10/18/02 Inspected by Tom Aft

Engine reground by Aircraft Specialties. Hydraulic Lifters reconditioned by Rock Aviation - Bourne, TX. Cylinders reworked and honed to a ring finish std steel bore. Magnetos overhauled. Fuel System overhauled by Mike's Fuel Metering - Tulsa, OK. Engine test run by Custom Airmotive - Tulsa, OK. Engine is approved for return to service.

Thomas H. Aft  
Sky Tech International, Inc.

SIGNATURE

LICENSE NUMBER

DATE

R.P.M.

TIME OF GROUND

Ground

Air

Hrs.

Min.

GARDNER AVIATION SP  
LOG ID# 937 04-Decern  
N4482S S/N TC-1882

ENGINE AND PROPELLER WAS  
INTERNATIONAL REINSTALL  
PHC-C3VF-2UF SN:E85395B

I CERTIFY THAT THIS ENG  
DETERMINED TO BE IN AIR

John Bennaman  
JOHN BENNAMAN

BROUGHT FORWARD

TOTALS

BROUG

[illegible]

**Pg 1 / 1**

RIGHT

# REBUILT ENGINE LOG

N44825

AIRCRAFT N NUMBER

I0470L-21B

ENGINE MODEL NUMBER

297518-R

ENGINE SERIAL NUMBER

USE ONLY  
FUEL  
CONFORMING  
TO ASTM D910.

USE OF AUTOMOTIVE  
GAS IS NOT  
APPROVED.

Sky Tech International, Inc.  
 PO Box 912 Ardmore, OK 73401  
 Broken Arrow, OK 74013  
 Customer Doug Turner W.O. No. 2408  
 Qty. 1 Type Teledyne Cont. S/N 297518-RCS  
 Part Name Engine P/N 10-470-L  
 Work done Overhauled  
 by Tom Left  
 Date 10/18/02 Inspected by Tom Left  
 to a ring finish std steel bore. Magnetos overhauled. Fuel System overhauled  
 by Mike's Fuel Metering - Tulsa, OK. Engine test run by Custom Airmotive -  
 Tulsa, OK. Engine is approved for return to service.  
 Tom H. Left  
 Sky Tech International, Inc.

SERVIEABLE PART


[illegible][illegible]

10

DATE		
	TSM OH O Teledyne Continental IO-470-L S/N 297518-R CS <u>10/18/2002</u>	SIGNATURE LICENSE NUMBER
	Engine overhauled this date in accordance with Federal Aviation Administration Regulations, Manufacture's Overhaul Manual and Parts Manual. New parts include: oil seals, cylinder base seals, gaskets, packings, circlips, lockplates, retaining rings, Crankshaft blade bushings, counterweight bushings, pistons (STD) R, piston rings, piston pins, rocker shafts, exhaust valves, exhaust valves, intake valves and seats (as needed), bearing inserts - rods and mains (STD), ball bearings, roller bearings, rubber couplings, coner pins, lockwashers, and spark plugs. All steel magnifluxed by Aircraft Specialties - Tulsa, OK. All hardware plated by United Plating - Tulsa, OK.	
	Crankshaft polished rods and mains (S'D) and ultrasonic by Aircraft Specialties. Camshaft reground by Aircraft Specialties. Hydraulic Lifters reconditioned by Rock Aviation - Bourne, TX. Cylinders reworked and honed to a ring finish std steel bore. Magnetos overhauled. Fuel System overhauled by Mike's Fuel Metering - Tulsa, OK. Engine test run by Custom Airmotive - Tulsa, OK. Engine is approved for return to service.	
	<i>[Signature]</i> Sky Tech International, Inc.	
BROUG		
TOTALS		

[illegible]

[illegible]



DATE	R.P.M.		TIME ON GROUND			TIME IN AIR			TOTAL TIME		REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			
	<div style="border: 1px solid black; padding: 5px;"> <p>GARDNER AVIATION SPECIALIST, INC. 216 BARRY WHATLEY WAY GRIFFIN, GA 30224            LOG ID# 937 04-December-2002 WO# 18303/1 AC TT 1960.0 HOBBS 1960.0            N4482S S/N TC-1882 BEECH 95-B55 TSFREM 458.0</p> </div> <p>Pg 1 / 1</p> <p>ENGINE AND PROPELLER WAS REMOVED FROM AIRCRAFT. ENGINE WAS OVERHAULED AND CERTIFIED BY SKY TECH INTERNATIONAL. REINSTALLED ENGINE AND NEW HARTZELL PROPELLER MODEL THREE BLADE PROPELLERS MODEL PHC-C3YF-2UF SN:EB53968. SERVICED ENGINE WITH AEROSHELL 100 MINERAL BASE OIL.</p> <p>I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AIRWORTHY CONDITION.</p> <p> 11/4/2002  <small>JOHN BENNAMAN Date</small></p>												
BROUGHT FORWARD													
TOTALS													

## ENGINE LOG

[illegible][illegible]



## ENGINE LOG

[illegible]

DATE	Gr	SIGNATURE	LICENSE NUMBER
7/10/2003	Continental		
Engine	IO-470-L	S/N 297518-R CS	
Engine overhauled this date in accordance with Federal Aviation Administration Regulations, Manufacturer's Overhaul Manual and Parts Manual. New parts include: oil seals, cylinder base seals, gaskets, packings, circlips, lockplates, retaining rings, crankshaft blade bushings, counterweight bushings, counterweight pins, pistons, piston rings, piston pins, rocker shafts, exhaust valves, intake valves and seats (as needed), bearing inserts - rods and mains (M010), ball bearings, roller bearings, hydraulic lifters, rubber couplings, cotter pins, lockwashers, and spark plugs. All steel magnifluxed by Aircraft Specialties - Tulsa, OK. All hardware plated by United Plating - Tulsa, OK. Crankcase replaced with factory replacement. Crankcase, (2) counterweights, and camshaft replaced with yellow tagged units from Aircraft Specialties. Engine test run by Custom Airmotive - Tulsa, OK. Engine is approved for return to service.			
 			
BROUGHT F			

## ENGINE LOG

[illegible]

DATE	Gr	SIGNATURE	LICENSE NUMBER
7/10/2003	Continental		
Engine	IO-470-L	S/N 297518-R CS	
Engine overhauled this date in accordance with Federal Aviation Administration Regulations, Manufacturer's Overhaul Manual and Parts Manual. New parts include: oil seals, cylinder base seals, gaskets, packings, circlips, lockplates, retaining rings, crankshaft blade bushings, counterweight bushings, counterweight pins, pistons, piston rings, piston pins, rocker shafts, exhaust valves, intake valves and seats (as needed), bearing inserts - rods and mains (M010), ball bearings, roller bearings, hydraulic lifters, rubber couplings, cotter pins, lockwashers, and spark plugs. All steel magnifluxed by Aircraft Specialties - Tulsa, OK. All hardware plated by United Plating - Tulsa, OK. Crankcase replaced with factory replacement. Crankcase, (2) counterweights, and camshaft replaced with yellow tagged units from Aircraft Specialties. Engine test run by Custom Airmotive - Tulsa, OK. Engine is approved for return to service.			
 			
BROUGHT F			
TC			

## ENGINE LOG

[illegible]

DATE	Gr	7/10/2003
		Bi e
		Engine or
		Regulation
		oil seals,
		crankshaf
		piston rin
		needed),
		hydraulic
		steel mag
		Plating -
		counterwe
		Specialtie
		for return
BROUGHT F		

DATE	R. P. M.		TIME ON GROUND			TIME IN AIR			TOTAL TIME		REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			
<div style="border: 1px solid black; padding: 5px;"> <b>GARDNER AVIATION SPECIALIST, INC. 215 BARRY WHATLEY WAY GRIFFIN, GA 30224</b>            LOG ID# 1276 28 July 2003 WO# 18694/4 AC TT 1969.0            N4482S S/N TC-1882 BEECH 95-B51         </div>													
***** ITEM # 18694-4 REINSTALL ENGINE ***** ACTION: REINSTALLED ENGINE ASSEMBLY AFTER ENGINE WAS OVERHAULED AND CERTIFIED BY CUSTOM AIRMOTIVE INC. ENGINE WAS GROUND RUN AND RIGGED PER BEECH SERVICE INSTRUCTIONS. SERVICED WITH 12 QUARTS AEROSHELL 100 MINERAL OIL.													
<div style="display: flex; justify-content: space-between; align-items: center;"> <div>             JOHN BENNAMAN         </div> <div> <u>7/28/2003</u>            Date         </div> </div>													
<div style="display: flex; justify-content: space-between;"> <div>           BROUGHT FORWARD            TOTALS         </div> <div> <!-- Empty grid for totals --> </div> </div>													

[illegible]



U.S. Department  
of Transportation  
Federal Aviation  
Administration

# MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

Form Approved  
OMB No. 2120-0020  
For FAA Use Only  
Office Identification

INSTRUCTIONS: Print or type all entries. See FAR 43.9, FAR 43 Appendix B, and AC43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This is required by law (49 U.S.C. 1421). Failure to report can result in a civil penalty not to exceed \$ 1000 for each such violation (Section 901 Federal Aviation Act of 1958).

1. Aircraft	Make <b>BEECH</b>	Model <b>95-B55</b>
	Serial No. <b>TC-1882</b>	Nationality and Registration Mark <b>N4482S</b>
2. Owner	Name (As shown on registration certificate) <b>RIVERCHASE DEVELOPMENT AVIATION CO.</b>	Address (As shown on registration certificate) <b>30 OLD RUDNICK LANE DOVER, DE 19901 USA</b>

## 3. For FAA Use Only

4. Unit Identification				5. Type	
Unit	Make	Model	Serial No.	Repair	Alteration
AIRFRAME	(As described in Item 1 above)				X
POWERPLANT	CONTINENTAL	IO-470L	297519ORCS &		X
PROPELLER					
APPLIANCE	Type				
	Manufacturer				

## 6. Conformity Statement

A. Agency's Name and Address <b>GARDNER AVIATION SPECIALIST, INC. 215 BARRY WHATLEY WAY GRIFFIN, GA 30224</b>	B. Kind of Agency <input type="checkbox"/> U. S. Certified Mechanic <input type="checkbox"/> Foreign Certified Mechanic <input checked="" type="checkbox"/> Certified Repair Station <input type="checkbox"/> Manufacturer	C. Certificate No. <b>LIMITED AIRFRAME RADIO CLASS I, II, III</b>
--	--	--

D. I certify that the repair and/or alteration made to the unit(s) identified in Item 4 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U. S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.

Date <b>20-November-2003</b>	Signature of Authorized Individual <b>JOHN BENNAMAN</b>
---------------------------------	--

## 7. Approval for Return to Service

Pursuant to the authority given persons specified below, the unit identified in Item 4 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is ☒ APPROVED ☐ REJECTED

BY	FAA Fil Standards Inspector	Manufacturer	Inspection Authorization	Other (Specify)
	FAA Designee	<input checked="" type="checkbox"/> Repair Station	Person Approved by Transport Canada Airworthiness Group	
Date of Approval or Rejection <b>20-November-2003</b>		Certificate or Designation No. <b>[REDACTED]</b>	Signature of Authorized Individual <b>JOHN BENNAMAN</b>	

# NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

## 8. DESCRIPTION OF WORK ACCOMPLISHED (If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

**N4482S BEECH 95-B55 TC-1882**

THE FOLLOWING WORK WAS ACCOMPLISHED ON WO #19054.

### EQUIPMENT REMOVED:

MFG	MODEL	DESCRIPTION	LOC
EDO AIRE	IU028-204-7	FUEL FLOW INDICATOR	FS61

### EQUIPMENT INSTALLED:

MFG	MODEL	DESCRIPTION	PART NUMBER	INSTALL MANUAL	REV	LOC
WSI	AV200	WEATHER RCVR	305391-000	305427-00	IR	FS199
COMANT	CI-1530-1	WEATHER ANTENNA	305394	305427-00	IR	FS147
SHADIN	DIGIFLO-L	FUEL FLOW IND	912041T-38-D	4084	10/84	FS61
SHADIN	201B	TRANSDUCERS	680501-1	4084	10/84	FS25
AMERI KING	AK450	ELT	AK450	IM-450		FS230
AMERI KING	AK450	REMOTE UNIT	450004	IM-450		FS61

INSTALLED WSI AV-200 INFLIGHT WEATHER INFORMATION SYSTEM IN ACCORDANCE WITH WSI INSTALLATION MANUAL PN:305427-00 REV IR DATED JULY 16, 2003. INSTALLED THE RECEIVER IN THE AFT SECTION OF THE FUSELAGE. INSTALLED A WX SENSOR ON THE TOP OF THE AFT CABIN SECTION. INTERFACED THIS SYSTEM TO THE UPS AVIATION TECHNOLOGIES MX20 MULTI-FUNCTION DISPLAY. NOTE: INSTALLED AV200 TID# 300644. RELOCATED AN EXISTING COM ANTENNA FROM THE TOP OF THE AFT CABIN SECTION FS147 TO THE TOP OF THE EMPENAGE AT FS197. INSTALLED THE WSI ANTENNA WHERE THE COM ANTENNA WAS ORIGINALLY LOCATED.

REMOVED IU028 FUEL FLOW INDICATOR. INSTALLED SHADIN DIGIFLO-L FUEL FLOW INDICATOR PN:910532P SN:4888 AND FUEL FLOW TRANSDUCERS PN:68050-A1 SN:130436 AND SN:130437. INTERFACED THE INDICATOR TO THE GARMIN GNS430. INSTALLED THIS SYSTEM IN ACCORDANCE WITH SHADIN REPORT# 4036 DATED SEPT 10, 1986 AND STC# SA579GL. INSTALLED FUEL FLOW TRANSDUCERS IN ACCORDANCE WITH SHADIN REPORT# 4029 DATED NOV 5, 1990 AND STC# SE552GL. NOTE: THAT THE K FACTOR IS SET AT 29.8.

INSTALLED NEW AMERI KING AK-450 ELT SN:467644 IN ACCORDANCE WITH INSTALLATION MANUAL PN:IM-450. THIS INSTALLATION MEETS THE REQUIREMENTS OF TSO-C91a. THE ELT REMOTE UNIT WAS INSTALLED IN THE PILOTS INSTRUMENT PANEL.

THE UNITS LISTED ABOVE WERE INSTALLED IN ACCORDANCE WITH THE REFERENCED AIRCRAFT MAINTENANCE MANUALS AND AC 43.13B. CIRCUIT BREAKERS FOR THIS EQUIPMENT ARE LOCATED WITH THE OTHER AVIONICS CIRCUIT BREAKERS.

THE ALTERATIONS LISTED MEET THE FOLLOWING FAR'S: 23.303, 23.305, 23.603, 23.611, 23.1301, 23.1309, 23.1321, 23.1357, 23.1365, 23.1431, 23.1519, 23.1547 AND APPLICABLE RULES PERTAINING TO THE AIRCRAFT'S CERTIFICATION BASIS.

THE UNITS LISTED IN THIS ALTERATION WERE INSPECTED, CALIBRATED AND TESTED IN ACCORDANCE WITH MANUFACTURES INSTRUCTIONS AND FOUND TO OPERATE AS INTENDED.

ALL FUNCTIONS ARE COMPATIBLE TO OTHER AIRCRAFT SYSTEMS.

WEIGHT AND BALANCE AND LOG BOOK ENTRIES MADE PER FAR43.9 AND FAR91.407

-----THE END-----

☐ ADDITIONAL SHEETS ARE ATTACHED

## Supplemental Type Certificate

**STC Number:**  
**SE443GL**

**This certificate issued to:**  
Shadin Company, Inc

**STC Holder's Address:**  
14280 N. 23rd Avenue  
Plymouth MN 55447-4910  
United States

**Description of the Type Design Change:**  
Incorporation of a fuel flow transducer.

**Application Date:**

**Status:**  
Amended, 06/30/1989

**Responsible Office:**  
ACE-115C Chicago Aircraft Certification Office Tel: [REDACTED]

**TC Number -- Make -- Model:**  
E5CE -- Teledyne Continental Motors -- IO-520-BB  
E5CE -- Teledyne Continental Motors -- IO-520-L  
E5CE -- Teledyne Continental Motors -- IO-520-K  
E5CE -- Teledyne Continental Motors -- IO-520-F  
E5CE -- Teledyne Continental Motors -- IO-520-A  
E5CE -- Teledyne Continental Motors -- IO-520-BA  
E5CE -- Teledyne Continental Motors -- IO-520-B  
E5CE -- Teledyne Continental Motors -- IO-520-D  
E5CE -- Teledyne Continental Motors -- IO-520-J

**Full Text of STC:**

▼ **Comments**

Comments:

## Supplemental Type Certificate

**STC Number:**

**SE552GL**

**This certificate issued to:**

Shadin Company, Inc

**STC Holder's Address:**

14280 N. 23rd Avenue

Plymouth MN 55447-4910

United States

**Description of the Type Design Change:**

Incorporation of a fuel flow transducer.

**Application Date:**

**Status:**

Amended, 01/24/1991

**Responsible Office:**

ACE-115C Chicago Aircraft Certification Office Tel: [REDACTED]

**TC Number -- Make -- Model:**

3E1 -- Teledyne Continental Motors -- IO-470-U

3E1 -- Teledyne Continental Motors -- IO-470-V

3E1 -- Teledyne Continental Motors -- IO-470-S

3E1 -- Teledyne Continental Motors -- IO-470-N

3E1 -- Teledyne Continental Motors -- IO-470-VO

3E1 -- Teledyne Continental Motors -- IO-470-L

3E1 -- Teledyne Continental Motors -- IO-470-J

3E1 -- Teledyne Continental Motors -- IO-470-E

3E1 -- Teledyne Continental Motors -- IO-470-D

3E1 -- Teledyne Continental Motors -- IO-470-K

**Full Text of STC:**

### ▼ Comments

Comments:

Shadin Co. Inc.  
6950 Wayzata Blvd.  
Minneapolis, MN 55426

SUPPLMNT.MNL

FAA APPROVED

AIRPLANE FLIGHT MANUAL SUPPLEMENT

FOR


Model: Beech Baron 95-55, 95-55A, 95-55B,  
95-B55A, 95-B55B

REG. NO. N4482S

SER. NO. TC-1882

This supplement must be attached to the FAA Approved Airplane Flight Manual when the Digital Fuel Flow Meter is installed in accordance with STC SA579GL. The information contained herein supplements the information of the Basic Airplane Flight Manual; for limitations, procedure, and performance information not contained in this supplement, consult the basic Airplane Flight Manual.

FAA APPROVED:

  
W. F. Horn, Chief,  
Chicago Aircraft  
Certification Office  
FAA Central Region

DATE:

JUN 10 1987

United States of America  
Department of Transportation — Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SE5526L

*This certificate, issued to* Shadin Company, Inc.  
14280 N. 23rd Avenue  
Plymouth, Minnesota 55447

*certifies that the change in the type design for the following product with the limitations and conditions*  
*therefor as specified herein meets the airworthiness requirements of Part 13 of the Civil Air*  
*Regulations.* See Type Certificate Data Sheet No. 3E1 for complete certification basis.

*Original Product — Type Certificate Number:* 3E1

*Make:* Teledyne Continental Motors

*Model:* IO-470-D, IO-470-J, IO-470-K, IO-470-L,  
IO-470-N, IO-470-U, IO-470-V, IO-470-VO,  
IO-470-E, IO-470-S

*Description of Type Design Change:*

Incorporation of a Fuel Flow Transducer in accordance with Shadin Company Report Number 4029, dated November 5, 1990, or later FAA Approved revisions.

*Limitations and Conditions:*

This approval should not be extended to other engines of these models on which other previously approved modifications are incorporated, unless it is determined by the installer that the interrelationship between this change and any other previously approved modifications will introduce no adverse effect on the airworthiness of these engines.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* July 14, 1981

*Date received:*

*Date of issuance:* August 25, 1981

*Date amended:* January 24, 1991



*By direction of the Administrator*

*Donald P. Michal*

Donald P. Michal, <sup>(Signature)</sup> Manager  
Chicago Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America  
Department of Transportation -- Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SA5796L

*This certificate, issued to*

Shadin Company, Inc.  
6950 Wayzata Boulevard  
Minneapolis, MN 55426

*certifies that the change in the type design for the following product with the limitations and conditions*

*therefor as specified herein meets the airworthiness requirements of Part 3 of the Civil Air*

*Regulations. See Type Certificate Data Sheet 3A16 for complete certification basis.*

*Original Product -- Type Certificate Number:*

3A16

*Make:*

Beech

*Model:*

95-55, 95-A55, 95-B55, 95-B55A, 95-B55B

*Description of Type Design Change:*

Installation of a Shadin Company Fuel Flow Indicating System in accordance with Shadin Company Report Number 4036, revised September 10, 1986, or other FAA approved revision.

*Limitations and Conditions:*

1. If the original Fuel Flow Indicator is removed, FAA Approved Flight Manual Supplement dated June 10, 1987 (or other FAA approved revision) is required. 2. This approval should not be extended to other airplanes of this model that incorporate any other previously approved modification, unless it is determined that the interrelationship between this change and any other previously approved modification will introduce no adverse effect on the airworthiness of these airplanes.

*This certificate and the supporting data which is the basis for approval shall remain in effect until*

*revoked, suspended, revoked, or a termination date is otherwise established by the Administrator of the*

*Federal Aviation Administration.*

*Date of application:*

July 14, 1981

*Date issued:*

*Date of issuance:*

November 30, 1981

*Date amended:*

July 1, 1982, June 10, 1987



*By signature of the Administrator*

W. F. Horn

(Signature)

Manager, Chicago Aircraft Certification  
Office, ACF-115C, Central Region

(Title)

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*

*This certificate may be transferred in accordance with FAR 21.47.*

# Shadin

COMPANY INCORPORATED

6831 Oxford Street  
St. Louis Park, MN 55426  
U.S.A.

INVOICE NO.	INVOICE DATE	PAGE
00027924	11/06/03	1

2464  
S GARDNER AVIATION SPECIALISTS  
O LATTN: TANYA  
D 215 BARRY WHATLEY WAY  
T GRIFFIN GA 30224  
O

000001  
S GARDNER AVIATION SPECIALISTS  
H LATTN: TANYA  
P 215 BARRY WHATLEY WAY  
T GRIFFIN GA 30224  
O

TOTAL DUE

SHADIN CO., INC.

St. Louis Park, MN 55426

PLEASE RETURN THIS PORTION OF THE INVOICE WITH YOUR PAYME

SLS1	SLS2	DUE DATE	DISC. DUE DATE	ORDER NO.	ORDER DATE	SHIP DATE	SHIP NO.
EC		11/16/03		00014818	11/06/03	11/06/03	000001
TERMS DESCRIPTION		CUSTOMER P.O. NUMBER			SHIP VIA		
COD		VERBAL			UPS BLUE COD		
ITEM ID	TX CL	UNIT OF MEASURE	ORDERED	SHIPPED	UNIT PRICE	EXTENSION	
KIT A1	00	EA	2.0000	2.0000		880.00	
TRANSDUCER KIT A1, 680501A							
→ Ser 130436-29.8					440.0000		
Ser 130437-29.8					440.0000		
SE443GL STC PAPERWORK	00		1.0000	1.0000	.0000		
IO-470-L ENGINES							
SHIP UPS BLUE COD	00		1.0000	1.0000	.0000		
Subtotal						880.00	
TAXABLE	NONTAXABLE		FREIGHT	SALES TAX	MISC. CHARGE	TOTAL	
.00	880.00		18.20	.00	.00	898.20	

3

RS - ADJUSTMENTS - REMARKS

SIGNATURE

LICEN  
NUMBER

Y WAY GRIFFIN, GA 30224

Pg 1/1

REMOVED KMA20 AUDIO PANEL, SPA-400  
 ERROR, KN73 GS RECEIVER, KR85 ADF RECEIVER AND  
 KA39 CONVERTORS. INSTALLED A GARMIN GMA340  
 N INSTALLATION MANUAL PN:190-00149-01 REV  
 NS430 GPS/NAV/COM AS THE NEW #1 GPS/NAV/COM  
 90-00140-02 REVISION J. INTERFACED TO THE  
 THE EXISTING ENCODER SUPPLIES ALTITUDE  
 RD CABIN WHERE AN OLD GPS SENSOR WAS  
 N DISPLAY JUST BELOW THE AUDIO PANEL IN THE  
 TO SUPPLY ALTITUDE INFORMATION FOR THE  
 D THE WX20 IN ACCORDANCE WITH UPS AVIATION  
 13/02 AND STCSA02154AK. INSTALLED KING  
 #2 NAV INDICATOR. REMOVED CENTURY  
 DVED FOR CESSNA 337 WAS INSPECTED AND  
 OIFICATION TO BE ELIGIBLE FOR INSTALLATION  
 STEM IN ACCORDANCE WITH STEC INSTALL  
 INSTALLED BF GOODRICH WX900 STORMSCOPE  
 INSTALLATION MANUAL PN:78-8060-6104-6 REV B.  
 IS.

REMARKS

61

INSPECTION - MAINTENANCE - REPAIRS - ALTERATIONS

GARDNER AVIATION SPECIALIST, INC. 215 BARRY WHATLEY WAY GRIFFIN, GA 30224  
 LOG ID# 1273 28-July-2003 WO# 18694/7 HOBBS 1969.0  
 N4482S S/N TC-1882 BEECH 95-B55

Pg 1/1

\*\*\*\* ITEM # 18694-7 IFR CERTIFICATION \*\*\*\*  
 ACTION: PERFORMED ALTIMETER CERTIFICATION, STATIC LEAK CHECK, TRANSPONDER CERTIFICATION, AND  
 ALTITUDE REPORTING TEST PER FAR 91.411 AND 91.413 REQUIREMENTS. CALIBRATED ALTIMETER TO 20,000 FEET.

ALTIMETER: 5934-1 S/N: V6640  
 ENCODER: AK-350 S/N: 52145  
 TRANSPONDER: GTX320A S/N: 83807583

*John Benhaman* 7/28/2003  
 JOHN BENHAMAN Date

**HARTZELL PROPELLER INC.**

**Aircraft Accident/Incident Report No.: 031121**

Date of Accident: November 21, 2004  
Location: Griffin, GA  
  
NTSB File No.: ATL04FA038  
  
Aircraft: Beech 95-B55 Baron  
  
Registration No.: N4482S  
Serial No.: TC1882  
  
Operator: per N-number:  
River Chase Development Aviation Inc.  
30 Old Rudnick Ln  
Dover, DE 19901  
  
Written by: Tom McCreary  
Air Safety Investigation Manager  
  
Date: August 19, 2004

Contents:	Page
Accident Synopsis .....	2
Summary and Analysis of Findings .....	2
Conclusion .....	2
Propeller Teardown Factual Information .....	3
Photographic Summary .....	10

## **HARTZELL PROPELLER INC.**

**Aircraft Accident/Incident Report No.: 031121**

### **ACCIDENT SYNOPSIS**

According to the NTSB preliminary report, the aircraft climbed to 200' after take-off, turned left, and crashed into the roof of a commercial building.

Aircraft Damage:      Destroyed  
Injuries:                One person on board, one fatal

### **SUMMARY AND ANALYSIS OF FINDINGS**

The left propeller had multiple blade angle witness marks (8°, 10°, 14°, 20°, and 24°). The multiplicity of marks indicates that most, if not all, are post-impact indications.

The right propeller had a witness mark at 13° blade angle (approximate low pitch position). If this were a pre-impact blade angle, it would indicate something less than maximum power but a more definitive calculation could not be made because, at low speed, the propeller would be the at low pitch position at any power setting less than maximum.

The left propeller had significant blade bending and twisting. Normally this, plus torsional fracture of the engine shaft, suggests power ON at impact. However, some of the harsh damage is likely attributable to the manner of impact, as evidenced by edgewise bending near the shank of blade L3. Also, blade L1 was straight with little damage, which suggests that the left propeller was not at high power (except that possibly the crankshaft fractured and the propeller separated prior to L1 blade impact).

The right propeller had very little bending or twisting of the blades. This suggests that it had low rotational energy at the time of impact.

Blades from both propellers had evidence of rotational scoring.

### **CONCLUSIONS**

Both propellers were rotating and not feathered at the time of impact. The blade damage suggested that right propeller impacted with low power or no power. The left propeller appeared to have significant rotational energy but the power output could not be determined.

There were no discrepancies noted that would preclude normal operation. All damage was consistent with impact damage.

**HARTZELL PROPELLER INC.****Aircraft Accident/Incident Report No.: 031121****PROPELLER TEARDOWN REPORT**

**Date of Investigation:** July 19, 2004

**Location:** Hartzell Propeller Inc.  
Piqua, Ohio

**Propeller Model:** PHC-C3YF-2UF with FC7663B-2 blades

**Representatives:** Tom McCreary Hartzell Propeller Inc.  
Richard Hermanns FAA - FSDO Cincinnati

**General Comments:**

This type propeller is a 3-bladed single-acting, hydraulically operated constant speed model. Oil pressure from the propeller governor is used to move the blades to the low pitch (blade angle) direction. A spring, an air charge, and blade counterweight twisting moments move the blades to the high pitch/feather direction in the absence of governor oil pressure. The blades and hub are of aluminum construction. Propeller rotation is clockwise as viewed from the rear.

**Installation Data:** (Data reference the 30-inch station)

Low Pitch:	13.5	± 0.1	degrees
Start Lock:	19.0	± 1.5	degrees
Feather:	84.0	± 1.0	degrees

**Service History:**

Logbook information was not available.

	<u>S/N</u>	<u>Date of manufacture</u>	<u>TTSN</u>	<u>ISO</u>
Left Hub	EB5395B	9/6/02	unknown	unknown
Blades	J78031	9/6/02	unknown	unknown
	J78032	9/6/02	unknown	unknown
	J78029	9/6/02	unknown	unknown
Right Hub	EB5396B	9/6/02	unknown	unknown
Blades	J77937	9/6/02	unknown	unknown
	J77936	9/6/02	unknown	unknown
	J77938	9/6/02	unknown	unknown

**HARTZELL PROPELLER INC.**

**Aircraft Accident/Incident Report No.: 031121**

**Position:** LEFT

**Hub Serial Number:** EB5395B

**Factory No.:** A61993B

**Blade Model:** FC7663B-2

S/N L1: J78031

S/N L2: J78032



S/N L3: J78029

**Blade Orientation:**

L1-L2-L3 clockwise as viewed from the rear of the propeller. The hub serial number was between the # L1 and # L2 blades.

**As Received Condition:**

The spinner dome had not been removed. The engine shaft was fractured near the propeller mounting flange. The engine flange had not been removed from the propeller.



**HARTZELL PROPELLER INC.**

**Aircraft Accident/Incident Report No.: 031121**

**Spinner Assembly:**

The spinner dome was crushed on the forward end and dented on two sides. The front spinner cap had spiral crushing. The spinner bulkhead was crushed on one side

**Propeller Cycling:**

The pitch change mechanism was seized and cycling of the mechanism was not possible. The air valve was broken and it did not retain its air charge.

**Engine/Propeller Mounting:**

The engine shaft was fractured about 1/2 inch aft of the propeller mounting flange. The engine shaft had spiral cracks around the fracture surface. The propeller attachment bolts and propeller mounting flange were unremarkable.

**Cylinder: (S/N C1675)**

The cylinder was unremarkable. It had a decal indicating use of Aeroshell # 6 grease and an air charge decal P/N CPR 22A.

**Piston:**

Intact and unremarkable

**Pitch Change Rod:**

Intact and unremarkable

**Fork:**

Intact and unremarkable

**Spring/Spring Guides:**

Intact and unremarkable

**Low Pitch Stop and Feather Stop:**

The low pitch stop had a light impact mark. The feather stop was unremarkable

**Start Lock:**

Intact and operable

**Hub Assembly:**

Intact and unremarkable

**Preload Plates:**

NOTE: For this propeller model, when the blade knob is aligned with the hub parting line, the blade angle at the reference station is  $48^\circ$  (knob  $12^\circ + 36 = 48^\circ$ ).

# 1 preload plate had an impact mark from fork contact at  $40^\circ$  from the hub centerline. This equates to  $8^\circ$  blade angle.

# 2 preload plate had three impact marks from fork contact at  $28^\circ$ ,  $34^\circ$ , and  $38^\circ$  from the hub centerline. These equate to  $20^\circ$ ,  $14^\circ$ , and  $10^\circ$  blade angle respectively.

# 3 preload plate had an impact mark caused by contact with the pitch change knob at  $24^\circ$  from the hub centerline. This equates to  $24^\circ$  blade angle.


**Propeller Blades:**

L3 blade pitch change knob was fractured. L1 and L2 blade pitch change knobs were intact. All three blade counterweights were intact.

L1 blade had rotational marks on the outer 14 inches on the camber side. It had gouges in the leading edges on the outer 1/3 of the blade.

L2 blade was bent aft about  $30^\circ$  at mid-blade. It was bent slightly forward at 2/3 radius. The outer two inches of the tip was bent aft and twisted toward low pitch.

L3 blade was bent forward approximately  $20^\circ$  at 1/4 radius. It was bent aft and twisted toward low pitch at mid-blade. There were very deep gouges in the leading edge. There was rotational scoring on the camber side. The blade had a chordwise aft bend near the shank. There was rotational marking (appeared to be roof tar) on the outer 12 inches of the blade on the camber side.



**HARTZELL PROPELLER INC.**

**Aircraft Accident/Incident Report No.: 031121**

**Position: RIGHT**

**Hub Serial Number: EB5396B**

**Factory No.: A61994B**

**Blade Model: FC7663-2R**

S/N 1: J77937

S/N 2: J77936

S/N 3: J77938

**Blade Orientation:**

1-2-3 counterclockwise as viewed from the rear of the propeller. The hub serial number was between the # 1 and # 2 blades.

**As Received Condition:**

The spinner dome had not been removed. The propeller had been removed from the engine. The propeller attachment nuts had been re-installed on the mounting studs.



**Spinner Assembly:**

The spinner dome had frontal crushing in a spiral pattern. The spinner bulkhead was unremarkable.

**Propeller Cycling:**

Cycling of the mechanism was not attempted.

The air valve was broken and it did not retain its air charge.

**Engine/Propeller Mounting:**

The mounting flange was intact and unremarkable.

**Cylinder:** (S/N: E1667)

The cylinder was unremarkable. It had a decal indicating use of Aeroshell # 6 grease, an installation torque decal, TOR 60-70, and an air charge decal P/N CPR 22A.

**Piston:**

Intact and unremarkable

**Pitch Change Rod:**

Intact and unremarkable

**Fork:**

Intact and unremarkable

**Spring/Spring Guides:**

Intact and unremarkable

**Low Pitch Stop and Feather Stop:**

The low pitch stop had a light impact mark. The feather stop was unremarkable

**Start Lock:**

Intact and operable

**Hub Assembly:**

The hub had internal damage caused by inward movement of the blades/preload plates. The cylinder attachment and mounting flange were intact and unremarkable.

**HARTZELL PROPELLER INC.**

**Aircraft Accident/Incident Report No.: 031121**

**Preload Plates:**

NOTE: For this propeller model, when the blade knob is aligned with the hub parting line, the blade angle at the reference station is  $48^\circ$  (knob  $12^\circ + 36 = 48^\circ$ ).

# 1 and # 3 preload plates did not have any marks that could be used to calculate a blade angle.

# 2 preload plate had an impact mark at  $35^\circ$  from the hub centerline. This equates to  $13^\circ$  blade angle.


**Propeller Blades:**

All three blade had traces of what appeared to be roofing tar on the camber side of the blades. # 3 blade pitch change knob was fractured. # 1 and # 2 blade pitch change knobs were intact. All three blade counterweights were intact.

# 1 blade had rotational scoring on the camber side with leading edge damage in the tip area. It was mildly bent aft about  $10^\circ$  at mid-blade.

# 2 blade appeared to be undamaged except for the presence of black tar on the camber side.

# 3 blade was slight bent forward at 1/3 radius. The outer two inches of the tip was curled aft. The tip had rotational scoring on the camber side with leading edge damage.



# HARTZELL PROPELLER INC.

Aircraft Accident/Incident Report No.: 031121

## PHOTOGRAPHIC SUMMARY

NOTE: The following digital photographs are original and unedited and available on compact disc. The numbering sequence may not be chronological as some may have been deleted if out-of-focus, too dark, redundant, etc. Photos used in the text of this report are taken from photos on this list but may have been adjusted from the original. Modifications to images used in the report are limited to cropping, magnification, file compression, or enhancement of color, brightness, or contrast for the sole purpose to improve clarity of the report. No other alterations are permitted.

<u>PHOTOGRAPH NUMBER</u>	<u>DESCRIPTION</u>
Dscn0128.jpg	both propellers, as received
	<b>RIGHT PROPELLER</b>
Dscn0129.jpg	right propeller, as received
Dscn0130.jpg	right propeller, as received
Dscn0131.jpg	right propeller, as received
Dscn0132.jpg	propeller, spinner dome removed
Dscn0133.jpg	cylinder, # 2 and # 3 blade counterweights
Dscn0134.jpg	cylinder, #1 blade counterweight
Dscn0135.jpg	miscellaneous parts
Dscn0136.jpg	rear hub half
Dscn0137.jpg	front hub half
Dscn0138.jpg	low pitch stop
Dscn0139.jpg	piston, start lock, feather spring
Dscn0140.jpg	cylinder
Dscn0141.jpg	# 1 preload plate
Dscn0142.jpg	# 2 preload plate
Dscn0143.jpg	# 3 preload plate
Dscn0144.jpg	# 1 blade butt
Dscn0145.jpg	# 2 blade butt
Dscn0146.jpg	# 3 blade butt
Dscn0147.jpg	fractured pitch change knob
Dscn0148.jpg	fractured pitch change knob
Dscn0149.jpg	all three blades, camber side
Dscn0150.jpg	all three blades, camber side
Dscn0151.jpg	# 3 blade tip
Dscn0152.jpg	# 1 blade tip
Dscn0153.jpg	all three blades, lead edge
Dscn0154.jpg	all three blades, flat side
Dscn0155.jpg	spinner dome
Dscn0156.jpg	spinner dome
Dscn0157.jpg	spinner dome
	<b>LEFT PROPELLER</b>
Dscn0158.jpg	left propeller mounting flange, fractured engine shaft
Dscn0159.jpg	left propeller, as received
Dscn0160.jpg	left propeller, as received
Dscn0161.jpg	left propeller, as received
Dscn0162.jpg	spinner dome

**HARTZELL PROPELLER INC.**

**Aircraft Accident/Incident Report No.: 031121**

Dscn0163.jpg	miscellaneous parts
Dscn0164.jpg	rear hub half
Dscn0165.jpg	front hub half
Dscn0166.jpg	cylinder
Dscn0167.jpg	start lock, feather spring
Dscn0168.jpg	low pitch stop
Dscn0169.jpg	piston, pitch change rod
Dscn0170.jpg	L1 blade butt
Dscn0171.jpg	L2 blade butt
Dscn0172.jpg	L3 blade butt
Dscn0173.jpg	fractured pitch change knob
Dscn0174.jpg	L1 preload plate
Dscn0175.jpg	L2 preload plate
Dscn0176.jpg	L3 preload plate
Dscn0177.jpg	fork
Dscn0178.jpg	all three blades, lead edge
Dscn0179.jpg	L3 blade tip
Dscn0180.jpg	L2 blade tip
Dscn0181.jpg	all three blades, camber side
Dscn0182.jpg	L3 blade shank
Dscn0183.jpg	L1 blade tip
Dscn0184.jpg	all three blade
Dscn0185.jpg	fractured engine flange
Dscn0186.jpg	fractured engine flange



6831 OXFORD STREET, ST. LOUIS PARK, MINNESOTA 55426-4412, U.S.A  
PHONE: 952-927-6500 FAX: 952-924-1111  
Website: [www.shadin.com](http://www.shadin.com)

## INSPECTION REPORT

REF NTSB Accident Report #: ATL04FA038: Beech Craft Baron, N4482S; Shadin Fuel Flow Transducers, P/N Kit A, S/Ns 130436 and 130437

The transducers and connection hoses were inspected.

1. S/N 130437 - Transducer appeared intact with no visible damage. Fuel was poured into the inlet side of the transducer. The fuel exited the outlet side of the transducer without visible restriction to flow.
2. S/N 130436 - Transducer appeared charred. Fuel was poured into the inlet side of the transducer. The flow of fuel to the outlet side of the transducer appeared restricted. The fitting on the inlet side was removed and the inlet inspected. Inspection revealed debris around the inlet orifice, and this debris was captured and inspected microscopically. The debris had radius features similar to that of the connection hose. After removing the debris from the transducer, fuel was again poured into the inlet and the fuel exited the outlet without visible restriction to flow.

12/11/2003

Witnessed by:

A handwritten signature in black ink, appearing to read "R. Reda", written over a horizontal line.

Rasheed Reda  
Shadin Co., Inc. General Manager

A handwritten signature in black ink, appearing to read "Scot Thompson", written over a horizontal line.

Scot Thompson  
FAA Principal Avionics Inspector

A handwritten signature in black ink, appearing to read "Tom Messiah", written over a horizontal line.

Tom Messiah  
Technical Support Supervisor

Enclosure: Shadin invoice 00027924



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

# Memorandum

Subject: **INFORMATION:** Accident #ATL04FA038,  
N4482S

Date: December 12, 2003

From: Scot E. Thompson  
Principal Avionics Inspector  
MSP FSDO GL-15


Reply to  
Attn. of:

To: Investigator Eric Alleyne--NTSB  
Atlanta Federal Building  
Room 3M25  
60 Forsyth St. SW  
Atlanta, GA 30303

This is an addendum to the inspection report from Shadin  
Company Incorporated dated 12/11/2003.

On transducer S/N 130436 (charred transducer) it was noted  
that the inlet hose coupler was not as tight as the outlet  
hose coupler.

On transducer S/N 130437 it was noted that both hose  
couplers were tight.

  
Scot E. Thompson

251  
438  
900 L

**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL PHC-C3YF-24F

PROPELLER S/N EB5395B

LOGBOOK # left

## PROPELLER MAINTENANCE RECORD

Position Left

### PITCH RANGE

Propeller Model PHC-C3YF-2UF

High/Feather \_\_\_\_\_

Propeller S/N EB 5395B

Start Lock \_\_\_\_\_

Blade Design \_\_\_\_\_

Low \_\_\_\_\_

Blade S/N's

Reverse \_\_\_\_\_

No. 1 \_\_\_\_\_

Aircraft Manufacturer Hartzell

No. 2 \_\_\_\_\_

Aircraft Model 95-B55

No. 3 \_\_\_\_\_

S/N TC-1882


No. 4 \_\_\_\_\_

Registration N 4482S

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
	<div style="border: 1px solid black; padding: 5px;"> <b>GARDNER AVIATION SPECIALIST, INC. 216 BARRY WHATLEY WAY GRIFFIN, GA 30224</b>  <b>LOG ID# 938 04-December-2002 WO# 18303/1 AC TT 1960.0 HOBBS 1960.0</b>  <b>N4482S S/N TC-1882 BEECH 95-B55</b> </div>			Pg 1 / 1
	INSTALLED THIS PROPELLER ONTO THE LEFT ENGINE OF BEECHCRAFT 95-B55 N4482S SN:TC-B55 IN ACCORDANCE WITH BEECH SERVICE MANUAL AND HARTZELL STC# SA795CE.			
	I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AIRWORTHY CONDITION.			
	 JOHN BENNAMAN		12/4/2002 Date	


**HARTZELL**

# PROPELLER LOGBOOK

PROPELLER MODEL PHC-C3YF-24F

PROPELLER S/N EB5396B

LOGBOOK # Right

# PROPELLER MAINTENANCE RECORD

Position Right

## PITCH RANGE

Propeller Model PHC-C3YF-2UF

High/Feather \_\_\_\_\_

Propeller S/N EB5396B

Start Lock \_\_\_\_\_

Blade Design \_\_\_\_\_

Low \_\_\_\_\_

Blade S/N's

Reverse \_\_\_\_\_

No. 1 \_\_\_\_\_

Aircraft Manufacturer Hartzell

No. 2 \_\_\_\_\_

Aircraft Model 95-B55

No. 3 \_\_\_\_\_

S/N TC-1882


No. 4 \_\_\_\_\_

Registration N4482S

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
<div style="border: 1px solid black; padding: 5px;"> <p>GARDNER AVIATION SPECIALIST, INC. 215 BARRY WHATLEY WAY GRIFFIN, GA 30224            LOG ID# 938 04-December-2002 WO# 18303/1 AC TT 1960.0 HOBBS 1960.0            N4482S S/N TC-1882 BEECH 95-B55</p> </div>				
INSTALLED THIS PROPELLER ONTO THE RIGHT ENGINE OF BEECHCRAFT 95-B55 N4482S SN:TC-B55 IN ACCORDANCE WITH BEECH SERVICE MANUAL AND HARTZELL STC# SA795CE.				Pg 1 / 1
I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND IS DETERMINED TO BE IN AIRWORTHY CONDITION.				
 JOHN BENNAMAN			12/4/2002 Date	


# Balance

Wgt. Qty. and Type	Lead	#1 <u>14</u>	#2 <u>2W</u>	#3 <u>0</u>	#4 <u>0</u>
	Trail	#1 <u>0</u>	#2 <u>0</u>	#3 <u>0</u>	#4 <u>0</u>
	Front (Assy. S/N)			Back	

Balanced By: M Date: 9-5

# Inspection

## Non-installed Hardware and Dimensional Checks

### "F" Flange Only

(6) A-1381 Washers ✓  
 (6) A-2044 Lock Nuts ✓  
 A-2429-14 Studs ✓  
 Torqued 25 ft. lbs. ✓  
 Mtg Stud Protrusion ✓  
 Dowel Pin Protrusion ✓

### "L" Flange Only

(4) B-6489-25 Bolts ✓  
 (4) B-6526-7 Washers ✓

### "N" Flange Only

(8) A-3257 Nuts ✓  
 (8) A-2048-2 Washers ✓  
 A-3254 Studs ✓  
 Torqued 35 ft. lbs. ✓  
 Mtg Stud Protrusion ✓  
 Dowel Pin Protrusion ✓  
 C-3317-230 O-Ring ✓

Safeties ✓ Visually Inspect Mtg. Flange and Hub Bore ✓  
 Spinner Mtg Kit A-2476-1 9 Installed ✓ Included ✓ N/A ✓  
 De-ice Kit No. A2386-1 Installed/Ck'd ✓ Included/Ck'd ✓ N/A ✓  
 Ohms Reading <100K #1 ✓ #2 ✓ #3 ✓ #4 ✓ N/A ✓  
 Air Chamber Charged per Requirements in Manual 202A ✓ N/A ✓

Comments:

Inspected By: John J. Martin Stamp HP 92 Date: 9-5-02

The approved design data for this propeller incorporates all changes required by applicable Airworthiness Directives.

Hartzell Propeller Inc.  
Assembly Inspection Check-off Record  
**COMPACT PROPELLER**

Approved By: S. Wead

Date: 9/4/02

Form Rev.: B

Exp. ☐

**Inspection**

Prop S/N EB 5396B Model PHC-L34F-24F W.O. No. M 593460  
Drawing D3255 Dwg. Rev. CO IDS No. 231 IDS Date 9-1-00

**Serialized Parts**

Builder		Inspector	
Hub Part No. <u>E-7167-2</u>		Part No. <u>B3202H-5</u>	Serial No.
Hub Factory No. <u>A6994B</u>	Bulkhead S/N <u>          </u>	Cwt. <u>FC7643B-2R</u>	#1 <u>J77937</u>
Fork Ser. No. <u>ND8357</u>	Slip/Slinger Ring S/N <u>          </u>		#2 <u>J77938</u>
Piston Ser. No. <u>C4540</u>	Cylinder S/N <u>E1667</u>		#3 <u>J77936</u>
			#4 <u>          </u>

**Builder**

Check for Leaks ✓

Check Feather Angle (Record Angle) 84.4

Assembled By: T. Jon

Date: 9-5-02

**2nd Check Verification**

Blade Angles Checked at 30° Radius ✓ Low Pitch (Within 2 Deg.) 13.4 / 13.6 High Pitch 18.5 / 18.7  
Friction ✓ Function Test "0"-175"psi ✓ Reverse Pitch NA /  
Track/Length (Aluminum .125" max) (Composite .250" max.) ✓  
Modified By: RA Date: 9-5-02

United States of America  
 Department of Transportation — Federal Aviation Administration  
**Supplemental Type Certificate**

*Number*

SA579GL

*This certificate, issued to*

Shadin Company, Inc.  
 6950 Wayzata Boulevard  
 Minneapolis, MN 55426

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified herein meets the airworthiness requirements of Part 3 of the Civil Air Regulations. See Type Certificate Data Sheet 3A16 for complete certification basis.*

*Original Product — Type Certificate Number:*

3A16

*Make:*

Beech

*Model:*

95-55, 95-A55, 95-B55, 95-B55A, 95-B55B

*Description of Type Design Change:*

Installation of a Shadin Company Fuel Flow Indicating System in accordance with Shadin Company Report Number 4036, revised September 10, 1986, or other FAA approved revision.

*Limitations and Conditions:*

1. If the original Fuel Flow Indicator is removed, FAA Approved Flight Manual Supplement dated June 10, 1987 (or other FAA approved revision) is required. 2. This approval should not be extended to other airplanes of this model that incorporate any other previously approved modification, unless it is determined that the interrelationship between this change and any other previously approved modification will introduce no adverse effect on the airworthiness of these airplanes.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:*

July 14, 1981

*Date received:*

*Date of issuance:*

November 30, 1981

*Date recommended:*

July 1, 1982, June 10, 1987



*By approval of the Administrator*

W. F. Horn

(Signature)

Manager, Chicago Aircraft Certification  
 Office, ACF-115C Central Region  
 (Title)

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*

*This certificate may be transferred in accordance with FAR 21.47.*


Shadin Co., Inc.  
6950 Wayzata Blvd.  
Minneapolis, MN 55426


Report # : 4036  
Original Date: 14 July 1981  
Revision Date: 10 September 1986


PAGE CONTROL CHART

<u>SEC. I.</u>	<u>DATE</u>	<u>REVISION</u>
Drawing List		
4036-21 Installation Schematic	7 Feb 81	A
4036-22 Installation Schematic	20 May 82	A
4036-23 Installation Schematic	20 May 82	A
<u>SEC. II.</u>		
System Description		
Page 1	10 Sep. 86	-
Page 2	10 Sep. 86	-
Page 3	10 Sep. 86	-
Page 4	10 Sep. 86	-
Page 5	10 Sep. 86	-
<u>SEC. III.</u>		
Installation Procedure		
Page 1	10 Sep. 86	-
Page 2	10 Sep. 86	-
Page 3	10 Sep. 86	-
Page 4	10 Sep. 86	-
Page 5	10 Sep. 86	-
Page 6	10 Sep. 86	-
Page 7	10 Sep. 86	-
Page 8	10 Sep. 86	-
<u>SEC. IV.</u>		
Technical Specifications		
Page 1	10 Sep. 86	-
Page 2	10 Sep. 86	-
<u>SEC. V.</u>		
Flight Manual Supplement		
Page 1	10 Sep. 86	-
Page 2	10 Sep. 86	-

FAA  
APPROVED  
JUN 10 1987  
CHICAGO AIRCRAFT  
CERTIFICATION OFFICE  
CENTRAL REGION







Report: 4036  
Date : 10 Sep 86  
Rev. : -  
Sec. : II.1  
=====

SYSTEM DESCRIPTION (P/N 9105XX)  
=====

Digiflo, the Digital Fuel Flow Meter, is designed to provide fuel management information to replace Analog Mechanical Fuel Flow Meters, to maintain a high degree of accuracy (2% or better), and to provide additional functions such as time remaining, fuel used, and fuel remaining.

The system consists of a panel-mounted unit and a fuel flow transducer. The transducer is located in the fuel line between the fuel control unit and the fuel injector for the injected engine and between the engine-driven fuel pump and the carburetor for the carburetted engines. It generates electrical pulses corresponding to the amount of fuel passing through and is designed in such a way that if its rotor is locked it cannot interrupt the fuel flow to the engine.

The panel-mounted unit contains all circuits necessary to count the generated pulses through the microprocessor and to display the fuel flow and other functions. The rate of fuel flow per hour is always displayed at the lower half of the instrument face. The time remaining, fuel used, and fuel remaining are continuously computed and either displayed or stored for later display at the upper display window by pressing the appropriate button.

During power shut-down, the amount of fuel remaining and fuel used are stored into the memory, which is nonvolatile and requires no battery to retain the data.

Time remaining calculations are based on fuel remaining and actual fuel flow, which means that reducing the power will result in increasing the displayed time remaining which at any particular power setting drops below 30 minutes, the "Time Remaining" digits in the display window will start flashing.

The test function will enable the pilot to check the software and hardware against any malfunction through simulating two sample rates and checking the results against stored results. The test is initiated by pressing the test button and requires 13 seconds.

Report: 4036  
Date : 10 Sep 86  
Rev. : ~  
Sec. : II.2  
=====

During installation the system is front panel-programmable for the maximum usable fuel. If a full load of fuel is on board, by moving the toggle switch to full fuel position and pressing the enter button, the predetermined amount of fuel is entered into the system. If a partial fuel load has been added, the system is capable of adding the new fuel load to whatever is remaining on board and using the new load for all calculations.

The accuracy of this instrument depends entirely upon the accuracy of the data entered. A periodical checking of the actual fuel onboard will eliminate the accumulation of errors due to evaporation, leaks, theft, etc.

The transducer pulse count (each transducer is marked with it's pulse count) is matched to the microprocessor. The system has been set to match the transducers shipped with the system. If a different pulse count is being used, the instrument must be re-calibrated.

Report: 4036  
Date : 10 Sep 86  
Rev. : -  
Sec. : II.3  
=====

SYSTEM DESCRIPTION (91053X)  
=====

GENERAL DESCRIPTION

DIGIFLO-L is a Fuel Management System designed to provide complete Fuel Management information under real flight conditions without any manual entry of data (except for the initial fuel on board information). It is connected to the engine Fuel Flow Transducer for Fuel Flow information and to the Apollo II Loran-C receiver serial port for navigation data (ground speed and estimated time enroute).

The system is available with either gallons or pounds read-outs, and it can be installed virtually on any reciprocating or turbine engine by selecting the proper size Fuel Flow Transducer.

The system provides:

1. Specific Range: in NM/Gal. or NM/10 Lb. of Fuel Burned. This is an indication of how efficient is the cruise and the optimum cruise speed could be obtained by selecting the power setting which yields the highest NM Gal.
2. Fuel to Destination: It calculates (under the real wind conditions) the Fuel necessary to reach the destination as selected on the Loran receiver by multiplying the Fuel Flow by the ETE to the destination.
3. Fuel Reserve: The system calculates the amount of Fuel which will be available on board when the aircraft reaches the destination as indicated on the Loran-C receiver way point. This feature provides the pilot with the necessary information to evaluate the reserve fuel situation based on accurate information early enough to take the necessary action. The Reserve Fuel = Fuel on Board minus the fuel to destination.
4. Endurance: The system calculates the time left to fly in hours and minutes based on the fuel on board and fuel consumption. Endurance = Fuel available in gallons divided by the Fuel flow in GPH.
5. Fuel Remaining: The system keeps track of the fuel remaining on board. Fuel Remaining = Initial starting

Report: 4036  
Date : 10 Sep 86  
Rev. : -  
Sec. : II.4  
=====

6. Fuel Used: The system keeps track of the fuel used since the last fuel entry.
7. Not Enough Fuel: The system will flash the display digits when the rotary switch is in the Fuel to Destination position and the Fuel to Destination is more than the Fuel Remaining and will show a negative sign followed by the amount of Fuel Short to reach the destination.
8. Fuel Reserve will be Used: The system will flash the display digits when the rotary switch is in either Fuel to Destination or Reserve Fuel if the endurance is less than the time to reach the destination plus 45 minutes. This warning is intended to alert the pilot that the prevailing conditions will require the use or some of the 45 minute Fuel Reserve.
9. Fuel Flow: The system provides a digital readout of the fuel flow per hour for each engine to a tenth of a gallon under 99.9 gallons and to the nearest gallons at and above 100 gallons. For LB/HR versions the readout is to the nearest LB under 999 LB/HR and to the nearest 10 LB above 999 lb/hr.

#### SYSTEM COMPONENTS

The system consists of three basic units.

1. The Fuel Flow Transducer which is located in the fuel line to the engine to provide the Fuel Flow information.
2. The Loran receiver to provide the ground speed and the ETE through the serial port.
3. The indicator which includes the Microprocessor, the Interface, the Display and the Display Controls.

#### DISPLAY

The fuel flow is always displayed at the lower windows. The top window displays all other functions with the priority of the rotary switch functions.

Report: 4036  
Date : 10 Sep 86  
Rev. : -  
Sec. : II.5  
=====

### SYSTEM MEMORY

The system includes an non volatile memory for retaining the basic settings and the Fuel Remaining and Fuel Used during the power shut down.

### TEST FUNCTIONS AND ERROR MESSAGES

A diagnostic software is built into the system and is initiated by pressing the "test" button, the program checks the hardware and the display. If the test is successful a "good" is displayed on the top window if not a "bad" is displayed. The system is considered unserviceable until a corrective action is taken.

At the end of the test routine the system will display the following:

1. Software basic # and revision level.
2. The K factor setting for each engine in the respective flow window (pulse count/gallon). This number must match the pulse count stamped on the flow transducer otherwise an error will occur.
3. The display units (Gal., LB 5.8, LB. 6.7) are part of checking the internal settings.
4. The Loran-C distance as shown on the Loran-C Receiver to check the Data Interface Integrity. If the system is not capable of reading the Loran-C Data the word "LbAd" will be displayed in the top window.

An "Err1" display is an indication that there is a problem with the nonvolatile memory. This error will cause the unit to seize to function.

An "Err2" display is an indication that there is a problem with the random access memory. This error will cause the unit to seize to function.

Report: 4036  
Date : 10 Sep 86  
Rev. : -  
Sec. : III.2  
=====

6. Using drawing # 4036-21, connect the transducer(s) as indicated. Use wristlock connector and insulating sleeves. After positively identifying the left and right engine wires, solder them to the appropriate pin on the connector plug.
7. If the installer elects to retain the original fuel flow meter skip step 8.
8. If the installer elects to remove the original fuel flow gauge then the fuel lines to the gauge have to be disconnected, drained, removed and the fitting at the firewall has to be capped using AN-929-4 cap. Install the indicator in the same hole on the instrument panel.
9. Install the indicator in the panel.
10. Turn the master switch on and check for 28V. DC at pin K. If no 28V. DC verify wiring, if 28V DC. is verified, turn power off and connect plug to the indicator.
11. Fill the tanks, turn the master switch on, enter the useable fuel into the memory using the information contained in the information booklet. In case of lb. version, multiply the gallons by 5.8 to obtain the total useable pounds.
12. Make the necessary entries in the airframe and engine logs.

Report: 4036  
Date : 10 Sep 86  
Rev. : -  
Sec. : III.3  
=====

### INSTALLATION PROCEDURE

=====

#### GENERAL

A complete thorough familiarization and understanding of the system is necessary before commencing the installation. All work must conform to A. C 43.13-1A ch. 11, Sec. 2, 3, 7 requirements. This procedure is to be used if the original fuel flow indicator is retained. Use drawing # 4036-22. Only S/N TC2355 and up is eligible for this procedure.

#### PROCEDURE

1. Refer to Beech wiring diagram (indicating - Fuel Flow System).
2. Switch off battery master switch. Gain access to the instrument panel back, by removing the instrument panel padded glare shield.
3. Disconnect the Fuel Flow Indicator Connector. Identify the following wires:
  - 1 - wire #E53A20 as L.H. fuel flow signal
  - 2 - wire #E55A20 as L.H. fuel flow signal
  - 3 - wire #E54A20 as R.H. fuel flow signal
  - 4 - wire #E56A20 as R.H. fuel flow signal
4. The connector P/N 126-220 and the interface P/N 630502 are wired and supplied as one unit. Cut the identified wires at least 6 inches from the connector.
5. Insert the wire coming from the indicator into the butt connector and crimp, insert the wire coming from the transducer and the colored wire coming from the interface into the other side of the butt connector and crimp.
6. Reconnect all four wires using above procedure and route them all to the intended location of the Digital Fuel Flow Meter.
7. Solder the connector to the wires using drawing # 4036-22.

Report: 4036  
Date : 10 Sep 86  
Rev. : -  
Sec. : III.4  
=====

8. Mount the circuit breaker to the right hand sub-panel and connect it to the DC buss, identify the circuit breaker by engraving "Fuel Flow Digital", wire it to pin K in the indicator.
9. Mount the indicator in the intended location and plug it.
10. Fill the tanks and turn the master switch on. Enter the useable gallons of fuel into the memory using the information in the information booklet. In case of using the lb. version, multiply the total useable gallons by 5.8 to obtain the total useable lbs.
11. Make necessary entry into the airframe and engine logs.

Report: 4036  
Date : 10 Sep 86  
Rev. : -  
Sec. : III.5

=====

## INSTALLATION PROCEDURE

=====

### GENERAL

A complete thorough familiarization and understanding of the system is necessary before commencing the installation. All work must conform to A. C 43.13-1A ch. 11, Sec. 2, 3, 7 requirements. This procedure is to be used if the original fuel flow indicator is being replaced by the digital indicator. Use drawing # 4036-23. Only S/N TC2355 and up is eligible for this procedure.

### PROCEDURE

1. Refer to Beech wiring diagram (indicating - Fuel Flow System).
  2. Switch off battery master switch. Gain access to the instrument panel back, by removing the instrument panel padded glare shield.
  3. Disconnect the Fuel Flow Indicator Connector. Identify the following wires:
    - 1 - wire #E53A20 as L.H. fuel flow signal
    - 2 - wire #E55A20 as L.H. fuel flow signal
    - 3 - wire #E54A20 as R.H. fuel flow signal
    - 4 - wire #E56A20 as R.H. fuel flow signal
  4. Use drawing # 4036-23, clip Pl60 connector as close as possible to the rubber grommet.
  5. Insert the wire coming from the indicator into the butt connector and crimp, insert the wire coming from the transducer into the other side of the butt connector and crimp.
- - - - - insert all four wires using above procedure and route

United States of America  
Department of Transportation — Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SE443GL

*This certificate issued to*

Shadin Company, Inc.  
14280 N. 23rd Avenue  
Plymouth, Minnesota 55447-4910

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 13 of the Civil Air*

*Regulations.* See Type Certificate Data Sheet E5CE for complete certification basis.

*Original Product — Type Certificate Number:*

E5CE

*Make:*

Teledyne Continental Motors

*Model:*

IO-520-A, IO-520-B, IO-520-D, IO-520-F,  
IO-520-J, IO-520-K, IO-520-L, IO-520-BA,  
and IO-520-BB

*Description of Type Design Change:*

Incorporation of a fuel flow transducer in accordance with Shadin Company Report Number 4022, revised May 16, 1989, or subsequent FAA Approved revision.

*Limitations and Conditions:*

This approval should not be extended to other engines of these models on which other previously approved modifications are incorporated, unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of those engines.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* June 24, 1980

*Date received:*

*Date of issuance:* September 15, 1980

*Date amended:* August 10, 1981; May 21, 1984;  
June 30, 1989



*By direction of the Administrator*

*Donald P. Michal*

Donald P. Michal, <sup>Signature</sup>Manager  
Chicago Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

Shadin Company, Inc.  
14280 North 23rd Avenue  
Plymouth, MN 55447-4910

4022

Report: #4022  
Original Date: 16 July 1990  
Revision Date: 5 October 1991  
Subject: Fuel Flow Transducer Addition  
Teledyne Continental  
10-520-B, -BA, -BB, -A, -D, -F,  
-J, -K, -L

F A A  
A P P R O V E D

NOV 20 1991

CHICAGO AIRCRAFT  
CERTIFICATION OFFICE  
CENTRAL REGION

L7

Shadin Company, Inc.  
14280 North 23rd Avenue  
Plymouth, MN 55447-4910

REPORT #4022

Original Date: 16 July 1980  
Revision Date: 5 October 1991

PAGE CONTROL CHART

FAA  
APPROVED

NOV 20 1991

CHICAGO AIRCRAFT  
CERTIFICATION OFFICE  
CENTRAL REGION

L7


SEC. I.	DATE	REVISION
Drawing List		
4022-D-20 Transducer Installation	29 Jun. 80	B
4022-21 Transducer Installation	24 Jan. 84	A
4022-22 Transducer Installatio	24 Jan. 84	B
SEC. II.		
System Description		
Page 1	12 Dec. 84	-
Page 2	12 Dec. 84	-
SEC. III.		
Installation Procedure		
Page 1	12 Dec. 84	-
Page 2	12 Dec. 84	-
Page 3	12 Dec. 84	-
Page 4	12 Dec. 84	-
Page 5	12 Dec. 84	-
Page 6	12 Dec. 84	-
SEC. IV.		
Technical Specifications		
Page 1	24 Jun. 80	A

LIST OF MATERIALS			
F/N	QTY	PART NO.	DESCRIPTION
1	1	201-B	TRANSDUCER
2	1	643003	BRACKET, MOUNTING
3	2	AN818-4-4	NIPPLE, FLARED, PIPE THREAD
4	2	816-4	AEROQUIP HOSE FITTING
5	15"	801-4	AEROQUIP HOSE
6	40 1/4"	303-4	AEROQUIP HOSE
7	14"	AE102/624-B	AEROQUIP FIRE SLEEVE
8	2	A-3122-14-1J	STRATOFLEX SPEED CLAMP
9	1	810504	FIRE SHIELD BOX
10	2	AN 4-12A	BOLT
11	2	MS20365-428	NUT
12	2	AN960-418L	WASHER

1 - QUANTITIES ARE FOR ONE ENGINE



2 - NO TEFLON TAPE SEAL IS ALLOWED

NOTE:  
FIRE SLEEVE SHOWN CUT-AWAY FOR  
PURPOSES OF ILLUSTRATION ONLY.



UNLESS OTHERWISE NOTED		ORIGINAL DATE OF DRAWING 6-29-80		SHADIN COMPANY, INC.	
DIMENSIONS ARE IN INCHES		DRAFTSMAN		MINNEAPOLIS MINNESOTA 55428	
TOLERANCES:		CHECKER		FUEL FLOW TRANSDUCER ADDITION	
		ENGINEER		TELEDYNE CONTINENTAL	
		SUBMITTED		10-520-B, -BA, -BB	
MATERIAL:		NEXT ASSEMBLY:		CODE IDENT NO.	REV LTR
				4022-D-20	B
				SCALE	WGT. SHEET 1 OF 1

LIST OF MATERIALS			
F/N	QTY	PART NO.	DESCRIPTION
1	1	660526	TRANSDUCER, FUEL FLOW
2	1	543003	BRACKET, MOUNTING
3	1	543005	BRACKET, MOUNTING
4	2	816-4	AEROQUIP HOSE FITTING
5	15'	601-4	AEROQUIP HOSE
6	REF.	303-4	AEROQUIP HOSE (AS REQUIRED)
7	14"	AE102/624-8	AEROQUIP FIRE SLEEVE
8	2	A-3122-14-1J	STRATOFLEX SPEED CLAMP
9	4	AN501A10-8	BOLT 10-32 x 1/4"
10	2	AN 4-4A	BOLT
11	2	MS20365-428	NUT
12	2	AN960-416L	WASHER
13	2	578168	REDUCER, -8 TO -4 FLARE
14	1	MS3106A10SL-3S	CONNECTOR, 3 PIN
15	1	690501	PICKUP ASSY




UNLESS OTHERWISE NOTED		ORIGINAL DATE OF DRAWING		JAN 24 - 84		SHADIN COMPANY, INC.	
DIMENSIONS ARE IN INCHES		DRAFTSMAN				MINNEAPOLIS MINNESOTA	
TOLERANCES:		CHECKER				55426	
		ENGINEER				FUEL FLOW TRANSDUCER ADDITION	
		SUBMITTED				TELEDYNE CONTINENTAL	
						10-520-B, -BA, -BB	
MATERIAL:		NEXT ASSEMBLY:		CODE IDENT NO.		SIZE	REV LT
				4022-21		B	A
				SCALE		WGT.	SHEET 1 OF 1

# LIST OF MATERIALS

F/N	QTY.	PART NO.	DESCRIPTION
1	1	201-B/680501	TRANSDUCER
2	1	543003	BRACKET, MOUNTING
3	1	AN816-4-4	NIPPLE, FLARED, PIPE THREAD
4	2	816-4	AEROQUIP HOSE FITTING
5	14"	601-4	AEROQUIP HOSE
6	40.5"	303-4	AEROQUIP HOSE
7	14"	AE102/624-8	AEROQUIP FIRE SLEEVE
8	1	AN742-D24C	CLAMP
9	1	610504	FIRE SHIELD BOX
10	33'	AE102/624-18	AEROQUIP FIRE SLEEVE
11	33'	MIL-H-8000	HOSE 3/4 ID
12	1	AN823-4	FITTING, ELBOW 45°
13	1	AN912-1	FITTING, BUSHING 1/4-1/2

NOTE: QUANTITIES ARE FOR ONE ENGINE  
NO TEFLON TAPE SEAL IS ALLOWED



UNLESS OTHERWISE NOTED DIMENSIONS ARE IN INCHES	ORIGINAL DATE OF DRAWING	Jan 24, 1984	
	DRAFTSMAN		
TOLERANCES:	CHECKER		
	ENGINEER		
	SUBMITTED		
MATERIAL:	NEXT ASSEMBLY:		
		CODE IDENT. NO	SIZE
		4022-22	B
		SCALE	WGT.
		SHEET	OF

**SHADIN COMPANY, INC.**

MINNEAPOLIS, MINN 55412 U.S.A.

FUEL FLOW TRANSDUCER ADDITION  
TELEDYNE CONTINENTAL  
10-520-A.D.F.K.L.J

REV LTR

B

Report: 4022  
Date: 12 December 1984  
Rev.: -  
Sec.: II.1  
=====

## SYSTEM DESCRIPTION

Digiflo, The Digital Fuel Flow Meter, is designed to replace Analog Mechanical Pressure-type Fuel Flow Meters. It eliminates the hazardous fuel lines from behind the panel. It maintains a high degree of accuracy ( $\pm 2\%$  or better) and provides additional functions such as time remaining, fuel used, and fuel remaining.

The system consists of a fuel flow transducer, located between the fuel control unit and fuel flow divider which generates electrical pulses corresponding to the amount of fuel passing through. The transducer is designed in such a way that if the rotor is blocked it cannot interrupt the fuel flow to the engine.

The panel mounted unit contains all circuits necessary to count the generated pulses through the microprocessor and to display the fuel flow and other functions. The fuel flow in gallons per hour is always displayed at the left window. The time remaining, gallons used, and gallons remaining are continuously computed and either displayed or stored for later display. The time remaining is displayed at the right display window. Gallons remaining and gallons used share the same right window and either can be displayed by pressing the appropriate button.

During power shut-down, the amount of fuel remaining and fuel used is stored into the memory, which is nonvolatile, and requires no battery.

Time remaining calculations are based on fuel remaining and actual fuel flow, which means that reducing the power or leaning the mixture will result in increasing the time remaining.

If the calculated time remaining at any particular power setting drops below 30 minutes, the "Time Remaining" digits in the display window will start flashing.

The test function will enable the pilot to check the software and hardware against any malfunction by running a diagnostic software program.

Report: 4022  
Date: 12 December 1984  
Rev.: -  
Sec.: II.2  
=====

The accuracy of this instrument depends entirely upon the accuracy of the data entered. A periodical checking of the actual fuel onboard will eliminate the accumulation of errors due to evaporation, leaks, theft, etc.

The indicator K factor is matched with the flow transducer pulse count. If the transducer needs to be replaced, a new one with the same pulse count should be used or an error could occur.

Report: 4022  
Date: 12 December 1984  
Rev.: -  
Sec.: III.1  
=====

## INSTALLATION PROCEDURE

For the -B, -BA, -BB engines with fuel flow transducer P/N 680501. Refer to Dwg. #4022-D-20.

### GENERAL

A complete thorough familiarization and understanding of the system is necessary before commencing the installation. All work must conform with A.C. 43.13 1A ch. 11 Sec. 2.

### PROCEDURE

- 1) Identify the engine dash number and use the appropriate drawing. The transducer's dash number should match the dash number stamped on the instrument housing.
- 2) Shut off DC power, fuel valves and mixture controls.
- 3) Gain access to the top front section of the engine, locate and remove the injection pump to the flow divider hose. Fabricate new hose using approx. 40" (length could vary from model to model) piece of 303 Aeroquip hose. Install the 491-4 end fittings per.
- 4) Rotate the 90° elbow (MS-51504) at the inlet of the flow divider 180° to be pointing to the port side of the engine.
- 5) Use 14" piece of 601 hose to fabricate a new hose. Install the Aeroquip 816-4 fittings at each end using the attached instructions. Install the fire sleeves and clamp it after proof testing.
- 6) Remove the crankcase bolts. Install the transducer assembly on the engine as per 4022-D-20 with the inlet port pointing to the right, retighten, (refer to Teledyne Continental Overhaul Manual for recommended torque)
- 7) Connect the wire harness to the transducers using the B-14-D wristlocks with plastic sleeves to insulate and secure with tiewraps.
- 8) Turn the master switch on, fuel selectors on, run booster pumps and check for leaks.

Report: 4022  
Date: 12 December 1984  
Rev.: -  
Sec.: III.2  
=====

- 9) Start the engine and check the metered and unmetered fuel pressure. Readjust if necessary following airframe and engine manufacturers instructions.
- 10) Make necessary entry into the engine logs.

Report: 4022  
Date: 12 December 1984  
Rev.: -  
Sec.: III.3  
=====

#### INSTALLATION PROCEDURE

For the -B, -BA, -BB engines with fuel flow transducer P/N 660526. Refer to Dwg. #4022-21.

#### GENERAL

A complete thorough familiarization and understanding of the system is necessary before commencing the installation. All work must conform with A.C. 43.13 1A ch. 11 Sec. 2.

#### PROCEDURE

- 1) Identify the engine dash number and use the appropriate drawing. The transducer's dash number should match the dash number stamped on the instrument housing.
- 2) Shut off DC power, fuel valves and mixture controls.
- 3) Gain access to the top front section of the engine, locate and remove the injection pump to the flow divider hose. Fabricate new hose using approx. 40" (length could vary from model to model) piece of 303 Aeroquip hose. Install the 491-4 end fittings.
- 4) Rotate the 90° elbow (MS-51504) at the inlet of the flow divider 180° to be pointing to the port side of the engine.
- 5) Use 14" piece of 601 hose to fabricate a new hose. Install the Aeroquip 816-4 fittings at each end using the attached instructions. Install the fire sleeves and clamp it after proof testing.
- 6) Remove the crankcase bolts. Install the transducer assembly on the engine as per 4022-21 with the inlet port pointing to the right, retighten, (refer to Tele-dyne Continental Overhaul Manual for recommended torque)
- 7) Connect the wire harness to the transducers using the MS3106A10SL-3S Connector.
- 8) Turn the master switch on, fuel selectors on, run booster pumps and check for leaks.

Report: 4022  
Date: 12 December 1984  
Rev.: -  
Sec.: III.4  
=====

- 9) Start the engine and check the metered and unmetered fuel pressure. Readjust if necessary following airframe and engine manufacturers instructions.
- 10) Make necessary entry into the engine logs.

Report: 4022  
Date: 12 December 1984  
Rev.: -  
Sec.: III.5  
=====

#### INSTALLATION PROCEDURE

For the -A, -D, -F, -K, -L engines with flow transducer P/N 680501. Refer to Dwg. #4022-22.

#### GENERAL:

A complete thorough familiarization and understanding of the system is necessary before commencing the installation. All work must conform with A.C. 43.13-1A ch. 11 Sec. 2.

#### PROCEDURE:

- 1) Identify the engine dash number and use the appropriate drawing. The transducer's dash number should match the dash number stamped on the instrument housing.
- 2) Shut off DC power, fuel valves and mixture controls, remove breather tube and replace with 33" MIL-H-600 3/4" ID hose covered with Aeroquip AE 102/624-18 fire sleeve. Route the hose as shown in Dwg. 4022-22 using a 742-D24C clamp to support the hose assembly.
- 3) Gain access to the top front section of the engine, locate and remove the injection pump to the flow divider hose. Fabricate new hose using 40 1/2" piece of 303 Aeroquip hose. Install the 491-4 end fitting per the attached instructions.
- 4) Rotate the 90 degree elbow (MS-51504) at the inlet of the flow divider 180 degrees to be pointing to the port side of the engine.
- 5) Use 14" piece of 601 hose to fabricate a new hose. Install the Aeroquip 816-4 fittings at each end. Install the fire sleeves and clamp it after proof testing.
- 6) Install, tighten the AN816-4-4 fitting and the bushing and fitting assembly.

Report: 4022  
Date: 12 December 1984  
Rev.: -  
Sec.: III.6  
=====

- 7) Remove the crankcase bolts. Install the transducer assembly into the engine as per 4022-22 with the inlet pointing to the right, retighten, refer to Teledyne Continental Overhaul Manual for recommended torque. Reconnect the 303 hose to the inlet of the transducer and the 14" 601 hose between the transducer outlet and the flow divider.
- 8) Connect the wires to the transducers using the B-14-D wristlocks, with plastic sleeves to insulate and secure them with tie wraps.
- 9) Turn the master switch on, fuel selectors on, run the booster pumps and check for leaks.
- 10) Start the engine and check the metered and unmetered fuel pressure. Readjust if necessary following air-frame and engine manufacturer instruction.
- 11) Make necessary entry into the engine logs.

Report: 4022  
Date: 24 June 1980  
Rev.: A  
Sec.: IV.1  
=====

## TECHNICAL SPECIFICATIONS

### INDICATOR SPECIFICATIONS

P/N:	9105xx or 9120xx
Maximum useable fuel:	900 Gallons
Maximum altitude:	40,000 ft.
Operating temperature:	-30 deg. C to 50 deg. C
Humidity:	up to 95% @ 32 deg. C
Flow Range: When used with P/N 680501	.6-60 GPH/Engine
When used with P/N 660526	1.5-70 GPH/Engine

### ELECTRICAL RATING

Input voltage:	14-28 Volt D.C
Input current:	400 ma @ 14V 28V DC

### MECHANICAL RATING

Vibration:	5g
Weight:	Panel Unit: 15 oz.

### TRANSDUCER SPECIFICATIONS

Fuel:	Aviation gasoline
P/N:	680501      660526
Linear Flow Range:	0.6-60 GPH    7-70 GPH
Linearity Across Flow Range, percent of reading:	+/-2%      +/-1%
Average K Factor (pulses/gal):	84,000      4,000
Pressure Drop: @ 15 GPH	.3 psi      .2 psi
@ 30 GPH	1.2 psi      .75 psi
@ 60 GPH	2.6 psi      1.7 psi
Minimum Bursting Pressure:	2000 psi    16000 psi
Temperature Range:	-65'C/125'C same
Life Expectancy:	5,000 hr.    12000 hr.
Spec:	TSO C-44a    TSO C-44a
Weight:	5 oz.      5 oz.

# STOP

YOUR AIRCRAFT MAY  
HAVE OPTIONAL  
EQUIPMENT INSTALLED  
THIS COULD CHANGE THE  
LENGTH OF FUEL LINES  
REQUIRED TO INSTALL  
THIS SYSTEM. PLEASE  
CHECK YOUR AIRCRAFT  
FOR PROPER LENGTH  
BEFORE CUTTING OR  
BUYING FUEL LINES.

United States of America  
Department of Transportation — Federal Aviation Administration  
**Supplemental Type Certificate**

*Number* SE552GL

*This certificate, issued to* Shadin Company, Inc.  
14280 N. 23rd Avenue  
Plymouth, Minnesota 55447

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 13 of the Civil Air Regulations.* See Type Certificate Data Sheet No. 3E1 for complete certification basis.

*Original Product — Type Certificate Number:* 3E1

*Make:* Teledyne Continental Motors

*Model:* IO-470-D, IO-470-J, IO-470-K, IO-470-L,  
IO-470-N, IO-470-U, IO-470-V, IO-470-V0,  
IO-470-E, IO-470-S

*Description of Type Design Change:*

Incorporation of a Fuel Flow Transducer in accordance with Shadin Company Report Number 4029, dated November 5, 1990, or later FAA Approved revisions.

*Limitations and Conditions:*

This approval should not be extended to other engines of these models on which other previously approved modifications are incorporated, unless it is determined by the installer that the interrelationship between this change and any other previously approved modifications will introduce no adverse effect on the airworthiness of these engines.

*This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.*

*Date of application:* July 14, 1981

*Date received:*

*Date of issuance:* August 25, 1981

*Date amended:* January 24, 1991



*By direction of the Administrator*

*Donald P. Michael*

Donald P. Michael, <sup>1st</sup> Deputy Manager  
Chicago Aircraft Certification Office

(Title)

*Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.*

*This certificate may be transferred in accordance with FAR 21.47.*

Shadin Company, Inc.  
14280 North 23RD Avenue  
Plymouth, MN 55447

Report: #4029  
Date July 14, 1981  
Revision Date : Nov. 5, 1990  
Subject: Fuel Flow Transducers  
Addition  
Teledyne Continental  
ID-470-D, U, V, VO, J,  
N, K, L, E, S

F A A  
A P P R O V E D

JAN 24 1991

CHICAGO AIRCRAFT  
CERTIFICATION OFFICE  
CENTRAL REGION

L7

Shadin Company, Inc.  
14280 North 23RD Avenue  
Plymouth, MN 55447

## REPORT #4029

Original Date: 14 July, 81  
Revision Date: 05 November, 90

PAGE CONTROL CHART  
-----

FAA  
APPROVED

JAN 24 1991

CHICAGO AIRCRAFT  
CERTIFICATION OFFICE  
CENTRAL REGION

L7

SEC. I.  
-----

Drawing List  
4029-21 Transducer Installation

DATE	REVISION
-----	-----
05 Nov. 90	A

SEC. II.  
-----

System Description  
Page 1  
Page 2

05 Nov. 90	A
05 Nov. 90	A

SEC. III.  
-----

Installation Procedure  
Page 1  
Page 2  
Page 3

05 Nov. 90	A
05 Nov. 90	A
05 Nov. 90	A

SEC. IV.  
-----

Technical Specifications  
page 1

05 Nov. 90	A
------------	---

Shadin Co., Inc.  
Report #: 4029  
Date: Nov. 5, 1990  
Rev: A  
Sec.: II.1

=====

### DIGITAL FUEL FLOW METER SYSTEM DESCRIPTION

Digiflo, the Digital Fuel Flow Meter, is designed to replace Analog Mechanical Fuel Flow Meters. It eliminates the fuel lines in such instruments from behind the panel. Digiflo can be used for both injected and or pressure carbureted engines. It maintains a high degree of accuracy (2 percent or better) which was not possible before. Digiflo provides additional functions such as time remaining, gallons used and gallons remaining.

The system consists of a fuel flow transducer, located in the fuel control unit and fuel flow divider which generates electrical pulses corresponding to the amount of fuel passing through. The transducer is designed in such a way that if the rotor is blocked it cannot interrupt the fuel flow to the engine.

The panel mounted unit contains all circuits necessary to count the generated pulses thorough the microprocessor and to display the fuel flow and other functions using permanently installed software. The fuel flow in gallons per hour is always displayed at the lower half of the instrument face. The time remaining, gallons used, and gallons remaining are continuously computed and either dislodged or stored for later display. The time remaining is displayed at the upper display window. Gallons remaining and gallons used share the same upper window and either can be displayed by pressing the appropriate button.

During power shut-down, the amount of fuel remaining is stored into the non volatile memory, which does not require a battery to retain the data.

Time remaining calculations are based on gallons remaining and actual fuel flow, which means that reducing the power or leaning the mixture will result in increasing the time remaining.

If the calculated time remaining at any particular power setting drops below 60 minutes, the "Time Remaining" digits in the display window will start flashing.

The test function will enable the pilot to check the software and hardware against any malfunction through simulating two sample rates and checking the results against stored results.

Shadin Co., Inc.  
Report: 4029  
Date: Nov. 5, 1990  
Rev.: A  
Sec.: II.2

=====


The accuracy of this instruments depends entirely upon the accuracy of the data entered. A periodical check of the actual fuel onboard will eliminate the accumulation of errors due to evaporation, leaks, theft, etc.

To match the transducer pulse count (K factor), (each transducer is marked with a dash number), to the microprocessor and to adapt it for use to a single or twin engines, one or two transducers per engine, a 6 pole DIP switch has been provided on the top board. The switch has been set to match the transducers shipped with the system. In case a transducer with a different dash number is being used, the instrument has to be recalibrated.

PARTS LIST			
ITEM	QTY.	PART NO.	DESCRIPTION
1	1	201-B/600501	TRANSDUCER
2	1	543003	BRACKET, MOUNTING
3	1	AN816-4-4	NIPPLE, FLARED, PIPE TH'D
4	3	816-4	AEROQUIP HOSE FITTING
5	14"	601-4	AEROQUIP HOSE
6	40.5"	303-4	AEROQUIP HOSE
7	14"	AE102/624-8	AEROQUIP FIRE SLEEVE
8	2	AN742-D24C	CLAMP
9	1	610504	FIRE SHIELD BOX
10	33'	AE102/624-18	AEROQUIP FIRE SLEEVE
11	33'	MIL-H-6000	HOSE - 3/4" ID
12	1	AN823-4	FITTING, ELBOW 45°
13	1	AN912-1	FITTING, BUSHING 1/4 - 1/8

NOTE: QUANTITIES SHOWN ARE FOR ONE ENGINE.

NO TEFLON TAPE SEALS ALLOWED ON FITTINGS.



REV. A NOV. 5 '90 REDRAWN - ADD -E, -S ENGINE

UNLESS OTHERWISE NOTED DIMENSIONS ARE IN INCHES		ORIGINAL DATE OF DRAWING 6-14-81		<b>SEADIN COMPANY, INC.</b> CHICAGO, ILLINOIS 60604, U.S.A.	
TOLERANCES:		DRAFTSMAN J. BEAUFOT		FUEL FLOW TRANSDUCER ADDITION	
		CHECKER		TELEDYNE CONTINENTAL	
		APPROVED		10-470-C, D, J, K, L, U, V, VO, N, E, S	
		SUBMITTED		CODE IDENT. NO.	
MATERIAL:		NEXT ASSEMBLY:		4029-21	REV. A
				SCALE	WGT.
				SHEET 1 OF 1	

Shadin Co., Inc.  
Report: 4029  
Date: Nov. 5, 1990  
Rev.: A  
Sec.: III.1  
=====

## INSTALLATION PROCEDURE

### GENERAL

A complete thorough familiarization and understanding of the system is necessary before commencing the installation. All work must conform with A.C. 43.13 1A ch. 11 sect. 2.

### PROCEDURE

- 1) Identify the engine dash number and use the appropriate drawing. The transducer's dash number should match the dash number stamped on the instrument housing.
- 2) Shut off DC power, fuel valves and mixture controls, remove breather tube and replace with 3/32" MIL-H-600 3/4" ID hose covered with Aeroquip AE 102/624-18 fire sleeve. Route the hose as shown in Dwg. 4029-21 using a 742-D24C clamp to support the hose assembly.
- 3) Gain access to the top front section of the engine, locate and remove the injection pump to the flow divider hose. Fabricate new hose using 40 1/2" piece of 303 Aeroquip hose. Install the 491-4 and fittings per the attached instructions.
- 4) Rotate the 90 deg elbow (MS-51504) at the inlet of the flow divider 180 deg to be pointing to the right side of the engine.
- 5) Use 15" piece of 601 hose to fabricate a new hose. Install the Aeroquip 816-4 fittings at each end using the attached instructions. Install the fire sleeves and clamp it after proof testing.
- 6) Install and tighten the AN816-4-4 fittings in the inlet side of the transducer. Install the AN 912-1 bushing into the transducer, then install the AN 823-4 45 deg. elbow in it and adjust the elbow to be pointing straight to the back.

Shadin Co., Inc.  
Report: 4029  
Date: Nov. 5, 1990  
Rev.: A  
Sec.: III.2

=====

- 7) Remove the crankcase bolts. Install the transducer assembly into the engine as per 4029-21 with the inlet pointing to the left, retighten, refer to Teledyne Continental Overhaul Manual for recommended torque.
- 8) Connect the wires to the transducers using the 8-14-D wrist-locks, with plastic sleeves to insulate and secure them with tie wraps.
- 9) Turn the master switch on, fuel selectors on, run the booster pumps and check for leaks.
- 10) Start the engine and check the metered and unmetered fuel pressure. Readjust if necessary following airframe and engine manufacturer instruction.
- 11) Make necessary entry into the engine logs.

Shadin Co., Inc.

Report: 4029

Date: Nov. 5, 1990

Rev.: A

Sec.: III.3

=====

#### ASSEMBLY INSTRUCTIONS FOR 303 HOSE AND 491 FITTINGS

- Step 1 Cut hose squarely to length. Use hose cut-off machine or fine tooth hacksaw. Do not remove cover.
- Step 2 Place socket in vise. Do not overtighten vise on thin walled sockets of lightweight fittings. Screw hose into socket until it bottoms. Back-off 1/4 turn.
- Step 3 Tighten nipple and nut on assembly mandrel.
- Step 4 Lubricate inside of hose and nipple threads liberally. Use lubricating oil or light grease.
- Step 5 Screw nipple into socket and hose using wrench on assembly tool hex. Nut must swivel freely when assembly tool is removed. Maximum allowable gap is 1/16 inch.
- Clean, inspect, proof test (see below)

#### ASSEMBLY INSTRUCTIONS FOR 601 HOSE AND 816 FITTINGS

- Step 1 Cut hose squarely to length. Use hose cut-off machine or fine tooth hacksaw. TO minimize wire braid flare-out, wrap hose with masking tape and saw through tape. Remove tape before step 2.
- Step 2 Insert hose in socket with a twisting, pushing motion until hose is in line with back of socket threads.
- Step 3 Important-mark hose position around hose at rear of socket. Use a grease pencil, painted line or tape.
- Step 4 Lubricate inside of hose and nipple threads liberally. Use SAE 30 lubricating oil. Avoid getting oil in the cutting spur of the nipple.
- Step 5 Carefully insert nipple and engage nipple and socket threads while holding hose in position with other hand. Make sure that hose does not push out of socket by observing mark made in step 3.
- Step 6 Complete assembly using wrench while continuing to hold in position. Maximum allowable gap is .041 inches in sizes 3,4, and 5, and .031 inches in size 6 and up.
- Step 7 IMPORTANT-check for hose push-out by observing hose position mark. None should be evident.
- Clean, inspect, proof test (see below)

#### CLEAN, INSPECT, PROOF TEST

1. CLEAN...Clean hose after cutting to length. Be sure all cutting residue is dislodged. After assembly, clean each hose assembly internally using clean, dry compressed air.
2. INSPECT...Examine hose assembly internally for cut or bulged inner tube, obstructions and cleanliness. Examine Aeroquip hose assemblies with "little gem" Fittings for hose push-out.

Shadin Co., Inc.  
Report: 4029  
Date: Nov. 5, 1990  
Rev.: A  
Sec.: IV.1  
=====

## TECHNICAL SPECIFICATIONS

### SPECIFICATIONS

Maximum useable fuel	1800 gallons
Maximum altitude:	40,000 ft.
Operating temperature:	-30 C to 50 C
Humidity:	up to 95% @ 32 C
Accuracy:	+/- 2%
Flow Range:	.6 - 60 GPH/Engine

### ELECTRICAL RATING

Input voltage:	14-28 volt D.C.
Input current:	500 ma @ 14V. or 28V. Avg.
Memory Battery (internal):	Rechargeable nickel cadmium GE 3.6V.

### MECHANICAL RATING

Vibration:	5g
Weight:	Panel Unit: 1.3 lb. Transducer: App. 5 oz

### TRANSDUCER SPECIFICATIONS

Model Number:	201B
Flow Range:	0.6-60 GPH
Linearity Across Flow Range, percent of reading:	+/- 1% (8-60 GPH) +/- 3% (0.6-60 GPH)

Average K Factor (pulses/Gal.): 84,000

Pressure Drop:	.3 psi @ 15 GPH
	1.2 psi @ 30 GPH
	2.6 psi @ 60 GPH

Working Pressure:	200 psi
Minimum Bursting Pressure:	2000 psi
Temperature Range:	-65 C/125 C
Life Expectancy:	5,000 hr.

**YOUR AIRCRAFT MAY  
HAVE OPTIONAL  
EQUIPMENT INSTALLED.  
THIS COULD CHANGE  
THE LENGTH OF FUEL  
LINES REQUIRED TO  
INSTALL THIS SYSTEM.  
PLEASE CHECK YOUR  
AIRCRAFT FOR PROPER  
LENGTH BEFORE  
CUTTING OR BUYING  
FUEL LINES.**



U.S. Department  
of Transportation  
Federal Aviation  
Administration

THESE RECORDS MAY BE RELEASABLE UNDER THE FOIA REQUEST 15  
DAYS AFTER SIGNATURE DATE UNLESS WE HEAR OTHERWISE FROM  
FAA NTSB COUNSEL

Mike Monroney  
Aeronautical Center

P.O. Box 25082  
Oklahoma City, Oklahoma 73125

Thursday, January 15, 2004

National Transportation Safety Board  
Atlanta Federal Ctr, Rm 3M25, 60 Forsyth Street, SW  
Atlanta, GA 30303

ACCIDENT # 0347 INDIVIDUAL#: 001 NAME: BENNAMAN, JOHN R. MODE: AVIATION  
DATE OF ACCIDENT 11/21/2003 DATE RECEIVED 12/03/2003 PUTREFACTION: No  
N# 4482S NTSB # ATL04FA038 CAMI REF # 200300347001  
LOCATION OF ACCIDENT GRIFFIN, GA  
SPECIMENS Bile, Blood, Brain, Gastric, Heart, Kidney, Liver, Lung, Muscle, Spleen, Urine, Vitreous

### FINAL FORENSIC TOXICOLOGY FATAL ACCIDENT REPORT

**CARBON MONOXIDE:** The carboxyhemoglobin (COHb) saturation is determined by spectrophotometry with a 10% cut off. Where possible, positive COHb values are confirmed by GC/TCD.

>> 13 (%) CARBON MONOXIDE detected in Blood

**CYANIDE:** The presence of cyanide is screened by Conway Diffusion. Positive cyanides are quantitated using spectrophotometry. The limit of quantitation of cyanide is 0.25 ug/mL. Normal blood cyanide concentrations are less than 0.15 ug/mL, while lethal concentrations are greater than 3ug/mL.

>> NO CYANIDE detected in Blood

**VOLATILES:** The volatile concentrations are determined by headspace gas chromatography at a cut off of 10 mg/dL. Where possible, positive ethanol values are confirmed by Radiative Energy Attenuation.

>> NO ETHANOL detected in Urine

**DRUGS:** Immunoassay and chromatography are used to screen for legal and illegal drugs which include: amphetamine (0.010), opiates (0.010), marijuana (0.001), cocaine (0.020), phencyclidine (0.002), benzodiazepines (0.030), barbiturates (0.060), antidepressants (0.100), antihistamines (0.020), meprobamate (0.100), methaqualone (0.100), and nicotine (0.050). The values in () are the threshold values in ug/mL used to report positive results. Values below this concentration are normally reported as not detected. GC/Mass Spec, HPLC/Mass Spec, or GC/FTIR, is used to confirm most positive results.

>> NO DRUGS LISTED ABOVE DETECTED in Urine

Dennis Canfield, PhD.  
Manager, Bioaeronautical  
Sciences Research Laboratory

Date: 2004.01.22  
15:02:59 -06'00'

# Osmose

December 1, 2003

Lieutenant James Landham  
Griffin Police Department  
868 W. Poplar St.  
Griffin, GA 30223

Lieutenant Landham:


I, Norma B. Jones, being receptionist for:

Osmose, Inc.  
1016 Everee Inn Rd.  
Griffin, GA 30224  
[REDACTED]

Wish to make the following statement concerning the airplane crash at Stowe-Woodward on Friday, November 21, 2003, at approximately 1 o'clock or a bit thereafter (I never looked at the clock).

I first thought I heard a freight train (loud noise), then looking up from our switchboard here in the Osmose lobby I actually saw the plane on impact. Next it looked like an explosion (fire and smoke) in the sky. Did nothing more than actually saw the plane on impact.

Respectfully,

  
Norma B. Jones

Randy Uecker

Osmose

016 Everree Inn Rd.  
Griffin, GA 30224

It was Friday 21, 2003 and a clear/cool day. Our company (Osmose) was having a luncheon for the employees out at the warehouse, which sits just at the end of the runway. I was late getting out there (just after 12:30). Most of the folks were already in the warehouse where the tables had been set. Since it was crowded, I found a nice spot outside in the sun. I was about 12 yards from the road (Ann St.) sitting at the end of a 3 ft.-high dividing wall. I was chatting with 2 others. Our conversation was in it's final words when the aircraft was rolling on the runway (at this moment - unnoticed). The other 2 guys had gathered their empty plates and were walking toward the warehouse as I looked up at the plane. The wonderful roar of the twin engines buzzing 100 ft. above my right shoulder just grabbed my attention. It was "just another take-off". Routine. Just like all the others I had seen in years past... The nose-up attitude was "normal" and nothing seemed like it was being "strained" or "bogged-down"... all was at full power. I saw that it was indeed a twin. It was light in color, either white or an off-white. I do not recall seeing any landing gear. Then, just as it had passed myself and was now even with our office building, one of the engines coughed (a kind of loud "Poof", not a "Bang") and immediately started sputtering. I do not remember hearing any pitch or power changes as the plane continued on. As the sputtering started, the plane started to roll to the left. At this point, I believe the craft to be somewhere between 100 and 200 ft. AGL. My first thought was that the pilot may be trying to turn back to the field for a landing. There were tall bushes in my line of sight, but I could see past (through) them. I was focused on the outline of the aircraft. The plane was obviously losing altitude and continued to turn slowly left. It looked to me that just before impact that the craft was mostly stalled. There were no abrupt movements to "stabilize" the aircraft, though it seemed to be leveling "some" (no longer rolling left). It was still in a left-wing-low and a nose-up attitude when it impacted. From my vantage point, I thought the plane had just cleared the building... I thought it crashed just behind the Stowe-Woodward Plant. Only a couple of seconds went by and there was already a large black plume of smoke rising skyward. Myself and several others sprinted toward the crash site. As I was running across our front parking lot is when I realized that it was on top of the Stowe-Woodward building.




Date: 12-1-03

Randy Uecker

I had just clocked in from lunch at approx. 1 p.m. and was standing in the parking lot when I heard a aircraft taking off. The engine was sputtering. As I continued to watch the plane gained a little altitude, then banked to the left as it was losing altitude. The plane disappeared behind the tree line and a huge explosion followed.

Brian Oldham  
Atlanta Air Recovery

I just clocked in from lunch, when I noticed  
an airplane taking off. It caught my  
attention because of the sputtering engine.  
The plane gained little altitude before  
banking to the left and disappearing behind  
the tree line into a big explosion.

  
Steven M. Ross  
Atlanta Air Recovery

# CUSTOMER WORK ORDER REPORT

## GARDNER AVIATION SPECIALIST, INC.

WO # 19054-AI Task 3 AV pg 1

FAA Certified Repair Station #

Cust Code: STJE Phone:

JERRY STEELE DEVELOPMENT CO.  
3786 HWY 20 EAST  
MCDONOUGH, GA 30253 USA



Item	
Part #	
Model	
Serial #	
Mfr.	
Discrep.	INSTALL SHADIN FUEL FLOW

A/C Tail #	N4482S		
A/C Make	BEECH		
A/C Model	95-B55	Ser#	TC-1882
Job Status	OPENED		
Job type	STANDARD		
Open Date	Oct-02-2003 Thursday		
Promised			
Started	Nov-05-2003 Wednesday		
Finished			
Printed	Nov-22-2003 Saturday 11:01		

**Discrepancy & Corrective Action**

REMOVED T10028 FUEL FLOW INDICATOR.

INSTALLED SHADIN DIGIFLO-L FUEL FLOW INDICATOR PN:910532P SN:4888 AND FUEL FLOW TRANSDUCERS PN:68050-A1 SN:130436 AND SN:130437. INTERFACED THE INDICATOR TO THE GARMIN GNS430. INSTALLED THIS SYSTEM IN ACCORDANCE WITH SHADIN REPORT# 4036 DATED SEPT 10, 1986 AND STC# SA579GL. INSTALLED FUEL FLOW TRANSDUCERS IN ACCORDANCE WITH SHADIN REPORT# 4029 DATED NOV 5, 1990 AND STC# SE552GL. NOTE: THAT THE K FACTOR IS SET AT 29.8. COMPLETED FAA FORM 337.

Labor Date	Empl	Description	Hrs
13Nov2003	Thu	JHICKS	1.00 RG
13Nov2003	Thu	JHICKS	1.00 RG
13Nov2003	Thu	JHICKS	0.60 RG
11Nov2003	Tue	JHICKS	2.00 RG
14Nov2003	Fri	JHICKS	6.50 RG
17Nov2003	Mon	JHICKS	2.60 RG
17Nov2003	Mon	FRANK	8.00 RG
17Nov2003	Mon	ALRU	2.30 RG
17Nov2003	Mon	JHICKS	2.80 RG
18Nov2003	Tue	FRANK	4.10 RG
18Nov2003	Tue	FRANK	2.90 RG
19Nov2003	Wed	ALRU	1.00 RG

Equip Model	Description	Qty
910532P \ 4888	SHADIN DIGIFLO-L	1
KIT A-1 \ 130436	FUEL TRANSDUCER	1
KIT A-1 \ 130437	FUEL TRANSDUCER	1

Part Number Used	SKU Description	Qty
IK-9337	18767 INST KIT	1.00
491-4	3821 FITTING	6.00
816-4	4908 FITTINGS	6.00
AN912-1	18802	4.00
7277-2-2	4647 CIRCUIT BREAKER	1.00
7277-2-7-1/2	4652 CIRCUIT BREAKER	1.00
225554-6	2566 90 DEGREE TNC, RG142-400	1.00
UG88	17024 CONNECTOR BNC DUAL CRIMP MALE	2.00
UG89	18728 CONNECTOR BNC DUAL CRIMP FEMAL	1.00

Other type	Description	Qty
SHIP UPS NDA	FROM EDMO	1.00
SHIP UPS NDA	FROM SHADDIN	1.00
SHIP UPS NDA	FROM EDMO	1.00

**MAINTENANCE RELEASE / RETURN TO SERVICE CRS# G3SR222J**

The aircraft, airframe, engine, or appliance identified above was repaired and inspected in accordance with current regulations of the FAA and is approved for return to service.

Inspector / Authorized Signature

Certificate #

Date

PART NUMBER: 910532P  
SERIAL NUMBER: 4888  
INVOICE NUMBER: 758902  
DATE: 11-06-03

L: 29.8 Left K-Factor (where XXXXXX is valid from 0 to 20,000. These are in 10's. A setting of 1234 would be a K-Factor of 12,340)

R(r): 29.8 Right K-Factor

U

Units:  
0 = Gallons ✓  
1 = Liters  
2 = Lbs 5.8  
3 = Lbs 6.7  
4 = Kilograms  
5 = Lbs 6.5  
6 = Lbs 6.35

E

Engine Type:  
0 = Single Engine  
1 = Twin Engine ✓

O

Output Type:  
0 = Off  
1 = King  
2 = AirData  
3 = Arnav  
4 = Trimble  
5 = Garmin ✓

I

Loran Input:  
0 = Off  
1 = On ✓

F

Filter Type: ✓  
0 = Injector  
1 = Carburetor

★★★★ ATTENTION ★★★★★


1. It is the responsibility of the installing agency to verify the settings of Shadin Fuel Flow Systems and or Air Data Computers.
2. The installation of other than Shadin approved parts is possibly an unapproved installation and may not be covered under warranty.

# NOTES:




1. ALL LINEAR DIMENSIONS ARE REFERENCE ONLY.
2. TO INSTALL FITTINGS, APPLY THREAD SEALANT IN ACCORDANCE WITH AC 43.13. TORQUE FITTINGS TO 15 FT-LBS MAX. DO NOT USE TEFLON TAPE.
3. INSTALL TRANSDUCER IN HORIZONTAL POSITION WITH WIRES ON TOP.
4. REFER TO KIT A-1 PARTS LIST.

## WIRE TABLE

COLOR	SIGNAL NAME
BLACK	GROUND
WHITE	SIGNAL
RED	POWER 12VDC



1/4" NPT (x2)







UNLESS OTHERWISE NOTED DIMENSIONS ARE IN INCHES TOLERANCES: $\pm .01$					DRAWING DATE 9/17/02 DRAFTER PAB APPROVED PJD		<b>SHADIN CO., INC.</b> MINNEAPOLIS, MN 55426		
FINISH: N/A MATERIAL: N/A SCALE: NONE					FILE NAME KITAI-JDWG DIRECTORY INSTALL_KIT		INSTALL DWG, KIT A1, 680501A		
0208/014 - 9-19-02 PAB PJD BASELINE RELEASE ECO # REV. DATE BY APP'D DESCRIPTION					DRAWING NO. 4005-E34		SIZE A		P/N KIT A1

# NOTES:

1. ALL LINEAR DIMENSIONS ARE REFERENCE ONLY.
2. TO INSTALL FITTINGS, APPLY THREAD SEALANT IN ACCORDANCE WITH AC 43.13. TORQUE FITTINGS TO 15 FT-LBS MAX. DO NOT USE TEFLON TAPE.
3. INSTALL TRANSDUCER IN HORIZONTAL POSITION WITH WIRES ON TOP.
4. REFER TO KIT A-1 PARTS LIST.

WIRE TABLE	
COLOR	SIGNAL NAME
BLACK	GROUND
WHITE	SIGNAL
RED	POWER 12VDC





0208/014	-	9-19-02	PAB	PJD	BASELINE RELEASE
ECO #	REV.	DATE	BY	APP'D	DESCRIPTION

UNLESS OTHERWISE NOTED DIMENSIONS ARE IN INCHES TOLERANCES: $\pm 20^\circ$		DRAWING DATE 9/17/02	SHADIN CO., INC. MINNEAPOLIS, MN 55426	
FINISH: N/A		DRAWN BY PAB	INSTALL DWG, KIT A1, 680501A	
MATERIAL: N/A		APPROVED BY PJD	DRAWING NO. 4005-E34	
SCALE: NONE		FILE NAME KITAI-JDWG	SIZE A	REV -
		DIRECTORY INSTALL_KITS	P/N KIT A1	
		SHEET 1 OF 1		

**National Transportation Safety Board**  
RELEASE OF AIRCRAFT WRECKAGEACCIDENT IDENTIFICATION  
NUMBER  
ATL-04-F-A038

## PART 1 -- RELEASE OF AIRCRAFT WRECKAGE

REGISTERED OWNER (name and address) International Loss Management 35 Technology Parkway South Norcross GA 30092		REGISTRATION NUMBER - N 4482S
		MAKE BE-95
MODEL Beech	DATE OF ACCIDENT 11/23/03	LOCATION Griffin, GA
The National Transportation Safety Board has <input checked="" type="checkbox"/> has not <input type="checkbox"/> completed its investigation of the aircraft wreckage described above. All wreckage except that listed on the reverse side is hereby released to the registered owner, or owner's representative, for appropriate disposition. (If no parts are retained, insert NONE.)		
SIGNATURE OF NTSB REPRESENTATIVE 		TITLE Aviation Safety Investigator
		DATE 07/02/04
(This section may be signed by a person, not the owner's representative, who has the knowledge of the disposition of the wreckage and its parts. Such signature does not place a responsibility for disposition of the wreckage upon that person.)		
I HEREBY ACKNOWLEDGE: <input checked="" type="checkbox"/> Receipt of the above described aircraft wreckage. <input checked="" type="checkbox"/> Removal of the parts, if any, listed on the reverse side of this form.		
SIGNATURE 		TITLE For underwriter
		DATE 7/5/04
REMARKS Received, As released by the NTSB. Parts and wreckage have not been inventoried.		

<b>National Transportation Safety Board</b> RECEIPT OF AIRCRAFT PARTS	<b>ACCIDENT IDENTIFICATION NUMBER</b> ATL-04-F-A038
--	--

## PART II -- RELEASE OF AIRCRAFT PARTS

<b>REGISTRATION NUMBER</b> 4482S	<b>MAKE</b> BE-95	<b>MODEL</b> Beech
<b>DATE OF ACCIDENT</b> 11/23/03	<b>LOCATION</b> Griffin, GA	

The National Transportation Safety Board has retained, for further examination, those parts, pieces, or components listed below. When the examination is complete, they will be returned to:


OWNER OR OWNER'S REPRESENTATIVE --  
ADDRESS

*INTERNATIONAL LOSS MANAGEMENT*  
*35 Technology Parkway South*  
*Norcross GA 30092*

## PARTS, PIECES, OR COMPONENTS RETAINED:

*PROPELLER LEFT PNC-C34F-2UF*  
*SN- EB5395B*

*PROPELLER Right PNC-C34F-2UF*  
*EB5396B*

<b>SIGNATURE OF NTSB REPRESENTATIVE</b> 	<b>TITLE</b> Aviation Safety Investigator	<b>DATE</b> 07/02/04
--	--	-------------------------

The registered owner or owner's representative will acknowledge receipt of the material by signing this form in the spaces designated

<b>SIGNATURE OF OWNER OR OWNER'S REPRESENTATIVE</b> ADDRESS	<b>TITLE</b>	<b>DATE</b>
--	--------------	-------------

**ENGINE FAILURE AFTER LIFT-OFF  
AND IN FLIGHT**

An immediate landing is advisable regardless of take-off weight. Continued flight cannot be assured if take-off weight exceeds the weight determined from the TAKE-OFF WEIGHT graph. Higher take-off weights will result in a loss of altitude while retracting the landing gear and feathering the propeller. Continued flight requires immediate pilot response to the following procedures.

1. Landing Gear and Flaps - UP
2. Throttle (inoperative engine) - CLOSED
3. Propeller (inoperative engine) - FEATHER
4. Power (operative engine) - AS REQUIRED
5. Airspeed - MAINTAIN SPEED AT ENGINE FAILURE (100 KTS (115 MPH) MAX.) UNTIL OBSTACLES ARE CLEARED

*After positive control of the airplane is established:*

6. Secure inoperative engine:
  - a. Mixture Control - IDLE CUT-OFF
  - b. Fuel Selector - OFF
  - c. Fuel Boost Pump - OFF
  - d. Magneto/Start Switch - OFF
  - e. Generator/Alternator Switch - OFF
  - f. Cowl Flap - CLOSED
7. Electrical Load - MONITOR (Maximum load of 1.0 on remaining engine)

**NOTE**

The most important aspect of engine failure is the necessity to maintain lateral and directional control. If airspeed is below 78 kts (90 mph), reduce power on the operative engine as required to maintain control.

## Brief of Accident

Adopted 9/13/2005

ATL04FA038

File No. 18063

11/21/2003

Griffin, GA

Aircraft Reg No. N4482S

Time (Local): 12:45 EST

Make/Model: Beech / 55  
 Engine Make/Model: Continental / IO-470L-21B  
 Aircraft Damage: Destroyed  
 Number of Engines: 2  
 Operating Certificate(s): None  
 Type of Flight Operation: Flight Test  
 Reg. Flight Conducted Under: Part 91: General Aviation

	Fatal	Serious	Minor/None
Crew	1	0	0
Pass	0	0	0

Last Depart. Point: Same as Accident  
 Destination: Griffin, GA  
 Airport Proximity: Off Airport/Airstrip

Condition of Light: Day  
 Weather Info Src: Weather Observation Facility  
 Basic Weather: Visual Meteorological Cond  
 Lowest Ceiling: None  
 Visibility: 10.00 SM  
 Wind Dir/Speed: Calm  
 Temperature (°C): 22  
 Obstr to Vision: No Obscuration; No Precipitation  
 Precipitation:

Pilot-in-Command Age: 47

Flight Time (Hours)

Certificate(s)/Rating(s)

Commercial; Multi-engine Land; Single-engine Land; Glider

Instrument Ratings

Airplane

Total All Aircraft: 2500

Last 90 Days: 50

Total Make/Model: Unk/Nr

Total Instrument Time: 400

According to the company's chief maintenance inspector, the purpose of the flight was to conduct a maintenance test flight of the airplane on recently installed equipment the pilot/ mechanic had just completed. Before engine start-up the pilot/ mechanic conducted a pre-flight of the airplane, and then taxied out to the ramp and ran the engine up to full rpm three consecutive times before the test flight. The pilot taxied to runway 32, and proceeded to add full power for take-off. As the airplane began to rotate for climb out the engines sounded like they began to "backfire". The engines continued to make this sound as it climbed out. The airplane climbed approximately 200 feet and the left wing pitch down. The airplane descended under the tree line and a "loud explosion" was heard. The airplane collided with a building a quarter mile from the departure end of runway 32. Post-accident examination of the cabin section, main fuselage, and wing assemblies revealed that they were fire damaged. All flight control and communication instruments were fire damaged. Post-accident examination of blades from both propeller assemblies revealed rotational scoring. Post-accident examination of the propellers revealed both propellers were rotating and not in the feathered position. There were no pre-impact mechanical anomalies noted with the propeller blades. Review of the maintenance work order revealed that a Shadin Digilfo-L fuel flow indicator and fuel flow transducers on the right and left engines were installed by the pilot/mechanic prior to the flight. Post-accident examination of left fuel flow transducer serial number 130436 revealed it was charred, and the inlet hose coupler was not as tight as the outlet hose coupler. Fuel was poured into the inlet side of the transducer, and the outlet flow was restricted. The fitting on the inlet side was removed and the inlet was inspected. Debris was found around the inlet orifice. After removing the debris from the Fuel flow transducer, fuel was again poured into the inlet and fuel exited the outlet without restriction to flow. Post examination of the right fuel flow transducer serial number 130437 revealed it was intact with no visible damage, and both hose couplers were tight. Fuel was poured into the inlet side of the transducer, and the fuel exited the outlet side of the transducer without visible restriction to flow.

Occurrence #1: LOSS OF ENGINE POWER  
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. ALL ENGINES
  2. (F) MAINTENANCE,MODIFICATION - IMPROPER - PILOT IN COMMAND
  3. (F) FUEL SYSTEM,LINE - BLOCKED(PARTIAL)
  4. (F) FUEL SYSTEM - STARVATION
- 

Occurrence #2: FORCED LANDING  
Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: LOSS OF CONTROL - IN FLIGHT  
Phase of Operation: DESCENT - EMERGENCY

Findings

5. (C) PROCEDURES/DIRECTIVES - NOT FOLLOWED - PILOT IN COMMAND
  6. (C) PROPELLER FEATHERING - NOT PERFORMED - PILOT IN COMMAND
- 

Occurrence #4: IN FLIGHT COLLISION WITH OBJECT  
Phase of Operation: DESCENT - UNCONTROLLED

Findings

7. OBJECT - BUILDING(NONRESIDENTIAL)

Findings Legend: (C) = Cause, (F) = Factor

---

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

A loss of engine power due to the pilot's failure to follow the engine failure after liftoff emergency procedure to feather the left engine propeller resulting in a loss of control during climbout, and the subsequent collision with a commercial building. A factor was the fuel starvation of the left engine due to debris in the fuel line.